



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37925
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	5/23/2022 10:59 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	65.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Reinforce Filter Fence)	Communication	Repair SSF 3 locations	48 Hours	
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions



Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/23/2022 10:59 AM	<b>Report #</b>	37925
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Completed a regular scheduled VADEQ SWPPP inspection on private and JNF property on Brush Mountain. The ROW surface remains stable with adequate grasses and/or straw mulch present to prevent rilling of soils. Slope breakers are functioning properly. No erosion is being caused by stormwater runoff. Sumps and yend treatments are acceptable. No impact has occurred at resource crossings. Resource buffers are stable with vegetation and adequate ECDs in place. Perimeter ECDs are in place. ECD maintenance needs identified today will be given to the contractor. Three items were identified.</p> <p>Re-attach SSF fabric to chain link fence at 11642+00, 11643+00 and 11644+00. There was no impact at either location.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	5/23/2022 10:59 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11668+50	<b>Field Station#</b>	11663+00		
<b>Pic 1 Desc.</b>	Stable conditions at top of Brush Mountain.	<b>Pic 2 Desc.</b>	Slope breakers functional. ROW stable.		
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11661+00	<b>Field Station#</b>	11645+00		
<b>Pic 3 Desc.</b>	ECDs in place.	<b>Pic 4 Desc.</b>	ECDs in place.		
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11626+04	<b>Field Station#</b>	11614+20		
<b>Pic 5 Desc.</b>	The S-HH18 crossing is stable.	<b>Pic 6 Desc.</b>	The S-RR14 crossing is stable.		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/23/2022 10:59 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Mon, May 23, 2022, 09:02:18 EDT Position: -037.313576, 39.08049415 (±5.0m) Altitude: 582m (±4.0m) Datum: WGS-84 Azimuth/Bearing: 200° S20W 3956mils Magnetic (±12°) Elevation Angle: -35.1° Horizon Angle: +01.1° Zoom: 1.0X S-006</small></p>		 <p><small>Date &amp; Time: Mon, May 23, 2022, 08:57:39 EDT Position: -037.313576, 39.08049415 (±5.0m) Altitude: 582m (±4.0m) Datum: WGS-84 Azimuth/Bearing: 200° S20W 3956mils Magnetic (±12°) Elevation Angle: -35.1° Horizon Angle: +01.1° Zoom: 1.0X 11644+00 repair SSF</small></p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11607+81	<b>Field Station#</b>	11644+00		
<b>Pic 7 Desc.</b>	The S-006 crossing is stable.	<b>Pic 8 Desc.</b>	COMMUNICATION; photo example of SSF repair requested.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/23/2022 10:59 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37939
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	5/23/2022 12:53 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11899+89
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	65.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.40
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Roadside Ditch	Acceptable			
Rock Check Dam	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/23/2022 12:53 PM	<b>Report #</b>	37939
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Completed VA SWPPP inspection from ST# 11899+89 (AR 266.03) to ST# 12005+00 (Spread Break)          Accompanied by fellow EI Daniel Fortune on SWPPP inspection from MP 225.37 to MP 227.37.          No compliance issues found.          Active construction site; additional deficiencies may be identified by other EIs.          Observed no environmental maintenance crews actively working on this section of ROW at time of inspection.          This section of ROW has undergone permanent restoration and vegetation is present. Permanent waterbars (section 6 other) with level spreaders, and perimeter controls are in place where designated on E&amp;S sheets.          Triple barrier sensitive resource buffers are in place at karst features.          AR 266 and 266.03 are maintained in acceptable condition. Broad based dips with end treatments, and roadside ditch with rock check dams are in place.          The ROW is wet and in stable condition. No sensitive resources have been impacted.          Light rain throughout duration of inspection. Catawba rain gauge measured 0.4" of accumulated rainfall.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	5/23/2022 12:53 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Mon, May 23, 2022, 10:11:00 EDT  Position: +037.25241° / +080.33211° (+11.1°)  Altitude: 2280ft (+9.8ft)  Datum: WGS-84  Azimuth/Bearing: 011° N28E 042mils True (+10°)  Elevation Grade: +00%  Horizon Grade: +00%  Zoom: 0.5X  11903+25</p> 		<p>Date &amp; Time: Mon, May 23, 2022, 10:16:58 EDT  Position: +037.25241° / +080.33211° (+11.1°)  Altitude: 2280ft (+9.8ft)  Datum: WGS-84  Azimuth/Bearing: 025° N28E 042mils True (+10°)  Elevation Grade: +00%  Horizon Grade: +00%  Zoom: 0.5X  11910+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11903+25	<b>Field Station#</b>	11910+00		
<b>Pic 1 Desc.</b>	Level spreader in place	<b>Pic 2 Desc.</b>	Permanent vegetation present		
<p>Date &amp; Time: Mon, May 23, 2022, 09:38:07 EDT  Position: +039.28274° / +080.33022° (+15.5ft)  Altitude: 2390ft (+11.1ft)  Datum: WGS-84  Azimuth/Bearing: 301° N59W 595mils True (+12°)  Elevation Grade: +03%  Horizon Grade: +00%  Zoom: 0.5X  11925+00</p> 		<p>Date &amp; Time: Mon, May 23, 2022, 09:45:15 EDT  Position: +039.28106° / +080.33377° (+10.8ft)  Altitude: 2390ft (+11.1ft)  Datum: WGS-84  Azimuth/Bearing: 301° N59W 595mils True (+12°)  Elevation Grade: +01%  Horizon Grade: +00%  Zoom: 0.5X  11930+50</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11925+00	<b>Field Station#</b>	11930+50		
<b>Pic 3 Desc.</b>	CFS perimeter control in place	<b>Pic 4 Desc.</b>	P1 silt fence perimeter control in place		
<p>Date &amp; Time: Mon, May 23, 2022, 09:16:49 EDT  Position: +039.25597° / +080.33597° (+13.5ft)  Altitude: 1930ft (+13.3ft)  Datum: WGS-84  Azimuth/Bearing: 335° N55W 530mils True (+10°)  Elevation Grade: +00%  Horizon Grade: +00%  Zoom: 0.5X  11974+50</p> 		<p>Date &amp; Time: Mon, May 23, 2022, 09:18:19 EDT  Position: +039.25597° / +080.33597° (+13.5ft)  Altitude: 1930ft (+13.3ft)  Datum: WGS-84  Azimuth/Bearing: 007° N55E 116mils True (+15°)  Elevation Grade: +00%  Horizon Grade: +00%  Zoom: 1.25X  11988+25</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11974+50	<b>Field Station#</b>	11988+25		
<b>Pic 5 Desc.</b>	Waterbars in place	<b>Pic 6 Desc.</b>	RCE in place		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/23/2022 12:53 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	5/23/2022 12:53 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37913
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	5/23/2022 6:56 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	65.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			







## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No







<b>A/E</b>	124300137	<b>Date/Time</b>	5/23/2022 6:56 AM	<b>Report #</b>	37913
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Completed a VA SWPPP at LY 029. The perimeter controls consist of 18" triple stacked CFS in place and functioning as designed. The RCE was clean, no mud or other debris on road. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified.</p> <p>Completed a VA SWPPP at LY 028. The perimeter controls CFS in place and functioning as designed. The RCE was clean, no mud or other debris on road. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified.</p> <p>Completed a VA SWPPP at LY 026. The perimeter controls CFS functioning as designed. The RCE was clean, no mud or other debris on road. The yard was free of debris. Used oils were stored properly in secondary containment. The generator and air compressor were in secondary containment that was maintained properly. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified. Construction of a neighboring company started which affects our parking lot / Will monitor progress.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/23/2022 6:56 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	Permanent stabilization in place y28		Pic 2 Desc.	CFS perimeter controls functional y28	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	CFS perimeter controls functional y28		Pic 4 Desc.	RCE functional y28	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	CFS perimeter controls functional y28		Pic 6 Desc.	Containment in place	



<b>AFE</b>	124300137	<b>Date/Time</b>	5/23/2022 6:56 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Mon, May 23, 2022 08:56:09 EDT  Position: +037.361090 / -080.679932 (+15.5h)  Altitude: 1677ft (+11.1h)  Datum: WGS-84  Azimuth/Bearing: 331° N2W 588mils True (+10°)  Elevation Angle: -36.4°  Horizon Angle: -109.0°  Zoom: 2.0X  y29</p> 		<p>Date &amp; Time: Mon, May 23, 2022 08:58:09 EDT  Position: +037.355850 / -080.678749 (+15.5h)  Altitude: 1700ft (+11.9h)  Datum: WGS-84  Azimuth/Bearing: 264° S44W 4493mils True (+10°)  Elevation Angle: -29.5°  Horizon Angle: -10.3°  Zoom: 2.0X  y29</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 7 Desc.</b>	RCE functional y29	<b>Pic 8 Desc.</b>	Broad base dips functional y29		
<p>Date &amp; Time: Mon, May 23, 2022 08:51:51 EDT  Position: +037.362275 / -080.679291 (+15.5h)  Altitude: 1718ft (+11.1h)  Datum: WGS-84  Azimuth/Bearing: 173° S07E 3076mils True (+10°)  Elevation Angle: -56.5°  Horizon Angle: -105.7°  Zoom: 1.0X  y29</p> 		<p>Date &amp; Time: Mon, May 23, 2022 09:01:06 EDT  Position: +037.362425 / -080.679381 (+15.5h)  Altitude: 1700ft (+11.0h)  Datum: WGS-84  Azimuth/Bearing: 341° S11W 4003mils True (+10°)  Elevation Angle: -41.5°  Horizon Angle: -101.1°  Zoom: 1.0X  y29</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 9 Desc.</b>	Culvert in place y29	<b>Pic 10 Desc.</b>	Housekeeping trash in good condition y29		
<p>Date &amp; Time: Mon, May 23, 2022 09:04:04 EDT  Position: +037.363185 / -080.679581 (+15.5h)  Altitude: 1700ft (+11.1h)  Datum: WGS-84  Azimuth/Bearing: 162° N2W 590mils True (+10°)  Elevation Angle: -40.3°  Horizon Angle: -101.1°  Zoom: 1.0X  y29</p> 		<p>Date &amp; Time: Mon, May 23, 2022 09:04:04 EDT  Position: +037.363185 / -080.679581 (+15.5h)  Altitude: 1712ft (+11.7h)  Datum: WGS-84  Azimuth/Bearing: 270° W00W 430mils True (+10°)  Elevation Angle: -38.7°  Horizon Angle: -102.7°  Zoom: 1.0X  y29</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 11 Desc.</b>	Permanent stabilization in place y29	<b>Pic 12 Desc.</b>	CFS perimeter controls functional y29		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/23/2022 6:56 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time Mon, May 23, 2022 05:25:05 EDT  Position: +037.519309° / -080.48345° (±11.81)  Altitude: 1798ft (±11.1ft)  Datum: WGS-84  Azimuth/Bearing: 040° N40E 135mils True (±10°)  Elevation Angle: +89.2°  Horizon Angle: -00.5°  Zoom: 1.0X  y26</p> 		<p>Date &amp; Time Mon, May 23, 2022 05:25:05 EDT  Position: +037.519309° / -080.48345° (±11.81)  Altitude: 1798ft (±11.1ft)  Datum: WGS-84  Azimuth/Bearing: 207° N207W 402mils True (±10°)  Elevation Angle: +89.2°  Horizon Angle: -00.5°  Zoom: 1.0X  y26</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 13 Desc.</b>	CFS perimeter controls functional y26	<b>Pic 14 Desc.</b>	Construction zone in parking lot monitoring it.y26		
<p>Date &amp; Time Mon, May 23, 2022 05:25:05 EDT  Position: +037.519309° / -080.48345° (±11.81)  Altitude: 1804ft (±11.7ft)  Datum: WGS-84  Azimuth/Bearing: 207° N207W 402mils True (±10°)  Elevation Angle: +89.2°  Horizon Angle: -00.5°  Zoom: 1.0X  y26</p> 		<p>Date &amp; Time Mon, May 23, 2022 05:25:05 EDT  Position: +037.519309° / -080.48345° (±11.81)  Altitude: 1804ft (±11.7ft)  Datum: WGS-84  Azimuth/Bearing: 191° N191E 403mils True (±12°)  Elevation Angle: +89.2°  Horizon Angle: -00.5°  Zoom: 1.0X  y26</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 15 Desc.</b>	Housekeeping trash in good condition y26	<b>Pic 16 Desc.</b>	Secondary containment in place y26		
<p>Date &amp; Time Mon, May 23, 2022 05:25:05 EDT  Position: +037.519309° / -080.48345° (±11.81)  Altitude: 1804ft (±11.7ft)  Datum: WGS-84  Azimuth/Bearing: 207° N207W 402mils True (±10°)  Elevation Angle: +89.2°  Horizon Angle: -00.5°  Zoom: 2.0X  y26</p> 		<p>Date &amp; Time Mon, May 23, 2022 05:25:05 EDT  Position: +037.519309° / -080.48345° (±11.81)  Altitude: 1804ft (±11.7ft)  Datum: WGS-84  Azimuth/Bearing: 191° N191E 403mils True (±12°)  Elevation Angle: +89.2°  Horizon Angle: -00.5°  Zoom: 1.0X  y26</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 17 Desc.</b>	Secondary containment in place y26	<b>Pic 18 Desc.</b>	RCE functional y26		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37944
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/23/2022 4:11 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11899+89
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	68.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/23/2022 4:11 PM	<b>Report #</b>	37944
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from ST# 11788+52 (Mount Tabor Road) to ST# 11899+89 (AR 266.03) Accompanied by EI Trey Ingram on SWPPP inspection from MP 223.27 to MP 225.37. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Environmental crews rained out due to projected weather forecast. This section of ROW has undergone permanent restoration. Permanent waterbars (section 6 other) and level spreaders in place where designated on E&S sheets. Majority of perimeter controls have been removed due to final restoration vegetation growth. Sensitive resource buffers are in place at pond P-KL2. Mount Tabor road crossing RCE is maintained and in acceptable condition. No sensitive resources have been impacted. Checked rain gauge at Mount Tabor Road. Gauge reading was trace.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE		124300137		Date/Time		5/23/2022 4:11 PM		Report #							
Pictures															
				<p>Date &amp; Time: Mon, May 23, 2022, 08:45:05 EDT Position: #037 298992 / -080 344286 (±15.4ft) Altitude: 2133ft (±11.2ft) Datum: WGS-84 Azimuth/Bearing: 035° N35E 0622mils True (±14°) Elevation Angle: -15.1° Horizon Angle: -02.7° Zoom: 1.0X 11864+00</p>								<p>Date &amp; Time: Mon, May 23, 2022, 08:46:01 EDT Position: #037 298992 / -080 344286 (±15.4ft) Altitude: 2133ft (±11.2ft) Datum: WGS-84 Azimuth/Bearing: 267° S67W 439mils True (±14°) Elevation Angle: -05.3° Horizon Angle: -00.4° Zoom: 1.0X 11890+00</p>			
GPS Location				See photo for GPS location.				GPS Location				See photo for GPS location.			
Field Station#				11864+00				Field Station#				11890+00			
Pic 1 Desc.				Sensitive resource P-KL2.				Pic 2 Desc.				ROW permanently stabilized. Waterbar and level spreader in place.			
				<p>Date &amp; Time: Mon, May 23, 2022, 09:15:03 EDT Position: #037 298660 / -080 346861 (±16.2ft) Altitude: 2196ft (±17.2ft) Datum: WGS-84 Azimuth/Bearing: 062° N27W 0782mils True (±14°) Elevation Angle: -13.4° Horizon Angle: -04.3° Zoom: 1.0X 11853+00</p>								<p>Date &amp; Time: Mon, May 23, 2022, 09:15:03 EDT Position: #037 298660 / -080 346861 (±16.2ft) Altitude: 2196ft (±17.2ft) Datum: WGS-84 Azimuth/Bearing: 062° N44E 0782mils True (±10°) Elevation Angle: -10.6° Horizon Angle: -00.4° Zoom: 1.0X Tabor</p>			
GPS Location				See photo for GPS location.				GPS Location				See photo for GPS location.			
Field Station#				11853+00				Field Station#				11789+00			
Pic 3 Desc.				ROW restored. Waterbars and level spreaders in place.				Pic 4 Desc.				Rain gauge at Mount Tabor Road reads 0.01.			
				<p>Date &amp; Time: Mon, May 23, 2022, 09:16:50 EDT Position: #037 298660 / -080 346861 (±16.2ft) Altitude: 2140ft (±33.1ft) Datum: WGS-84 Azimuth/Bearing: 342° N34W 6080mils True (±15°) Elevation Angle: -13.4° Horizon Angle: -00.6° Zoom: 1.0X 11889+00</p>								<p>Date &amp; Time: Mon, May 23, 2022, 09:16:50 EDT Position: #037 298660 / -080 346861 (±16.2ft) Altitude: 2140ft (±33.1ft) Datum: WGS-84 Azimuth/Bearing: 342° N18W 6080mils True (±15°) Elevation Angle: -13.4° Horizon Angle: -00.6° Zoom: 1.0X 11889+00</p>			
GPS Location				See photo for GPS location.				GPS Location				See photo for GPS location.			
Field Station#				11790+00				Field Station#				11789+00			
Pic 5 Desc.				Super silt fence in place along LOD.				Pic 6 Desc.				RCE in place at Mount Tabor Road.			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/23/2022 4:11 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/23/2022 4:11 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37915
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	5/23/2022 7:31 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+52
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	65.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/23/2022 7:31 AM	<b>Report #</b>	37915
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 221.02 (11670+00) to MP 223.27 (11788+52). Accompanied by fellow EI Clint Sears. Inspection performed prior to and during rain event. No issues identified. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	5/23/2022 7:31 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11671+50	<b>Field Station#</b>	11687+42		
<b>Pic 1 Desc.</b>	Section of RoW showing conditions and controls.	<b>Pic 2 Desc.</b>	Overview S-MN21.		
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11704+10	<b>Field Station#</b>	11710+00		
<b>Pic 3 Desc.</b>	S-MN22.	<b>Pic 4 Desc.</b>	Section of RoW showing conditions and controls.		
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11740+65	<b>Field Station#</b>	11743+97		
<b>Pic 5 Desc.</b>	S-EF65.	<b>Pic 6 Desc.</b>	S-EF62.		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/23/2022 7:31 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	7		<b>GPS Location</b>	8	
<b>Field Station#</b>	11752+00		<b>Field Station#</b>	11767+44	
<b>Pic 7 Desc.</b>	Section of RoW showing conditions and controls.		<b>Pic 8 Desc.</b>	S-IJ52/W-IJ46.	
<b>GPS Location</b>	9		<b>GPS Location</b>	10	
<b>Field Station#</b>	11775+00		<b>Field Station#</b>	11788+52	
<b>Pic 9 Desc.</b>	Section of RoW showing conditions and controls.		<b>Pic 10 Desc.</b>	RCE Mt Tabor rd.	
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 11 Desc.</b>			<b>Pic 12 Desc.</b>		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/23/2022 7:31 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37999
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/24/2022 4:15 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10655+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10798+92
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	65.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	3.30
				<b>Rain Accumulation Time (days)</b>	1.00


1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	5/24/2022 4:15 PM	<b>Report #</b>	37999
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from ST# 10655+00 (Hendrickson Road) to ST# 10798+92 (Cascade Road) MP 201.6 to MP 205.67. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed environmental maintenance crews walking through section checking ECDs. This section of ROW is temporarily stabilized with seed and mulch. Vegetation growth is present throughout section. Clean water diversion berms, pipes and level spreaders are in place. ECDs in place per E&S sheets. Sensitive resource buffers are in place at streams S-G30, S-G32, S-G33 S-G35, S-SS4, S-Z9, S-Z7 braid 1, and S-Z7 braid 2. Wetland W-Z11 buffer zone in place. AR 240, Old Stoney Road, Buffalo Anklets Road, AR 241.04, Hendrickson Road, Big Branch Hollow Road, and Cascade Road crossings RCEs are maintained and in acceptable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	5/24/2022 4:15 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time Tue, May 24, 2022 04:23:01 EDT Position: +377.34444° / -88.65556° (+109.80) Altitude: 2318ft (+239.8ft) Datum: WGS-84 Azimuth/Bearing: 276° S84W 480mils True (+18°) Elevation Angle: +01.0° Horizon Angle: -02.0° Zoom: 1.0X 10745+00</p>		 <p>Date &amp; Time Tue, May 24, 2022 08:34:30 EDT Position: +377.34444° / -88.65556° (+109.80) Altitude: 2318ft (+239.8ft) Datum: WGS-84 Azimuth/Bearing: 092° S88E 1636mils True (+36°) Elevation Angle: +26.0° Horizon Angle: -02.4° Zoom: 1.0X 10728+50</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10745+00		<b>Field Station#</b>	10728+50	
<b>Pic 1 Desc.</b>	ROW temporarily stabilized with seed and mulch. Vegetation growth is present.		<b>Pic 2 Desc.</b>	Waterbars in place.	
 <p>Date &amp; Time Tue, May 24, 2022 09:11:04 EDT Position: +377.34444° / -88.65556° (+109.80) Altitude: 2334ft (+239.8ft) Datum: WGS-84 Azimuth/Bearing: 214° N45W 556mils True (+18°) Elevation Angle: +04.6° Horizon Angle: -00.6° Zoom: 1.0X 10690+00</p>		 <p>Date &amp; Time Tue, May 24, 2022 09:24:00 EDT Position: +377.34444° / -88.65556° (+109.80) Altitude: 2233ft (+28.7ft) Datum: WGS-84 Azimuth/Bearing: 312° N47W 556mils True (+18°) Elevation Angle: -07.4° Horizon Angle: -03.1° Zoom: 1.0X 10670+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10690+00		<b>Field Station#</b>	10670+00	
<b>Pic 3 Desc.</b>	Clean water diversion pipe and clean water diversion berm in place.		<b>Pic 4 Desc.</b>	RCE in place at AR 240.	
 <p>Date &amp; Time Tue, May 24, 2022 09:47:15 EDT Position: +377.34444° / -88.65556° (+109.80) Altitude: 2233ft (+28.7ft) Datum: WGS-84 Azimuth/Bearing: 031° N47E 055mils True (+14°) Elevation Angle: -17° Horizon Angle: -02° Zoom: 1.0X 10758+50 S-G35</p>		 <p>Date &amp; Time Tue, May 24, 2022 09:49:03 EDT Position: +377.34444° / -88.65556° (+109.80) Altitude: 2164ft (+10.8ft) Datum: WGS-84 Azimuth/Bearing: 102° S78E 1813mils True (+14°) Elevation Angle: -31.5° Horizon Angle: -06.1° Zoom: 1.0X 10762+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10758+50		<b>Field Station#</b>	10762+00	
<b>Pic 5 Desc.</b>	Stream S-G35.		<b>Pic 6 Desc.</b>	Rock inlet in place at slope drain.	

<b>A/E</b>	124300137	<b>Date/Time</b>	5/24/2022 4:15 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/24/2022 4:15 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37980
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	5/24/2022 11:12 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10798+92
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10929+80
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	59.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	2.30
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Rock Construction Entrance	Communication			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Sediment Filter Log	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Energy Dissipater	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/24/2022 11:12 AM	<b>Report #</b>	37980
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed aVA SWPPP inspection from ST# 10798+92 (MP 204.53) to ST# 10929+80 (MP 207). Compliance issues noted: @ 10819+03 rilling on the access road. Observance: Perimeter controls in place & functioning as designed. ROW has been temporary stabilized. Area of open ditch @ 10862+00. All other ECDs and BMPs functional at time of inspection. 50' buffers in place at stream crossings S-Z10, S-Z11, S-Z12, S-Z13,W-Z3, S-Z14, S-A33, S-A34, S-A32, S-Y3 and S-Y2. AR-241.03, 241.02, Kow Camp roads and Doe creek road RCEs are maintained in acceptable condition. The ROW is muddy and in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137	Date/Time	5/24/2022 11:12 AM	Report #	
Pictures						
						
GPS Location		See photo		GPS Location		See photo
Field Station#		10804+00		Field Station#		10929+00
Pic 1 Desc.		RCE functional		Pic 2 Desc.		Equipment bridge functional
						
GPS Location		See photo		GPS Location		See photo
Field Station#		10927+00		Field Station#		10925+00
Pic 3 Desc.		Wattles in place		Pic 4 Desc.		Water bars and ET in place
						
GPS Location		See photo		GPS Location		See photo
Field Station#		10897+00		Field Station#		10882+50
Pic 5 Desc.		Perimeter controls in place		Pic 6 Desc.		Equipment bridge functional



<b>AFE</b>	124300137	<b>Date/Time</b>	5/24/2022 11:12 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10861+00	<b>Field Station#</b>	10855+00		
<b>Pic 7 Desc.</b>	Open ditch	<b>Pic 8 Desc.</b>	Resource buffers in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10833+00	<b>Field Station#</b>	10826+00		
<b>Pic 9 Desc.</b>	ET functional	<b>Pic 10 Desc.</b>	Level spreader in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10817+00	<b>Field Station#</b>	10819+03		
<b>Pic 11 Desc.</b>	Picture showing condition of row	<b>Pic 12 Desc.</b>	Rilling in access road needs repaired		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/24/2022 11:12 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38032
<b>Inspector</b>	David Schoolcraft			<b>Date/Time</b>	5/25/2022 11:31 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11184+85
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11254+99
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	60.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.05
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Erosion Control Blanket	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions




Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/25/2022 11:31 AM	<b>Report #</b>	38032
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Met with environmental team</p> <p>Preformed VA SWPPP inspection from 11184+85 (MP 211.83) to 11254+99 (MP 213.6) Accompanied by fellow EI Eric Hanlon</p> <p>This section of ROW has no current forward progress construction going on. However maintenance crews are on site repairing ditch subsidence as needed in temporary stabilized area. 11222+50 - 11247+00</p> <p>No deficiencies found</p> <p>Water bars (other)</p> <p>All perimeter controls, ECDs and BMPs functional at time of inspection. Stream buffers and controls in place at the time of inspection.</p> <p>11222+50 to 11206+27 stabilization in restoration is thin and continuing to be monitored by inspection. Was over seeded on 4/12/22 and 4/13/22</p> <p>11207+00 to 11222+50 monitoring ditch subsidence.</p> <p>No sensitive resources have been impacted</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	5/25/2022 11:31 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed, May 25, 2022, 08:47:47 EDT Position: +097.506502° / -080.569810° (-15.08) Altitude: 1968ft (-11.2ft) Datum: WGS-84 Azimuth/Bearing: 085° N85E 151mils True (-14°) Elevation Angle: +14.2° Horizon Angle: -04.9° Zoom: 0.5X 11185+00</p>		 <p>Date &amp; Time: Wed, May 25, 2022, 08:48:06 EDT Position: +097.506502° / -080.569810° (-15.08) Altitude: 1968ft (-11.2ft) Datum: WGS-84 Azimuth/Bearing: 190° S10W 317mils True (-14°) Elevation Angle: -01.0° Horizon Angle: -03.5° Zoom: 0.5X 11189+00</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11185+00	<b>Field Station#</b>	11189+00		
<b>Pic 1 Desc.</b>	Access road	<b>Pic 2 Desc.</b>	Level spreader		
 <p>Date &amp; Time: Wed, May 25, 2022, 09:15:46 EDT Position: +097.506502° / -080.569810° (-15.08) Altitude: 1968ft (-11.2ft) Datum: WGS-84 Azimuth/Bearing: 085° N85E 275mils True (-14°) Elevation Angle: -10.2° Horizon Angle: -00.9° Zoom: 0.5X 11191+00</p>		 <p>Date &amp; Time: Wed, May 25, 2022, 09:15:46 EDT Position: +097.506502° / -080.569810° (-15.08) Altitude: 1968ft (-11.2ft) Datum: WGS-84 Azimuth/Bearing: 337° N23W 599mils True (-14°) Elevation Angle: +06.3° Horizon Angle: -01.1° Zoom: 0.5X 11206+00</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11191+00	<b>Field Station#</b>	11206+00		
<b>Pic 3 Desc.</b>	Drainage Feature	<b>Pic 4 Desc.</b>	Restoration continued monitoring growth and overseeding		
 <p>Date &amp; Time: Wed, May 25, 2022, 09:24:23 EDT Position: +097.506502° / -080.569810° (-15.08) Altitude: 2012m (-78.7ft) Datum: WGS-84 Azimuth/Bearing: 108° S72E 1920mils True (-13°) Elevation Angle: +08.1° Horizon Angle: +10.8° Zoom: 0.5X 11229+00</p>		 <p>Date &amp; Time: Wed, May 25, 2022, 09:26:06 EDT Position: +097.506502° / -080.569810° (-15.08) Altitude: 2002m (-81.3ft) Datum: WGS-84 Azimuth/Bearing: 317° S23W 308mils True (-13°) Elevation Angle: -13.3° Horizon Angle: -01.9° Zoom: 0.5X 11239+00</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11229+00	<b>Field Station#</b>	11239+00		
<b>Pic 5 Desc.</b>	Perimeter controls	<b>Pic 6 Desc.</b>	Sump pit		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/25/2022 11:31 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11245+00	<b>Field Station#</b>	11248+00		
<b>Pic 7 Desc.</b>	Water bar end treatment	<b>Pic 8 Desc.</b>	Water bars		
				Insert image here	
<b>GPS Location</b>	See Photo	<b>GPS Location</b>			
<b>Field Station#</b>	11250+00	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	Stream overview	<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/25/2022 11:31 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38045
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/25/2022 3:28 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10929+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11023+80
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	63.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.05
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	5/25/2022 3:28 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11019+00		<b>Field Station#</b>	11011+50	
<b>Pic 1 Desc.</b>	Clean water diversion berm in place.		<b>Pic 2 Desc.</b>	Clean water diversion pipe inlet in place.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10986+00		<b>Field Station#</b>	10966+00	
<b>Pic 3 Desc.</b>	Sensitive resource buffer in place at streams S-E24 and S-E25.		<b>Pic 4 Desc.</b>	Triple barrier ECDs in place at cave feature.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10947+00		<b>Field Station#</b>	10930+25	
<b>Pic 5 Desc.</b>	ROW permanently stabilized.		<b>Pic 6 Desc.</b>	RCE in place at Doe Creek Road.	



<b>A/E</b>	124300137	<b>Date/Time</b>	5/25/2022 3:28 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/25/2022 3:28 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38044
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	5/25/2022 3:11 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11098+47
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	62.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

## 5. Site Conditions







Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	5/25/2022 3:11 PM	<b>Report #</b>	38044
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11023+80 (AR 244) to ST# 11098+47 (AR 245.02) Accompanied by fellow EI Daniel Fortune on SWPPP inspection from MP 208.78 to MP 210.2 No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed environmental maintenance crew at ST# 11033+00 performing vegetative maintenance. ST# 11023+80 to ST# 11072+00 has undergone temporary stabilization. Cleanwater diversion berms and topsoil piles have been stabilized. Perimeter controls, slope drains with stone inlet protection, and waterbars with end treatments are in place. Final restoration has occurred between ST# 11072+00 and ST# 11098+47. Area is stabilized with seed and mulch. Vegetation growth is present. CFS in place to minimize rilling and maintain sheet flow. Open ditch observed for approximately 300 feet between ST# 11059+80 and ST # 11062+80. Triple barrier protection around karst feature located at station number 11055+00. Sensitive resource buffers are in place at stream crossings S-IJ18, S-IJ17, and S-IJ16-B. AR-244, 245.01, and 245.02 RCEs are maintained in acceptable condition. The ROW is wet and in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/25/2022 3:11 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11205+50	<b>Field Station#</b>	11037+50		
<b>Pic 1 Desc.</b>	Stream buffer in place	<b>Pic 2 Desc.</b>	CFS triple stack perimeter control in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11046+00	<b>Field Station#</b>	11049+75		
<b>Pic 3 Desc.</b>	End treatments in place	<b>Pic 4 Desc.</b>	Stream buffer in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11048+00	<b>Field Station#</b>	11053+30		
<b>Pic 5 Desc.</b>	Erosion control blanket in place	<b>Pic 6 Desc.</b>	P1 silt fence perimeter control in place		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/25/2022 3:11 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed, May 25, 2022, 10:23:09 EDT Position: +037 317239 / -080 964419 (±11.40) Altitude: 2192ft (±13.10) Datum: WGS-84 Azimuth/Bearing: 118° S46E 2044mils True (±12°) Elevation Grade: -018% Horizon Grade: +008% Zoom: 0.5X 11054+00</p>		 <p>Date &amp; Time: Wed, May 25, 2022, 10:56:06 EDT Position: +037 317334 / -080 964444 (±11.80) Altitude: 2177ft (±9.84) Datum: WGS-84 Azimuth/Bearing: 138° S51E 2009mils True (±12°) Elevation Grade: -025% Horizon Grade: +005% Zoom: 0.5X 11064+00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11056+00	<b>Field Station#</b>	11064+00		
<b>Pic 7 Desc.</b>	Triple protection ECDs in place at karst feature	<b>Pic 8 Desc.</b>	Waterbars in place		
 <p>Date &amp; Time: Wed, May 25, 2022, 10:56:06 EDT Position: +037 317334 / -080 964444 (±11.80) Altitude: 2163ft (±12.61) Datum: WGS-84 Azimuth/Bearing: 140° S40E 2030mils True (±12°) Elevation Grade: -027% Horizon Grade: -006% Zoom: 0.5X 11065+84</p>		 <p>Date &amp; Time: Wed, May 25, 2022, 11:03:06 EDT Position: +037 317337 / -080 964476 (±12.00) Altitude: 2007ft (±13.10) Datum: WGS-84 Azimuth/Bearing: 100° S40E 1670mils True (±12°) Elevation Grade: +003% Horizon Grade: -003% Zoom: 0.5X 11073+00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11065+84	<b>Field Station#</b>	11073+00		
<b>Pic 9 Desc.</b>	Cleanwater drainage feature in place	<b>Pic 10 Desc.</b>	Permanent vegetation in place		
 <p>Date &amp; Time: Wed, May 25, 2022, 11:05:49 EDT Position: +037 318287 / -080 959447 (±12.40) Altitude: 2000ft (±11.20) Datum: WGS-84 Azimuth/Bearing: 100° S29W 1650mils True (±12°) Elevation Grade: +002% Horizon Grade: +002% Zoom: 0.5X 11092+00</p>		 <p>Date &amp; Time: Wed, May 25, 2022, 11:05:49 EDT Position: +037 312692 / -080 959456 (±12.10) Altitude: 1920ft (±11.70) Datum: WGS-84 Azimuth/Bearing: 109° S81E 2401mils True (±12°) Elevation Grade: -014% Horizon Grade: -000% Zoom: 0.5X 11098+30</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11092+00	<b>Field Station#</b>	11098+30		
<b>Pic 11 Desc.</b>	CFS perimeter control in place	<b>Pic 12 Desc.</b>	RCE in place		



<b>A/E</b>	124300137	<b>Date/Time</b>	5/25/2022 3:11 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38019
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	5/25/2022 6:42 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11098+47
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11184+85
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	64.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.05
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Rock Construction Entrance	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/25/2022 6:42 AM	<b>Report #</b>	38019
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Discussed RoW/ECD conditions, within this section, with fellow EI Clint Sears. Performed SWPPP inspection from MP 210.2 (11098+47) and MP 211.83 (11184+85) Accompanied by fellow EI Clint Sears. This section of RoW is partially restored. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Section 6 - other (waterbars) Assessed AR 245.02 and AR 249.02.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time	5/25/2022 6:42 AM	Report #	
Pictures					
					
GPS Location 1		GPS Location 2			
Field Station# 11105+00		Field Station# 11117+00			
Pic 1 Desc. Section of restored RoW showing conditions and controls.		Pic 2 Desc. Section of restored RoW showing conditions and controls.			
					
GPS Location 3		GPS Location 4			
Field Station# 11130+00		Field Station# 11134+00			
Pic 3 Desc. Section of restored RoW showing conditions and controls.		Pic 4 Desc. Representative photo of permanent waterbar and level spreaders installed.			
					
GPS Location 5		GPS Location 6			
Field Station# 11140+00		Field Station# 11146+50			
Pic 5 Desc. Section of restored RoW showing conditions and controls.		Pic 6 Desc. CWDP outlet protection functional.			



<b>AFE</b>	124300137	<b>Date/Time</b>	5/25/2022 6:42 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	7	<b>GPS Location</b>	8		
<b>Field Station#</b>	11159+25	<b>Field Station#</b>	11167+83		
<b>Pic 7 Desc.</b>	S-NN17.	<b>Pic 8 Desc.</b>	RCE off of AR 249.01.		
		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>	9	<b>GPS Location</b>			
<b>Field Station#</b>	11176+00	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	Section of restored RoW showing conditions and controls.	<b>Pic 10 Desc.</b>			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/25/2022 6:42 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38069
<b>Inspector</b>	David Schoolcraft			<b>Date/Time</b>	5/26/2022 10:31 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11600+01
<b>County</b>	Craig	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	58.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			


<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/26/2022 10:31 AM	<b>Report #</b>	38069
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with environmental team Performed VA SWPPP inspection from 11524+16 (MP 218.26) to 11600+01 (MP 219.70) Accompanied by fellow EI Eric Hanlon This section of ROW has no current construction. No deficiencies found. Water bars (other) All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. Stream buffers and controls in place at the time of inspection. No sensitive resources have been impacted					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	5/26/2022 10:31 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11526+00	<b>Field Station#</b>	11530+00		
<b>Pic 1 Desc.</b>	Stabilization and restoration	<b>Pic 2 Desc.</b>	Perimeter controls		
					
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11532+00	<b>Field Station#</b>	11582+00		
<b>Pic 3 Desc.</b>	Level spreader	<b>Pic 4 Desc.</b>	Section of ROW showing conditions		
					
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11583+50	<b>Field Station#</b>	11584+00		
<b>Pic 5 Desc.</b>	P1 Silt Fence checks	<b>Pic 6 Desc.</b>	Water bar and Sump Pit		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/26/2022 10:31 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Thu, May 26, 2022, 09:53:47 EDT Position: +39°31'24.1"N -080°40'17.0"W (±117.4ft) Altitude: 2057ft (±105.0ft) Datum: WGS-84 Azimuth/Bearing: 252°57'2"W 4480mils True (±12°) Elevation Angle: +10° Horizon Angle: +02.2° Zoom: 0.5X 11585+00</small></p>		 <p><small>Date &amp; Time: Thu, May 26, 2022, 09:58:49 EDT Position: +39°31'07.5"N -080°40'11.1"W (±117.4ft) Altitude: 2062ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 199°54'E 2671mils True (±12°) Elevation Angle: +03.7° Horizon Angle: +00.1° Zoom: 0.5X 11587+00</small></p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11585+00	<b>Field Station#</b>	1158+70		
<b>Pic 7 Desc.</b>	Stream	<b>Pic 8 Desc.</b>	Stream Overview		
 <p><small>Date &amp; Time: Thu, May 26, 2022, 09:55:03 EDT Position: +39°31'51.0"N -080°40'23.1"W (±117.4ft) Altitude: 2016ft (±115.0ft) Datum: WGS-84 Azimuth/Bearing: 099°58'E 4760mils True (±12°) Elevation Angle: +09.6° Horizon Angle: -03.4° Zoom: 1.0X 11595+00</small></p>		 <p><small>Date &amp; Time: Thu, May 26, 2022, 09:58:19 EDT Position: +39°31'52.0"N -080°40'25.0"W (±117.4ft) Altitude: 2028ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 348°N12W 4160mils True (±12°) Elevation Angle: +11.0° Horizon Angle: -01.9° Zoom: 0.5X 11600+01</small></p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11595+00	<b>Field Station#</b>	11600+01		
<b>Pic 9 Desc.</b>	Stabilization	<b>Pic 10 Desc.</b>	RCE		
 <p><small>Date &amp; Time: Thu, May 26, 2022, 09:16:18 EDT Position: +39°26'33.0"N -080°45'55.0"W (±117.4ft) Altitude: 3000ft (±11.0ft) Datum: WGS-84 Azimuth/Bearing: 100°53'E 3100mils True (±12°) Elevation Angle: +1.3° Horizon Angle: -02.7° Zoom: 1.0X 11524+16 AR258.02</small></p>		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>			
<b>Field Station#</b>	11524+16	<b>Field Station#</b>			
<b>Pic 11 Desc.</b>	Equipment Bridge AR258.02	<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/26/2022 10:31 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38082
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	5/26/2022 3:44 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11353+67
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	66.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/26/2022 3:44 PM	<b>Report #</b>	38082
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11254+99 (Rt 42) to ST# 11353+67 (Old Furnace) Accompanied by fellow EI Daniel Fortune on SWPPP inspection from MP 213.6 to MP 215.04 No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed environmental maintenance crew at ST# 11262+00 performing vegetative maintenance. This section of ROW has undergone temporary stabilization. Topsoil stock piles and cleanwater diversion berms have been stabilized. Slope drains with stone inlet protection, Perimeter controls, and waterbars with end treatments are in place Triple protection ECDs are in place at karst feature. Sensitive resource buffers are in place at stream crossings S-MM18, S-NN12, and S-NN11. AR-256, 256.02, and 253.02 RCEs are maintained in acceptable condition. The ROW is wet and in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/26/2022 3:44 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu, May 26, 2022, 10:44:15 EDT  Position: -837.296227° / -880.491372° (+10.07)  Altitude: 1827ft (+1575ft)  Datum: WGS-84  Azimuth/Bearing: 304° N12W 440mils True (+12°)  Elevation Grade: -022°  Horizon Grade: -000°  Zoom: 0.5X  11256+15</p> 		<p>Date &amp; Time: Thu, May 26, 2022, 10:42:26 EDT  Position: -837.296227° / -880.491372° (+11.6ft)  Altitude: 2000ft (+1531ft)  Datum: WGS-84  Azimuth/Bearing: 304° N66W 540mils True (+12°)  Elevation Grade: -042°  Horizon Grade: -000°  Zoom: 0.5X  11256+00</p> 			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11256+15		<b>Field Station#</b>	11256+00	
<b>Pic 1 Desc.</b>	Supersilt fence in place		<b>Pic 2 Desc.</b>	Waterbars in place	
<p>Date &amp; Time: Thu, May 26, 2022, 10:45:45 EDT  Position: -837.296227° / -880.491372° (+10.17ft)  Altitude: 2113ft (+1127ft)  Datum: WGS-84  Azimuth/Bearing: 304° N45W 580mils True (+12°)  Elevation Grade: -000°  Horizon Grade: -000°  Zoom: 0.5X  11261+50</p> 		<p>Date &amp; Time: Thu, May 26, 2022, 10:27:16 EDT  Position: -837.296027° / -880.491372° (+15.5ft)  Altitude: 2208ft (+1121ft)  Datum: WGS-84  Azimuth/Bearing: 062° N42E 1102mils True (+12°)  Elevation Grade: -014°  Horizon Grade: -011°  Zoom: 0.5X  11263+00</p> 			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11261+50		<b>Field Station#</b>	11263+00	
<b>Pic 3 Desc.</b>	End treatments in place		<b>Pic 4 Desc.</b>	CFS triple stack perimeter control in place	
<p>Date &amp; Time: Thu, May 26, 2022, 10:23:20 EDT  Position: -837.294152° / -880.487151° (+10.1ft)  Altitude: 2273ft (+1170ft)  Datum: WGS-84  Azimuth/Bearing: 174° S06E 3093mils True (+12°)  Elevation Grade: -052°  Horizon Grade: -002°  Zoom: 0.5X  11271+00</p> 		<p>Date &amp; Time: Thu, May 26, 2022, 10:11:45 EDT  Position: -837.294152° / -880.487151° (+10.5ft)  Altitude: 2283ft (+1170ft)  Datum: WGS-84  Azimuth/Bearing: 227° S47W 4036mils True (+12°)  Elevation Grade: -040°  Horizon Grade: -002°  Zoom: 0.5X  11271+00</p> 			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11269+00		<b>Field Station#</b>	11271+00	
<b>Pic 5 Desc.</b>	Plunge pool in place		<b>Pic 6 Desc.</b>	Stone inlet protection in place	



<b>AFE</b>	124300137	<b>Date/Time</b>	5/26/2022 3:44 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu May 26, 2022, 10:49:59 EDT  Position: +39.29333° / -88.43333° (±11.80)  Altitude: 2110ft (±234.4ft)  Datum: WGS-84  Azimuth/Bearing: 101° S00W 000mils True (±13°)  Elevation Grade: -001%  Horizon Grade: -001%  Zoom: 0.5X  11280+00</p> 		<p>Date &amp; Time: Thu May 26, 2022, 10:49:59 EDT  Position: +39.29333° / -88.43333° (±11.80)  Altitude: 2110ft (±234.4ft)  Datum: WGS-84  Azimuth/Bearing: 240° S00W 462mils True (±13°)  Elevation Grade: -001%  Horizon Grade: -001%  Zoom: 0.5X  11286+50</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11280+00	<b>Field Station#</b>	11286+50		
<b>Pic 7 Desc.</b>	Cleanwater diversion berm in place	<b>Pic 8 Desc.</b>	Slope drain pipe in place		
<p>Date &amp; Time: Thu May 26, 2022, 10:59:29 EDT  Position: +39.29416° / -88.43068° (±11.80)  Altitude: 2122ft (±239.8ft)  Datum: WGS-84  Azimuth/Bearing: 211° S37W 065mils True (±13°)  Elevation Grade: -01%  Horizon Grade: -003%  Zoom: 0.5X  11293+00</p> 		<p>Date &amp; Time: Thu May 26, 2022, 10:59:29 EDT  Position: +39.29333° / -88.42916° (±11.80)  Altitude: 2014ft (±215.0ft)  Datum: WGS-84  Azimuth/Bearing: 232° S52W 412mils True (±13°)  Elevation Grade: -007%  Horizon Grade: -003%  Zoom: 2.0X  11328+00 S-NN12</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11293+00	<b>Field Station#</b>	11328+00		
<b>Pic 9 Desc.</b>	Stream buffer in place	<b>Pic 10 Desc.</b>	Stream buffer in place		
<p>Date &amp; Time: Thu May 26, 2022, 11:46:19 EDT  Position: +39.29316° / -88.43511° (±11.80)  Altitude: 2143ft (±236.2ft)  Datum: WGS-84  Azimuth/Bearing: 102° S00E 306mils True (±13°)  Elevation Grade: -002%  Horizon Grade: -001%  Zoom: 0.5X  11352+00 AR256.02</p> 		<p>Date &amp; Time: Thu May 26, 2022, 09:23:17 EDT  Position: +39.29333° / -88.43333° (±11.80)  Altitude: 2007ft (±175.8ft)  Datum: WGS-84  Azimuth/Bearing: 014° N14E 000mils True (±12°)  Elevation Grade: -000%  Horizon Grade: -000%  Zoom: 0.5X  11353+47</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11352+00	<b>Field Station#</b>	11353+47		
<b>Pic 11 Desc.</b>	Triple protection ECDs in place	<b>Pic 12 Desc.</b>	RCE in place		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/26/2022 3:44 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38059
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	5/26/2022 6:38 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11353+67
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11471+56
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	66.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions





Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/26/2022 6:38 AM	<b>Report #</b>	38059
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 215.04 (11353+67) and MP 217.26 (11471+56). Accompanied by fellow EI Clint Sears. This section of RoW is partially restored. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Section 6 - other (waterbars).					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/26/2022 6:38 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11469+00	<b>Field Station#</b>	11451+87		
<b>Pic 1 Desc.</b>	Section of RoW showing conditions and controls.		<b>Pic 2 Desc.</b>	S-0012.	
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11451+18	<b>Field Station#</b>	11448+93		
<b>Pic 3 Desc.</b>	S-0013.		<b>Pic 4 Desc.</b>	S-0014/W-CD12.	
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11438+00	<b>Field Station#</b>	11432+00		
<b>Pic 5 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 6 Desc.</b>	Representative photo of permanent waterbar and level spreaders installed.	



<b>AFE</b>	124300137	<b>Date/Time</b>	5/26/2022 6:38 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	7	<b>GPS Location</b>	8		
<b>Field Station#</b>	11408+00	<b>Field Station#</b>	11360+54		
<b>Pic 7 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 8 Desc.</b>	S-KL43.	
					
<b>GPS Location</b>	9	<b>GPS Location</b>	10		
<b>Field Station#</b>	11397+00	<b>Field Station#</b>	11381+00		
<b>Pic 9 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 10 Desc.</b>	Section of restored RoW showing conditions and controls.	
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			



<b>A/E</b>	124300137	<b>Date/Time</b>	5/26/2022 6:38 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38086
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/26/2022 3:12 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11471+56
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11524+16
<b>County</b>	Craig	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	64.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/26/2022 3:12 PM	<b>Report #</b>	38086
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from ST# 11471+56 (Steele Acres) to ST# 11524+16 (258.02) Accompanied by EI Trey Ingram on SWPPP inspection from MP 217.26 to MP 218.26. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. This section of ROW has undergone temporary stabilization. Topsoil stock piles and cleanwater diversion berms have been stabilized. Slope drains with stone inlet protection, Perimeter controls, and waterbars with end treatments are in place Triple protection ECDs are in place at karst feature. Sensitive resource buffers are in place at stream crossings S-PP3, and S-PP4. AR-258.01, 258.02, and Stever's Gap road crossing RCEs are maintained in acceptable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE		124300137		Date/Time		5/26/2022 3:12 PM		Report #							
Pictures															
				<p>Date &amp; Time: Thu, May 26, 2022, 08:24:41 EDT Position: +027.312337° / -080.41500° (-1502.60m) Altitude: 2233ft (-684m) Datum: WGS-84 Azimuth/Bearing: 087° N08E 0897mils True (+12°) Elevation Angle: -24.6° Horizon Angle: -03.9° Zoom: 1.0X 11472+00</p>								<p>Date &amp; Time: Thu, May 26, 2022, 08:24:04 EDT Position: +027.312337° / -080.41500° (-1502.60m) Altitude: 2233ft (-684m) Datum: WGS-84 Azimuth/Bearing: 087° N08E 1507mils True (+12°) Elevation Angle: -24.6° Horizon Angle: -03.9° Zoom: 1.0X 11476+00</p>			
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.					
Field Station#		11472+00						Field Station#		11476+00					
Pic 1 Desc.		Triple barrier ECDs in place along LOD.						Pic 2 Desc.		Rock inlet in place at slope drain pipe.					
				<p>Date &amp; Time: Thu, May 26, 2022, 06:55:01 EDT Position: +027.336977° / -080.436661° (-696.170) Altitude: 2209ft (-676m) Datum: WGS-84 Azimuth/Bearing: 087° N08E 0432mils True (+13°) Elevation Angle: -14.2° Horizon Angle: -01.2° Zoom: 1.0X 11486+50</p>								<p>Date &amp; Time: Thu, May 26, 2022, 06:55:04 EDT Position: +027.336977° / -080.431777° (-686.010) Altitude: 2169ft (-665m) Datum: WGS-84 Azimuth/Bearing: 087° N08E 1169mils True (+13°) Elevation Angle: -03.4° Horizon Angle: -00.3° Zoom: 1.0X 11490+00</p>			
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.					
Field Station#		11486+50						Field Station#		11490+00					
Pic 3 Desc.		Plunge pool in place.						Pic 4 Desc.		RCE in place at Stevers Gap Road.					
				<p>Date &amp; Time: Thu, May 26, 2022, 08:53:11 EDT Position: +027.322296° / -080.429718° (-1536.86m) Altitude: 2253ft (-689m) Datum: WGS-84 Azimuth/Bearing: 204° S24W 3627mils True (+13°) Elevation Angle: -26.5° Horizon Angle: -03.9° Zoom: 1.0X 11493+00</p>								<p>Date &amp; Time: Thu, May 26, 2022, 08:53:55 EDT Position: +027.314400° / -080.433650° (-15283.80m) Altitude: 2253ft (-689m) Datum: WGS-84 Azimuth/Bearing: 008° N08E 0142mils True (+15°) Elevation Angle: -23.3° Horizon Angle: -00.3° Zoom: 1.0X 11503+00</p>			
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.					
Field Station#		11493+00						Field Station#		11503+00					
Pic 5 Desc.		Priority one silt fence in place along LOD.						Pic 6 Desc.		Rock lined channel in place at convey water.					

<b>A/E</b>	124300137	<b>Date/Time</b>	5/26/2022 3:12 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/26/2022 3:12 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38103
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	5/27/2022 8:04 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+52
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	64.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	1.80
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)






E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Berm	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Problem Area	See punch list		
Silt Fence (Reinforce Filter Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/27/2022 8:04 AM	<b>Report #</b>	38103
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
ee photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 221.02 (11670+00) to MP 223.27 (11788+52). Accompanied by fellow EI Clint Sears. Inspection performed during rain event. One location of weather impact to controls was identified and added to the punch list following proper notifications. All other perimeter controls, ECDs and BMPs functional at time of inspection. Continued rainfall and high water levels hinder/obstructed view of some controls. Further inspections following water levels subsiding may result in additional issues identified. Naturally fallen trees and debris have created a dam, at the crossing of S-MN21, resulting in the stream backing up. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	5/27/2022 8:04 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11671+25	<b>Field Station#</b>	11687+42		
<b>Pic 1 Desc.</b>	Section of RoW showing conditions and controls.	<b>Pic 2 Desc.</b>	S-MN21.		
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11687+42	<b>Field Station#</b>	11704+10		
<b>Pic 3 Desc.</b>	Upstream S-MN21 dammed by naturally fallen trees and debris.	<b>Pic 4 Desc.</b>	S-MN22.		
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11710+50	<b>Field Station#</b>	11711+50		
<b>Pic 5 Desc.</b>	Section of RoW showing conditions and controls.	<b>Pic 6 Desc.</b>	Undermined P-1.		



AFE		124300137		Date/Time		5/27/2022 8:04 AM		Report #			
Pictures											
											
GPS Location		7		GPS Location		8					
Field Station#		11714+00		Field Station#		1740+55					
Pic 7 Desc.		Section of RoW showing conditions and controls.		Pic 8 Desc.		S-EF66.					
											
GPS Location		9		GPS Location		10					
Field Station#		11743+97		Field Station#		11751+00					
Pic 9 Desc.		S-EF62.		Pic 10 Desc.		Section of RoW showing conditions and controls.					
								Insert image here			
GPS Location		11		GPS Location							
Field Station#		11767+44		Field Station#							
Pic 11 Desc.		S-IJ52/W-IJ46.		Pic 12 Desc.							

<b>A/E</b>	124300137	<b>Date/Time</b>	5/27/2022 8:04 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38133
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	5/27/2022 4:01 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11899+89
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	70.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	1.20
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Roadside Ditch	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			







<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/27/2022 4:01 PM	<b>Report #</b>	38133
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11899+89 (AR 266.03) to ST# 12005+00 (Spread Break) MP 225.37 to MP 227.37. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. This section of ROW has undergone permanent restoration and vegetation is present. Permanent waterbars (section 6 other) with level spreaders, and perimeter controls are in place where designated on E&S sheets. Triple barrier sensitive resource buffers are in place at karst features. AR 266 and 266.03 are maintained in acceptable condition. Broad based dips with end treatments, and roadside ditch with rock check dams are in place. The ROW is wet and in stable condition. No sensitive resources have been impacted. Catawba rain gauge measured 1.2" of accumulated rainfall.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/27/2022 4:01 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time Fri, May 27, 2022 05:47:00 EDT  Position: +40°23'56"N / -89.5558° W (-12.47)  Altitude: 2330 ft (-17.37)  Datum: WGS-84  Azimuth/Bearing: 83° S45E 399mils True (-13°)  Elevation Grade: -41%  Horizon Grade: -00%  Zoom: 0.5X  11904+50</p> 		<p>Date &amp; Time Fri, May 27, 2022 05:48:00 EDT  Position: +40°23'56"N / -89.5558° W (-12.47)  Altitude: 2330 ft (-17.37)  Datum: WGS-84  Azimuth/Bearing: 155° S45E 426mils True (-13°)  Elevation Grade: -43%  Horizon Grade: -00%  Zoom: 0.5X  11920+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11904+50	<b>Field Station#</b>	11920+00		
<b>Pic 1 Desc.</b>	P1 silt fence perimeter control in place	<b>Pic 2 Desc.</b>	Permanent vegetation present		
<p>Date &amp; Time Fri, May 27, 2022 05:54:40 EDT  Position: +40°23'56"N / -89.5558° W (-12.47)  Altitude: 2330 ft (-17.37)  Datum: WGS-84  Azimuth/Bearing: 134° S45E 399mils True (-13°)  Elevation Grade: -40%  Horizon Grade: -00%  Zoom: 0.5X  11922+00</p> 		<p>Date &amp; Time Fri, May 27, 2022 05:54:50 EDT  Position: +40°23'56"N / -89.5558° W (-12.47)  Altitude: 2330 ft (-17.37)  Datum: WGS-84  Azimuth/Bearing: 134° S45E 399mils True (-13°)  Elevation Grade: -40%  Horizon Grade: -00%  Zoom: 0.5X  11923+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11922+00	<b>Field Station#</b>	11923+00		
<b>Pic 3 Desc.</b>	CFS perimeter control in place	<b>Pic 4 Desc.</b>	Level spreader in place		
<p>Date &amp; Time Fri, May 27, 2022 06:12:40 EDT  Position: +40°23'56"N / -89.5558° W (-12.47)  Altitude: 2330 ft (-17.37)  Datum: WGS-84  Azimuth/Bearing: 134° S45E 399mils True (-13°)  Elevation Grade: -40%  Horizon Grade: -00%  Zoom: 0.5X  11947+00</p> 		<p>Date &amp; Time Fri, May 27, 2022 06:41:00 EDT  Position: +40°23'56"N / -89.5558° W (-12.47)  Altitude: 2330 ft (-17.37)  Datum: WGS-84  Azimuth/Bearing: 134° S45E 399mils True (-13°)  Elevation Grade: -40%  Horizon Grade: -00%  Zoom: 0.5X  11900+81</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11947+00	<b>Field Station#</b>	11900+81		
<b>Pic 5 Desc.</b>	Waterbars in place	<b>Pic 6 Desc.</b>	RCE in place		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/27/2022 4:01 PM	<b>Report #</b>	
<b>Pictures</b>					
<small>           Date &amp; Time: Fri, May 27, 2022, 09:31:17 EDT            Position: +037.278224°N +080.327634°W (-1549.0ft)            Altitude: 2172ft (+105.0ft)            Datum: WGS-84            Azimuth/Bearing: 230° 58'W 4782mils True (+12°)            Elevation Grade: -00%            Horizon Grade: -00%            Zoom: 0.5X            11943+00         </small> 		<small>           Date &amp; Time: Fri, May 27, 2022, 09:34:12 EDT            Position: +037.283122°N +080.325344°W (-15.5ft)            Altitude: 1931ft (+11.1ft)            Datum: WGS-84            Azimuth/Bearing: 221° 54'W 3929mils True (+12°)            Elevation Grade: -01%            Horizon Grade: -00%            Zoom: 0.5X            11965+00         </small> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11943+00	<b>Field Station#</b>	11965+00		
<b>Pic 7 Desc.</b>	Triple protection ECDs in place at karst feature	<b>Pic 8 Desc.</b>	P1 silt fence perimeter control in place		
<small>           Date &amp; Time: Fri, May 27, 2022, 09:29:01 EDT            Position: +037.271164°N +080.306664°W (-645.0ft)            Altitude: 1920ft (+60.0ft)            Datum: WGS-84            Azimuth/Bearing: 148° 30'SE 3370mils True (+12°)            Elevation Grade: -03%            Horizon Grade: -01%            Zoom: 0.5X            11972+00         </small> 		<small>           Date &amp; Time: Fri, May 27, 2022, 09:29:56 EDT            Position: +037.263544°N +080.322574°W (-14.1ft)            Altitude: 1901ft (+44.1ft)            Datum: WGS-84            Azimuth/Bearing: 171° 01'NE 0150mils True (+12°)            Elevation Grade: -02%            Horizon Grade: -01%            Zoom: 0.5X            11978+50         </small> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11972+00	<b>Field Station#</b>	11978+50		
<b>Pic 9 Desc.</b>	Waterbars in place	<b>Pic 10 Desc.</b>	Triple protection ECDs in place at karst feature		
<small>           Date &amp; Time: Fri, May 27, 2022, 09:29:03 EDT            Position: +037.267592°N +080.322342°W (-15.0ft)            Altitude: 1702ft (+11.2ft)            Datum: WGS-84            Azimuth/Bearing: 072° N22E 1280mils True (+12°)            Elevation Grade: -04%            Horizon Grade: -00%            Zoom: 0.5X            AR-266         </small> 		<small>           Date &amp; Time: Fri, May 27, 2022, 09:33:52 EDT            Position: +037.268153°N +080.320102°W (-13.0ft)            Altitude: 1637ft (+11.7ft)            Datum: WGS-84            Azimuth/Bearing: 108° S78E 1612mils True (+12°)            Elevation Grade: -04%            Horizon Grade: -00%            Zoom: 0.5X            Catawba 1.2"         </small> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11978+54	<b>Field Station#</b>	11988+96		
<b>Pic 11 Desc.</b>	RCE in place	<b>Pic 12 Desc.</b>	Catawba rain gauge measured 1.2" of rainfall		



<b>A/E</b>	124300137	<b>Date/Time</b>	5/27/2022 4:01 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38136
<b>Inspector</b>	David Schoolcraft			<b>Date/Time</b>	5/27/2022 6:07 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	70.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	2.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/27/2022 6:07 PM	<b>Report #</b>	38136
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Completed a VA SWPPP at LY 029. The perimeter controls consist of 18" triple stacked CFS in place and functioning as designed. The RCE was clean, no mud or other debris on road. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified.</p> <p>Completed a VA SWPPP at LY 028. The perimeter controls CFS in place and functioning as designed. The RCE was clean, no mud or other debris on road. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified.</p> <p>Completed a VA SWPPP at LY 026. The perimeter controls CFS functioning as designed. The RCE was clean, no mud or other debris on road. The yard was free of debris. Used oils were stored properly in secondary containment. The generator and air compressor were in secondary containment that was maintained properly. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified. Construction of a neighboring company started which affects our parking lot / Will monitor progress.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					









<b>AFE</b>	124300137	<b>Date/Time</b>	5/27/2022 6:07 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time Fri, May 27, 2022 08:45:22 EDT  Position: +037 318250° / +080 65650° (+21.8ft)  Altitude: 1807ft (+21.8ft)  Datum: WGS-84  Azimuth/Bearing: 125° S34E 3180mils True (+10°)  Elevation Angle: +13.1°  Horizon Angle: +00.1°  Zoom: 1.0X  LY26</p> 		<p>Date &amp; Time Fri, May 27, 2022 08:46:19 EDT  Position: +037 318250° / +080 65650° (+21.8ft)  Altitude: 1807ft (+21.8ft)  Datum: WGS-84  Azimuth/Bearing: 145° S41E 2380mils True (+10°)  Elevation Angle: +18.0°  Horizon Angle: +00.1°  Zoom: 1.0X  LY26</p> 			
<b>GPS Location</b>	LY 26	<b>GPS Location</b>	LY 26		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	Housekeeping trash in good condition	<b>Pic 2 Desc.</b>	Secondary containment in place		
<p>Date &amp; Time Fri, May 27, 2022 08:46:19 EDT  Position: +037 318250° / +080 65650° (+21.8ft)  Altitude: 1807ft (+21.8ft)  Datum: WGS-84  Azimuth/Bearing: 127° S31E 3090mils True (+10°)  Elevation Angle: +13.3°  Horizon Angle: +00.0°  Zoom: 1.0X  LY26</p> 		<p>Date &amp; Time Fri, May 27, 2022 08:46:19 EDT  Position: +037 318250° / +080 65650° (+21.8ft)  Altitude: 1807ft (+21.8ft)  Datum: WGS-84  Azimuth/Bearing: 052° N52E 3724mils True (+13°)  Elevation Angle: +18.8°  Horizon Angle: +04.0°  Zoom: 1.0X  LY26</p> 			
<b>GPS Location</b>	LY 26	<b>GPS Location</b>	LY 26		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	Supplies in proper containments	<b>Pic 4 Desc.</b>	Perimeter ECDS		
<p>Date &amp; Time Fri, May 27, 2022 08:48:20 EDT  Position: +037 319022° / +080 65650° (+21.2ft)  Altitude: 1833ft (+21.2ft)  Datum: WGS-84  Azimuth/Bearing: 027° N35E 0516mils True (+12°)  Elevation Angle: +12.0°  Horizon Angle: +0.3°  Zoom: 1.0X  LY26</p> 		<p>Date &amp; Time Fri, May 27, 2022 08:51:17 EDT  Position: +037 319022° / +080 65650° (+21.2ft)  Altitude: 1807ft (+21.2ft)  Datum: WGS-84  Azimuth/Bearing: 260° S80W 4622mils True (+10.1°)  Elevation Angle: +06.6°  Horizon Angle: +01.1°  Zoom: 1.0X  LY26</p> 			
<b>GPS Location</b>	LY 26	<b>GPS Location</b>	LY 26		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 5 Desc.</b>	RCE in Good condition	<b>Pic 6 Desc.</b>	Neighboring construction		



AFE	124300137	Date/Time	5/27/2022 6:07 PM	Report #			
Pictures							
<div><div><div><div><div><div><span>Date &amp; Time: Fri, May 27, 2022, 09:15:35 EDT</span></div><div><span>Position: +037.363547, -080.675591, 1515.4m</span></div><div><span>Altitude: 1522ft (+15.3m)</span></div><div><span>Datum: WGS-84</span></div><div><span>Azimuth/Bearing: 087.167E, 1003mils True (+10°)</span></div><div><span>Elevation Angle: +05.6°</span></div><div><span>Horizon Angle: -01.1°</span></div><div><span>Zoom: 1.0X</span></div><div><span>LY 29</span></div></div></div><div></div></div></div></div>				<div><div><div><div><div><div><span>Date &amp; Time: Fri, May 27, 2022, 09:16:55 EDT</span></div><div><span>Position: +037.363553, -080.675591, 1515.4m</span></div><div><span>Altitude: 1522ft (+15.3m)</span></div><div><span>Datum: WGS-84</span></div><div><span>Azimuth/Bearing: 087.167E, 1003mils True (+10°)</span></div><div><span>Elevation Angle: +05.0°</span></div><div><span>Horizon Angle: -04.6°</span></div><div><span>Zoom: 0.5X</span></div><div><span>LY 29</span></div></div></div><div></div></div></div></div>			
GPS Location	LY 29	GPS Location	LY 29				
Field Station#	12005+00	Field Station#	12005+00				
Pic 7 Desc.	Trash containment	Pic 8 Desc.	Perimeter controls				
<div><div><div><div><div><div><span>Date &amp; Time: Fri, May 27, 2022, 09:17:20 EDT</span></div><div><span>Position: +037.363576, -080.675591, 1515.4m</span></div><div><span>Altitude: 1722ft (+17.3m)</span></div><div><span>Datum: WGS-84</span></div><div><span>Azimuth/Bearing: 106° 57'4E, 1084mils True (+10°)</span></div><div><span>Elevation Angle: +05.6°</span></div><div><span>Horizon Angle: -01.6°</span></div><div><span>Zoom: 1.0X</span></div><div><span>LY 29</span></div></div></div><div></div></div></div></div>				<div><div><div><div><div><div><span>Date &amp; Time: Fri, May 27, 2022, 09:17:50 EDT</span></div><div><span>Position: +037.363225, -080.677421, 1519.4m</span></div><div><span>Altitude: 1718ft (+17.1m)</span></div><div><span>Datum: WGS-84</span></div><div><span>Azimuth/Bearing: 105° 23'27E, 1038mils True (+10°)</span></div><div><span>Elevation Angle: +00.8°</span></div><div><span>Horizon Angle: -03.5°</span></div><div><span>Zoom: 1.0X</span></div><div><span>LY 29</span></div></div></div><div></div></div></div></div>			
GPS Location	LY 29	GPS Location	LY 29				
Field Station#	12005+00	Field Station#	12005+00				
Pic 9 Desc.	Containment in place	Pic 10 Desc.	Perimeter control				
<div><div><div><div><div><div><span>Date &amp; Time: Fri, May 27, 2022, 09:18:05 EDT</span></div><div><span>Position: +037.360923, -080.676144, 1505.5m</span></div><div><span>Altitude: 1664ft (+16.4m)</span></div><div><span>Datum: WGS-84</span></div><div><span>Azimuth/Bearing: 087.167E, 1191mils True (+10°)</span></div><div><span>Elevation Angle: +06.1°</span></div><div><span>Horizon Angle: -02.7°</span></div><div><span>Zoom: 1.0X</span></div><div><span>LY 29</span></div></div></div><div></div></div></div></div>				<div><div><div><div><div><div><span>Date &amp; Time: Fri, May 27, 2022, 09:18:25 EDT</span></div><div><span>Position: +037.360971, -080.676176, 1511.6m</span></div><div><span>Altitude: 1651ft (+16.5m)</span></div><div><span>Datum: WGS-84</span></div><div><span>Azimuth/Bearing: 207° 40'27E, 1609mils True (+10°)</span></div><div><span>Elevation Angle: +04.2°</span></div><div><span>Horizon Angle: +01.1°</span></div><div><span>Zoom: 1.0X</span></div><div><span>LY 29</span></div></div></div><div></div></div></div></div>			
GPS Location	LY 29	GPS Location	LY 29				
Field Station#	12005+00	Field Station#	12005+00				
Pic 11 Desc.	Broad base dips functional	Pic 12 Desc.	access road to LY				



<b>AFE</b>	124300137	<b>Date/Time</b>	5/27/2022 6:07 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Fri, May 27, 2022, 13:55:54 EDT  Position: +337.334162° / -88.803167° (-15.4h)  Altitude: 1579ft (+11.2h)  Datum: WGS-84  Azimuth/Bearing: 095° S85E 1689mils True (+10°)  Deviation Angle: +1.7°  Horizontal Angle: -02.1°  Zoom: 1.0X  LY 28</p> 		<p>Date &amp; Time: Fri, May 27, 2022, 13:29:18 EDT  Position: +337.334162° / -88.803167° (-15.4h)  Altitude: 1579ft (+11.2h)  Datum: WGS-84  Azimuth/Bearing: 095° S85E 1689mils True (+10°)  Deviation Angle: +0.3°  Horizontal Angle: -02.1°  Zoom: 1.0X  LY 28</p> 			
<b>GPS Location</b>	LY28	<b>GPS Location</b>	LY 28		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 13 Desc.</b>	Trash house keeping	<b>Pic 14 Desc.</b>	Secondary containment on placate		
<p>Date &amp; Time: Fri, May 27, 2022, 13:56:40 EDT  Position: +337.334162° / -88.803167° (-15.4h)  Altitude: 1580ft (+11.2h)  Datum: WGS-84  Azimuth/Bearing: 318° N32W 1689mils True (+10°)  Deviation Angle: +0.0°  Horizontal Angle: -01.3°  Zoom: 1.0X  LY 28</p> 		<p>Date &amp; Time: Fri, May 27, 2022, 13:56:50 EDT  Position: +337.334162° / -88.803167° (-15.4h)  Altitude: 1580ft (+11.2h)  Datum: WGS-84  Azimuth/Bearing: 320° N20W 1689mils True (+10°)  Deviation Angle: +0.4°  Horizontal Angle: -01.5°  Zoom: 1.0X  LY 28</p> 			
<b>GPS Location</b>	LY28	<b>GPS Location</b>	LY 28		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 15 Desc.</b>	Secondary containment in place	<b>Pic 16 Desc.</b>	Perimeter controls		
<p>Date &amp; Time: Fri, May 27, 2022, 13:56:50 EDT  Position: +337.334162° / -88.803167° (-15.4h)  Altitude: 1581ft (+11.2h)  Datum: WGS-84  Azimuth/Bearing: 320° N20E 1689mils True (+10°)  Deviation Angle: +0.3°  Horizontal Angle: -00.6°  Zoom: 1.0X  LY 28</p> 		<p>Date &amp; Time: Fri, May 27, 2022, 13:56:50 EDT  Position: +337.334162° / -88.803167° (-15.4h)  Altitude: 1581ft (+11.2h)  Datum: WGS-84  Azimuth/Bearing: 317° N17E 1689mils True (+10°)  Deviation Angle: +0.4°  Horizontal Angle: -00.1°  Zoom: 1.0X  LY 28</p> 			
<b>GPS Location</b>	LY 28	<b>GPS Location</b>	LY 28		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 17 Desc.</b>	Access Road	<b>Pic 18 Desc.</b>	RCE		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38112
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	5/27/2022 11:07 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	60.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	2.50
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Reinforce Filter Fence)	Communication	Repair and/or replace SSF fabric		
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			




## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/27/2022 11:07 AM	<b>Report #</b>	38112
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>A regular scheduled VADEQ SWPPP inspection was completed on private and JNF lands at Brush Mountain. The area received approximately 2.5" of rainfall in the past 24 hours. I did not find any erosion occurring or sediment beyond the LOD. The surface remains stable. No impact has occurred at resource crossings. Buffers are stable and bridge ECDs are adequate. The slope breakers, sumps and end treatments continue to control stormwater runoff effectively. I did locate 3 areas where maintenance is needed on SSF. The contractor will be notified. Stone washed into Craig Creek Road from the RCE. An environmental crew removed the rock within an hour of notification.</p> <p>ECD maintenance needs identified today are;          11625+00 re-attach SSF fabric to chain link          11633+50 re-attach SSF fabric to chain link          11662+00-11662+25 replace worn SSF fabric</p> <p>Note; worn CFS installed on JNF will not be replaced at this time as there is no disturbed soils, no rilling is occurring and the surface is well vegetated.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/27/2022 11:07 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri, May 27, 2022, 08:31:24 EDT Position: +037.305222, -080.376108 (+5.0m) Altitude: 805m (+5.0m) Datum: WGS-84 Azimuth: +102° +1813m (+12°) Elevation Angle: -30.6° Horizon Angle: -32.8° Zoom: 1.0X 11659+00</p>		 <p>Date &amp; Time: Fri, May 27, 2022, 08:31:23 EDT Position: +037.305343, -080.376635 (+5.0m) Altitude: 777m (+5.0m) Datum: WGS-84 Azimuth: +102° +1813m (+12°) Elevation Angle: -30.6° Horizon Angle: -32.8° Zoom: 1.0X 11659+00</p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11665+00	<b>Field Station#</b>	11659+00		
<b>Pic 1 Desc.</b>	Communication; SSF fabric torn and in need of replacement.	<b>Pic 2 Desc.</b>	Sumps and end treatments checked for maintenance needs.		
 <p>Date &amp; Time: Fri, May 27, 2022, 08:39:09 EDT Position: +037.305575, -080.394900 (+5.0m) Altitude: 769m (+5.0m) Datum: WGS-84 Azimuth: +097° +1813m (+12°) Elevation Angle: -28.3° Horizon Angle: -28.3° Zoom: 1.0X 11658+00</p>		 <p>Date &amp; Time: Fri, May 27, 2022, 08:41:22 EDT Position: +037.305905, -080.394395 (+5.0m) Altitude: 795m (+5.0m) Datum: WGS-84 Azimuth: Bearing: 337° N23W 592 mils Magnetic (+12°) Elevation Angle: -27.6° Horizon Angle: -49.4° Zoom: 1.0X 11661+00</p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11658+00	<b>Field Station#</b>	11661+00		
<b>Pic 3 Desc.</b>	Perimeter ECDs are in place and effective.	<b>Pic 4 Desc.</b>	Perimeter ECDs were checked for maintenance needs.		
 <p>Date &amp; Time: Fri, May 27, 2022, 09:04:56 EDT Position: +037.318194, -080.377639 (+5.0m) Altitude: 812m (+5.0m) Datum: WGS-84 Azimuth: +039° +1813m (+12°) Elevation Angle: -26.5° Horizon Angle: -21.0° Zoom: 1.0X 11630+00</p>		 <p>Date &amp; Time: Fri, May 27, 2022, 09:10:04 EDT Position: +037.319595, -080.378929 (+5.0m) Altitude: 590m (+5.0m) Datum: WGS-84 Azimuth: +077° +1369mils (+12°) Elevation Angle: -20.2° Horizon Angle: -28.8° Zoom: 1.0X 11626+50</p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11630+00	<b>Field Station#</b>	11626+50		
<b>Pic 5 Desc.</b>	Sumps and end treatments functioning properly.	<b>Pic 6 Desc.</b>	Sumps and end treatments are functional.		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/27/2022 11:07 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Fri May 27, 2022 09:10:56 EDT Position: +037 313911 / -080 39826 (±5.0m) Altitude: 587m (±8.0m) Datum: WGS-84 Azimuth: -140° -1267mits (±12°) Elevation Angle: -06.6° Horizon Angle: -27.2° Zoom: 1.0X S-HH18</small></p>		 <p><small>Date &amp; Time: Fri May 27, 2022 09:24:53 EDT Position: +037 313620 / -080 402548 (±10.0m) Altitude: 587m (±8.0m) Datum: WGS-84 Azimuth: -078° -1387mits (±11°) Elevation Angle: -07.3° Horizon Angle: -27.4° Zoom: 1.0X S-RR14</small></p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11626+04	<b>Field Station#</b>	11614+20		
<b>Pic 7 Desc.</b>	The S-HH18 crossing is currently stable.	<b>Pic 8 Desc.</b>	The S-RR14 crossing is currently stable.		
 <p><small>Date &amp; Time: Fri May 27, 2022 07:29:39 EDT Position: +037 313621 / -080 402604 (±5.0m) Altitude: 552m (±8.0m) Datum: WGS-84 Azimuth: Bearing: 156° S24E 2773mits Magnetic (±10°) Elevation Angle: -09.9° Horizon Angle: -01.9° Zoom: 1.0X S-006</small></p>		<div style="text-align: center;">Insert image here</div>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>			
<b>Field Station#</b>	11607+81	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	The S-006 crossing is currently stable.	<b>Pic 10 Desc.</b>			
<div style="text-align: center;">Insert image here</div>		<div style="text-align: center;">Insert image here</div>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/27/2022 11:07 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38143
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/27/2022 3:37 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11899+89
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	74.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	1.80
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Culvert	Acceptable			
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/27/2022 3:37 PM	<b>Report #</b>	38143
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from ST# 11788+52 (Mount Tabor Road) to ST# 11899+89 (AR 266.03) Accompanied by EI Trey Ingram on SWPPP inspection from MP 223.27 to MP 225.37. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Environmental crews rained out due to projected weather forecast. This section of ROW has undergone permanent restoration. Permanent waterbars (section 6 other) and level spreaders in place where designated on E&S sheets. Majority of perimeter controls have been removed due to final restoration vegetation growth. Sensitive resource buffers are in place at pond P-KL2. Mount Tabor road crossing RCE is maintained and in acceptable condition. No sensitive resources have been impacted. Checked rain gauge at Mount Tabor Road. Gauge read 1.8 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/27/2022 3:37 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11789+00		Field Station#	11890+00	
Pic 1 Desc.	Rain gauge at Mount Tabor Road reads 1.8 inches.		Pic 2 Desc.	ROW permanently restored. Waterbar and level spreader in place.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11818+00		Field Station#	11840+00	
Pic 3 Desc.	ROW permanently restored.		Pic 4 Desc.	ROW permanently restored. Waterbar and level spreader in place.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11790+00		Field Station#	11789+00	
Pic 5 Desc.	Super silt fence in place along LOD.		Pic 6 Desc.	RCE in place at Mount Tabor Road crossing.	

<b>A/E</b>	124300137	<b>Date/Time</b>	5/27/2022 3:37 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	5/27/2022 3:37 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38157
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	5/28/2022 3:23 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10599+95
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11670+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	70.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)





E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

## 5. Site Conditions







Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/28/2022 3:23 PM	<b>Report #</b>	38157
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Met with two Global security guards at yard 26 to discuss protesters that had mobilized this morning at Green Valley Road (10311+43). A group of approximately 50 protesters were seen at Hwy 100 this afternoon. I traveled between Yard 37 and the top of Brush Mountain (11670+00) and did not encounter any protesters. Notified the guard at Yard 37 of protest activity in the area. Spoke with a USFS LEO officer named David Ford at FS Road 188 and notified him of protester plan to be at that location tomorrow morning.</p> <p>The ROW received an average of 0.3" rainfall last night. Checked the equipment bridge at S-RR13 (11613+69) on access road MN-258.04. No change in conditions at the bridge. Awaiting direction from ETRN regarding replacement of bridge. Checked resource crossing S-PP20 (11588+41), S-PP21 (11585+48) and adjacent wetland W-CD46 (11589+25). No impact has occurred. The ROW is stable at all locations visited today.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	5/28/2022 3:23 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Sat, May 28, 2022, 10:40:50 EDT  Position: +037.422342° / -080.666770° (+000.0m)  Altitude: 553m (+61.2m)  Datum: WGS-84  Azimuth/Bearing: 092° S38E 1597mils Magnetic (+10°)  Elevation Angle: +01.1°  Horizon Angle: +00.0°  Zoom: 1.0X  Yard 37</p> 		<p>Date &amp; Time: Sat, May 28, 2022, 10:47:05 EDT  Position: +037.346723° / -080.749992° (+10.0m)  Altitude: 643m (+8.0m)  Datum: WGS-84  Azimuth/Bearing: 007° N07E 0124mils Magnetic (+10°)  Elevation Angle: -09.8°  Horizon Angle: -09.6°  Zoom: 1.0X  Entrance to Pocahontas Road</p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	10458+97		
<b>Pic 1 Desc.</b>	Yard 37.	<b>Pic 2 Desc.</b>	Entrance to Pocahontas Road. No evidence of traffic this morning.		
<p>Date &amp; Time: Sat, May 28, 2022, 11:00:00 EDT  Position: +037.319353° / -080.666041° (+0.0m)  Altitude: 618m (+13.8m)  Datum: WGS-84  Azimuth/Bearing: 300° N48W 5540mils Magnetic (+10°)  Elevation Angle: +05.4°  Horizon Angle: +00.4°  Zoom: 1.0X  Norcross Road, 10599+95</p> 		<p>Date &amp; Time: Sat, May 28, 2022, 11:30:30 EDT  Position: +037.342123° / -080.621289° (+10.0m)  Altitude: 563m (+32.0m)  Datum: WGS-84  Azimuth/Bearing: 181° S01W 3290mils Magnetic (+07°)  Elevation Angle: +00.7°  Horizon Angle: -04.7°  Zoom: 1.0X  Cascade Drive 10798+83</p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	10599+95	<b>Field Station#</b>	10798+83		
<b>Pic 3 Desc.</b>	No protester sightings in the Norcross Road or Big Stony Road area.	<b>Pic 4 Desc.</b>	No protest activity in Cascade Drive area. ROW stable.		
<p>Date &amp; Time: Sat, May 28, 2022, 11:01:00 EDT  Position: +037.319353° / -080.666041° (+0.0m)  Altitude: 650m (+5.0m)  Datum: WGS-84  Azimuth/Bearing: 304° N54W 5440mils Magnetic (+10°)  Elevation Angle: +01.0°  Horizon Angle: -02.4°  Zoom: 1.0X  Mountain Lake Road 11158+12</p> 		<p>Date &amp; Time: Sat, May 28, 2022, 12:00:00 EDT  Position: +037.366622° / -080.466691° (+4.0m)  Altitude: 568m (+8.0m)  Datum: WGS-84  Azimuth/Bearing: 154° S34E 2790mils Magnetic (+10°)  Elevation Angle: +02.2°  Horizon Angle: -00.0°  Zoom: 1.0X  Community Park on Hwy 42</p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11158+12	<b>Field Station#</b>	11298+08		
<b>Pic 5 Desc.</b>	No protest activity at Mountain Lake Road area. ROW stable.	<b>Pic 6 Desc.</b>	No protesters at the Newport Community Park.		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/28/2022 3:23 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Sat, May 28, 2022, 12:05:52 EDT Position: +037.294045° / -080.495293° (±5.0m) Altitude: 884m (±6.0m) Datum: WGS-84 Azimuth/Bearing: 107° S71E 1938mils Magnetic (±10°) Elevation Angle: -02.5° Horizon Angle: -04.7° Zoom: 1.0X New signage recently installed in Newport</p>		 <p>Date &amp; Time: Sat, May 28, 2022, 12:06:19 EDT Position: +037.316240° / -080.402727° (±5.0m) Altitude: 676m (±6.0m) Datum: WGS-84 Azimuth/Bearing: 109° S71E 1938mils Magnetic (±10°) Elevation Angle: -17.3° Horizon Angle: -00.9° Zoom: 1.0X S-PP21</p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11254+88	<b>Field Station#</b>	11613+69		
<b>Pic 7 Desc.</b>	Recently installed "MVP Blast Zone" signage installed on Hwy 42 in Newport VA.	<b>Pic 8 Desc.</b>	The S-RR13 crossing. Root ball still lodged against bridge. Bridge remains intact.		
 <p>Date &amp; Time: Sat, May 28, 2022, 13:14:44 EDT Position: +037.316390° / -080.408418° (±5.0m) Altitude: 626m (±6.0m) Datum: WGS-84 Azimuth/Bearing: 311° N69W 5529mils Magnetic (±14°) Elevation Angle: -08.7° Horizon Angle: -02.6° Zoom: 1.0X S-PP20</p>		 <p>Date &amp; Time: Sat, May 28, 2022, 13:40:17 EDT Position: +037.317230° / -080.405111° (±5.0m) Altitude: 631m (±6.0m) Datum: WGS-84 Azimuth/Bearing: 165° S15E 2933mils Magnetic (±14°) Elevation Angle: -12.4° Horizon Angle: -01.3° Zoom: 1.0X S-PP21</p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11588+41	<b>Field Station#</b>	11585+48		
<b>Pic 9 Desc.</b>	The S-PP20 crossing is stable.	<b>Pic 10 Desc.</b>	The SPP21 crossing shows no impact.		
 <p>Date &amp; Time: Sat, May 28, 2022, 13:20:17 EDT Position: +037.316312° / -080.408545° (±5.0m) Altitude: 618m (±6.0m) Datum: WGS-84 Azimuth/Bearing: 189° S09W 3186mils Magnetic (±12°) Elevation Angle: -03.1° Horizon Angle: -00.0° Zoom: 1.0X W-CD46</p>		 <p>Date &amp; Time: Sat, May 28, 2022, 13:52:00 EDT Position: +037.301723° / -080.402513° (±5.0m) Altitude: 846m (±6.0m) Datum: WGS-84 Azimuth/Bearing: 269° S08W 4764mils Magnetic (±12°) Elevation Angle: -07.4° Horizon Angle: -01.1° Zoom: 1.0X Brush Mountain</p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11589+25	<b>Field Station#</b>	11670+00		
<b>Pic 11 Desc.</b>	Adjacent wetland W-CD46 has no impact.	<b>Pic 12 Desc.</b>	Approximately 8 vehicles parked at entrance to FS Road 188. None appeared to belong to protest group.		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/28/2022 3:23 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		