



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38181
<b>Inspector</b>	David Schoolcraft			<b>Date/Time</b>	5/30/2022 1:03 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10655+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10749+92
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	85.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions



Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/30/2022 1:03 PM	<b>Report #</b>	38181
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with environmental team Preformed VA SWPPP inspection from 10655+00 (MP 201.6) to 10749+92 (MP 203.6) Accompanied by fellow EI Eric Hanlon This section of ROW has no current construction. No deficiencies found. All perimeter controls, ECDs and BMPs functional at time of inspection. Stream buffers and controls in place at the time of inspection. No sensitive resources have been impacted					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/30/2022 1:03 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Mon, May 30, 2022, 10:49:03 EDT Position: +037 353500 / -080 663728 (+11.7ft) Altitude: 2211ft (+11.7ft) Datum: WGS-84 Azimuth/Bearing: 304° N54W 3406mils True (+12°) Elevation Angle: +10.3° Horizon Angle: -00.9° Zoom: 0.5X 10656+46</p>		 <p>Date &amp; Time: Mon, May 30, 2022, 10:51:41 EDT Position: +037 353550 / -080 666169 (+11.7ft) Altitude: 2247ft (+11.7ft) Datum: WGS-84 Azimuth/Bearing: 072° N72E 3280mils True (+12°) Elevation Angle: -00.5° Horizon Angle: -04.4° Zoom: 0.5X 10661+00</p>		<b>GPS Location</b>	See Photo
<b>Field Station#</b>	10656+46	<b>Field Station#</b>	10661+00	<b>GPS Location</b>	See Photo
<b>Pic 1 Desc.</b>	Perimeter controls	<b>Pic 2 Desc.</b>	Stabilization water bars		
 <p>Date &amp; Time: Mon, May 30, 2022, 10:56:22 EDT Position: +037 352042 / -080 660884 (+11.6ft) Altitude: 2231ft (+9.8ft) Datum: WGS-84 Azimuth/Bearing: 354° N64W 6293mils True (+12°) Elevation Angle: +33.2° Horizon Angle: -03.8° Zoom: 0.5X 10668+00</p>		 <p>Date &amp; Time: Mon, May 30, 2022, 10:59:10 EDT Position: +037 350708 / -080 659592 (+11.4ft) Altitude: 2163ft (+13.1ft) Datum: WGS-84 Azimuth/Bearing: 299° N61W 5316mils True (+12°) Elevation Angle: +27.9° Horizon Angle: +08.8° Zoom: 0.5X 10674+90</p>		<b>GPS Location</b>	See Photo
<b>Field Station#</b>	10668+00	<b>Field Station#</b>	10674+90	<b>GPS Location</b>	See Photo
<b>Pic 3 Desc.</b>	Stone outlet protections	<b>Pic 4 Desc.</b>	RCE		
 <p>Date &amp; Time: Mon, May 30, 2022, 11:13:02 EDT Position: +037 348392 / -080 640200 (+11.5ft) Altitude: 2320ft (+11.7ft) Datum: WGS-84 Azimuth/Bearing: 303° N57W 5387mils True (+12°) Elevation Angle: +03.3° Horizon Angle: +00.9° Zoom: 0.5X 10727+00</p>		 <p>Date &amp; Time: Mon, May 30, 2022, 11:42:30 EDT Position: +037 345922 / -080 637632 (+11.6ft) Altitude: 2245ft (+11.7ft) Datum: WGS-84 Azimuth/Bearing: 151° S29E 2684mils True (+12°) Elevation Angle: -20.0° Horizon Angle: -00.1° Zoom: 0.5X 10741+00</p>		<b>GPS Location</b>	See Photo
<b>Field Station#</b>	10727+00	<b>Field Station#</b>	10741+00	<b>GPS Location</b>	See Photo
<b>Pic 5 Desc.</b>	Drainage feature	<b>Pic 6 Desc.</b>	Sump pit end treatment		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/30/2022 1:03 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Photo 7 Time: Mon, May 30, 2022 11:42:18 EDT  Position: +037 3445721 -090 083539 124300  Altitude: 2300ft (+9.8m)  Datum: WGS-84  Azimuth Bearing: 189.597W 3340mils True (2.3)  Elevation Angle: -00.3  Horizon Angle: -00.3  Zoom: 1.0X  10743+00</p>		 <p>Photo 8 Time: Mon, May 30, 2022 11:42:21 EDT  Position: +037 3445721 -090 083539 124300  Altitude: 2300ft (+9.8m)  Datum: WGS-84  Azimuth Bearing: 189.597W 3340mils True (2.3)  Elevation Angle: -00.3  Horizon Angle: -00.3  Zoom: 1.0X  10749+00</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	10743+00	<b>Field Station#</b>	10749+00		
<b>Pic 7 Desc.</b>	Equipment bridge	<b>Pic 8 Desc.</b>	RCE		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/30/2022 1:03 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38174
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	5/30/2022 9:49 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10798+92
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10859+46
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	81.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions




Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/30/2022 9:49 AM	<b>Report #</b>	38174
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Discussed RoW/ECD conditions, within this section, with fellow EI Joe Sweeden. Performed SWPPP inspection from MP 204.53 (10798+92) and MP 205.67 (10859+46). Accompanied by fellow EI Joe Sweeden. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Assessed access roads Archer Trail and Collins Avenue.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE		124300137		Date/Time		5/30/2022 9:49 AM		Report #							
Pictures															
															
Date & Time: Mon, May 30, 2022, 09:30:09 EDT Position: 1383458.731 E / 374287.345 N (±11.4M) Altitude: 1926ft (±13.1ft) Datum: WGS-84 Azimuth/Bearing: 108° S72E 1920mils True (±10°) Elevation/Angle: -05.9° Horizon Angle: -00.6° Zoom: 0.5X 10799+00 S-Z10/W-Z3				Date & Time: Mon, May 30, 2022, 09:42:26 EDT Position: 1383755.022 E / 374168.056 N (±11.4M) Altitude: 2344ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 303° N57W 5387mils True (±12°) Elevation/Angle: -05.7° Horizon Angle: -01.6° Zoom: 0.5X 10801+52 S-Z11/S-Z12/S-Z13											
GPS Location				1				GPS Location				2			
Field Station#				10799+00				Field Station#				0801+52			
Pic 1 Desc.				S-Z10/W-Z3.				Pic 2 Desc.				S-Z11/S-Z12/S-Z13.			
															
Date & Time: Mon, May 30, 2022, 09:49:11 EDT Position: 1383100.428 E / 373979.100 N (±11.4M) Altitude: 1974ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 121° S55E 2101mils True (±12°) Elevation/Angle: -08.8° Horizon Angle: -03.7° Zoom: 0.5X 10804+00				Date & Time: Mon, May 30, 2022, 10:16:49 EDT Position: 1386164.083 E / 373882.682 N (±11.4M) Altitude: 2574ft (±11.1ft) Datum: WGS-84 Azimuth/Bearing: 305° N54W 6240mils True (±12°) Elevation/Angle: -01.7° Horizon Angle: -01.8° Zoom: 0.5X 10818+00											
GPS Location				3				GPS Location				4			
Field Station#				10804+00				Field Station#				10818+00			
Pic 3 Desc.				Section of RoW showing conditions and controls.				Pic 4 Desc.				Section of RoW showing conditions and controls.			
															
Date & Time: Mon, May 30, 2022, 10:21:55 EDT Position: 1385220.676 E / 373339.848 N (±11.4M) Altitude: 2355ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 305° N56W 6240mils True (±12°) Elevation/Angle: -03.7° Horizon Angle: -00.0° Zoom: 0.5X 10826+50				Date & Time: Mon, May 30, 2022, 10:23:26 EDT Position: 1386164.083 E / 373882.682 N (±11.4M) Altitude: 2574ft (±11.1ft) Datum: WGS-84 Azimuth/Bearing: 059° N59E 1049mils True (±12°) Elevation/Angle: -03.0° Horizon Angle: -01.7° Zoom: 0.5X 10831+00											
GPS Location				5				GPS Location				6			
Field Station#				10826+50				Field Station#				10831+00			
Pic 5 Desc.				CWDP outlet protection functional.				Pic 6 Desc.				Section of RoW showing conditions and controls.			



<b>AFE</b>	124300137	<b>Date/Time</b>	5/30/2022 9:49 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	7	<b>GPS Location</b>	8		
<b>Field Station#</b>	10819+03	<b>Field Station#</b>	1087+50		
<b>Pic 7 Desc.</b>	S-YZ1/Collins Ave.	<b>Pic 8 Desc.</b>	Temporary repair on previously reported punch list item.		
		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>	9	<b>GPS Location</b>			
<b>Field Station#</b>	10956+00	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	Overview S-A33/S-A34.	<b>Pic 10 Desc.</b>			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			



<b>A/E</b>	124300137	<b>Date/Time</b>	5/30/2022 9:49 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38189
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/30/2022 4:02 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10749+92
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10797+92
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	82.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Erosion Control Blanket	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/30/2022 4:02 PM	<b>Report #</b>	38189
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from ST# 10747+92 (Hendrickson Road) to ST# 10798+92 (Cascade Road) Accompanied by EI Trey Ingram on SWPPP inspection from MP 204.53 to MP 205.67. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed environmental maintenance crews walking through section checking ECDs. This section of ROW is temporarily stabilized with seed and mulch. Vegetation growth is present throughout section. Clean water diversion berms, pipes and level spreaders are in place. ECDs in place per E&S sheets. Sensitive resource buffers are in place at streams S-G35, S-SS4, S-Z9, S-Z7 braid 1, and S-Z7 braid 2. Hendrickson Road, Big Branch Hollow Road, and Cascade Road crossings RCEs are maintained and in acceptable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 5/30/2022 4:02 PM		Report #	
Pictures					
 <p>Date &amp; Time: Mon, May 30, 2022, 09:10:15 EDT Position: +037.344521° / -080.633693° (+239.9ft) Altitude: 2283ft (+134.0ft) Datum: WGS-84 Azimuth/Bearing: 088° N88E 156mils True (+15°) Elevation Angle: -26.0° Horizon Angle: -00.7° Zoom: 1.0x 10753+00</p>		 <p>Date &amp; Time: Mon, May 30, 2022, 09:10:19 EDT Position: +037.344387° / -080.633693° (+239.9ft) Altitude: 2156ft (+229.9ft) Datum: WGS-84 Azimuth/Bearing: 042° N42E 0747mils True (+13°) Elevation Angle: -12.8° Horizon Angle: -04.3° Zoom: 1.0x 10758+00 S-G35</p>			
GPS Location		See photo for GPS location.		GPS Location	
Field Station#		10753+00		Field Station#	
Pic 1 Desc.		Waterbars in place.		Pic 2 Desc.	
				Sensitive resource buffer in place at stream S-G35.	
 <p>Date &amp; Time: Mon, May 30, 2022, 09:17:31 EDT Position: +037.345245° / -080.630042° (+826.1ft) Altitude: 2089ft (+136.4ft) Datum: WGS-84 Azimuth/Bearing: 150° S44E 2618mils True (+15°) Elevation Angle: -27.8° Horizon Angle: -08.2° Zoom: 1.0x 10761+00</p>		 <p>Date &amp; Time: Mon, May 30, 2022, 09:17:16 EDT Position: +037.345245° / -080.630042° (+826.1ft) Altitude: 2273ft (+146.6ft) Datum: WGS-84 Azimuth/Bearing: 186° S06W 3007mils True (+15°) Elevation Angle: -30.7° Horizon Angle: -02.3° Zoom: 1.0x 10772+00</p>			
GPS Location		See photo for GPS location.		GPS Location	
Field Station#		10761+00		Field Station#	
Pic 3 Desc.		Rock inlet protection at slope drain pipe.		Pic 4 Desc.	
				Clean water diversion pipe and level spreader in place.	
 <p>Date &amp; Time: Mon, May 30, 2022, 09:19:09 EDT Position: +037.345245° / -080.622379° (+619.3ft) Altitude: 1933ft (+111.2ft) Datum: WGS-84 Azimuth/Bearing: 285° N75W 5067mils True (+13°) Elevation Angle: -09.7° Horizon Angle: -00.2° Zoom: 1.0x 10793+00</p>		 <p>Date &amp; Time: Mon, May 30, 2022, 09:20:08 EDT Position: +037.342634° / -080.620161° (+619.3ft) Altitude: 1925ft (+110.1ft) Datum: WGS-84 Azimuth/Bearing: 125° S55E 4222mils True (+13°) Elevation Angle: -08.5° Horizon Angle: -00.7° Zoom: 1.0x 10797+92</p>			
GPS Location		See photo for GPS location.		GPS Location	
Field Station#		10793+00		Field Station#	
Pic 5 Desc.		ROW temporarily stabilized.		Pic 6 Desc.	
				RCE in place at Cascade Road.	



<b>A/E</b>	124300137	<b>Date/Time</b>	5/30/2022 4:02 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/30/2022 4:02 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38190
<b>Inspector</b>	Daniel Fortune			<b>Date/Time</b>	5/30/2022 8:32 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10859+47
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+80
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	66.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00




1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/30/2022 8:32 PM	<b>Report #</b>	38190
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. - ALL STATION NUMBERS ARE APPROXIMATE - Completed a VA SWPPP inspection from MP 205.67 (10859+46) to MP 207.0 (10929+80). No Deficiencies documented for repairs today. Other deficiencies may be found and documented my other EI's and or contractor staff. No crew activity observed at the time of inspection. Precision observed the Memorial Day Holiday. This section of row remains adequately stabilized at the time of inspection. Temporary vegetation is visible throughout. Some areas heavier than others. The recent soil sluffing from spoil pile near 10888+50 remains stable with no further separation. The temporary water bars appear to be functioning as intended. Sump pits, water bar end treatments, and temporary slope drain pipes also appear to be functioning as intended with no maintenance required at this time. All other perimeter controls, ECDs and BMPs functional at time of inspection. There are three (3) stream resources within this section of row inspected. No impacts at this time of inspection. S-Y2...10929+43 (Doe Creek Rd)- No impact to stream. Buffer zones are undisturbed and vegetated. Equipment bridge clean and functional. S-Y3...10927+77 (Doe Creek Rd)- No impact to stream. Buffer zones are undisturbed and vegetated. Equipment bridge clean and functional. S-A32...10929+43 (Doe Creek Rd)- No impact to stream. Buffer zones are undisturbed and vegetated. Equipment bridge clean and functional.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	5/30/2022 8:32 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Mon, May 30, 2022, 10:47:08 EDT Position: +037.331365 / -080.562997 (s:15.6m) Altitude: 2120ft (s:11.0m) Datum: WGS-84 Azimuth/Bearing: 245° S45W 235mils True (s:12.1) Elevation Grade: +025 Horizon Grade: +001 Zoom: 0.5X 10929+70 S-Y2</p>		 <p>Date &amp; Time: Mon, May 30, 2022, 10:45:00 EDT Position: +037.331365 / -080.563346 (s:15.3m) Altitude: 2120ft (s:11.0m) Datum: WGS-84 Azimuth/Bearing: 190° S10W 339mils True (s:12.1) Elevation Grade: +046 Horizon Grade: +000 Zoom: 0.8X 10927+77 S-Y3</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	10929+70	<b>Field Station#</b>	10927+77		
<b>Pic 1 Desc.</b>	S-Y2 stream conditions. Water heavily flowing clean and clear.		<b>Pic 2 Desc.</b>	S-Y3 stream resource area. ECDs found functional	
 <p>Date &amp; Time: Mon, May 30, 2022, 10:43:13 EDT Position: +037.332227 / -080.567067 (s:16.4m) Altitude: 2158ft (s:11.0m) Datum: WGS-84 Azimuth/Bearing: 124° S54E 224mils True (s:12.1) Elevation Grade: +024 Horizon Grade: +000 Zoom: 0.5X 10883+10 S-A32</p>		 <p>Date &amp; Time: Mon, May 30, 2022, 10:43:13 EDT Position: +037.332227 / -080.567067 (s:16.4m) Altitude: 2158ft (s:11.0m) Datum: WGS-84 Azimuth/Bearing: 109° S50E 231mils True (s:12.1) Elevation Grade: +021 Horizon Grade: +006 Zoom: 1.0X 10926+45</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	10883+10	<b>Field Station#</b>	10926+45		
<b>Pic 3 Desc.</b>	Over view of the S-A32 stream resource conditions. All ECDs found functional		<b>Pic 4 Desc.</b>	Perimeter CFS and empty sump pit conditions.	
 <p>Date &amp; Time: Mon, May 30, 2022, 10:29:08 EDT Position: +037.333186 / -080.576774 (s:13.5m) Altitude: 2111ft (s:19.2m) Datum: WGS-84 Azimuth/Bearing: 288° N72W 5120mils True (s:12.1) Elevation Grade: +027 Horizon Grade: +001 Zoom: 0.5X 10880+00</p>		 <p>Date &amp; Time: Mon, May 30, 2022, 10:31:46 EDT Position: +037.332595 / -080.576577 (s:13.5m) Altitude: 2111ft (s:19.2m) Datum: WGS-84 Azimuth/Bearing: 172° S30E 1971mils True (s:12.1) Elevation Grade: +016 Horizon Grade: +005 Zoom: 0.8X 10889+50</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	10880+00	<b>Field Station#</b>	10889+50		
<b>Pic 5 Desc.</b>	View of steep slope temporary stabilization		<b>Pic 6 Desc.</b>	Stabilization of steep slope and additional P1 silt fencing to contain further soil sluffing.	

<b>AFE</b>	124300137	<b>Date/Time</b>	5/30/2022 8:32 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	10871+00	<b>Field Station#</b>	10875+00		
<b>Pic 7 Desc.</b>	Temporary level spreader and slope drain pipe conditions.	<b>Pic 8 Desc.</b>	Temporary stabilization and current condition of temporary water bar.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/30/2022 8:32 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38233
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/31/2022 4:14 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10929+80
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11023+80
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	83.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



AFE	124300137	Date/Time	5/31/2022 4:14 PM	Report #	
Pictures					
 <p>Date &amp; Time: Tue, May 31, 2022, 09:05:25 EDT Position: +037.3244027 / -080.554781 / +421.2ft Altitude: 2411ft (+49.8ft) Datum: WGS-84 Azimuth/Bearing: 312° S49W 5547mils True (+14) Elevation/Angle: -26.1° Horizon/Angle: -00.8° Zoom: 1.0x 11019+00</p>		 <p>Date &amp; Time: Tue, May 31, 2022, 09:05:25 EDT Position: +037.3244027 / -080.554781 / +421.2ft Altitude: 2411ft (+49.8ft) Datum: WGS-84 Azimuth/Bearing: 225° S45W 400mils True (+17) Elevation/Angle: -26.1° Horizon/Angle: -00.8° Zoom: 1.0x 11017+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11019+00		Field Station#	11017+00	
Pic 1 Desc.	Clean water diversion berm in place.		Pic 2 Desc.	Slope drain in place over fill slope.	
 <p>Date &amp; Time: Tue, May 31, 2022, 09:12:17 EDT Position: +037.3244253 / -080.557088 / +292.0ft Altitude: 2411ft (+52.6ft) Datum: WGS-84 Azimuth/Bearing: 312° N49W 5547mils True (+14) Elevation/Angle: -12.7° Horizon/Angle: -00.0° Zoom: 1.0x 11011+15</p>		 <p>Date &amp; Time: Tue, May 31, 2022, 09:40:01 EDT Position: +037.3249297 / -080.566232 / +318.6ft Altitude: 2413ft (+11.3ft) Datum: WGS-84 Azimuth/Bearing: 292° N59W 5280mils True (+12) Elevation/Angle: -18.7° Horizon/Angle: -00.2° Zoom: 1.0x 10986+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11011+15		Field Station#	10986+00	
Pic 3 Desc.	Clean water diversion pipe inlet and clean water diversion berm in place.		Pic 4 Desc.	Sensitive resource buffer in place at streams S-E24 and S-E25.	
 <p>Date &amp; Time: Tue, May 31, 2022, 09:36:35 EDT Position: +037.3274011 / -080.571598 / +523.9ft Altitude: 2318ft (+35.1ft) Datum: WGS-84 Azimuth/Bearing: 097° S83E 1724mils True (+12) Elevation/Angle: -00.8° Horizon/Angle: -03.2° Zoom: 1.0x 10966+00</p>		 <p>Date &amp; Time: Tue, May 31, 2022, 09:47:47 EDT Position: +037.328030 / -080.573676 / +15.9ft Altitude: 2273ft (+25.7ft) Datum: WGS-84 Azimuth/Bearing: 293° N67W 5209mils True (+12) Elevation/Angle: -01.8° Horizon/Angle: -05.7° Zoom: 1.0x 10961+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10966+00		Field Station#	10961+00	
Pic 5 Desc.	Triple barrier ECDs in place at cave.		Pic 6 Desc.	ROW permanently restored.	

<b>A/E</b>	124300137	<b>Date/Time</b>	5/31/2022 4:14 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/31/2022 4:14 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38200
<b>Inspector</b>	Joe Sweeden			<b>Date/Time</b>	5/31/2022 7:19 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11098+47
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11184+85
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	77.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/31/2022 7:19 AM	<b>Report #</b>	38200
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable				
Level Spreader	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed Virginia SWPPP inspection from MP 210.2 (11098+47) and MP 211.83 (11184+85), AR 245.02-249.02, with EI, Chris Burns. No deficiencies were found. The majority of this section of ROW is fully restored. Areas around Mountain Lake road are not. Water bars (other) and level spreaders in the restored area are installed to specifications and are functioning as designed. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/31/2022 7:19 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11182+50		<b>Field Station#</b>	11174+00	
<b>Pic 1 Desc.</b>	Level spreader		<b>Pic 2 Desc.</b>	Water bar, level spreader	
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11163+00		<b>Field Station#</b>	11146+00	
<b>Pic 3 Desc.</b>	Water bar end treatment		<b>Pic 4 Desc.</b>	Water bar, stabilized ROW	
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11136+00		<b>Field Station#</b>	11122+00	
<b>Pic 5 Desc.</b>	Compost sock		<b>Pic 6 Desc.</b>	Water way	



<b>AFE</b>	124300137	<b>Date/Time</b>	5/31/2022 7:19 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	1105+37		<b>Field Station#</b>	11184+50	
<b>Pic 7 Desc.</b>	Restored ROW		<b>Pic 8 Desc.</b>	Water bars (other) level spreaders	
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 9 Desc.</b>			<b>Pic 10 Desc.</b>		
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 11 Desc.</b>			<b>Pic 12 Desc.</b>		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/31/2022 7:19 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38218
<b>Inspector</b>	David Schoolcraft			<b>Date/Time</b>	5/31/2022 10:49 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11184+85
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11254+99
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/31/2022 10:49 AM	<b>Report #</b>	38218
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with environmental team Preformed VA SWPPP inspection from 11184+85 (MP 211.83) to 11254+99 (MP 213.6) Accompanied by fellow EI Eric Hanlon This section of ROW has no current forward progress construction going on. However maintenance crews are on site repairing ditch subsidence as needed in temporary stabilized area. 11222+50 - 11247+00 No deficiencies found Water bars (other) All perimeter controls, ECDs and BMPs functional at time of inspection. Stream buffers and controls in place at the time of inspection. 11222+50 to 11206+27 stabilization in restoration is thin and continuing to be monitored by inspection. Was over seeded on 4/12/22 and 4/13/22 11207+00 to 11222+50 monitoring ditch subsidence. No sensitive resources have been impacted					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	5/31/2022 10:49 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11185+00	<b>Field Station#</b>	11187+00		
<b>Pic 1 Desc.</b>	Access and controls	<b>Pic 2 Desc.</b>	Level spreader		
					
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11191+00	<b>Field Station#</b>	11207+00		
<b>Pic 3 Desc.</b>	Drainage Feature	<b>Pic 4 Desc.</b>	Restoration monitoring growth		
					
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11214+00	<b>Field Station#</b>	11218+50		
<b>Pic 5 Desc.</b>	Perimeter controls	<b>Pic 6 Desc.</b>	Restoration monitoring growth and subsidence		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/31/2022 10:49 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11235+00	<b>Field Station#</b>	11239+00		
<b>Pic 7 Desc.</b>	Section of ROW showing conditions and controls	<b>Pic 8 Desc.</b>	Maintenance crews working on ditch subsidence		
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11241+00	<b>Field Station#</b>	11252+25		
<b>Pic 9 Desc.</b>	Stabilization	<b>Pic 10 Desc.</b>	Waterbars		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/31/2022 10:49 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38238
<b>Inspector</b>	Daniel Fortune			<b>Date/Time</b>	5/31/2022 6:27 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11098+67
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	78.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			




### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/31/2022 6:27 PM	<b>Report #</b>	38238
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Completed a VA SWPPP inspection from ST# 11023+80 - 11098+47 (MP 208.78-210.2). AR 244 - 245.02. Fellow EI assisted in todays inspection. No deficiencies were observed in todays inspection.</p> <p>"Station numbers are approximate".</p> <p>The ROW received 0.0" of precipitation in the last 24 hours. The row condition is dry and remains at a stable repose. No issues at this time.</p> <p>The ROW from AR 244 near 11025+02 to near 11070+21 has been temporarily stabilized. And temporary water bars were found functional. No erosion issues.</p> <p>The ROW from station 11070+21 to near 11098+00 has had final Restoration completed. There are annual grasses thriving and remain visible. There are 12" CFS that are being used as water bars (section 6) at this time. There are no erosion issues visible in the final restored areas. The perimeter controls appear to be functional at this time.</p> <p>One area of open ditch near 11061+00. Rock Road approaches were cleaned and functioning as intended. No sensitive resources have been impacted. Undisturbed Fully vegetated buffer zones are protected with functional ECDs</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	5/31/2022 6:27 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Tue, May 31, 2022, 10:56:29 EDT Position: +037.315319 / -080.541605 (+35.1ft) Altitude: 2221ft (+52.5ft) Datum: WGS-84 Azimuth/Bearing: 082° N82E 1658mils True (±12°) Elevation Grade: -000% Horizon Grade: -007% Zoom: 0.5X 11072+00</p>		 <p>Date &amp; Time: Tue, May 31, 2022, 10:45:45 EDT Position: +037.315509 / -080.544076 (+42.9ft) Altitude: 2027ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 040° N40E 0711mils True (±12°) Elevation Grade: -025% Horizon Grade: -001% Zoom: 0.5X 11065+84</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11072+00	<b>Field Station#</b>	11065+84		
<b>Pic 1 Desc.</b>	Final restoration area.	<b>Pic 2 Desc.</b>	Drainage feature conditions.		
 <p>Date &amp; Time: Tue, May 31, 2022, 10:57:35 EDT Position: +037.315112 / -080.543999 (+34.1ft) Altitude: 2131ft (+53.7ft) Datum: WGS-84 Azimuth/Bearing: 082° N82E 0124mils True (±12°) Elevation Grade: -007% Horizon Grade: -001% Zoom: 0.5X 11057+00</p>		 <p>Date &amp; Time: Tue, May 31, 2022, 10:31:29 EDT Position: +037.314989 / -080.542481 (+16.0ft) Altitude: 2147ft (+53.7ft) Datum: WGS-84 Azimuth/Bearing: 326° N38W 5778mils True (±12°) Elevation Grade: -014% Horizon Grade: -001% Zoom: 0.5X 11049+96</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11057+00	<b>Field Station#</b>	11049+96		
<b>Pic 3 Desc.</b>	Functional Perimeter controls protecting off site karst area.	<b>Pic 4 Desc.</b>	S-IJ16b and 17 Stream resource area. Adequate ECD's and a functional equipment bridge crossing.		
 <p>Date &amp; Time: Tue, May 31, 2022, 10:26:38 EDT Position: +037.315232 / -080.543804 (+34.0ft) Altitude: 2231ft (+53.4ft) Datum: WGS-84 Azimuth/Bearing: 105° S75E 1057mils True (±12°) Elevation Grade: -035% Horizon Grade: -002% Zoom: 0.5X 11045+00</p>		 <p>Date &amp; Time: Tue, May 31, 2022, 10:22:01 EDT Position: +037.315412 / -080.550450 (+14.3ft) Altitude: 2226ft (+53.2ft) Datum: WGS-84 Azimuth/Bearing: 327° N38W 5812mils True (±12°) Elevation Grade: -077% Horizon Grade: -000% Zoom: 0.5X 11040+00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11045+00	<b>Field Station#</b>	11040+00		
<b>Pic 5 Desc.</b>	Steep slope stabilization with ECB. No Issues at this time.	<b>Pic 6 Desc.</b>	Stone inlet protection, slope drain pipe, and sump pit with functional water bar end treatment.		

<b>AFE</b>	124300137	<b>Date/Time</b>	5/31/2022 6:27 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Tue, May 31, 2022, 10:03:11 EDT Position: +937 322702, -890 552429, +147 591 Altitude: 2406ft (+39 4m) Datum: WGS 84 Azimuth/Bearing: 172° S08E 3058mils True (42°) Elevation Grade: -024% Horizon Grade: +001% Zoom: 0.5X 11038+00</small></p>				 <p><small>Date &amp; Time: Tue, May 31, 2022, 10:14:17 EDT Position: +937 322702, -890 552429, +147 591 Altitude: 2406ft (+39 4m) Datum: WGS 84 Azimuth/Bearing: 200° N20W 5156mils True (42°) Elevation Grade: -01% Horizon Grade: +000% Zoom: 0.5X 11025+50</small></p>	
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11038+00	<b>Field Station#</b>	11025+50		
<b>Pic 7 Desc.</b>	Temporary stabilization of row.	<b>Pic 8 Desc.</b>	S-IJ18 Stream resource area. No issues and equipment bridge found functional.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/31/2022 6:27 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38249
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	6/1/2022 6:15 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11353+67
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11471+56
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	82.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			







<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	6/1/2022 6:15 AM	<b>Report #</b>	38249
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 215.04 (11353+67) and MP 217.26 (11471+56). Accompanied by fellow EI Joe Sweeden. This section of RoW is partially restored. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Section 6 - other (waterbars).					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	6/1/2022 6:15 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11469+00	<b>Field Station#</b>	11451+87		
<b>Pic 1 Desc.</b>	Section of RoW showing conditions and controls.		<b>Pic 2 Desc.</b>	S-0012.	
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11451+08	<b>Field Station#</b>	11448+93		
<b>Pic 3 Desc.</b>	S-0013.		<b>Pic 4 Desc.</b>	S-0014/W-CD12.	
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11438+00	<b>Field Station#</b>	11432+00		
<b>Pic 5 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 6 Desc.</b>	Representative photo of permanent waterbar and level spreaders installed.	



<b>AFE</b>	124300137	<b>Date/Time</b>	6/1/2022 6:15 AM	<b>Report #</b>	
<b>Pictures</b>					
<div><div><div>Date &amp; Time Wed Jun 01, 2022 07:50:05 EDT Position 1632437.425 E / 3367437.13 N (a11.40) Altitude 2217ft (a11.40) Datum WGS-84 Azimuth/Bearing 221° S41W 8929mils True (a12°) Elevation Angle -11.1° Horizon Angle -41.1° Zoom 0.5X 11413+00</div><div></div></div></div>		<div><div><div>Date &amp; Time Wed Jun 01, 2022 07:50:18 EDT Position 1632437.425 E / 3367437.13 N (a11.40) Altitude 2217ft (a11.40) Datum WGS-84 Azimuth/Bearing 221° S41W 8929mils True (a12°) Elevation Angle -11.1° Horizon Angle -41.1° Zoom 0.5X 11413+00</div><div></div></div></div>			
<b>GPS Location</b>	7		<b>GPS Location</b>	8	
<b>Field Station#</b>	11413+00		<b>Field Station#</b>	11397+00	
<b>Pic 7 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 8 Desc.</b>	Section of restored RoW showing conditions and controls.	
<div><div><div>Date &amp; Time Wed Jun 01, 2022 08:05:21 EDT Position 1632437.425 E / 3367437.13 N (a11.40) Altitude 2125ft (a11.40) Datum WGS-84 Azimuth/Bearing 233° N68E 1422mils True (a12°) Elevation Angle -10.8° Horizon Angle -49.5° Zoom 0.5X 11385+00</div><div></div></div></div>		<div><div><div>Date &amp; Time Wed Jun 01, 2022 08:10:11 EDT Position 1632437.425 E / 3367437.13 N (a11.40) Altitude 2039ft (a11.40) Datum WGS-84 Azimuth/Bearing 233° S53W 4291mils True (a12°) Elevation Angle -10.5° Horizon Angle -44.0° Zoom 0.5X 11377+00</div><div></div></div></div>			
<b>GPS Location</b>	9		<b>GPS Location</b>	10	
<b>Field Station#</b>	11385+50		<b>Field Station#</b>	11377+00	
<b>Pic 9 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 10 Desc.</b>	Section of restored RoW showing conditions and controls.	
<div><div><div>Date &amp; Time Wed Jun 01, 2022 08:40:42 EDT Position 1632437.425 E / 3367437.13 N (a11.40) Altitude 2039ft (a11.40) Datum WGS-84 Azimuth/Bearing 121° S58E 2151mils True (a12°) Elevation Angle -18.3° Horizon Angle -40.9° Zoom 0.5X 11360+54 S-KL43</div><div></div></div></div>		<div><div><div>Date &amp; Time Wed Jun 01, 2022 08:47:37 EDT Position 1632437.425 E / 3367437.13 N (a11.40) Altitude 2039ft (a11.40) Datum WGS-84 Azimuth/Bearing 088° N68E 6082mils True (a10°) Elevation Angle -18.3° Horizon Angle -40.9° Zoom 0.5X 11353+67</div><div></div></div></div>			
<b>GPS Location</b>	11		<b>GPS Location</b>	12	
<b>Field Station#</b>	11360+54		<b>Field Station#</b>	11353+67	
<b>Pic 11 Desc.</b>	S-KL43.		<b>Pic 12 Desc.</b>	RCE Old Furnace.	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/1/2022 6:15 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38280
<b>Inspector</b>	Daniel Fortune			<b>Date/Time</b>	6/1/2022 3:29 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11353+47
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	81.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			








## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	6/1/2022 3:29 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11353+22		<b>Field Station#</b>	11346+00	
<b>Pic 1 Desc.</b>	S-NN11 Stream resource condition.		<b>Pic 2 Desc.</b>	Temporary stabilization	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11327+90		<b>Field Station#</b>	11313+59	
<b>Pic 3 Desc.</b>	S-NN12 Stream conditions		<b>Pic 4 Desc.</b>	Perimeter super silt fence and protected sump pit conditions.	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11293+66		<b>Field Station#</b>	11285+20	
<b>Pic 5 Desc.</b>	Over view of the S-MM18		<b>Pic 6 Desc.</b>	Side slope CC4 stabilization.	



<b>AFE</b>	124300137	<b>Date/Time</b>	6/1/2022 3:29 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11269+00	<b>Field Station#</b>	11265+00		
<b>Pic 7 Desc.</b>	Stone inlet protection and slope drain pipe conditions. All found functional.	<b>Pic 8 Desc.</b>	Continued temporary vegetation growth.		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>			
<b>Field Station#</b>	11256+80	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	Steep slope temporary stabilization and perimeter CFS end treatment controls.	<b>Pic 10 Desc.</b>			
					
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			



<b>A/E</b>	124300137	<b>Date/Time</b>	6/1/2022 3:29 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38266
<b>Inspector</b>	David Schoolcraft			<b>Date/Time</b>	6/1/2022 11:22 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11600+01
<b>County</b>	Craig	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	78.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00


1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Communication	See Comments / Punchlist		
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Communication	See Comments / Punchlist		
Silt Fence (Filter Fabric Fence)	Communication	See Comments / Punchlist		
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			







## 5. Site Conditions



Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/1/2022 11:22 AM	<b>Report #</b>	38266
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable				
Level Spreader	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with environmental team Performed VA SWPPP inspection from 11524+16 (MP 218.26) to 11600+01 (MP 219.70) Accompanied by fellow EI Eric Hanlon This section of ROW has no current construction. Deficiencies found: Access Road 258.02 is had Rilling and erosion. Do to rain event. 11552+00 Damaged P1 Silt fence Need repaired 11567+93 Stream S-PP22 Bridge waddles need replaced, P1 Silt fence no longer filters need replaced, and waddles on end treatment need cleaned off and replaced. 11576+00 P1 Silt Fence needed replaced no loner filtering. Water bars (other) All other perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. Stream buffers and controls in place at the time of inspection. No sensitive resources have been impacted					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	6/1/2022 11:22 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed Jun 01 2022 08:52:03 EDT Position: +037.339152° / +080.429538° (+11.91ft) Altitude: +2270ft (+9.8ft) Datum: WGS-84 Azimuth/Bearing: 046° N06E 0818mils True (+12°) Elevation Angle: +08.5° Horizon Angle: +00.4° Zoom: 0.5X 11524+16 258.02</p>		 <p>Date &amp; Time: Wed Jun 01 2022 08:52:03 EDT Position: +037.339152° / +080.429538° (+11.91ft) Altitude: +2270ft (+9.8ft) Datum: WGS-84 Azimuth/Bearing: 046° N06E 0818mils True (+12°) Elevation Angle: +08.5° Horizon Angle: +00.4° Zoom: 0.5X 11524+00</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11524+16	<b>Field Station#</b>	11526+00		
<b>Pic 1 Desc.</b>	Wrong station number on Photo Access 258.02 Rilling and erosion.	<b>Pic 2 Desc.</b>	Restoration and stabilization		
 <p>Date &amp; Time: Wed Jun 01 2022 09:05:56 EDT Position: +037.339152° / +080.429538° (+11.91ft) Altitude: +2270ft (+9.8ft) Datum: WGS-84 Azimuth/Bearing: 046° N06E 0818mils True (+12°) Elevation Angle: +08.5° Horizon Angle: +00.4° Zoom: 0.5X 11531+00</p>		 <p>Date &amp; Time: Wed Jun 01 2022 09:05:56 EDT Position: +037.339152° / +080.429538° (+11.91ft) Altitude: +2270ft (+9.8ft) Datum: WGS-84 Azimuth/Bearing: 046° N06E 0818mils True (+12°) Elevation Angle: +08.5° Horizon Angle: +00.4° Zoom: 0.5X 11539+00</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11531+00	<b>Field Station#</b>	11539+00		
<b>Pic 3 Desc.</b>	Level Spreader	<b>Pic 4 Desc.</b>	Perimeter Controls		
 <p>Date &amp; Time: Wed Jun 01 2022 09:16:31 EDT Position: +037.339152° / +080.429538° (+11.91ft) Altitude: +2270ft (+9.8ft) Datum: WGS-84 Azimuth/Bearing: 046° N06E 0818mils True (+12°) Elevation Angle: +08.5° Horizon Angle: +00.4° Zoom: 0.5X 11548+00</p>		 <p>Date &amp; Time: Wed Jun 01 2022 09:28:59 EDT Position: +037.339152° / +080.429538° (+11.91ft) Altitude: +2270ft (+9.8ft) Datum: WGS-84 Azimuth/Bearing: 027° N27E 0438mils True (+12°) Elevation Angle: +50.8° Horizon Angle: +40.7° Zoom: 0.5X 11552+00</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11548+00	<b>Field Station#</b>	11552+00		
<b>Pic 5 Desc.</b>	Section of ROW showing conditions and controls	<b>Pic 6 Desc.</b>	Damaged P1 Needs Replaced		



AFE	124300137	Date/Time	6/1/2022 11:22 AM	Report #	
Pictures					
<p><small>Date &amp; Time: Wed Jun 01 2022 10:54:29 EDT Position: -837.322590°W -080.414083°W (-837.32°W -080.41°W) Altitude: 2886ft (±210.0ft) Datum: WGS-84 Azimuth/Bearing: 023° N23E 1507mils True (±12°) Elevation Angle: +01.6° Horizon Angle: -00.5° Zoom: 1.0X 11562+50</small></p> 				<p><small>Date &amp; Time: Wed Jun 01 2022 10:43:27 EDT Position: -837.332420°W -080.413313°W (-837.33°W -080.41°W) Altitude: 2976ft (±135.0ft) Datum: WGS-84 Azimuth/Bearing: 040° N40E 1511mils True (±12°) Elevation Angle: +11.4° Horizon Angle: -00.5° Zoom: 1.0X 11553+75</small></p> 	
GPS Location	See photo	GPS Location	See Photo		
Field Station#	11562+50	Field Station#	11553+75		
Pic 7 Desc.	Sump Pit	Pic 8 Desc.	Water bars		
<p><small>Date &amp; Time: Wed Jun 01 2022 10:53:13 EDT Position: -837.311000°W -080.412990°W (-837.31°W -080.41°W) Altitude: 2958ft (±135.0ft) Datum: WGS-84 Azimuth/Bearing: 006° N06E 1150mils True (±12°) Elevation Angle: +16.3° Horizon Angle: -02.4° Zoom: 0.5X 11567+93</small></p> 				<p><small>Date &amp; Time: Wed Jun 01 2022 10:08:45 EDT Position: -837.311000°W -080.412990°W (-837.31°W -080.41°W) Altitude: 2958ft (±135.0ft) Datum: WGS-84 Azimuth/Bearing: 105° S75E 1367mils True (±12°) Elevation Angle: -00.1° Horizon Angle: +08.1° Zoom: 0.5X 11567+93</small></p> 	
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11567+93	Field Station#	11567+93		
Pic 9 Desc.	Waddles on bridge need replaced both sides S-PP22	Pic 10 Desc.	P1 Silt fence needs replaced and waddles for outlet protection need replaced. S-PP22		
<p><small>Date &amp; Time: Wed Jun 01 2022 10:15:16 EDT Position: -837.318701°W -080.409341°W (-837.32°W -080.41°W) Altitude: 2275ft (±133.0ft) Datum: WGS-84 Azimuth/Bearing: 088° N08E 1171mils True (±12°) Elevation Angle: -10.7° Horizon Angle: -02.7° Zoom: 0.5X 11578+50</small></p> 				<p><small>Date &amp; Time: Wed Jun 01 2022 10:23:47 EDT Position: -837.317710°W -080.409341°W (-837.32°W -080.41°W) Altitude: 2275ft (±133.0ft) Datum: WGS-84 Azimuth/Bearing: 089° N09E 0516mils True (±12°) Elevation Angle: -00.1° Horizon Angle: -00.4° Zoom: 0.5X 11585+00</small></p> 	
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11578+50	Field Station#	11585+00		
Pic 11 Desc.	Section of ROW showing conditions and controls	Pic 12 Desc.	Stream Overview S-PP21		

<b>AFE</b>	124300137	<b>Date/Time</b>	6/1/2022 11:22 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Wed Jun 01 2022 10:32:06 EDT Position: +037 316976 / -080 40848 (±11.6ft) Altitude: 2011ft (±210.0ft) Datum: WGS-84 Azimuth/Bearing: 098° S82E 1742mils (±1.53°) Elevation Angle: +04.6° Horizon Angle: -01.5° Zoom: 0.5X 11588+00</small></p>		 <p><small>Date &amp; Time: Wed Jun 01 2022 10:30:20 EDT Position: +037 313927 / -080 406387 (±11.6ft) Altitude: 1950ft (±19.7ft) Datum: WGS-84 Azimuth/Bearing: 258° S76W 4551mils True (±12.1°) Elevation Angle: +14.4° Horizon Angle: -07.3° Zoom: 0.5X 11600+01</small></p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11588+00	<b>Field Station#</b>	11600+01		
<b>Pic 13 Desc.</b>	Stream Over View S-PP20	<b>Pic 14 Desc.</b>	RCE		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>			





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38281
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	6/1/2022 4:46 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11471+56
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11524+16
<b>County</b>	Craig	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	81.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No





<b>AFE</b>	124300137	<b>Date/Time</b>	6/1/2022 4:46 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11473+00		<b>Field Station#</b>	11476+00	
<b>Pic 1 Desc.</b>	Triple barrier ECDs in place at off ROW karst area.		<b>Pic 2 Desc.</b>	Rock inlet protection in place at slope drain.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11482+00		<b>Field Station#</b>	11490+00	
<b>Pic 3 Desc.</b>	Waterbars in place. ROW temporarily stabilized with seed and mulch.		<b>Pic 4 Desc.</b>	RCE in place at Stevers Gap Road.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11504+00		<b>Field Station#</b>	11519+00	
<b>Pic 5 Desc.</b>	Rock lined channel in place.		<b>Pic 6 Desc.</b>	Sensitive resource buffer in place at stream S-PP4.	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/1/2022 4:46 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/1/2022 4:46 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38331
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	6/2/2022 1:22 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	6/2/2022 1:22 PM	<b>Report #</b>	38331
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>A regular scheduled VADEQ SWPPP inspection on JNF and private property was completed at Brush Mountain. The ROW remains stable with no areas of erosion discovered. Vegetation and/or mulch is currently adequate to prevent rilling or other form of sediment migration resulting in erosion. ECDs were found in place, functional and free of maintenance needs. No additional environmental controls are needed at this time. Slope breakers are functioning properly. Sumps and end treatments are in acceptable condition with no issues caused by concentrated runoff. Stream crossings are stable with no evidence of impact. Access roads and RCEs are in acceptable condition. No evidence of trespass or vandalism was discovered.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	6/2/2022 1:22 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11665+00	<b>Field Station#</b>	11660+00		
<b>Pic 1 Desc.</b>	Slope breakers functional. ROW surface stable.	<b>Pic 2 Desc.</b>	ECDs in place. ROW is currently stable.		
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11657+00	<b>Field Station#</b>	11634+00		
<b>Pic 3 Desc.</b>	No sediment collecting in sumps or migrating beyond limits.	<b>Pic 4 Desc.</b>	Perimeter ECDs are in place. ROW stable.		
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11626+04	<b>Field Station#</b>	11614+75		
<b>Pic 5 Desc.</b>	S-HH18 crossing is stable.	<b>Pic 6 Desc.</b>	ECDs are in place.		



<b>AFE</b>	124300137	<b>Date/Time</b>	6/2/2022 1:22 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11614+20	<b>Field Station#</b>	11607+81		
<b>Pic 7 Desc.</b>	The S-RR14 crossing is stable.	<b>Pic 8 Desc.</b>	The S-006 crossing is currently stable.		
		<div style="text-align: center;">Insert image here</div>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>			
<b>Field Station#</b>	11601+00	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	ROW currently stable.	<b>Pic 10 Desc.</b>			
<div style="text-align: center;">Insert image here</div>		<div style="text-align: center;">Insert image here</div>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	6/2/2022 1:22 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38341
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	6/2/2022 7:26 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11899+89
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	82.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Broad-Based Dip	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/2/2022 7:26 PM	<b>Report #</b>	38341
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from ST# 11788+52 (Mount Tabor Road) to ST# 11899+89 (AR 266.03) Accompanied by EI Trey Ingram on SWPPP inspection from MP 223.27 to MP 225.37. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. No environmental crew working in section at time of ROW. This section of ROW has undergone permanent restoration. Permanent waterbars (section 6 other) and level spreaders in place where designated on E&S sheets. Majority of perimeter controls have been removed due to final restoration vegetation growth. Sensitive resource buffers are in place at pond P-KL2. Mount Tabor road crossing RCE is maintained and in acceptable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/2/2022 7:26 PM	Report #			
Pictures							
<div><div><div>Date &amp; Time: Thu, Jun 02, 2022, 08:25:27 EDT Position: +037.249782° / -080.377881° (+5693.6ft) Altitude: 2247ft (+42.0ft) Datum: WGS-84 Azimuth/Bearing: 310° N55W 5510mils True (+12°) Elevation Angle: +82.2° Horizon Angle: +65.2° Zoom: 1.0X 11895+00</div></div></div>		<div><div><div>Date &amp; Time: Thu, Jun 02, 2022, 08:05:57 EDT Position: +037.259782° / -080.360636° (+23.1ft) Altitude: 2258ft (+43.0ft) Datum: WGS-84 Azimuth/Bearing: 330° N27W 5920mils True (+14°) Elevation Angle: +10.1° Horizon Angle: -00.3° Zoom: 1.0X 11830+00</div></div></div>					
	<b>GPS Location</b>		See photo for GPS location.	<b>GPS Location</b>	See photo for GPS location.		
	<b>Field Station#</b>		11895+00	<b>Field Station#</b>	11830+00		
<b>Pic 1 Desc.</b>	ROW permanently restored.	<b>Pic 2 Desc.</b>	ROW permanently restored. Waterbars with level spreaders in place.				
<div><div><div>Date &amp; Time: Thu, Jun 02, 2022, 09:04:26 EDT Position: +037.295989° / -080.360636° (+23.1ft) Altitude: 2215ft (+1.0ft) Datum: WGS-84 Azimuth/Bearing: 287° N73W 3100mils True (+15.1°) Elevation Angle: +04.0° Horizon Angle: +00.8° Zoom: 1.0X 11817+00</div></div></div>		<div><div><div>Date &amp; Time: Thu, Jun 02, 2022, 09:15:03 EDT Position: +037.295989° / -080.360636° (+23.1ft) Altitude: 2138ft (+33.2ft) Datum: WGS-84 Azimuth/Bearing: 266° S86W 4729mils True (+15°) Elevation Angle: -13.3° Horizon Angle: -01.6° Zoom: 1.0X 11789+00</div></div></div>					
	<b>GPS Location</b>		See photo for GPS location.	<b>GPS Location</b>	See photo for GPS location.		
	<b>Field Station#</b>		11817+00	<b>Field Station#</b>	11789+00		
<b>Pic 3 Desc.</b>	ROW permanently restored.	<b>Pic 4 Desc.</b>	RCE in place at Mount Tabor Road.				
<div><div><div>Date &amp; Time: Thu, Jun 02, 2022, 09:14:52 EDT Position: +037.259742° / -080.360341° (+5075.7ft) Altitude: 2233ft (+60.5ft) Datum: WGS-84 Azimuth/Bearing: 328° N32W 5831mils True (+15°) Elevation Angle: -21.7° Horizon Angle: +01.4° Zoom: 1.0X 11790+00</div></div></div>		<div><div><div>Date &amp; Time: Thu, Jun 02, 2022, 08:36:12 EDT Position: +037.259782° / -080.344223° (+15.6ft) Altitude: 2187ft (+11.9ft) Datum: WGS-84 Azimuth/Bearing: 010° N10E 6178mils True (+14°) Elevation Angle: -12.7° Horizon Angle: -00.4° Zoom: 1.0X 11864+00</div></div></div>					
	<b>GPS Location</b>		See photo for GPS location.	<b>GPS Location</b>	See photo for GPS location.		
	<b>Field Station#</b>		11790+00	<b>Field Station#</b>	11864+00		
<b>Pic 5 Desc.</b>	Super silt fence in place along LOD.	<b>Pic 6 Desc.</b>	Sensitive resource P-KL2.				

<b>A/E</b>	124300137	<b>Date/Time</b>	6/2/2022 7:26 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	6/2/2022 7:26 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38299
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	6/2/2022 6:56 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+52
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Stone Inlet Protection	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			






## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/2/2022 6:56 AM	<b>Report #</b>	38299
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 221.02 (11670+00) to MP 223.27 (11788+52). Accompanied by fellow EI Joe Sweeden. All perimeter controls, ECDs and BMPs functional at time of inspection. No impact to sensitive resources observed. Environmental crews actively applying soil amendments, seed and stabilization to partially denuded sections of RoW. Discussed RoW conditions and crew activities with LEI Brian's Shields, Fellow EI Joe Sweeden, Utility Inspector Joe Mossaro and PPL Environmental Foreman Jamie Grimes.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	6/2/2022 6:56 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Thu, Jun 02, 2022, 07:57:01 EDT Position: 144914.428 E / 353600.124 N (+12.31) Altitude: 261.4m (+15.4m) Datum: WGS-84 Azimuth/Bearing: 171° S95E 30.5mils True (+13°) Elevation Angle: -08.1° Horizon Angle: -02.5° Zoom: 0.5X #11669+00</p>		 <p>Date &amp; Time: Thu, Jun 02, 2022, 08:06:13 EDT Position: 144951.428 E / 357616.265 N (+15.5m) Altitude: 258.8m (+11.2m) Datum: WGS-84 Azimuth/Bearing: 337° N23W 59.9mils True (+13°) Elevation Angle: -05.4° Horizon Angle: -00.4° Zoom: 0.5X #11682+00</p>		<b>GPS Location</b>	1
<b>Field Station#</b>		1669+00	<b>GPS Location</b>	2	
<b>Pic 1 Desc.</b>		Section of RoW showing conditions and controls.	<b>Pic 2 Desc.</b>	Crews currently over seeding and establishing stabilization on partially denuded soils.	
 <p>Date &amp; Time: Thu, Jun 02, 2022, 08:13:11 EDT Position: 145124.417 E / 353600.402 N (+15.4m) Altitude: 243.6m (+11.2m) Datum: WGS-84 Azimuth/Bearing: 211° S31W 37.5mils True (+13°) Elevation Angle: -15.1° Horizon Angle: -09.8° Zoom: 0.5X #11687+00</p>		 <p>Date &amp; Time: Thu, Jun 02, 2022, 08:21:49 EDT Position: 145192.433 E / 354672.140 N (+15.5m) Altitude: 247.6m (+11.1m) Datum: WGS-84 Azimuth/Bearing: 294° N66W 52.7mils True (+12°) Elevation Angle: -02.3° Horizon Angle: -01.5° Zoom: 0.5X #11701+00</p>		<b>GPS Location</b>	3
<b>Field Station#</b>		11687+42	<b>GPS Location</b>	4	
<b>Pic 3 Desc.</b>		S-MN21.	<b>Pic 4 Desc.</b>	CFS perimeter controls functional.	
 <p>Date &amp; Time: Thu, Jun 02, 2022, 08:24:24 EDT Position: 145124.417 E / 353600.402 N (+15.4m) Altitude: 243.6m (+11.2m) Datum: WGS-84 Azimuth/Bearing: 004° N04E 01.07mils True (+12°) Elevation Angle: -14.9° Horizon Angle: -02.7° Zoom: 0.5X #11705+00</p>		 <p>Date &amp; Time: Thu, Jun 02, 2022, 08:28:07 EDT Position: 145133.401 E / 354183.133 N (+15.5m) Altitude: 239.5m (+11.2m) Datum: WGS-84 Azimuth/Bearing: 124° S34E 24.6mils True (+12°) Elevation Angle: -19.1° Horizon Angle: -01.3° Zoom: 0.5X #11710+00</p>		<b>GPS Location</b>	5
<b>Field Station#</b>		11705+10	<b>GPS Location</b>	6	
<b>Pic 5 Desc.</b>		S-MN22.	<b>Pic 6 Desc.</b>	Section of RoW showing conditions and controls.	



AFE	124300137	Date/Time	6/2/2022 6:56 AM	Report #	
Pictures					
 <p>Date &amp; Time: Thu, Jun 02, 2022, 08:40:54 EDT Position: 1453724.494 E / 355951.009 N (±15.5m) Altitude: 2223ft (±11.2m) Datum: WGS-84 Azimuth/Bearing: 014° N14E 0249mils True (±12°) Elevation Angle: -26.6° Horizon Angle: -03.2° Zoom: 0.5X 11734+00</p>			 <p>Date &amp; Time: Thu, Jun 02, 2022, 08:46:22 EDT Position: 1454231.355 E / 355852.097 N (±15.5m) Altitude: 2023ft (±11.2m) Datum: WGS-84 Azimuth/Bearing: 148° S32E 2631mils True (±12°) Elevation Angle: -18.9° Horizon Angle: -00.9° Zoom: 0.5X 11740+55 S-EF65</p>		
GPS Location	7	GPS Location	8		
Field Station#	11734+00	Field Station#	11740+55		
Pic 7 Desc.	Section of RoW showing conditions and controls.		Pic 8 Desc.	S-EF65.	
 <p>Date &amp; Time: Thu, Jun 02, 2022, 09:04:42 EDT Position: 1458811.296 E / 3501821.80 N (±15.5m) Altitude: 2203ft (±11.2m) Datum: WGS-84 Azimuth/Bearing: 084° N84E 1493mils True (±12°) Elevation Angle: -04.0° Horizon Angle: -00.7° Zoom: 0.5X 11756+00</p>			 <p>Date &amp; Time: Thu, Jun 02, 2022, 07:22:18 EDT Position: 1456779.072 E / 355974.262 N (±15.5m) Altitude: 2009ft (±11.2m) Datum: WGS-84 Azimuth/Bearing: 001° N01E 3018mils True (±12°) Elevation Angle: -15.7° Horizon Angle: +03.7° Zoom: 0.5X 11767+44 S-IJ52/W-IJ46</p>		
GPS Location	9	GPS Location	10		
Field Station#	11756+00	Field Station#	11767+44		
Pic 9 Desc.	Section of RoW showing conditions and controls.		Pic 10 Desc.	S-IJ52/W-IJ46.	
 <p>Date &amp; Time: Thu, Jun 02, 2022, 07:10:18 EDT Position: 1458720.772 E / 355882.498 N (±15.5m) Altitude: 2120ft (±11.4m) Datum: WGS-84 Azimuth/Bearing: 330° N80W 5567mils True (±12°) Elevation Angle: -01.6° Horizon Angle: -00.7° Zoom: 0.5X 11788+52</p>			Insert image here		
GPS Location	11	GPS Location			
Field Station#	11788+52	Field Station#			
Pic 11 Desc.	RCE off Mt Tabor rd.		Pic 12 Desc.		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/2/2022 6:56 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38336
<b>Inspector</b>	Daniel Fortune			<b>Date/Time</b>	6/2/2022 4:47 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11889+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	77.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Waterbar	Acceptable			
Compost Filter Sock	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No


<b>A/E</b>	124300137	<b>Date/Time</b>	6/2/2022 4:47 PM	<b>Report #</b>	38336
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>See photos for GPS coordinates.</p> <p>Completed a VA SWPPP inspection from MP 225.37 (11899+89) and MP 227.37 (12005+00). There had been light rain fall accumulation of .04 in the last 24 hours. More rain is expected throughout the afternoon into the early morning hours of 5/24/22. The row is well vegetated and no erosion issues at this time.</p> <p>No Deficiencies documented for repairs today.</p> <p>This section of row has been finally restored with heavy vegetation. Perennial and annual grasses are visible at this time. There are herbaceous vegetation that continue to grow from the permanent water bars. Permanent water bars have been installed and appear to be functioning as intended. (Other in section 6 above).</p> <p>Level Spreaders are functional</p> <p>Precision Crews: No crews observed on site.</p> <p>All other perimeter controls, ECDs and BMPs are weathered but appear to be functional at time of inspection. Vegetation is abundant and sufficient. At this time.</p> <p>No impact to sensitive resources observed. Assessed Ar 266.03. No issues</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	6/2/2022 4:47 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11929+18	<b>Field Station#</b>	11973+00		
<b>Pic 1 Desc.</b>	AR 266.02 conditions.	<b>Pic 2 Desc.</b>	Heavily vegetated final restoration area.		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11973+35	<b>Field Station#</b>	11978+86		
<b>Pic 3 Desc.</b>	Vegetated water bar conditions.	<b>Pic 4 Desc.</b>	Perimeter controls protecting the off LOD karst area.		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11990+22	<b>Field Station#</b>	12000+00		
<b>Pic 5 Desc.</b>	Final restoration area	<b>Pic 6 Desc.</b>	Final restoration area.		



AFE 124300137		Date/Time	6/2/2022 4:47 PM	Report #	
Pictures					
<p>Date &amp; Time: Thu, Jun 02, 2022, 10:32:33 EDT  Position: +037.269510° / -080.314115° (-122.8ft)  Altitude: 1579ft (+26.2ft)  Datum: WGS-84  Azimuth/Bearing: 229° S47W 4071mils True (+2°)  Elevation Grade: +002%  Horizon Grade: +003%  Zoom: 4.0X  12005+00</p> 		<p>Date &amp; Time: Thu, Jun 02, 2022, 10:06:10 EDT  Position: +037.267775° / -080.334375° (-19.6ft)  Altitude: 2257ft (+11.0ft)  Datum: WGS-84  Azimuth/Bearing: 103° S77E 1831mils True (+2°)  Elevation Grade: +002%  Horizon Grade: +002%  Zoom: 0.5X  11900+81</p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		12005+00		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		Spread break area. Temporary stabilization of row conditions.		<b>Pic 8 Desc.</b>	
<p>Date &amp; Time: Thu, Jun 02, 2022, 10:06:44 EDT  Position: +037.267898° / -080.334261° (-15.6ft)  Altitude: 2246ft (+10.9ft)  Datum: WGS-84  Azimuth/Bearing: 026° N26E 0462mils True (+12°)  Elevation Grade: +018%  Horizon Grade: +003%  Zoom: 0.5X  11900+81</p> 		<p>Date &amp; Time: Thu, Jun 02, 2022, 10:08:11 EDT  Position: +037.267338° / -080.333173° (-15.6ft)  Altitude: 2300ft (+10.0ft)  Datum: WGS-84  Azimuth/Bearing: 107° S08E 3093mils True (+2°)  Elevation Grade: +023%  Horizon Grade: +002%  Zoom: 0.5X  11906+21</p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11900+81		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		Heavily vegetated row and permanent level spreader conditions		<b>Pic 10 Desc.</b>	
<p>Date &amp; Time: Thu, Jun 02, 2022, 10:09:49 EDT  Position: +037.287083° / -080.332765° (-35.4ft)  Altitude: 2306ft (+39.4ft)  Datum: WGS-84  Azimuth/Bearing: 363° N17W 6098mils True (+12°)  Elevation Grade: +014%  Horizon Grade: +001%  Zoom: 0.5X  11910+00</p> 		<p>Date &amp; Time: Thu, Jun 02, 2022, 10:10:09 EDT  Position: +037.286667° / -080.336667° (-88.8ft)  Altitude: 2367ft (+55.4ft)  Datum: WGS-84  Azimuth/Bearing: 161° S35E 3066mils True (+12°)  Elevation Grade: +003%  Horizon Grade: +001%  Zoom: 4.0X  11921+00</p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11910+00		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		Final Restoration area.		<b>Pic 12 Desc.</b>	
				Final restoration conditions	

<b>AFE</b>	124300137	<b>Date/Time</b>	6/2/2022 4:47 PM	<b>Report #</b>	
<b>Pictures</b>					
			<p>Insert image here</p>		
<b>GPS Location</b>	See photo	<b>GPS Location</b>			
<b>Field Station#</b>	11913+00	<b>Field Station#</b>			
<b>Pic 13 Desc.</b>	Permanent level spreader and vegetated row conditions. No issues at this time.	<b>Pic 14 Desc.</b>			
<p>Insert image here</p>		<p>Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>			
<p>Insert image here</p>		<p>Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>			



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38301
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	6/2/2022 7:16 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	70.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

## 5. Site Conditions







Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	6/2/2022 7:16 AM	<b>Report #</b>	38301
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Completed a VA SWPPP at LY 029. The perimeter controls consist of 18" triple stacked CFS in place and functioning as designed. The RCE was clean, no mud or other debris on road. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified.</p> <p>Completed a VA SWPPP at LY 028. The perimeter controls CFS in place and functioning as designed. The RCE was clean, no mud or other debris on road. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified.</p> <p>Completed a VA SWPPP at LY 026. The perimeter controls CFS functioning as designed. The RCE was clean, no mud or other debris on road. The yard was free of debris. Used oils were stored properly in secondary containment. The generator and air compressor were in secondary containment that was maintained properly. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified. Construction of a neighboring company started which affects our parking lot / Will monitor progress.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	6/2/2022 7:16 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu Jun 02, 2022, 08:56:13 EDT  Position: +037.334304° / -080.803225° (-11.4ft)  Altitude: 1524ft (-11.4ft)  Datum: WGS-84  Azimuth/Bearing: 313° N47°W, 565mils true (-10°)  Elevation Angle: -17.6°  Horizon Angle: -01.9°  Zoom: 1.0X  Y28</p> 		<p>Date &amp; Time: Thu Jun 02, 2022, 08:56:48 EDT  Position: +037.334349° / -080.803057° (-11.7ft)  Altitude: 1530ft (-11.7ft)  Datum: WGS-84  Azimuth/Bearing: 173° S06°E, 400mils true (-10°)  Elevation Angle: -01.8°  Horizon Angle: -00.7°  Zoom: 1.0X  Y28</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	CFS perimeter controls functional y28	<b>Pic 2 Desc.</b>	Housekeeping trash in good condition y28		
<p>Date &amp; Time: Thu Jun 02, 2022, 08:53:28 EDT  Position: +037.334273° / -080.802619° (-11.1ft)  Altitude: 1520ft (-11.1ft)  Datum: WGS-84  Azimuth/Bearing: 205° S25°W, 364mils true (-10°)  Elevation Angle: -01.5°  Horizon Angle: -00.2°  Zoom: 2.0X  Y28</p> 		<p>Date &amp; Time: Thu Jun 02, 2022, 08:46:47 EDT  Position: +037.332927° / -080.808757° (-11.7ft)  Altitude: 1530ft (-11.7ft)  Datum: WGS-84  Azimuth/Bearing: 003° N03°E, 393mils true (-10°)  Elevation Angle: -00.2°  Horizon Angle: -00.6°  Zoom: 1.0X  Y28</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	CFS perimeter controls functional y28 Permanent stabilization in place	<b>Pic 4 Desc.</b>	RCE functional y28		
<p>Date &amp; Time: Thu Jun 02, 2022, 08:57:45 EDT  Position: +037.334361° / -080.803041° (-11.4ft)  Altitude: 1520ft (-11.4ft)  Datum: WGS-84  Azimuth/Bearing: 318° N42°W, 565mils true (-10°)  Elevation Angle: -19.1°  Horizon Angle: -05.1°  Zoom: 1.0X  Y28</p> 		<p>Date &amp; Time: Thu Jun 02, 2022, 08:58:05 EDT  Position: +037.334464° / -080.803057° (-11.4ft)  Altitude: 1520ft (-11.4ft)  Datum: WGS-84  Azimuth/Bearing: 168° S12°E, 298mils true (-10°)  Elevation Angle: -4.3°  Horizon Angle: -00.0°  Zoom: 1.0X  Y28</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 5 Desc.</b>	CFS perimeter controls in place y28	<b>Pic 6 Desc.</b>	CFS perimeter controls in place y28		



AFE 124300137		Date/Time	6/2/2022 7:16 AM	Report #	
Pictures					
<p>Date &amp; Time: Thu, Jun 02, 2022, 08:26:49 EDT  Position: +037.318599 / -080.658031 / ±15.5ft  Altitude: 1809ft (±11.0ft)  Datum: WGS 84  Azimuth/Bearing: 200° S22W 400mils True (±10°)  Elevation Angle: +01.2°  Horizon Angle: +02.0°  Zoom: 1.0X  Y26</p> 		<p>Date &amp; Time: Thu, Jun 02, 2022, 08:26:19 EDT  Position: +037.318544 / -080.657725 / ±15.5ft  Altitude: 1803ft (±11.2ft)  Datum: WGS 84  Azimuth/Bearing: 263° S43W 4320mils True (±10°)  Elevation Angle: +04.9°  Horizon Angle: +03.7°  Zoom: 1.0X  Y26</p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		12005+00		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		Crew working on parking lot y26		<b>Pic 8 Desc.</b>	
<p>Date &amp; Time: Thu, Jun 02, 2022, 08:25:49 EDT  Position: +037.318702 / -080.657174 / ±15.5ft  Altitude: 1808ft (±11.2ft)  Datum: WGS 84  Azimuth/Bearing: 251° S71W 668mils True (±10°)  Elevation Angle: +00.3°  Horizon Angle: +01.8°  Zoom: 2.0X  Y26</p> 		<p>Date &amp; Time: Thu, Jun 02, 2022, 08:26:19 EDT  Position: +037.318327 / -080.656377 / ±15.4ft  Altitude: 1801ft (±11.3ft)  Datum: WGS 84  Azimuth/Bearing: 202° S22W 392mils True (±10°)  Elevation Angle: +02.6°  Horizon Angle: +01.1°  Zoom: 2.0X  Y26</p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		12005+00		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		Secondary containment in place y26		<b>Pic 10 Desc.</b>	
<p>Date &amp; Time: Thu, Jun 02, 2022, 08:25:02 EDT  Position: +037.318738 / -080.656255 / ±15.5ft  Altitude: 1815ft (±11.1ft)  Datum: WGS 84  Azimuth/Bearing: 301° N59W 5351mils True (±10°)  Elevation Angle: +07.0°  Horizon Angle: +04.3°  Zoom: 1.0X  Y26</p> 		<p>Date &amp; Time: Thu, Jun 02, 2022, 08:26:19 EDT  Position: +037.318599 / -080.655399 / ±15.1ft  Altitude: 1810ft (±11.7ft)  Datum: WGS 84  Azimuth/Bearing: 175° S33E 3111mils True (±10°)  Elevation Angle: +02.4°  Horizon Angle: +01.1°  Zoom: 1.0X  Y26</p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		12005+00		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		RCE functional y26		<b>Pic 12 Desc.</b>	
				CFS perimeter controls functional y26	



<b>AFE</b>	124300137	<b>Date/Time</b>	6/2/2022 7:16 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu, Jun 02, 2022, 08:14:49 EDT  Position: +037.346994° / -080.676939° (-23.3h)  Altitude: 1686ft (-39.4h)  Datum: WGS-84  Azimuth Bearing: 332° N28W 5902mils True (±10°)  Elevation Angle: -03°  Horizon Angle: -00.7°  Zoom: 2.0X  Y29</p> 		<p>Date &amp; Time: Thu, Jun 02, 2022, 08:15:49 EDT  Position: +037.346994° / -080.676939° (-23.3h)  Altitude: 1700ft (-39.4h)  Datum: WGS-84  Azimuth Bearing: 266° S84W 4893mils True (±10°)  Elevation Angle: 2.1h  Horizon Angle: -00.7°  Zoom: 2.0X  Y29</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 13 Desc.</b>	RCE functional y29	<b>Pic 14 Desc.</b>	Broad base dips functional y29		
<p>Date &amp; Time: Thu, Jun 02, 2022, 08:11:37 EDT  Position: +037.346230° / -080.677319° (-23.3h)  Altitude: 1729ft (-39.4h)  Datum: WGS-84  Azimuth Bearing: 171° S50E 3040mils True (±10°)  Elevation Angle: -02.7°  Horizon Angle: -05.0°  Zoom: 2.0X  Y29</p> 		<p>Date &amp; Time: Thu, Jun 02, 2022, 08:16:49 EDT  Position: +037.346230° / -080.677319° (-23.3h)  Altitude: 1731ft (-39.4h)  Datum: WGS-84  Azimuth Bearing: 337° N23W 5991mils True (±10°)  Elevation Angle: -02.1°  Horizon Angle: -00.8°  Zoom: 2.0X  Y29</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 15 Desc.</b>	Culvert functional y29	<b>Pic 16 Desc.</b>	Housekeeping trash in good condition y29		
<p>Date &amp; Time: Thu, Jun 02, 2022, 08:10:21 EDT  Position: +037.346110° / -080.676999° (-23.3h)  Altitude: 1728ft (-39.4h)  Datum: WGS-84  Azimuth Bearing: 307° N35W 5307mils True (±10°)  Elevation Angle: -01.8°  Horizon Angle: -00.3°  Zoom: 1.0X  Y29</p> 		<p>Date &amp; Time: Thu, Jun 02, 2022, 08:09:20 EDT  Position: +037.346195° / -080.677133° (-23.3h)  Altitude: 1718ft (-39.4h)  Datum: WGS-84  Azimuth Bearing: 284° S84W 4893mils True (±10°)  Elevation Angle: -04.1°  Horizon Angle: -00.3°  Zoom: 1.0X  Y29</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 17 Desc.</b>	Permanent stabilization in place y29	<b>Pic 18 Desc.</b>	CFS perimeter controls functional y29		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38389
<b>Inspector</b>	Daniel Fortune			<b>Date/Time</b>	6/3/2022 1:52 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10859+46
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+80
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	72.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.70
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			







<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	6/3/2022 1:52 PM	<b>Report #</b>	38389
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. - ALL STATION NUMBERS ARE APPROXIMATE - Completed a VA SWPPP inspection from MP 205.67 (10859+46) to MP 207.0 (10929+80). No Deficiencies documented for repairs today. Other deficiencies may be found and documented my other EI's and or contractor staff. Observations today - Envionmental crews (1702 and 1706) were on site between 10923+00 to 10926+45 installing ECB and straw mulching. This section of row remains adequately stabilized at the time of inspection. Temporary vegetation is visible throughout. Some areas heavier than others. The recent soil sluffing from spoil pile near 10888+50 has been repaired with proper grading, temporary seedin g, and additional ECB. The temporary water bars appear to be functioning as intended. Sump pits, water bar end treatments, and temporary slope drain pipes also appear to be functioning as intended with no maintenance required at this time. All other perimeter controls, ECDs and BMPs functional at time of inspection. There are three (3) stream resources within this section of row inspected. No impacts at this time of inspection. S-Y2...10929+43 (Doe Creek Rd)- No impact to stream. Buffer zones are undisturbed and vegetated. Equipment bridge clean and functional. S-Y3...10927+77 (Doe Creek Rd)- No impact to stream. Buffer zones are undisturbed and vegetated. Equipment bridge clean and functional. S-A32...10929+43 (Doe Creek Rd)- No impact to stream. Buffer zones are undisturbed and vegetated. Equipment bridge clean and functional.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	6/3/2022 1:52 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10859+47	<b>Field Station#</b>	10861+00		
<b>Pic 1 Desc.</b>	RCE conditions	<b>Pic 2 Desc.</b>	Temporary vegetation through the travel lane.		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10868+00	<b>Field Station#</b>	10880+00		
<b>Pic 3 Desc.</b>	Temporary stabilization of row	<b>Pic 4 Desc.</b>	Steep slope stabilization and current water bar conditions.		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10881+20	<b>Field Station#</b>	10883+10		
<b>Pic 5 Desc.</b>	Temporary vegetated water bar conditions.	<b>Pic 6 Desc.</b>	S-A32 Stream conditions.		



<b>AFE</b>	124300137	<b>Date/Time</b>	6/3/2022 1:52 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri, Jun 03, 2022, 10:06:03 EDT Position: +037.3347077° / -080.593332° (+48.7ft) Altitude: 2337ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 231° S51W 4107mils True (+13°) Elevation Grade: -071° Horizon Grade: -005° Zoom: 0.5X 10883+10 S-A2</p>		 <p>Date &amp; Time: Fri, Jun 03, 2022, 10:06:03 EDT Position: +037.3347077° / -080.593332° (+48.7ft) Altitude: 2337ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 191° S40E 3058mils True (+13°) Elevation Grade: -020° Horizon Grade: -015° Zoom: 0.5X 10886+00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10883+10	<b>Field Station#</b>	10886+00		
<b>Pic 7 Desc.</b>	S-A 32 equipment bridge crossing conditions.	<b>Pic 8 Desc.</b>	Perimeter P1 silt fence conditions.		
 <p>Date &amp; Time: Fri, Jun 03, 2022, 10:06:03 EDT Position: +037.3347077° / -080.593332° (+48.7ft) Altitude: 2337ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 231° S51W 4107mils True (+13°) Elevation Grade: -071° Horizon Grade: -005° Zoom: 0.5X 10887+96</p>		 <p>Date &amp; Time: Fri, Jun 03, 2022, 10:06:28 EDT Position: +037.3344444° / -080.595308° (+48.7ft) Altitude: 2270ft (+23.1ft) Datum: WGS-84 Azimuth/Bearing: 192° S08E 3058mils True (+13°) Elevation Grade: -020° Horizon Grade: -015° Zoom: 0.5X 10887+96</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10887+96	<b>Field Station#</b>	10887+96		
<b>Pic 9 Desc.</b>	Plunge pool conditions.	<b>Pic 10 Desc.</b>	Perimeter CFS and temporary end treatment conditions.		
 <p>Date &amp; Time: Fri, Jun 03, 2022, 10:06:03 EDT Position: +037.3344444° / -080.594793° (+48.7ft) Altitude: 2337ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 159° N58E 5280mils True (+13°) Elevation Grade: +000° Horizon Grade: +001° Zoom: 1.0X 10889+88</p>		 <p>Date &amp; Time: Fri, Jun 03, 2022, 10:10:46 EDT Position: +037.3344444° / -080.594793° (+48.7ft) Altitude: 2337ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 227° N63W 5280mils True (+13°) Elevation Grade: +004° Horizon Grade: +001° Zoom: 1.0X 10889+88</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10889+88	<b>Field Station#</b>	10889+88		
<b>Pic 11 Desc.</b>	Repaired sediment stuff area. Stabilization remains adequate at this time.	<b>Pic 12 Desc.</b>	Temporary stabilization of row and water bar conditions.		



<b>AFE</b> 124300137		<b>Date/Time</b> 6/3/2022 1:52 PM		<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	10924+30		<b>Field Station#</b>	10927+00	
<b>Pic 13 Desc.</b>	Additional added ECB to steep slope.		<b>Pic 14 Desc.</b>	S-Y3 vegetated stream buffer zones.	
			Insert image here		
<b>GPS Location</b>	See photo		<b>GPS Location</b>		
<b>Field Station#</b>	10929+70		<b>Field Station#</b>		
<b>Pic 15 Desc.</b>	S-Y2 Stream conditions. No Issues at this time.		<b>Pic 16 Desc.</b>		
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 17 Desc.</b>			<b>Pic 18 Desc.</b>		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38399
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	6/3/2022 6:06 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10749+92
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10798+92
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	78.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.90
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	6/3/2022 6:06 PM	<b>Report #</b>	38399
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from ST# 10747+92 (Hendrickson Road) to ST# 10798+92 (Cascade Road) Accompanied by EI Trey Ingram on SWPPP inspection from MP 204.53 to MP 205.67. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed environmental maintenance crews walking through section checking ECDs. This section of ROW is temporarily stabilized with seed and mulch. Vegetation growth is present throughout section. Clean water diversion berms, pipes and level spreaders are in place. ECDs in place per E&S sheets. Sensitive resource buffers are in place at streams S-G35, S-SS4, S-Z9, S-Z7 braid 1, and S-Z7 braid 2. Hendrickson Road, Big Branch Hollow Road, and Cascade Road crossings RCEs are maintained and in acceptable condition. No sensitive resources have been impacted. Checked rain gauges at Catawba Road - 0.25 inches and Mount Tabor Road - 0.6 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	6/3/2022 6:06 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri Jun 03 2022 09:28:21 EDT Position: +037.342342 / -080.628107 (+6097.6ft) Altitude: 2290ft (+657m) Datum: WGS-84 Azimuth/Bearing: 078° N78E 1387mils True (+16°) Elevation Angle: -28.8° Horizon Angle: -00.4° Zoom: 1.0X 10753+00</p>		 <p>Date &amp; Time: Fri Jun 03 2022 09:33:34 EDT Position: +037.344659 / -080.622527 (+19640.1ft) Altitude: 2270ft (+691m) Datum: WGS-84 Azimuth/Bearing: 065° N65E 1156mils True (+18°) Elevation Angle: -16.0° Horizon Angle: -04.2° Zoom: 1.0X 10758+50 S-G35</p>		<b>GPS Location</b>	See photo for GPS location.
<b>Field Station#</b>	10753+00	<b>Field Station#</b>	10758+50	<b>GPS Location</b>	See photo for GPS location.
<b>Pic 1 Desc.</b>	Waterbars in place. ROW temporarily stabilized.	<b>Pic 2 Desc.</b>	Sensitive resource buffer in place at stream S-G35.	<b>GPS Location</b>	See photo for GPS location.
 <p>Date &amp; Time: Fri Jun 03 2022 09:37:57 EDT Position: +037.338959 / -080.624772 (+7050.9ft) Altitude: 2095ft (+639m) Datum: WGS-84 Azimuth/Bearing: 076° S06E 3092mils True (+15°) Elevation Angle: -28.4° Horizon Angle: -00.2° Zoom: 1.0X 10762+00</p>		 <p>Date &amp; Time: Fri Jun 03 2022 09:40:26 EDT Position: +037.342861 / -080.623222 (+2825.4ft) Altitude: 2172ft (+662m) Datum: WGS-84 Azimuth/Bearing: 186° S14E 2931mils True (+15°) Elevation Angle: -23.0° Horizon Angle: -02.8° Zoom: 1.0X 10766+00</p>		<b>GPS Location</b>	See photo for GPS location.
<b>Field Station#</b>	10762+00	<b>Field Station#</b>	10766+00	<b>GPS Location</b>	See photo for GPS location.
<b>Pic 3 Desc.</b>	Rock inlet protection in place at slope drain inlet.	<b>Pic 4 Desc.</b>	Clean water diversion pipe and level spreader in place.	<b>GPS Location</b>	See photo for GPS location.
 <p>Date &amp; Time: Fri Jun 03 2022 09:53:38 EDT Position: +037.343316 / -080.624235 (+115.8ft) Altitude: 2090ft (+637m) Datum: WGS-84 Azimuth/Bearing: 066° S56E 2204mils True (+13°) Elevation Angle: -34.2° Horizon Angle: -01.0° Zoom: 1.0X 10789+00</p>		 <p>Date &amp; Time: Fri Jun 03 2022 09:56:00 EDT Position: +037.343316 / -080.624235 (+115.8ft) Altitude: 2090ft (+637m) Datum: WGS-84 Azimuth/Bearing: 066° S56E 2204mils True (+13°) Elevation Angle: -34.2° Horizon Angle: -01.0° Zoom: 1.0X 10793+00</p>		<b>GPS Location</b>	See photo for GPS location.
<b>Field Station#</b>	10789+00	<b>Field Station#</b>	10793+00	<b>GPS Location</b>	See photo for GPS location.
<b>Pic 5 Desc.</b>	Topsoil pile repaired where sloughing occurred. Stabilized with seed, mulch/ECB.	<b>Pic 6 Desc.</b>	ROW temporarily stabilized.	<b>GPS Location</b>	See photo for GPS location.



<b>A/E</b>	124300137	<b>Date/Time</b>	6/3/2022 6:06 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/3/2022 6:06 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38397
<b>Inspector</b>	David Schoolcraft			<b>Date/Time</b>	6/3/2022 4:51 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10655+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10749+92
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.50
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	6/3/2022 4:51 PM	<b>Report #</b>	38397
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with environmental team Preformed VA SWPPP inspection from 10655+00 (MP 201.6) to 10749+92 (MP 203.6) Accompanied by fellow EI Eric Hanlon This section of ROW has no current construction. No deficiencies found. All perimeter controls, ECDs and BMPs functional at time of inspection. Stream buffers and controls in place at the time of inspection. No sensitive resources have been impacted					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	6/3/2022 4:51 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Fri, Jun 03, 2022, 07:48:01 EDT  Position: +027.314665° / +080.63677° (+1021.14)  Altitude: 2263ft (+68.37)  Datum: WGS-84  Azimuth/Bearing: 082° N02E 10746mils True (+10°)  Elevation Angle: -00.3°  Horizon Angle: -00.3°  Zoom: 0.5X  10656+46</p> 		<p>Date &amp; Time: Fri, Jun 03, 2022, 07:48:01 EDT  Position: +027.314665° / +080.63677° (+1021.14)  Altitude: 2263ft (+68.37)  Datum: WGS-84  Azimuth/Bearing: 082° N02E 10746mils True (+10°)  Elevation Angle: -00.3°  Horizon Angle: -00.3°  Zoom: 0.5X  10660+00</p> 			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	10656+46	<b>Field Station#</b>	10660+00		
<b>Pic 1 Desc.</b>	Stabilization	<b>Pic 2 Desc.</b>	Perimeter controls		
<p>Date &amp; Time: Fri, Jun 03, 2022, 05:00:00 EDT  Position: +027.314665° / +080.63677° (+1021.14)  Altitude: 2339ft (+71.03)  Datum: WGS-84  Azimuth/Bearing: 272° N02W 4926mils True (+12°)  Elevation Angle: -01.5°  Horizon Angle: -06.5°  Zoom: 0.5X  10668+00</p> 		<p>Date &amp; Time: Fri, Jun 03, 2022, 05:00:00 EDT  Position: +027.314665° / +080.63677° (+1021.14)  Altitude: 2339ft (+71.03)  Datum: WGS-84  Azimuth/Bearing: 272° N02W 4926mils True (+12°)  Elevation Angle: -01.5°  Horizon Angle: -06.5°  Zoom: 1.0X  10737+00</p> 			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	10668+00	<b>Field Station#</b>	10737+00		
<b>Pic 3 Desc.</b>	Outlet protection	<b>Pic 4 Desc.</b>	Waterbars		
<p>Date &amp; Time: Fri, Jun 03, 2022, 08:22:47 EDT  Position: +027.314665° / +080.641629° (+1040.21)  Altitude: 2263ft (+68.37)  Datum: WGS-84  Azimuth/Bearing: 104° S74E 1884mils True (+12°)  Elevation Angle: -13.3°  Horizon Angle: -100.9°  Zoom: 0.5X  10733+18</p> 		<p>Date &amp; Time: Fri, Jun 03, 2022, 07:48:01 EDT  Position: +027.314665° / +080.63677° (+1021.14)  Altitude: 2263ft (+68.37)  Datum: WGS-84  Azimuth/Bearing: 139° S46E 2636mils True (+14°)  Elevation Angle: -01.6°  Horizon Angle: -00.2°  Zoom: 1.0X  10749+00</p> 			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10733+18	<b>Field Station#</b>	10749+00		
<b>Pic 5 Desc.</b>	Equipment Bridge	<b>Pic 6 Desc.</b>	RCE		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/3/2022 4:51 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	6/3/2022 4:51 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	38356
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	6/3/2022 7:27 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10798+92
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10859+46
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	72.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.90
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	6/3/2022 7:27 AM	<b>Report #</b>	38356
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Discussed RoW/ECD conditions, within this section, with fellow EI Joe Sweeden. Performed SWPPP inspection from MP 204.53 (10798+92) and MP 205.67 (10859+46). Accompanied by fellow EI Joe Sweeden. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE	124300137	Date/Time	6/3/2022 7:27 AM	Report #	
Pictures					
 <p>Date &amp; Time: Fri, Jun 03, 2022, 08:05:40 EDT Position: 138810.881 E / 372667.535 N (+11.40) Altitude: 2302ft (+530) Datum: WGS-84 Azimuth/Bearing: 338° 59' 10" N 61° 01' 00" W Elevation Angle: -12.7° Horizon Angle: +01.7° Zoom: 0.5X 10859+46</p>		 <p>Date &amp; Time: Fri, Jun 03, 2022, 08:10:07 EDT Position: 138788.067 E / 372664.292 N (+11.70) Altitude: 2188ft (+78.70) Datum: WGS-84 Azimuth/Bearing: 056° 14' 56" E 83° 45' 04" W Elevation Angle: -12.7° Horizon Angle: +01.7° Zoom: 0.5X 10856+04</p>			
GPS Location	1	GPS Location	2		
Field Station#	10859+46	Field Station#	10856+04		
Pic 1 Desc.	Section of RoW showing conditions and controls.	Pic 2 Desc.	S-A33.		
 <p>Date &amp; Time: Fri, Jun 03, 2022, 08:00:01 EDT Position: 138770.124 E / 372647.453 N (+11.40) Altitude: 2320ft (+530) Datum: WGS-84 Azimuth/Bearing: 348° 11' 24" W 61° 07' 12" E Elevation Angle: -04.7° Horizon Angle: -01.5° Zoom: 0.5X 10854+70 S-A34</p>		 <p>Date &amp; Time: Fri, Jun 03, 2022, 08:16:55 EDT Position: 138391.880 E / 373006.996 N (+11.40) Altitude: 2207ft (+530) Datum: WGS-84 Azimuth/Bearing: 131° 30' 10" W 52° 30' 10" E Elevation Angle: -24.7° Horizon Angle: -01.5° Zoom: 0.5X 10843+00</p>			
GPS Location	3	GPS Location	4		
Field Station#	10854+70	Field Station#	10843+00		
Pic 3 Desc.	S-A34.	Pic 4 Desc.	CWDP outlet protection functional.		
 <p>Date &amp; Time: Fri, Jun 03, 2022, 09:16:18 EDT Position: 138247.033 E / 373476.533 N (+10.50) Altitude: 2610ft (+78.70) Datum: WGS-84 Azimuth/Bearing: 163° 51' 12" E 233° 31' 12" W Elevation Angle: -15.5° Horizon Angle: +00.6° Zoom: 0.5X 10839+00</p>		 <p>Date &amp; Time: Fri, Jun 03, 2022, 09:20:54 EDT Position: 138285.333 E / 373770.437 N (+10.50) Altitude: 2636ft (+78.70) Datum: WGS-84 Azimuth/Bearing: 230° 57' 00" W 44° 44' 00" E Elevation Angle: -09.0° Horizon Angle: +01.0° Zoom: 0.5X 10835+00</p>			
GPS Location	5	GPS Location	6		
Field Station#	10839+00	Field Station#	10835+00		
Pic 5 Desc.	Section of RoW showing conditions and controls.	Pic 6 Desc.	Section of RoW showing conditions and controls.		



<b>AFE</b>	124300137	<b>Date/Time</b>	6/3/2022 7:27 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	7	<b>GPS Location</b>	8		
<b>Field Station#</b>	10818+00	<b>Field Station#</b>	10809+04		
<b>Pic 7 Desc.</b>	Section of RoW showing conditions and controls.	<b>Pic 8 Desc.</b>	S-Z14.		
<b>GPS Location</b>	9	<b>GPS Location</b>	10		
<b>Field Station#</b>	10804+00	<b>Field Station#</b>	10801+52		
<b>Pic 9 Desc.</b>	Section of RoW showing conditions and controls.	<b>Pic 10 Desc.</b>	S-Z11/S-Z12/S-Z13.		
		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>	11	<b>GPS Location</b>			
<b>Field Station#</b>	10799+00	<b>Field Station#</b>			
<b>Pic 11 Desc.</b>	S-Z10/W-Z3.	<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	6/3/2022 7:27 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		