



Visual Site Inspection Report

Project Name	H-602 Pipeline Spread I	AFE	124300139	Spread	H-602 Pipeline Spread I	
Contractor	Precision			Report #	38944	
Inspector	John White			Date/Time	6/20/2022 12:50 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	19+25	
County	Pittsylvania	Ground	Dry	Temperature (°F)	74.00	
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.80	
				Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Equipment Bridge		Acceptable				
Housekeeping		Acceptable				
Sediment Filter Log		Acceptable				
Sensitive Resource Buffer		Acceptable				
Sensitive Resource Signage		Acceptable				
Silt Fence (Filter Fabric Fence)		Acceptable				
Sump Pit		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	6/20/2022 12:50 PM	Report #	38944
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/20/2022 12:50 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	6+00	Field Station#	12+65		
Pic 1 Desc.	Observing temporary stabilization and ECD's		Pic 2 Desc.	Observing temporary stabilization,buffer, equipment crossing and ECD's	
GPS Location	O	GPS Location	O		
Field Station#	13+50	Field Station#	15+00		
Pic 3 Desc.	Observing temporary stabilization,water bar, sump, end treatment and ECD's		Pic 4 Desc.	Observing temporary stabilization and signage	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.			Pic 6 Desc.		

A/E	124300139	Date/Time	6/20/2022 12:50 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		













A/E	124300139	Date/Time	6/20/2022 12:50 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	38939
Inspector	Justin Burch			Date/Time	6/20/2022 11:22 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15480+67
State	VA	Inspection Area	Full	Station End	15584+23
County	Pittsylvania	Ground	Dry	Temperature (°F)	70.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Communication				
Waterbar End Treatment	Communication				
Silt Fence (Reinforce Filter Fence)	Communication				
Vegetative Stabilization (Permanent)	Acceptable				
Waterbar	Acceptable				
Equipment Bridge	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Cleanwater Diversion Berm	Acceptable				
Rock Construction Entrance	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/20/2022 11:22 AM	Report #	38939
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 15480+67 to 15584+23 (Toshes Road to Anderson Mill Road 1). 20 punch list items were submitted including 2 locations where P1 silt fence was deteriorated, 11 locations where CFS on waterbar end treatments were deteriorated, and 7 locations where perimeter CFS and other CFS was deteriorated. See the punch list for locations and other details for these punch list items. Other inspected ECDs in this area were either in acceptable condition or in the process of being replaced at the time of inspection. The EI observed that the solar farm ECDs adjacent to the ROW on both sides of Climax Road appeared to be in acceptable condition and that solar farm grading is ongoing between Toshes Road and Climax Road. The contractor has been working in the area since the last SWPPP inspection addressing punch list items. Since the last SWPPP inspection the area has received one rain event with totals of 0.80" at Snowberry Road and 1.00" at Anderson Mill Road 2. The ROW ground condition is dry. At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15482+00 to 15495+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/20/2022 11:22 AM	Report #	
Pictures					
 		 			
GPS Location	0	GPS Location	0		
Field Station#	15541+00	Field Station#	15541+00		
Pic 1 Desc.	CFS end treatment is deteriorated	Pic 2 Desc.	Perimeter CFS from 15540+50 to 15541+00 is deteriorated		
 		 			
GPS Location	0	GPS Location	0		
Field Station#	15540+00	Field Station#	15538+00		
Pic 3 Desc.	CFS end treatment is deteriorated	Pic 4 Desc.	CFS end treatment is deteriorated		
 		 			
GPS Location	0	GPS Location	0		
Field Station#	15538+00	Field Station#	15537+00		
Pic 5 Desc.	CFS at clean water diversion outlet is deteriorated	Pic 6 Desc.	CFS end treatment is deteriorated		

A/E	124300139	Date/Time	6/20/2022 11:22 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	15535+00	Field Station#	15533+00		
Pic 7 Desc.	Perimeter CFS is deteriorated from 15534+00 to 15535+00		Pic 8 Desc.	CFS at clean water diversion outlet is deteriorated	
					
GPS Location	0	GPS Location	0		
Field Station#	15532+75	Field Station#	15530+00		
Pic 9 Desc.	CFS end treatment is deteriorated		Pic 10 Desc.	CFS end treatment is deteriorated	
					
GPS Location	0	GPS Location	0		
Field Station#	15529+00	Field Station#	15540+00		
Pic 11 Desc.	CFS end treatment is deteriorated		Pic 12 Desc.	CFS end treatment is deteriorated	







AFE 124300139		Date/Time 6/20/2022 11:22 AM		Report #	
Pictures					
					
GPS Location		0		GPS Location 0	
Field Station#		15528+00		Field Station# 15528+00	
Pic 13 Desc.		CFS is deteriorated from 15526+50 to 15528+00		Pic 14 Desc. P1 silt fence is deteriorated	
					
GPS Location		0		GPS Location 0	
Field Station#		15526+50		Field Station# 15526+00	
Pic 15 Desc.		P1 silt fence is deteriorated		Pic 16 Desc. CFS end treatment is deteriorated	
					
GPS Location		0		GPS Location 0	
Field Station#		15525+00		Field Station# 15524+00	
Pic 17 Desc.		CFS end treatment is deteriorated		Pic 18 Desc. CFS end treatment is deteriorated	



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	38943
Inspector	Charles Head			Date/Time	6/20/2022 12:49 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15063+85
State	VA	Inspection Area	Full	Station End	15142+66
County	Pittsylvania	Ground	Dry	Temperature (°F)	74.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Waterbar	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/20/2022 12:49 PM	Report #	38943
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/20/2022 12:49 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	15072+86	Field Station#	15065+00		
Pic 1 Desc.	Approximately 15072+86. Overview of stream crossing, equipment bridge and ECDs at stream S-G11.		Pic 2 Desc.	Approximately 15065+00. Overview of ROW.	
					
GPS Location	0	GPS Location	0		
Field Station#	15084+00	Field Station#	15109+50		
Pic 3 Desc.	Approximately 15084+00. Overview of ROW.		Pic 4 Desc.	Approximately 15109+50. Overview of ROW.	
					
GPS Location	0	GPS Location	0		
Field Station#	15113+50	Field Station#	15139+00		
Pic 5 Desc.	Approximately 15113+50. Overview of road crossing and RCEs.		Pic 6 Desc.	Approximately 15139+00. Overview of ROW.	

A/E	124300139	Date/Time	6/20/2022 12:49 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/20/2022 12:49 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	38946
Inspector	John White			Date/Time	6/20/2022 1:03 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15947+64
State	VA	Inspection Area	Full	Station End	16027+46
County	Pittsylvania	Ground	Dry	Temperature (°F)	75.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/20/2022 1:03 PM	Report #	38946
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/20/2022 1:03 PM	Report #	
Pictures					
East Elevation 280°W (T) 36°49'50"N, 79°21'25"W ±68ft ▲ 632ft  Your Watermark 20 Jun 2022, 09:36:58		South West Elevation 57°NE (T) 36°49'54"N, 79°21'29"W ±19ft ▲ 653ft  Your Watermark 20 Jun 2022, 09:34:24			
GPS Location	O	GPS Location	O		
Field Station#	15977+36	Field Station#	15974+00		
Pic 1 Desc.	Observing temporary stabilization, water bar, signage, buffer, equipment crossing and ECD's	Pic 2 Desc.	Observing temporary stabilization, CWD outlet and ECD's		
North West Elevation 145°SE (T) 36°49'57"N, 79°21'33"W ±1177ft ▲ 636ft  Your Watermark 20 Jun 2022, 09:33:00		North East Elevation 243°SW (T) 36°50'11"N, 79°21'35"W ±11102ft ▲ 604ft  Your Watermark 20 Jun 2022, 09:32:13			
GPS Location	O	GPS Location	O		
Field Station#	15970+00	Field Station#	15965+50		
Pic 3 Desc.	Observing temporary stabilization and CWD berm	Pic 4 Desc.	Observing temporary stabilization and ECD's		
North East Elevation 239°SW (T) 36°49'50"N, 79°20'41"W ±13ft ▲ 626ft  Your Watermark 20 Jun 2022, 13:05:13		North Elevation 188°S (T) 36°49'51"N, 79°20'35"W ±2129ft ▲ 647ft  Your Watermark 20 Jun 2022, 12:58:50			
GPS Location	O	GPS Location	O		
Field Station#	16018+00	Field Station#	16022+00		
Pic 5 Desc.	Observing temporary stabilization, sump, end treatment and ECD's	Pic 6 Desc.	Observing temporary stabilization and water bar		

A/E	124300139	Date/Time	6/20/2022 1:03 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/20/2022 1:03 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	38934		
Inspector	Logan Box	Date/Time	6/20/2022 5:30 PM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13748+30
State	VA	Inspection Area	Partial	Station End	13853+45
County	Franklin	Ground	Dry	Temperature (°F)	81.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication				
Equipment Bridge	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Sump Pit	Acceptable				
Rock Construction Entrance	Acceptable				
Erosion Control Blanket	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/20/2022 5:30 PM	Report #	38934
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and ECDs at road crossings during routine inspection.</p> <p>Monitored sump pits and end treatment throughout areas of row.</p> <p>During inspection today the EI observed a section of P1 that requires maintenance due to 3rd party mowing activities, the I documented and added to the punch list for repair.</p> <p>There were no other environmental issues observed at the time of inspection today.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/20/2022 5:30 PM	Report #	
Pictures					
					
GPS Location	0000	GPS Location	0000		
Field Station#	13794+57	Field Station#	13812+02		
Pic 1 Desc.	Stream observation photo facing downstream during routine inspection today. No environmental issues observed at the time of inspection.	Pic 2 Desc.	P1 requires maintenance due to 3rd party mowing activities. Documented and added to the punch list.		
					
GPS Location	0000	GPS Location	0000		
Field Station#	13806+20	Field Station#	13794+57		
Pic 3 Desc.	Monitored ECDs at stream buffer. All in place and functioning at the time of inspection.	Pic 4 Desc.	Stream observation photo facing upstream during routine inspection. No issues observed at the time of inspection.		
					
GPS Location	0000	GPS Location	0000		
Field Station#	13784+35	Field Station#	13786+50		
Pic 5 Desc.	Monitored stabilization on hill side above stream crossing. ECDs in place and functioning.	Pic 6 Desc.	Monitored completed punch list item.. CFS installed and functioning.		

A/E	124300139	Date/Time	6/20/2022 5:30 PM	Report #	
Pictures					
		<p>Insert image here</p>		<p>Insert image here</p>	
GPS Location	0000	GPS Location			
Field Station#	13802+00	Field Station#			
Pic 7 Desc.	Row photo showing stabilization in upland area . No issues observed during inspection.	Pic 8 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	6/20/2022 5:30 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		






Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	38953
Inspector	Frank Craycroft			Date/Time	6/20/2022 3:12 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14649+67
State	VA	Inspection Area	Full	Station End	14694+77
County	Franklin	Ground	Dry	Temperature (°F)	75.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe		Acceptable			
Compost Filter Sock		Acceptable			
Sensitive Resource Buffer		Acceptable			
Silt Fence (Filter Fabric Fence)		Acceptable			
Silt Fence (Reinforce Filter Fence)		Acceptable			
Sump Pit		Acceptable			
Vegetative Stabilization (Permanent)		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Waterbar		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/20/2022 3:12 PM	Report #	38953
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation from SN 1465			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection of ROW from Hwy 40 to Jacks Creek Rd. All perimeter ECDs were functional and in good condition. All resource buffers in area are intact and bridges are free of sediment buildup. Vegetation is generally good to excellent with isolated areas of less productive growth. Recent cattle activity was observed from app. SN 14668+27 - 14680+00 which is also impacting vegetation. No signs of erosion or washing were observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/20/2022 3:12 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14656+50	Field Station#	14656+00		
Pic 1 Desc.	CIS S-H38 Vegetation	Pic 2 Desc.	CIS S-H38 ECDs		
					
GPS Location	0	GPS Location	0		
Field Station#	14659+00	Field Station#	14667+00		
Pic 3 Desc.	GAS W-H17 Vegetation	Pic 4 Desc.	Sump and J-Hook		
					
GPS Location	0	GPS Location	0		
Field Station#	14672+00	Field Station#	14679+00		
Pic 5 Desc.	CIS S-H37 ECDs	Pic 6 Desc.	CIS S-H36 ECDs		

A/E	124300139	Date/Time	6/20/2022 3:12 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14685+00	Field Station#	14687+00		
Pic 7 Desc.	Temporary vegetation	Pic 8 Desc.	Sump		
		<p style="text-align: center;">Insert image here</p>			
GPS Location	0	GPS Location			
Field Station#	14691+00	Field Station#			
Pic 9 Desc.	GAS S-H34 Silt fence	Pic 10 Desc.			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	6/20/2022 3:12 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision			Report #	38954	
Inspector	Frank Craycroft			Date/Time	6/20/2022 3:15 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0+00	
State	VA	Inspection Area	Full	Station End	0+00	
County	Franklin	Ground	Dry	Temperature (°F)	75.00	
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Rock Construction Entrance		Acceptable				
Secondary Containment		Acceptable				
Timber Mat		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waterbar		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	6/20/2022 3:15 PM	Report #	38954
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection of LY-032, -033, -048 and ANC-006. All portable equipment and hazardous materials were maintained within secondary containment. All perimeter ECDs were functional and in good condition. All trash and construction waste was maintained within bulk dumpsters on-site which had adequate additional storage. Rock entrances were free of dirt accumulation and in good condition. Stormwater drain inlets had proper perimeter protection and were free of debris.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/20/2022 3:15 PM	Report #	
Pictures					
					
GPS Location	0		GPS Location	0	
Field Station#	0+00		Field Station#	0+00	
Pic 1 Desc.	ANC-006 Stormwater drain inlet protection		Pic 2 Desc.	ANC-006 Secondary containment	
					
GPS Location	0		GPS Location	0	
Field Station#	0+00		Field Station#	0+00	
Pic 3 Desc.	LY-032 Equipment staging		Pic 4 Desc.	LY-032 Secondary containment	
					
GPS Location	0		GPS Location	0	
Field Station#	0+00		Field Station#	0+00	
Pic 5 Desc.	LY-033 Rock construction entrance		Pic 6 Desc.	LY-033 Secondary containment	

A/E	124300139	Date/Time	6/20/2022 3:15 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 7 Desc.	LY-048 Temporary vegetation	Pic 8 Desc.	LY-048 West perimeter CFS		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	6/20/2022 3:15 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report






Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	38951
Inspector	Ben Farmer			Date/Time	6/20/2022 2:39 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14171+36
State	VA	Inspection Area	Partial	Station End	14311+57
County	Franklin	Ground	Dry	Temperature (°F)	70.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	P1 has been damaged and needs to		
Silt Fence (Reinforced Filter Fabric Fence)	Communication	SSF fabric needs to be reattached		
Vegetative Stabilization (Temporary)	Communication	Slope needs to be stabilized		
Waterbar	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300139	Date/Time	6/20/2022 2:39 PM	Report #	38951
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 70F) Rain Gauge= 0.0" 14171+36-14311+57 -RCEs are in good condition at all road crossings. -Equipment bridge ECDs are in good condition and functioning -CWDs are functioning as intended. -SSF fabric needs to be reattached at 14222+00. -GAS slope of S-C20 needs additional stabilization at 14222+25. -P1 needs to be replaced at 14209+00. -Waterbars are in good condition throughout this section. -Slope drain is in good condition and functioning at 14232+00 -Resource buffers remain well vegetated. -CFS is in good condition throughout this section -Topsoil berms remain stabilized *Issues identified in the field have been added to the punch list to be addressed by the contractor					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/20/2022 2:39 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14176+09		Field Station#	14180+00	
Pic 1 Desc.	Equipment bridge ECDs are in good condition and functioning		Pic 2 Desc.	CWDs are functioning as intended	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14183+00		Field Station#	14209+00	
Pic 3 Desc.	Topsoil berms remain stabilized		Pic 4 Desc.	P1 has been damaged and needs to be replaced	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14222+00		Field Station#	14222+25	
Pic 5 Desc.	SSF fabric needs to be reattached		Pic 6 Desc.	Slope needs to be stabilized	

AFE	124300139	Date/Time	6/20/2022 2:39 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14223+41		Field Station#	14273+00	
Pic 7 Desc.	MVP-FR-311 is in good condition with controls in place		Pic 8 Desc.	CFS is in good condition throughout this section	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14277+00		Field Station#	14277+00	
Pic 9 Desc.	Waterbars are in good condition		Pic 10 Desc.	End treatments are functioning as intended	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14279+00		Field Station#	14311+57	
Pic 11 Desc.	Resource buffers remain well vegetated		Pic 12 Desc.	RCEs are in good condition at all road crossings.	

A/E	124300139	Date/Time	6/20/2022 2:39 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	38949
Inspector	Glenn Mike Renfro			Date/Time	6/20/2022 1:58 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0000+00
State	VA	Inspection Area	Full	Station End	0000+00
County	Franklin	Ground	Dry	Temperature (°F)	73.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.50
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Housekeeping	Acceptable				
Other - Explain in Comments	Acceptable	Inlet protection for catch basins			
Rock Construction Entrance	Acceptable				
Secondary Containment	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/20/2022 1:58 PM	Report #	38949
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> -Performed SWPPP inspections of Spread I laydown yards MVP-LY-045 and MVP-LY-046 in Rocky Mount, Va. - The locations have received .50" of rainfall since the last inspection and site conditions were dry. - All perimeter ECD's were inspected and no issues were observed. - The inlet protection for the catch basins at LY-046 were found to be in acceptable condition. - All secondary containment structures were inspected and no issues were identified during the time of inspection. - The RCE at LY-045 was in acceptable condition. - All equipment at both locations were inspected and no leaks were observed at the during today's inspection. - The General Construction permits and contact information are posted at the entrance of LY-046 as required. - There were no problems identified during today's inspection. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/20/2022 1:58 PM	Report #	
Pictures					
GPS Location	See picture		GPS Location	See picture	
Field Station#	0000+00		Field Station#	0000+00	
Pic 1 Desc.	Perimeter ECD's on west side of LY-046 in good condition.		Pic 2 Desc.	Perimeter ECD's on south end of LY-046 in good condition.	
GPS Location	See picture		GPS Location	See picture	
Field Station#	0000+00		Field Station#	0000+00	
Pic 3 Desc.	Secondary containment structure for fuel cell and BluDef in good condition at LY-046.		Pic 4 Desc.	General construction permits and contact information posted at main entrance of LY-046 as required.	
GPS Location	See picture		GPS Location	See picture	
Field Station#	0000+00		Field Station#	0000+00	
Pic 5 Desc.	Perimeter ECD's on northwest corner of LY-045 in good condition.		Pic 6 Desc.	Secondary containment structure at north end of LY-045 in good condition.	

AFE	124300139	Date/Time	6/20/2022 1:58 PM	Report #	
Pictures					
					
GPS Location	See picture		GPS Location	See picture	
Field Station#	0000+00		Field Station#	0000+00	
Pic 7 Desc.	Equipment inspected and no leaks observed during inspection at LY-045.		Pic 8 Desc.	RCE at LY-045 in good condition.	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 9 Desc.			Pic 10 Desc.		
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 11 Desc.			Pic 12 Desc.		





A/E	124300139	Date/Time	6/20/2022 1:58 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-603 Pipeline Spread I		AFE	124300139	Spread	H-603 Pipeline Spread I	
Contractor	Precision				Report #	38935	
Inspector	John White				Date/Time	6/20/2022 9:57 AM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	00+00	
State	VA	Inspection Area	Full		Station End	24+53	
County	Pittsylvania	Ground	Dry		Temperature (°F)	73.00	
Municipality	Chatham	Weather	Cloudy		Rain Gauge (in)	0.80	
					Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable					
Housekeeping		Acceptable					
Rock Construction Entrance		Acceptable					
Sensitive Resource Buffer		Acceptable					
Sensitive Resource Signage		Acceptable					
Silt Fence (Filter Fabric Fence)		Acceptable					
Sump Pit		Acceptable					
Vegetative Stabilization (Temporary)		Acceptable					
Waterbar End Treatment		Acceptable					
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300139	Date/Time	6/20/2022 9:57 AM	Report #	38935
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/20/2022 9:57 AM	Report #	
Pictures					
South West Elevation 48°NE (T) 36°50'6"N, 79°20'23"W ±16ft ▲ 663ft  <small>Your Watermark 20 Jun 2022, 09:53:10</small>			East Elevation 256°W (T) 36°50'1"N, 79°20'15"W ±13ft ▲ 651ft  <small>Your Watermark 20 Jun 2022, 09:53:50</small>		
GPS Location	O		GPS Location	O	
Field Station#	14+00		Field Station#	22+00	
Pic 1 Desc.	Observing temporary stabilization,RCE, signage, buffer and ECD's		Pic 2 Desc.	Observing temporary stabilization and buffer	
South West Elevation 50°NE (T) 36°50'5"N, 79°20'23"W ±387ft ▲ 631ft  <small>Your Watermark 20 Jun 2022, 09:55:21</small>			North West Elevation 147°SE (T) 36°50'5"N, 79°20'24"W ±26ft ▲ 654ft  <small>Your Watermark 20 Jun 2022, 09:55:28</small>		
GPS Location	O		GPS Location	O	
Field Station#	12+00		Field Station#	6+00	
Pic 3 Desc.	Observing temporary stabilization, sump, end treatment and ECD's		Pic 4 Desc.	Observing temporary stabilization and water bar	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 5 Desc.			Pic 6 Desc.		

A/E	124300139	Date/Time	6/20/2022 9:57 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	6/20/2022 9:57 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	38978
Inspector	Justin Burch			Date/Time	6/21/2022 8:59 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15142+66
State	VA	Inspection Area	Full	Station End	15260+00
County	Pittsylvania	Ground	Dry	Temperature (°F)	70.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Permanent)	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Equipment Bridge	Acceptable				
Compost Filter Sock	Acceptable				
Slope Drain Pipe	Acceptable				
Sump Pit	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/21/2022 8:59 AM	Report #	38978
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> • The EI performed a SWPPP inspection from 15142+66 to 15260+00 (Rock Creek Road to the Pigg River HDD Exit). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection. • The EI did not observe that any contractor activity has occurred in the area since the last SWPPP inspection. • Since the last SWPPP inspection the area has received one rain event with totals of 0.25" at Armstrong Road and 0.80" at Snowberry Road. • The ROW ground condition is dry. • At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15145+00 to 15153+00 and from 15173+00 to 15260+00. • The EI observed that the recently planted grass is beginning to grow in the inspection area. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/21/2022 8:59 AM	Report #	
Pictures					
133°SE (T) 17 N 626635 4089960 ±2086ft ▲ 912ft  15147+00 06-21-2022, 07:49:32			174°S (T) 17 N 626801 4089855 ±173ft ▲ 842ft  15154+00 06-21-2022, 07:54:18		
GPS Location	0		GPS Location	0	
Field Station#	15147+00		Field Station#	15154+00	
Pic 1 Desc.	Permanent vegetative stabilization in acceptable condition		Pic 2 Desc.	Waterbar in acceptable condition	
184°S (T) 17 N 626800 4089826 ±13ft ▲ 843ft  15154+00 06-21-2022, 07:55:14			272°W (T) 17 N 627022 4089725 ±62ft ▲ 779ft  15163+00 06-21-2022, 08:05:20		
GPS Location	0		GPS Location	0	
Field Station#	15154+00		Field Station#	15163+00	
Pic 3 Desc.	Waterbar end treatment in acceptable condition		Pic 4 Desc.	P1 silt fence and equipment bridge in acceptable conditions	
174°S (T) 17 N 627005 4089726 ±13ft ▲ 769ft  15163+00 06-21-2022, 08:06:13			173°S (T) 17 N 627215 4089576 ±13ft ▲ 741ft  15169+00 06-21-2022, 08:14:24		
GPS Location	0		GPS Location	0	
Field Station#	15163+00		Field Station#	15169+00	
Pic 5 Desc.	CFS and P1 silt fence in acceptable conditions		Pic 6 Desc.	Slope drain pipe and sump pit in acceptable conditions	

A/E	124300139	Date/Time	6/21/2022 8:59 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	15171+00	Field Station#	15172+00		
Pic 7 Desc.	Temporary vegetative stabilization in acceptable condition; recently planted grass is coming up		Pic 8 Desc.	Waterbar in acceptable condition	
					
GPS Location	0	GPS Location	0		
Field Station#	15172+00	Field Station#	15235+00		
Pic 9 Desc.	Waterbar end treatment in acceptable condition		Pic 10 Desc.	Permanent vegetative stabilization in acceptable condition	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.			Pic 12 Desc.		

A/E	124300139	Date/Time	6/21/2022 8:59 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	38993
Inspector	Charles Head			Date/Time	6/21/2022 1:16 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14694+77
State	VA	Inspection Area	Full	Station End	14802+19
County	Franklin	Ground	Dry	Temperature (°F)	83.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/21/2022 1:16 PM	Report #	38993
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/21/2022 1:16 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14701+00	Field Station#	14696+00		
Pic 1 Desc.	Approximately 14701+00. Overview of ROW.	Pic 2 Desc.	Approximately 14696+00. Overview of ROW.		
GPS Location	0	GPS Location	0		
Field Station#	14723+00	Field Station#	14794+00		
Pic 3 Desc.	Approximately 14723+00. Overview of ROW.	Pic 4 Desc.	Approximately 14794+00. Overview of stream crossing, equipment bridge and ECDs at stream S-H24.		
GPS Location	0	GPS Location	0		
Field Station#	14758+00	Field Station#	14716+50		
Pic 5 Desc.	Approximately 14758+00. Overview of road crossing and RCEs.	Pic 6 Desc.	Approximately 14716+50. Overview of wetland crossing, equipment bridge and ECDs at wetland W-H11.		

A/E	124300139	Date/Time	6/21/2022 1:16 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	6/21/2022 1:16 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	38992
Inspector	John White			Date/Time	6/21/2022 12:35 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15584+23
State	VA	Inspection Area	Full	Station End	15647+03
County	Pittsylvania	Ground	Dry	Temperature (°F)	90.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Communication	Perform maintenance			
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	Perform maintenance			
Sump Pit	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar End Treatment	Communication	Perform maintenance			
Rock Construction Entrance	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/21/2022 12:35 PM	Report #	38992
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. The Contractor is working on repairing the identified issues. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/21/2022 12:35 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15584+32	Field Station#	15584+32		
Pic 1 Desc.	Observing P1 that requires maintenance	Pic 2 Desc.	Observing P1 that requires maintenance		
GPS Location	O	GPS Location	O		
Field Station#	15585+00	Field Station#	15585+00		
Pic 3 Desc.	Observing CFS that requires maintenance	Pic 4 Desc.	Observing CFS that requires maintenance		
GPS Location	O	GPS Location	O		
Field Station#	15588+15	Field Station#	15592+00		
Pic 5 Desc.	Observing CFS that requires maintenance	Pic 6 Desc.	Observing end treatment that requires maintenance		

A/E	124300139	Date/Time	6/21/2022 12:35 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15593+00	Field Station#	15595+00		
Pic 7 Desc.	Observing end treatment that requires maintenance	Pic 8 Desc.	Observing temporary stabilization,CWD outlet and CFS that requires maintenance		
GPS Location	O	GPS Location	O		
Field Station#	15595+50	Field Station#	15647+03		
Pic 9 Desc.	Observing temporary stabilization, sump and end treatment that requires maintenance	Pic 10 Desc.	Observing road crossing and RCE's		
<div style="text-align: center;">Insert image here</div>		<div style="text-align: center;">Insert image here</div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	6/21/2022 12:35 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	38997
Inspector	Frank Craycroft			Date/Time	6/21/2022 3:05 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14311+57
State	VA	Inspection Area	Full	Station End	14454+22
County	Franklin	Ground	Dry	Temperature (°F)	85.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Plunge Pool	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Sump Pit	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	6/21/2022 3:05 PM	Report #	38997
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection of ROW from Farm View Rd to Webster Rd. Vegetation was generally good to excellent with travel lane and isolated areas showing less productive growth. No signs of erosion or washing were observed. All perimeter ECDs along edge of ROW and at resource buffers were functional and in good condition. Waterbars and sumps in area are functioning properly and show no signs of excessive sediment accumulation. RCEs and access roads in area are free of sediment buildup as are equipment bridges over resources.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/21/2022 3:05 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14320+00	Field Station#	14328+00		
Pic 1 Desc.	Perimeter ECDs	Pic 2 Desc.	Vegetation		
					
GPS Location	0	GPS Location	0		
Field Station#	14332+00	Field Station#	14338+00		
Pic 3 Desc.	Cleanwater outlet	Pic 4 Desc.	CIS S-A36		
					
GPS Location	0	GPS Location	0		
Field Station#	14350+00	Field Station#	14356+00		
Pic 5 Desc.	Sump and perimeter ECDs	Pic 6 Desc.	GAS S-A40 Buffer zone and ECDs		

AFE	124300139	Date/Time	6/21/2022 3:05 PM	Report #	
Pictures					
				Placeholder image here	
GPS Location	0	GPS Location	0		
Field Station#	14360+00	Field Station#	14370+00		
Pic 7 Desc.	Cleanwater outlet	Pic 8 Desc.	Temporary vegetation		
				Placeholder image here	
GPS Location	0	GPS Location	0		
Field Station#	14389+00	Field Station#	14400+00		
Pic 9 Desc.	CIS W-DD1 Buffer zone and ECDs	Pic 10 Desc.	Cleanwater outlet		
				Placeholder image here	
GPS Location	0	GPS Location	0		
Field Station#	14416+00	Field Station#	14423+00		
Pic 11 Desc.	Sump relay outlet	Pic 12 Desc.	GAS S-GH39 Buffer zone triple stack CFS		

AFE 124300139		Date/Time 6/21/2022 3:05 PM		Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14436+00	Field Station#	14441+00		
Pic 13 Desc.	CIS W-GH16 ECDs	Pic 14 Desc.	GAS W-GH16 Vegetation		
					
GPS Location	0	GPS Location			
Field Station#	14415+00	Field Station#			
Pic 15 Desc.	Temporary vegetation	Pic 16 Desc.			
					
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	38995
Inspector	Ben Farmer			Date/Time	6/21/2022 1:51 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13853+45
State	VA	Inspection Area	Partial	Station End	13958+31
County	Franklin	Ground	Dry	Temperature (°F)	68.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Communication	CFS has been damaged by 3rd part		
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300139	Date/Time	6/21/2022 1:51 PM	Report #	38995
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 68F) Rain Gauge= 0.0" 13853+45-13958+31 -Resource buffers remain well vegetated at all stream and wetland crossings. -CWDs are in good condition and functioning as intended -Equipment bridge ECDs are in good condition and functioning. -P1 is in good condition at all stream and wetland buffers -Steep slope at 13889+00 remains stabilized. -RCEs are in good condition at all road crossings. -Topsoil berms remain stabilized. -Sediment trap at 13897+00 is in good condition with no evidence of discharge. -CFS has been damaged by 3rd party and needs to be replaced at 13909+00. -Waterbars/end treatments are in good condition. -Slope drain is functioning at 13955+00. -Vegetation continues to fill in throughout this section. *Issues identified in the field have been added to the punch list to be addressed by the contractor.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/21/2022 1:51 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13958+31		Field Station#	13955+00	
Pic 1 Desc.	RCEs are in good condition at all road crossings		Pic 2 Desc.	Slope drain outlet is in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13948+00		Field Station#	13942+00	
Pic 3 Desc.	SSF is in good condition		Pic 4 Desc.	CWDs are functioning as intended	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13909+00		Field Station#	13897+00	
Pic 5 Desc.	CFS has been damaged by 3rd party and needs to be replaced		Pic 6 Desc.	Topsoil pile remains stabilized	

AFE	124300139	Date/Time	6/21/2022 1:51 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13897+00		Field Station#	13891+00	
Pic 7 Desc.	Sediment trap is functioning as intended		Pic 8 Desc.	Waterbars are in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13889+00		Field Station#	13876+00	
Pic 9 Desc.	Slope drain is in good condition and functioning		Pic 10 Desc.	P1 is in good condition at all stream and wetland buffers	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13875+73		Field Station#	13863+01	
Pic 11 Desc.	Equipment bridge ECDs are in good condition		Pic 12 Desc.	Resource buffers remain well vegetated	







A/E	124300139	Date/Time	6/21/2022 1:51 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	39049
Inspector	John White			Date/Time	6/22/2022 12:13 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15647+03
State	VA	Inspection Area	Full	Station End	15772+27
County	Pittsylvania	Ground	Dry	Temperature (°F)	92.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/22/2022 12:13 PM	Report #	39049
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were two issue identified during todays inspection and they were contractor addressed immediately.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/22/2022 12:13 PM	Report #	
Pictures					
 <p>North Elevation <small>198°S (T) 36°53'16"N, 79°25'56"W ±1325ft ▲ 808ft</small></p>		 <p>West Elevation <small>103°E (T) 36°53'16"N, 79°25'56"W ±98ft ▲ 792ft</small></p>			
GPS Location	O	GPS Location	O		
Field Station#	15650+00	Field Station#	15654+00		
Pic 1 Desc.	Observing temporary stabilization,water bar, sump and end treatment	Pic 2 Desc.	Observing temporary stabilization		
 <p>South Elevation <small>344°N (T) 36°53'0"N, 79°25'29"W ±1640ft ▲ 731ft</small></p>		 <p>North West Elevation <small>130°SE (T) 36°53'0"N, 79°25'29"W ±45ft ▲ 730ft</small></p>			
GPS Location	O	GPS Location	O		
Field Station#	15679+00	Field Station#	15682+00		
Pic 3 Desc.	Observing temporary stabilization,CWD outlet and ECD's	Pic 4 Desc.	Observing temporary stabilization,CWD berm and water bars		
 <p>South East Elevation <small>301°NW (T) 36°53'1"N, 79°25'35"W ±45ft ▲ 714ft</small></p>		 <p>East Elevation <small>278°W (T) 36°53'20"N, 79°25'58"W ±7375ft ▲ 814ft</small></p>			
GPS Location	O	GPS Location	O		
Field Station#	15671+93	Field Station#	15647+03		
Pic 5 Desc.	Observing temporary stabilization,signage, buffer, equipment crossing and ECD's	Pic 6 Desc.	Observing road crossing and RCE's		

A/E	124300139	Date/Time	6/22/2022 12:13 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/22/2022 12:13 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	39053
Inspector	Ben Farmer			Date/Time	6/22/2022 2:08 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13958+31
State	VA	Inspection Area	Partial	Station End	14062+17
County	Franklin	Ground	Dry	Temperature (°F)	74.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/22/2022 2:08 PM	Report #	39053
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 74F) Rain Gauge= 0.0" 13958+31-14062+17 -This section remains stabilized. -CWD/CWD inlets are in good condition and functioning as intended -MVP-ATWS-1446 remains stabilized with controls in place. -P1 is in good condition at all stream and wetland buffers. -No evidence of 3rd party pond discharging onto ROW at 14000+00 -Resource buffers remain well vegetated. -Slope on the CIS of Highway 220 remains stabilized with controls in place. -Waterbars/end treatments are functioning as intended. -CFS is in good condition -Slope drain is functioning as intended at 14058+00 -Rock check dams are functioning at 14059+00. -Vegetation continues to fill in throughout this section					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/22/2022 2:08 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	13960+00	Field Station#	13970+00		
Pic 1 Desc.	CWDs are functioning as intended	Pic 2 Desc.	This section remains temporarily stabilized		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	13998+00	Field Station#	13998+15		
Pic 3 Desc.	P1 is in good condition at all stream and wetland buffers.	Pic 4 Desc.	Equipment bridge ECDs are in good condition and functioning		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	14000+00	Field Station#	14009+11		
Pic 5 Desc.	No evidence of 3rd party pond discharging onto ROW.	Pic 6 Desc.	Slope remains stabilized		

AFE	124300139	Date/Time	6/22/2022 2:08 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14009+20		Field Station#	14018+47	
Pic 7 Desc.	SSF is in good condition		Pic 8 Desc.	RCEs are in good condition at all road crossings.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14027+00		Field Station#	14033+00	
Pic 9 Desc.	CFS is in good condition throughout this section		Pic 10 Desc.	Waterbars are in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14033+00		Field Station#	14035+00	
Pic 11 Desc.	End treatments are functioning as intended		Pic 12 Desc.	Resource buffers remain well vegetated	







A/E	124300139	Date/Time	6/22/2022 2:08 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	14050+00	Field Station#	14060+00		
Pic 13 Desc.	Slope remains stabilized with controls in place	Pic 14 Desc.	Rock check dams are in good condition		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			







Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	39030
Inspector	Justin Burch			Date/Time	6/22/2022 9:58 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15260+00
State	VA	Inspection Area	Full	Station End	15370+62
County	Pittsylvania	Ground	Dry	Temperature (°F)	83.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Sump Pit	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Plunge Pool	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Equipment Bridge	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/22/2022 9:58 AM	Report #	39030
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 15260+00 to 15370+62 (Pigg River HDD Exit to Snowberry Road). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection. Since the last SWPPP the contractor has worked in the area and replaced the broken gate post at 15309+50. Since the last SWPPP inspection the area has received one rain event with totals of 0.25" at Armstrong Road and 0.80" at Snowberry Road. The ROW ground condition is dry. At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15355+00 to 15370+00. At the time of inspection temporary vegetative stabilization was adequately mulched to inhibit erosion and recently planted grass is beginning to grow. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/22/2022 9:58 AM	Report #	
Pictures					
319°NW (T) 17 N 632275 4087398 ±239ft ▲ 773ft  15355+00 06-22-2022, 08:33:19			217°SW (T) 17 N 631807 4087815 ±78ft ▲ 777ft  15335+00 06-22-2022, 09:16:41		
GPS Location	0		GPS Location	0	
Field Station#	15355+00		Field Station#	15335+00	
Pic 1 Desc.	Perimeter CFS and temporary vegetative stabilization in acceptable conditions		Pic 2 Desc.	Sump pit in acceptable condition	
66°NE (T) 17 N 631800 4087817 ±36ft ▲ 772ft  15338+00 06-22-2022, 09:18:51			347°N (T) 17 N 631376 4088072 ±150ft ▲ 724ft  15318+00 06-22-2022, 09:32:37		
GPS Location	0		GPS Location	0	
Field Station#	15338+00		Field Station#	15318+00	
Pic 3 Desc.	Clean water diversion pipe and plunge pool in acceptable conditions		Pic 4 Desc.	Waterbar in acceptable condition	
350°N (T) 17 N 631363 4088084 ±32ft ▲ 720ft  15318+00 06-22-2022, 09:32:56			250°W (T) 17 N 631278 4088089 ±62ft ▲ 660ft  15314+00 06-22-2022, 09:48:14		
GPS Location	0		GPS Location	0	
Field Station#	15318+00		Field Station#	15314+00	
Pic 5 Desc.	Waterbar end treatment in acceptable condition		Pic 6 Desc.	Equipment bridge in acceptable condition	

A/E	124300139	Date/Time	6/22/2022 9:58 AM	Report #	
Pictures					
  <p>15313+00 06-22-2022, 09:49:30</p>		  <p>15305+00 06-22-2022, 10:21:38</p>			
GPS Location	0	GPS Location	0		
Field Station#	15313+00	Field Station#	15305+00		
Pic 7 Desc.	P1 silt fence in acceptable condition	Pic 8 Desc.	Temporary vegetative stabilization in acceptable condition		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	6/22/2022 9:58 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	39054
Inspector	Charles Head			Date/Time	6/22/2022 2:08 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14802+19
State	VA	Inspection Area	Full	Station End	14928+52
County	Franklin	Ground	Dry	Temperature (°F)	92.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/22/2022 2:08 PM	Report #	39054
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/22/2022 2:08 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14925+00	Field Station#	14870+43		
Pic 1 Desc.	Approximately 14925+00. Overview of ROW. Permanent vegetation.	Pic 2 Desc.	Approximately 14870+43. Overview of stream crossing, equipment bridge and ECDs at stream S-SS8.		
					
GPS Location	0	GPS Location	0		
Field Station#	14860+00	Field Station#	14846+00		
Pic 3 Desc.	Approximately 14860+00. Overview of ROW.	Pic 4 Desc.	Approximately 14846+00. Overview of road crossing and RCEs.		
					
GPS Location	0	GPS Location	0		
Field Station#	14840+00	Field Station#	14805+00		
Pic 5 Desc.	Approximately 14840+00. Overview of ROW.	Pic 6 Desc.	Approximately 14805+00. Overview of ROW.		

A/E	124300139	Date/Time	6/22/2022 2:08 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	6/22/2022 2:08 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		












Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	39060
Inspector	Frank Craycroft			Date/Time	6/22/2022 3:06 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14454+22
State	VA	Inspection Area	Full	Station End	14546+75
County	Franklin	Ground	Dry	Temperature (°F)	95.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Plunge Pool	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Sump Pit	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/22/2022 3:06 PM	Report #	39060
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection of ROW from Webster Rd to Tobacco Rd. Vegetation was generally moderate to good with areas of poor to moderate growth especially in travel lane and areas with active cattle impact. Stabilization methods are still present and no signs of erosion or washing were observed. All perimeter ECDs were functional and in good condition. Resource buffers in area are intact and no evidence of sedimentation within buffers or resources were observed. Equipment bridges and rock construction entrances are free of sediment buildup.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/22/2022 3:06 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14455+00	Field Station#	14455+00		
Pic 1 Desc.	GAS Webster Rd Sideslope stabilization		Pic 2 Desc.	GAS Webster Rd Temporary vegetation	
					
GPS Location	0	GPS Location	0		
Field Station#	14456+00	Field Station#	14467+00		
Pic 3 Desc.	Cleanwater diversion outlet		Pic 4 Desc.	Sideslope stabilization	
					
GPS Location	0	GPS Location	0		
Field Station#	14477+00	Field Station#	14485+00		
Pic 5 Desc.	Perimeter CFS		Pic 6 Desc.	CIS S-G22 Perimeter silt fence	

AFE	124300139	Date/Time	6/22/2022 3:06 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14488+00	Field Station#	14488+00		
Pic 7 Desc.	GAS S-G22	Pic 8 Desc.	Dry drainage ECDs		
					
GPS Location	0	GPS Location	0		
Field Station#	14495+00	Field Station#	14506+00		
Pic 9 Desc.	CIS S-G20 ECDs	Pic 10 Desc.	Sideslope stabilization		
					
GPS Location	0	GPS Location	0		
Field Station#	14514+00	Field Station#	14525+00		
Pic 11 Desc.	Cleanwater diversion outlet	Pic 12 Desc.	GAS Timber Ridge Rd Vegetation		







AFE 124300139		Date/Time 6/22/2022 3:06 PM		Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14530+00	Field Station#	14537+00		
Pic 13 Desc.	S-G18 ECDS	Pic 14 Desc.	Temporary stabilization		
				<p style="text-align: center;">Insert image here</p>	
GPS Location	0	GPS Location			
Field Station#	14545+00	Field Station#			
Pic 15 Desc.	CIS S-G17	Pic 16 Desc.			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	39106
Inspector	Ben Farmer			Date/Time	6/23/2022 2:22 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14062+17
State	VA	Inspection Area	Partial	Station End	14171+36
County	Franklin	Ground	Damp	Temperature (°F)	70.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Communication				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/23/2022 2:22 PM	Report #	39106
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 70F) Rain Gauge= 0.1" 14062+17-14171+36 -RCEs are in good condition at all road crossings. -Equipment bridge ECDs are in place and functioning -CWDs are functioning as intended. -MVP-FR-309.05 is in good condition with controls in place. -P1 is in good condition at all stream and wetland buffers. -Resource buffers remain well vegetated. -CFS has been damaged by 3rd party and needs to be replaced at 14118+00. -Waterbars/end treatments are in good condition and functioning -Slope drain is functioning as intended at 14157+00. -Vegetation continues to fill in throughout this section *Issues identified in the field have been added to the punch list to be addressed by the contractor.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/23/2022 2:22 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14062+17		Field Station#	14066+77	
Pic 1 Desc.	RCEs are in good condition at all road crossings.		Pic 2 Desc.	Equipment bridge ECDs are in good condition and functioning	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14070+00		Field Station#	14081+53	
Pic 3 Desc.	CWDs are functioning as intended		Pic 4 Desc.	MVP-FR-309.05 is in good condition with controls in place	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14090+00		Field Station#	14118+00	
Pic 5 Desc.	Topsoil berms remain stabilized		Pic 6 Desc.	CFS has been damaged by 3rd party and needs to be replaced	

AFE	124300139	Date/Time	6/23/2022 2:22 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14132+00		Field Station#	14141+62	
Pic 7 Desc.	CWD is functioning as intended		Pic 8 Desc.	P1 is in good condition at all stream and wetland buffers	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14155+00		Field Station#	14155+00	
Pic 9 Desc.	End treatments are functioning as intended		Pic 10 Desc.	Waterbars are in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14156+00		Field Station#	14157+55	
Pic 11 Desc.	Slope drain is functioning as intended		Pic 12 Desc.	Resource buffers remain well vegetated	







A/E	124300139	Date/Time	6/23/2022 2:22 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		








Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	39090
Inspector	Justin Burch			Date/Time	6/23/2022 9:06 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15370+62
State	VA	Inspection Area	Full	Station End	15480+67
County	Pittsylvania	Ground	Damp	Temperature (°F)	75.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Temporary)	Acceptable				
Sump Pit	Acceptable				
Cleanwater Diversion Berm	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Equipment Bridge	Acceptable				
Compost Filter Sock	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/23/2022 9:06 AM	Report #	39090
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 15370+62 to 15480+67 (Snowberry Road to Toshes Road). No punch list items were submitted due to the inspected ECDs being in compliance at the time of inspection. The EI observed that the turbidity in stream S-G4 (15426+54) (from upstream, non-MVP activities) had cleared up. The contractor has worked in this area performing seeding and mulching since the last SWPPP inspection. The EI observed that the perimeter solar farm ECDs on the CIS of Toshes Road appeared to be in acceptable condition. Since the last SWPPP inspection the area has received one rain event with totals of 0.10" at Snowberry Road and 0.10" at Anderson Mill Road 2. The ROW ground condition is damp. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 15438+00 to 15445+00. At the time of inspection the ROW was adequately mulched to inhibit erosion and the recently planted grass is beginning to grow. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/23/2022 9:06 AM	Report #	
Pictures					
					
GPS Location	0		GPS Location	0	
Field Station#	15372+00		Field Station#	15480+00	
Pic 1 Desc.	Temporary vegetative stabilization in acceptable condition		Pic 2 Desc.	Sump pit in acceptable condition	
					
GPS Location	0		GPS Location	0	
Field Station#	15469+00		Field Station#	15461+00	
Pic 3 Desc.	Clean water diversion berm in acceptable condition		Pic 4 Desc.	Waterbar in acceptable condition	
					
GPS Location	0		GPS Location	0	
Field Station#	15461+00		Field Station#	15460+00	
Pic 5 Desc.	Waterbar end treatment in acceptable condition		Pic 6 Desc.	Super silt fence in acceptable condition	

AFE	124300139	Date/Time	6/23/2022 9:06 AM	Report #	
Pictures					
 <p>306°NW (T) 17 N 634504 4086582 ±124ft ▲ 791ft 15435+09 06-23-2022, 09:00:57</p>		 <p>49°NE (T) 17 N 634213 4086681 ±19ft ▲ 797ft 15425+00 06-23-2022, 09:09:23</p>			
GPS Location	0	GPS Location	0		
Field Station#	15435+09	Field Station#	15425+00		
Pic 7 Desc.	Equipment bridge in acceptable condition	Pic 8 Desc.	Waterbar in acceptable condition		
 <p>59°NE (T) 17 N 634224 4086697 ±26ft ▲ 797ft 15425+00 06-23-2022, 09:09:54</p>		 <p>327°NW (T) 17 N 635595 4089712 ±14173ft ▲ 808ft 15421+00 06-23-2022, 09:23:05</p>			
GPS Location	0	GPS Location	0		
Field Station#	15425+00	Field Station#	15421+00		
Pic 9 Desc.	Waterbar end treatment in acceptable condition	Pic 10 Desc.	Perimeter CFS in acceptable condition		
 <p>266°W (T) 17 N 634651 4086507 ±410ft ▲ 830ft 15440+00 06-23-2022, 09:54:16</p>		<p style="text-align: center;">Insert image here</p>			
GPS Location	0	GPS Location			
Field Station#	15440+00	Field Station#			
Pic 11 Desc.	Permanent vegetative stabilization in acceptable condition	Pic 12 Desc.			







A/E	124300139	Date/Time	6/23/2022 9:06 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	39087
Inspector	Charles Head			Date/Time	6/23/2022 8:43 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14928+52
State	VA	Inspection Area	Full	Station End	15063+85
County	Franklin/Pittsylvania	Ground	Damp	Temperature (°F)	73.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/23/2022 8:43 AM	Report #	39087
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/23/2022 8:43 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14932+89	Field Station#	14950+47		
Pic 1 Desc.	Approximately 14932+89. Overview of stream crossing, equipment bridge and ECDs at stream S-G15.		Pic 2 Desc.	Approximately 14950+47. Overview of stream crossing, equipment bridge and ECDs at stream S-G13.	
					
GPS Location	0	GPS Location	0		
Field Station#	14973+00	Field Station#	14981+50		
Pic 3 Desc.	Approximately 14973+00. Overview of ROW. Permanent vegetation.		Pic 4 Desc.	Approximately 14981+50. Overview of road crossing, RCEs and ROW.	
					
GPS Location	0	GPS Location	0		
Field Station#	15002+00	Field Station#	15061+75		
Pic 5 Desc.	Approximately 15002+00. Overview of ROW.		Pic 6 Desc.	Approximately 15061+75. Overview of ROW.	

A/E	124300139	Date/Time	6/23/2022 8:43 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/23/2022 8:43 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	39102
Inspector	John White			Date/Time	6/23/2022 12:49 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15772+27
State	VA	Inspection Area	Full	Station End	15947+64
County	Pittsylvania	Ground	Dry	Temperature (°F)	85.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Rock-lined Channel	Acceptable				
Sump Pit	Acceptable				
Waterbar End Treatment	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/23/2022 12:49 PM	Report #	39102
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. Checked rain gauges, Anderson Mill #2=.10", Mill Creek =.10", Transco =.10". There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/23/2022 12:49 PM	Report #	
Pictures					
South East Elevation 313°NW (T) 36°51'15"N, 79°23'27"W ±39ft ▲ 814ft 		West Elevation 109°E (T) 36°51'15"N, 79°23'25"W ±19ft ▲ 813ft 			
GPS Location	O	GPS Location	O		
Field Station#	15835+00	Field Station#	15836+00		
Pic 1 Desc.	Observing temporary stabilization,CWD outlet and ECD's	Pic 2 Desc.	Observing temporary stabilization,rock lined channel and ECD's		
North East Elevation 224°SW (T) 36°51'14"N, 79°23'26"W ±295ft ▲ 813ft 		East Elevation 281°W (T) 36°51'20"N, 79°23'37"W ±127ft ▲ 846ft 			
GPS Location	O	GPS Location	O		
Field Station#	15839+00	Field Station#	15826+77		
Pic 3 Desc.	Observing temporary stabilization,equipment crossing and ECD's	Pic 4 Desc.	Observing road crossing and RCE's		
South East Elevation 329°NW (T) 36°51'23"N, 79°23'32"W ±13ft ▲ 831ft 		South Elevation 356°N (T) 36°51'23"N, 79°23'32"W ±13ft ▲ 830ft 			
GPS Location	O	GPS Location	O		
Field Station#	15825+00	Field Station#	15825+50		
Pic 5 Desc.	Observing temporary stabilization,plunge pool and ECD's	Pic 6 Desc.	Observing temporary stabilization,seep and end treatment		

A/E	124300139	Date/Time	6/23/2022 12:49 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/23/2022 12:49 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	39050
Inspector	Logan Box			Date/Time	6/23/2022 3:38 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13670+00
State	VA	Inspection Area	Partial	Station End	13748+30
County	Franklin	Ground	Dry	Temperature (°F)	90.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Silt Fence (Filter Fabric Fence)	Communication				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Rock Construction Entrance	Acceptable				
Rock-lined Channel	Acceptable				
Sump Pit	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/23/2022 3:38 PM	Report #	39050
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and ECDs at road crossings during routine inspection.</p> <p>Monitored sump pits and end treatment throughout areas of row.</p> <p>During inspection today the EI observed a section of P1 with wildlife damages . Documented and added to the punch list for maintenance repair.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/23/2022 3:38 PM	Report #	
Pictures					
					
GPS Location	00000	GPS Location	00000		
Field Station#	13678+71	Field Station#	13687+70		
Pic 1 Desc.	Stream observation photo facing upstream during routine inspection. No issues were observed at the time of inspection.		Pic 2 Desc.	P1 requires maintenance due to wildlife damages, documented and added to the punch list.	
					
GPS Location	00000	GPS Location	00000		
Field Station#	13678+71	Field Station#	13748+10		
Pic 3 Desc.	Stream observation photo facing downstream during routine inspection today. Good vegetation on stream banks.		Pic 4 Desc.	Observed ECDs at road crossings to insure they were functioning properly. No issues observed at the time of inspection.	
					
GPS Location	00000	GPS Location	00000		
Field Station#	13678+46	Field Station#	13687+70		
Pic 5 Desc.	Monitored ECDs throughout the row, no environmental issues observed at the time of inspection.		Pic 6 Desc.	Additional photo showing P1 that requires maintenance due to wildlife damages.	

A/E	124300139	Date/Time	6/23/2022 3:38 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/23/2022 3:38 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Pic 13 Desc.		Pic 14 Desc.		Pic 16 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 18 Desc.	
Insert image here			Insert image here		











Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	39107
Inspector	Frank Craycroft			Date/Time	6/23/2022 2:32 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14546+75
State	VA	Inspection Area	Full	Station End	14649+67
County	Franklin	Ground	Damp	Temperature (°F)	85.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.40
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Plunge Pool	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Sump Pit	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/23/2022 2:32 PM	Report #	39107
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Final restoration and full permanent			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection of ROW from Tobacco Rd to Hwy 40. Vegetation is generally moderate to good. Areas of poorer vegetation still have adequate mulching mediums and no signs of erosion or washing were observed. Waterbars and sumps in area were still functioning properly and no signs of sediment accumulation were observed. Equipment bridges and rock construction entrances are free of dirt buildup. All perimeter ECDs were functional and in good condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/23/2022 2:32 PM	Report #	
Pictures					
					
GPS Location	0		GPS Location	0	
Field Station#	14547+50		Field Station#	14565+00	
Pic 1 Desc.	GAS Tobacco Rd ATWS Vegetation		Pic 2 Desc.	Dry swale perimeter ECDs	
					
GPS Location	0		GPS Location	0	
Field Station#	14552+00		Field Station#	14567+00	
Pic 3 Desc.	Cleanwater diversion outlet		Pic 4 Desc.	CIS S-E18 Perimeter ECDs	
					
GPS Location	0		GPS Location	0	
Field Station#	14569+00		Field Station#	14583+00	
Pic 5 Desc.	Sumps and J-Hooks		Pic 6 Desc.	GAS S-E17 Vegetation	

AFE	124300139	Date/Time	6/23/2022 2:32 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14582+85	Field Station#	14583+50		
Pic 7 Desc.	S-E17 Buffer zone	Pic 8 Desc.	GAS S-E17 Perimeter ECDs		
					
GPS Location	0	GPS Location	0		
Field Station#	14598+00	Field Station#	14601+00		
Pic 9 Desc.	CIS Simmons Creek Rd Temporary stabilization	Pic 10 Desc.	GAS Simmons Creek Rd Temporary stabilization		
					
GPS Location	0	GPS Location	0		
Field Station#	14605+00	Field Station#	14607+00		
Pic 11 Desc.	Sump	Pic 12 Desc.	Cleanwater diversion plunge pool		







A/E	124300139	Date/Time	6/23/2022 2:32 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14610+00	Field Station#	1461+00		
Pic 13 Desc.	CIS S-E14 ECDs	Pic 14 Desc.	GAS S-E14 Temporary stabilization		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	39159
Inspector	Ben Farmer			Date/Time	6/24/2022 1:41 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14171+36
State	VA	Inspection Area	Partial	Station End	14311+57
County	Franklin	Ground	Dry	Temperature (°F)	70.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/24/2022 1:41 PM	Report #	39159
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 70F) Rain Gauge= 0.0" 14171+36-14311+57 -RCEs are in good condition at all road crossings. -Equipment bridge ECDs are in good condition and functioning -CWDs are functioning as intended. -SSF is in good condition -P1 is in good condition at all stream and wetland buffers. -Waterbars are in good condition throughout this section. -Slope drain is in good condition and functioning at 14232+00 -Resource buffers remain well vegetated. -CFS is in good condition throughout this section -Topsoil berms remain stabilized					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/24/2022 1:41 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14180+00		Field Station#	14182+00	
Pic 1 Desc.	CWDs are functioning as intended		Pic 2 Desc.	SSF is in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14190+00		Field Station#	14209+00	
Pic 3 Desc.	P1 is in good condition at all stream and wetland buffers		Pic 4 Desc.	Equipment bridge ECDs are in good condition and functioning	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14223+41		Field Station#	14232+00	
Pic 5 Desc.	MVP-FR-311 is in good condition with controls in place		Pic 6 Desc.	Slope drain is functioning as intended	

AFE	124300139	Date/Time	6/24/2022 1:41 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14251+00		Field Station#	14273+00	
Pic 7 Desc.	Slope remains stabilized		Pic 8 Desc.	CFS is in good condition throughout this section	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14278+00		Field Station#	14278+00	
Pic 9 Desc.	Waterbars are in good condition		Pic 10 Desc.	End treatments are functioning as intended	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14279+00		Field Station#	14311+57	
Pic 11 Desc.	Resource buffers remain well vegetated		Pic 12 Desc.	RCEs are in good condition at all road crossings.	





A/E	124300139	Date/Time	6/24/2022 1:41 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-602 Pipeline Spread I	AFE	124300139	Spread	H-602 Pipeline Spread I	
Contractor	Precision			Report #	39154	
Inspector	John White			Date/Time	6/24/2022 12:31 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	19+25	
County	Pittsylvania	Ground	Dry	Temperature (°F)	83.00	
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.10	
				Rain Accumulation Time (days)	4.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Equipment Bridge		Acceptable				
Housekeeping		Acceptable				
Sediment Filter Log		Acceptable				
Sensitive Resource Buffer		Acceptable				
Silt Fence (Filter Fabric Fence)		Acceptable				
Sump Pit		Acceptable				
Waterbar		Acceptable				
Waterbar End Treatment		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	6/24/2022 12:31 PM	Report #	39154
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/24/2022 12:31 PM	Report #	
Pictures					
North Elevation ☉ 184°S (T) ● 36°49'53"N, 79°20'31"W ±6197ft ▲ 643ft 		North West Elevation ☉ 156°SE (T) ● 36°49'45"N, 79°20'39"W ±13ft ▲ 623ft 			
GPS Location	O	GPS Location	O		
Field Station#	6+00	Field Station#	12+65		
Pic 1 Desc.	Observing temporary stabilization and access road	Pic 2 Desc.	Observing temporary stabilization,buffer, equipment crossing and ECD's		
South West Elevation ☉ 50°NE (T) ● 36°49'43"N, 79°20'40"W ±13ft ▲ 617ft 		South East Elevation ☉ 314°NW (T) ● 36°49'39"N, 79°20'38"W ±16ft ▲ 628ft 			
GPS Location	O	GPS Location	O		
Field Station#	13+50	Field Station#	15+00		
Pic 3 Desc.	Observing temporary stabilization,water bar, sump, end treatment and ECD's	Pic 4 Desc.	Observing temporary stabilization		
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.		Pic 6 Desc.			

A/E	124300139	Date/Time	6/24/2022 12:31 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/24/2022 12:31 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	39141
Inspector	Justin Burch			Date/Time	6/24/2022 10:19 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15480+67
State	VA	Inspection Area	Full	Station End	15584+23
County	Pittsylvania	Ground	Dry	Temperature (°F)	74.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Sump Pit	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Sensitive Resource Buffer	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/24/2022 10:19 AM	Report #	39141
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 15480+67 to 15584+23 (Toshes Road to Anderson Mill Road 1). No punch list items were submitted due to the inspected ECDs being in compliance at the time of inspection. The EI observed that the solar farm ECDs adjacent to the ROW on both sides of Climax Road appeared to be in acceptable condition and that solar farm grading is ongoing between Toshes Road and Climax Road. The contractor has worked in the area since the last SWPPP inspection addressing punch list items and performing seeding and mulching. Since the last SWPPP inspection the area has received one rain event with totals of 0.10" at Snowberry Road and 0.10" at Anderson Mill Road 2. The ROW ground condition is dry. At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15482+00 to 15495+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/24/2022 10:19 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	15499+00	Field Station#	15499+00		
Pic 1 Desc.	Waterbar in acceptable condition	Pic 2 Desc.	Waterbar end treatment in acceptable condition		
					
GPS Location	0	GPS Location	0		
Field Station#	15504+00	Field Station#	15520+00		
Pic 3 Desc.	Sump pit in acceptable condition	Pic 4 Desc.	P1 silt fence and sensitive resource buffer in acceptable conditions		
					
GPS Location	0	GPS Location	0		
Field Station#	15527+23	Field Station#	15528+00		
Pic 5 Desc.	Equipment bridge and CFS in acceptable conditions	Pic 6 Desc.	Sump pit in acceptable condition		

AFE	124300139	Date/Time	6/24/2022 10:19 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	15544+00	Field Station#	15544+00		
Pic 7 Desc.	Waterbar in acceptable condition		Pic 8 Desc.	Waterbar end treatment in acceptable condition	
					
GPS Location	0	GPS Location	0		
Field Station#	15533+00	Field Station#	15494+00		
Pic 9 Desc.	Clean water diversion pipe and CFS in acceptable conditions		Pic 10 Desc.	Permanent vegetative stabilization in acceptable condition	
		<div style="text-align: center; height: 150px;">Insert image here</div>			
GPS Location	0	GPS Location			
Field Station#	15504+00	Field Station#			
Pic 11 Desc.	Solar farm perimeter ECDs appear to be in acceptable conditions		Pic 12 Desc.		







A/E	124300139	Date/Time	6/24/2022 10:19 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	39139		
Inspector	Charles Head	Date/Time	6/24/2022 9:46 AM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15063+85
State	VA	Inspection Area	Full	Station End	15142+66
County	Pittsylvania	Ground	Dry	Temperature (°F)	73.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
			Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock		Acceptable			
Equipment Bridge		Acceptable			
Rock Construction Entrance		Acceptable			
Sensitive Resource Buffer		Acceptable			
Sensitive Resource Signage		Acceptable			
Silt Fence (Filter Fabric Fence)		Acceptable			
Waterbar		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/24/2022 9:46 AM	Report #	39139
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/24/2022 9:46 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	15139+00	Field Station#	15120+00		
Pic 1 Desc.	Approximately 15139+00. Overview of ROW.	Pic 2 Desc.	Approximately 15120+00. Overview of ROW.		
					
GPS Location	0	GPS Location	0		
Field Station#	15113+50	Field Station#	15084+00		
Pic 3 Desc.	Approximately 15113+50. Overview of road crossing and RCEs.	Pic 4 Desc.	Approximately 15084+00. Overview of ROW.		
					
GPS Location	0	GPS Location	0		
Field Station#	15072+86	Field Station#	15066+00		
Pic 5 Desc.	Approximately 15072+86. Overview of stream crossing, equipment bridge and ECDs at stream S-G11.	Pic 6 Desc.	Approximately 15066+00. Overview of ROW.		

A/E	124300139	Date/Time	6/24/2022 9:46 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/24/2022 9:46 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	39155
Inspector	John White			Date/Time	6/24/2022 12:36 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15947+64
State	VA	Inspection Area	Full	Station End	16027+46
County	Pittsylvania	Ground	Dry	Temperature (°F)	83.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sump Pit	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/24/2022 12:36 PM	Report #	39155
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/24/2022 12:36 PM	Report #	
Pictures					
	East Elevation ☉ 275°W (T) ● 36°49'50"N, 79°20'37"W ±68ft ▲ 642ft 			North Elevation ☉ 172°S (T) ● 36°49'50"N, 79°20'37"W ±19ft ▲ 641ft 	
GPS Location	O		GPS Location	O	
Field Station#	16024+00		Field Station#	16022+00	
Pic 1 Desc.	Observing temporary stabilization		Pic 2 Desc.	Observing temporary stabilization and water bars	
	North West Elevation ☉ 131°SE (T) ● 36°49'48"N, 79°20'44"W ±239ft ▲ 610ft 			North East Elevation ☉ 216°SW (T) ● 36°49'48"N, 79°20'44"W ±49ft ▲ 610ft 	
GPS Location	O		GPS Location	O	
Field Station#	16016+36		Field Station#	16018+00	
Pic 3 Desc.	Observing temporary stabilization,buffer, equipment crossing and ECD's		Pic 4 Desc.	Observing temporary stabilization, sump and end treatment	
	South West Elevation ☉ 30°NE (T) ● 36°49'45"N, 79°20'49"W ±439ft ▲ 629ft 			North Elevation ☉ 182°S (T) ● 36°49'46"N, 79°20'50"W ±42ft ▲ 622ft 	
GPS Location	O		GPS Location	O	
Field Station#	16010+00		Field Station#	16010+00	
Pic 5 Desc.	Observing temporary stabilization,CWD outlet and ECD's		Pic 6 Desc.	Observing temporary stabilization and CWD inlet	

A/E	124300139	Date/Time	6/24/2022 12:36 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		






A/E	124300139	Date/Time	6/24/2022 12:36 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	39113
Inspector	Logan Box			Date/Time	6/24/2022 3:54 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13748+30
State	VA	Inspection Area	Partial	Station End	13853+45
County	Franklin	Ground	Dry	Temperature (°F)	90.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Erosion Control Blanket	Acceptable				
Plunge Pool	Acceptable				
Rock-lined Channel	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Sump Pit	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Rock Construction Entrance	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/24/2022 3:54 PM	Report #	39113
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and ECDs at road crossings during routine inspection.</p> <p>Monitored sump pits and end treatment throughout areas of row.</p> <p>During inspection today there were no environmental issues observed at the time of inspection.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/24/2022 3:54 PM	Report #	
Pictures					
					
GPS Location	00000	GPS Location	00000		
Field Station#	13846+93	Field Station#	13748+97		
Pic 1 Desc.	Stream observation photo facing upstream during routine inspection today. No issues were observed at the time of inspection.		Pic 2 Desc.	ECDs in place and functioning at stream crossing. No issues were observed at the time of inspection.	
					
GPS Location	0000	GPS Location	0000		
Field Station#	13759+00	Field Station#	13847+60		
Pic 3 Desc.	Row photo showing vegetation in temporary area of row. Good stabilization noted.		Pic 4 Desc.	Monitored reinforced silt fence and CFS near stream crossing, no environmental issues observed at the time of inspection.	
					
GPS Location	0000	GPS Location	0000		
Field Station#	13756+10	Field Station#	13846+93		
Pic 5 Desc.	Monitored ECDs throughout row inspection today. All in place and functioning at the time of inspection.		Pic 6 Desc.	Stream observation photo facing downstream, good stabilization observed on stream banks.	

A/E	124300139	Date/Time	6/24/2022 3:54 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location	00000	GPS Location			
Field Station#		Field Station#			
Pic 7 Desc.		Pic 8 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	6/24/2022 3:54 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I		AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision				Report #	39161	
Inspector	Frank Craycroft				Date/Time	6/24/2022 2:15 PM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	0+00	
State	VA	Inspection Area	Full		Station End	0+00	
County	Franklin	Ground	Dry		Temperature (°F)	85.00	
Municipality	N/A	Weather	Sunny		Rain Gauge (in)	0.00	
					Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable					
Housekeeping		Acceptable					
Secondary Containment		Acceptable					
Timber Mat		Acceptable					
Vegetative Stabilization (Temporary)		Acceptable					
Rock Construction Entrance		Acceptable					
Waste Management		Acceptable					
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300139	Date/Time	6/24/2022 2:15 PM	Report #	39161
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection of LY-032, -033, -048, and ANC-006. All portable equipment and hazardous materials were maintained within secondary containment. Stormwater drain inlets had proper perimeter protection and were free of debris and vegetation. All construction waste was maintained within bulk dumpsters. All perimeter ECDs were functional and in good condition. Rock entrances and staging areas were free of mud and dirt accumulation.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/24/2022 2:15 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 1 Desc.	LY-033 Timber mat staging area		Pic 2 Desc.	LY-032 Staging area	
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 3 Desc.	LY-032 Secondary containment		Pic 4 Desc.	LY-033 Stormwater drain inlet protections	
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 5 Desc.	LY-048 West perimeter CFS		Pic 6 Desc.	ANC-006 Perimeter CFS	

AFE	124300139	Date/Time	6/24/2022 2:15 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 7 Desc.	ANC-006 Perimeter CFS	Pic 8 Desc.	LY-048 North perimeter CFS		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	6/24/2022 2:15 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		











Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	39186
Inspector	Frank Craycroft			Date/Time	6/24/2022 2:01 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14649+67
State	VA	Inspection Area	Full	Station End	14694+77
County	Franklin	Ground	Dry	Temperature (°F)	85.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Sump Pit	Acceptable				
Plunge Pool	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/24/2022 2:01 PM	Report #	39186
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Final cleanup and permanent vegeta			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection of ROW from Hwy 40 to Jacks Creek Rd. Vegetation is generally moderate to good except in areas of active cattle grazing near access road MVP-FR-320. ROW remains stable in these areas as mulching mediums are still present. No signs of erosion or washing were observed. All ECDs observed were functional and in good condition. Waterbars and sumps in area still have adequate storage capacity and show no signs of sediment accumulation. Equipment bridges in area are clean and free of sediment deposits.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/24/2022 2:01 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14690+50	Field Station#	14694+50		
Pic 1 Desc.	Perimeter CFS	Pic 2 Desc.	CIS Jacks Creek Rd Vegetation		
					
GPS Location	0	GPS Location	0		
Field Station#	14693+00	Field Station#	14688+50		
Pic 3 Desc.	Sump and J-hook	Pic 4 Desc.	CIS S-H34 Perimeter CFS along travel lane		
					
GPS Location	0	GPS Location	0		
Field Station#	14687+00	Field Station#	14682+00		
Pic 5 Desc.	Perimeter SSF	Pic 6 Desc.	GAS S-H36 SSF and CFS		

AFE	124300139	Date/Time	6/24/2022 2:01 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14682+00	Field Station#	14679+00		
Pic 7 Desc.	GAS S-H36 Buffer zone	Pic 8 Desc.	CIS S-H36 Sump and ECDs		
					
GPS Location	0	GPS Location	0		
Field Station#	14676+00	Field Station#	14675+00		
Pic 9 Desc.	ATWS Perimeter CFS	Pic 10 Desc.	Vegetation in active pasture		
					
GPS Location	0	GPS Location	0		
Field Station#	14675+00	Field Station#	14672+00		
Pic 11 Desc.	GAS S-H37 Sumps and ECDs	Pic 12 Desc.	Perimeter SSF and CFS		







A/E	124300139	Date/Time	6/24/2022 2:01 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location			
Field Station#	14673+00	Field Station#			
Pic 13 Desc.	CIS S-H37 Buffer zone ECDs	Pic 14 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision			Report #	39157	
Inspector	Glenn Mike Renfro			Date/Time	6/24/2022 12:52 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0000+00	
State	VA	Inspection Area	Full	Station End	0000+00	
County	Franklin	Ground	Dry	Temperature (°F)	81.00	
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	4.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Other - Explain in Comments		Acceptable	Inlet protection for catch basins			
Rock Construction Entrance		Acceptable				
Secondary Containment		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	6/24/2022 12:52 PM	Report #	39157
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Performed SWPPP inspections of Spread I laydown yards MVP-LY-045 and MVP-LY-046 in Rocky Mount, Va. - The locations have not received any rainfall since the last inspection and site conditions were dry. - All perimeter ECD's were inspected and no issues were observed. - The inlet protection for the catch basins at LY-046 were found to be in acceptable condition. - All secondary containment structures were inspected and no issues were identified during the time of inspection. - The RCE at LY-045 was in acceptable condition. - All equipment at both locations were inspected and no leaks were observed at the during today's inspection. - The General Construction permits and contact information are posted at the entrance of LY-046 as required. - There were no problems identified during today's inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/24/2022 12:52 PM	Report #	
Pictures					
	 <p>SW W NW N 309°NW (T) 36°58'15"N, 79°52'10"W ±16ft ▲1170ft 24 Jun 2022, 10:17:23</p>			 <p>SW W NW N 297°NW (T) 36°58'20"N, 79°52'13"W ±13ft ▲1181ft 24 Jun 2022, 10:18:47</p>	
GPS Location	See picture		GPS Location	See picture	
Field Station#	0000+00		Field Station#	0000+00	
Pic 1 Desc.	Perimeter ECD's and secondary containment structure for light plant on south end of LY-046 in good condition.		Pic 2 Desc.	Perimeter ECD's on on northwest corner of LY-046 in good condition.	
	 <p>NE E SE S 123°SE (T) 36°58'17"N, 79°52'12"W ±13ft ▲1186ft 24 Jun 2022, 10:20:15</p>				
GPS Location	See picture		GPS Location	See picture	
Field Station#	0000+00		Field Station#	0000+00	
Pic 3 Desc.	Secondary containment structure for fuel cell at LY-046 in good condition.		Pic 4 Desc.	Perimeter ECD's on north end of LY-045 near bridge mats in good condition.	
	 <p>S SW W NW 262°W (T) 36°58'14"N, 79°52'9"W ±13ft ▲1198ft 24 Jun 2022, 10:15:58</p>			 <p>N NE E SE 53°NE (T) 36°58'8"N, 79°52'6"W ±13ft ▲1178ft 24 Jun 2022, 10:11:30</p>	
GPS Location	See picture		GPS Location	See picture	
Field Station#	0000+00		Field Station#	0000+00	
Pic 5 Desc.	Secondary containment structure on north end of LY-045 in good condition.		Pic 6 Desc.	Perimeter ECD's on west side of LY-045 near employee parking area in good condition.	

A/E	124300139	Date/Time	6/24/2022 12:52 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





A/E	124300139	Date/Time	6/24/2022 12:52 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-603 Pipeline Spread I	AFE	124300139	Spread	H-603 Pipeline Spread I	
Contractor	Precision			Report #	39152	
Inspector	John White			Date/Time	6/24/2022 11:30 AM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	24+53	
County	Pittsylvania	Ground	Dry	Temperature (°F)	84.00	
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.10	
				Rain Accumulation Time (days)	4.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Rock Construction Entrance		Acceptable				
Sensitive Resource Buffer		Acceptable				
Silt Fence (Filter Fabric Fence)		Acceptable				
Sump Pit		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waterbar		Acceptable				
Waterbar End Treatment		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	6/24/2022 11:30 AM	Report #	39152
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/24/2022 11:30 AM	Report #	
Pictures					
West Elevation 85°E (T) 36°50'6"N, 79°20'23"W ±29ft ▲ 652ft  <small>Your Watermark 24 Jun 2022, 11:23:26</small>			South East Elevation 294°NW (T) 36°50'1"N, 79°20'15"W ±118ft ▲ 656ft  <small>Your Watermark 24 Jun 2022, 11:25:02</small>		
GPS Location	O		GPS Location	O	
Field Station#	14+00		Field Station#	22+00	
Pic 1 Desc.	Observing temporary stabilization,RCE,buffer and ECD's		Pic 2 Desc.	Observing temporary stabilization and buffer	
West Elevation 112°E (T) 36°50'7"N, 79°20'36"W ±176ft ▲ 646ft  <small>Your Watermark 24 Jun 2022, 11:27:29</small>			North Elevation 201°S (T) 36°50'5"N, 79°20'24"W ±59ft ▲ 654ft  <small>Your Watermark 24 Jun 2022, 11:27:35</small>		
GPS Location	O		GPS Location	O	
Field Station#	12+00		Field Station#	6+00	
Pic 3 Desc.	Observing temporary stabilization,water bar, sump and end treatment		Pic 4 Desc.	Observing temporary stabilization and water bar	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 5 Desc.			Pic 6 Desc.		

A/E	124300139	Date/Time	6/24/2022 11:30 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	6/24/2022 11:30 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	Transco Interconnect Station	AFE	124300113	Spread	Transco Interconnect Sta
Contractor	Kanahwa			Report #	38942
Inspector	John White			Date/Time	6/20/2022 12:36 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00
State	VA	Inspection Area	Full	Station End	00+00
County	Pittsylvania	Ground	Dry	Temperature (°F)	74.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	6.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Rock-lined Channel	Acceptable			
Sediment Filter Log	Acceptable			
Sediment Basin	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300113	Date/Time	6/20/2022 12:36 PM	Report #	38942
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on the Transco Facility and Lay down yard. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300113	Date/Time	6/20/2022 12:36 PM	Report #	
Pictures					
North East Elevation 219°SW (T) 36°50'7"N, 79°20'24"W ±141ft ▲660ft 			South Elevation 8°N (T) 36°50'5"N, 79°20'31"W ±820ft ▲675ft 		
GPS Location	O		GPS Location	O	
Field Station#	00+00		Field Station#	00+00	
Pic 1 Desc.	Observing RCE		Pic 2 Desc.	Observing temporary stabilization and rock check dams	
South West Elevation 67°NE (T) 36°50'3"N, 79°20'30"W ±2283ft ▲669ft 			South West Elevation 51°NE (T) 36°49'57"N, 79°20'36"W ±22ft ▲649ft 		
GPS Location	O		GPS Location	O	
Field Station#	00+00		Field Station#	00+00	
Pic 3 Desc.	Observing lay down yard		Pic 4 Desc.	Observing temporary stabilization and sediment basin	
South Elevation 9°N (T) 36°50'0"N, 79°20'36"W ±5223ft ▲667ft 			East Elevation 277°W (T) 36°49'57"N, 79°20'36"W ±10259ft ▲656ft 		
GPS Location	O		GPS Location	O	
Field Station#	00+00		Field Station#	00+00	
Pic 5 Desc.	Observing temporary stabilization, rock drain and ECD's		Pic 6 Desc.	Observing temporary stabilization, storm water pond and ECD's	

A/E	124300113	Date/Time	6/20/2022 12:36 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300113	Date/Time	6/20/2022 12:36 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	Transco Interconnect Station	AFE	124300113	Spread	Transco Interconnect Sta
Contractor	Kanahwa			Report #	39153
Inspector	John White			Date/Time	6/24/2022 12:25 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00
State	VA	Inspection Area	Full	Station End	00+00
County	Pittsylvania	Ground	Dry	Temperature (°F)	83.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	4.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Rock-lined Channel	Acceptable			
Rock Filter Outlet	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sediment Filter Log	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sediment Basin	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300113	Date/Time	6/24/2022 12:25 PM	Report #	39153
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on the Transco Facility and Lay down yard. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300113	Date/Time	6/24/2022 12:25 PM	Report #	
Pictures					
South East Elevation 294°NW (T) 36°50'7"N, 79°20'24"W ±13ft ▲ 656ft 			North East Elevation 226°SW (T) 36°50'1"N, 79°20'33"W ±6354ft ▲ 656ft 		
GPS Location	O		GPS Location	O	
Field Station#	00+00		Field Station#	00+00	
Pic 1 Desc.	Observing RCE		Pic 2 Desc.	Observing lay down yard	
North Elevation 171°S (T) 36°49'57"N, 79°20'36"W ±13ft ▲ 652ft 			North East Elevation 213°SW (T) 36°49'57"N, 79°20'36"W ±13ft ▲ 653ft 		
GPS Location	O		GPS Location	O	
Field Station#	00+00		Field Station#	00+00	
Pic 3 Desc.	Observing rock lined channel, temporary stabilization and CFS checks		Pic 4 Desc.	Observing temporary stabilization and sediment basin	
North West Elevation 151°SE (T) 36°49'59"N, 79°20'32"W ±262ft ▲ 668ft 			East Elevation 274°W (T) 36°49'53"N, 79°20'35"W ±52ft ▲ 650ft 		
GPS Location	O		GPS Location	O	
Field Station#	00+00		Field Station#	00+00	
Pic 5 Desc.	Observing temporary stabilization, outlet and outlet protection		Pic 6 Desc.	Observing temporary stabilization, storm water pond and ECD's	

A/E	124300113	Date/Time	6/24/2022 12:25 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300113	Date/Time	6/24/2022 12:25 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		