



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40219
Inspector	Patrick Shields			Date/Time	7/25/2022 10:14 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10749+92
State	VA	Inspection Area	Full	Station End	10798+92
County	Giles	Ground	Dry	Temperature (°F)	82.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00


1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Communication	See comments		
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/25/2022 10:14 AM	Report #	40219
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 10749+92 (Hendrickson) to ST# 10798+92 (Cascade) Accompanied by fellow EI Jared Saunders on VA SWPPP inspection of MP 203.6 to MP 204.53. Deficiencies found at the following station numbers: 10749+92 to 10798+92 Overseed this section of ROW. All issues have been communicated to PPL contractor via punch list Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. This section of ROW is temporarily stabilized with seed and mulch. Vegetation growth is present throughout section. Clean water diversion berms, pipes and level spreaders are in place. ECDs in place per E&S sheets. Sensitive resource buffers are in place at stream crossings S-G35, S-SS4, S-Z9, S-Z7 braid 1, and S-Z7 braid 2. Hendrickson, Big Branch Hollow, and Cascade Road crossing RCEs are maintained in acceptable condition. The ROW is dry and in stable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/25/2022 10:14 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	10784+00		Field Station#	10752+50	
Pic 1 Desc.	Dead grass and bare spots need Overseeded		Pic 2 Desc.	Waterbars in place	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	10758+50		Field Station#	10761+60	
Pic 3 Desc.	Stream buffer in place		Pic 4 Desc.	Stone inlet protection in place	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	10764+75		Field Station#	10765+85	
Pic 5 Desc.	Stream buffer in place		Pic 6 Desc.	Cleanwater diversion outlet protection in place	

AFE	124300137	Date/Time	7/25/2022 10:14 AM	Report #	
Pictures					
<p>Date & Time: Mon, Jul 25, 2022 08:52:12 EDT Position: +037.342338° / -080.628971° (+15.3ft) Altitude: 2210ft (+6.2ft) Datum: WGS-84 Azimuth/Bearing: 249°/58.7W 4391mils True (+12°) Elevation Grade: -022% Horizon Grade: +006% Zoom: 0.5X 10769+00</p> 		<p>Date & Time: Mon, Jul 25, 2022 08:53:43 EDT Position: +037.342253° / -080.628992° (+15.3ft) Altitude: 2140ft (+6.5ft) Datum: WGS-84 Azimuth/Bearing: 102°/4.4E 3101mils True (+12°) Elevation Grade: -012% Horizon Grade: +001% Zoom: 0.5X 10771+75</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10769+00	Field Station#	10771+75		
Pic 7 Desc.	CFS perimeter control in place	Pic 8 Desc.	Cleanwater diversion outlet protection in place		
<p>Date & Time: Mon, Jul 25, 2022 08:55:14 EDT Position: +037.344169° / -080.628643° (+17.7ft) Altitude: 2141ft (+6.7ft) Datum: WGS-84 Azimuth/Bearing: 077°/N77E 1369mils True (+12°) Elevation Grade: -030% Horizon Grade: -005% Zoom: 0.5X 10773+50</p> 		<p>Date & Time: Mon, Jul 25, 2022 08:57:26 EDT Position: +037.342338° / -080.627193° (+15.3ft) Altitude: 2141ft (+6.7ft) Datum: WGS-84 Azimuth/Bearing: 070°/N70E 1344mils True (+12°) Elevation Grade: -007% Horizon Grade: -012% Zoom: 0.5X 10775+50</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10773+50	Field Station#	10777+50		
Pic 9 Desc.	Stream buffer in place	Pic 10 Desc.	Cleanwater drainage feature in place		
<p>Date & Time: Mon, Jul 25, 2022 09:00:14 EDT Position: +037.342923° / -080.623335° (+29.8ft) Altitude: 1956ft (+5.9ft) Datum: WGS-84 Azimuth/Bearing: 054°/N54E 0960mils True (+12°) Elevation Grade: -004% Horizon Grade: -007% Zoom: 0.5X 10792+00</p> 		<p>Date & Time: Mon, Jul 25, 2022 09:00:58 EDT Position: +037.342923° / -080.621697° (+33.9ft) Altitude: 1935ft (+5.8ft) Datum: WGS-84 Azimuth/Bearing: 128°/S12E 3280mils True (+12°) Elevation Grade: -003% Horizon Grade: -003% Zoom: 0.5X 10798+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10792+00	Field Station#	10798+00		
Pic 11 Desc.	Cleanwater diversion berm in place	Pic 12 Desc.	RCE in place		

A/E	124300137	Date/Time	7/25/2022 10:14 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40229
Inspector	Clint Sears			Date/Time	7/25/2022 1:04 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10859+46
State	VA	Inspection Area	Partial	Station End	10929+80
County	Giles	Ground	Dry	Temperature (°F)	88.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/25/2022 1:04 PM	Report #	40229
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with Environmental staff. Completed VA SWPPP inspection from (MP 205.67 to MP 207 St#10859+46 to St#10929+80) No deficiencies were found at time of inspection. This section of Row has undergone temporary stabilization. All ECD's and BMPs are in acceptable condition. Vegetation/stabilization is sufficient. Sensitive resource buffers have abundant vegetation. No sensitive resources have been impacted. Row is dry and in stable condition. Participated in spread G conference call at 11:30.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/25/2022 1:04 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10887+50	Field Station#	10889+00		
Pic 1 Desc.	Plunge pool in place	Pic 2 Desc.	Section of Row showing conditions and controls		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10860+00	Field Station#	10893+75		
Pic 3 Desc.	Perimeter controls are in place and in acceptable condition	Pic 4 Desc.	Section of Row showing conditions and controls		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	108+94	Field Station#	10903+00		
Pic 5 Desc.	Section of Row showing conditions and controls	Pic 6 Desc.	Section of Row showing conditions and controls		

AFE	124300137	Date/Time	7/25/2022 1:04 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10916+50	Field Station#	10923+65		
Pic 7 Desc.	Section of Row showing conditions and controls	Pic 8 Desc.	Section of Row showing conditions and controls		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10927+81	Field Station#	10864+40		
Pic 9 Desc.	Section of Row showing conditions and controls at S-Y3	Pic 10 Desc.	CFS perimeter controls and level spreader are in acceptable condition		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10874+69	Field Station#	10880+25		
Pic 11 Desc.	Section of Row showing conditions and controls	Pic 12 Desc.	Daylight drain is in place		

A/E	124300137	Date/Time	7/25/2022 1:04 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40199
Inspector	Eric Hanlon			Date/Time	7/25/2022 6:48 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10655+00
State	VA	Inspection Area	Full	Station End	10749+92
County	Giles	Ground	Dry	Temperature (°F)	65.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)






E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Flume Pipe	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/25/2022 6:48 AM	Report #	40199
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection from ST# 10655+00 (MP 201.6) to ST# 10749+92 (MP 203.6). No Compliance issues noted: Observance: Crew 1704 was out stabilizing row working back to Hendrickson. Perimeter controls in place & functioning as designed. ROW has been temporary stabilized. No areas with open ditch. All other ECDs and BMPs functional at time of inspection. 50' buffers in place at stream crossings S-G33, S-G32, S-G30 and W-Z11. AR-240, 241.04, 241.01, 241, Hendrickson and Big Stony creek road crossing RCEs are maintained in acceptable condition. The ROW is dry and in stable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/25/2022 6:48 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10664+00	Field Station#	10679+39		
Pic 1 Desc.	Picture showing condition of row	Pic 2 Desc.	Equipment bridge functional		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10693+00	Field Station#	10694+00		
Pic 3 Desc.	Perimeter controls in place & level spreader	Pic 4 Desc.	Resource buffers in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10698+00	Field Station#	10705+00		
Pic 5 Desc.	Wattles and P1 in place	Pic 6 Desc.	Water bars and end treatment in place		

A/E	124300137	Date/Time	7/25/2022 6:48 AM	Report #	
Pictures					
 <p><small>Date & Time: Mon, Jul 25, 2022, 08:25:54 EDT Position: +037.346505° / -080.641445° (±29.8m) Altitude: 2324ft (±52.8m) Datum: WGS-84 Azimuth/Bearing: 297° N41W 10.0mils True (±13°) Elevation Angle: -39.4° Horizon Angle: +04.6° Zoom: 0.5X 10733+18</small></p>		 <p><small>Date & Time: Mon, Jul 25, 2022, 08:15:42 EDT Position: +037.345542° / -080.638849° (±19.1m) Altitude: 2319ft (±11.7m) Datum: WGS-84 Azimuth/Bearing: 305° N55W 9.2mils True (±15°) Elevation Angle: -46.2° Horizon Angle: +04.2° Zoom: 0.5X 10744+60</small></p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10733+18	Field Station#	10744+60		
Pic 7 Desc.	Picture showing condition of row	Pic 8 Desc.	Equipment bridge functional		
 <p><small>Date & Time: Mon, Jul 25, 2022, 08:16:22 EDT Position: +037.344797° / -080.636300° (±14.0m) Altitude: 2315ft (±16.4m) Datum: WGS-84 Azimuth/Bearing: 123° S57E 10.0mils True (±10°) Elevation Angle: -12.8° Horizon Angle: +03.4° Zoom: 0.5X 10749+00</small></p>		 <p><small>Date & Time: Mon, Jul 25, 2022, 08:16:16 EDT Position: +037.344917° / -080.636286° (±17.8m) Altitude: 2300ft (±16.3m) Datum: WGS-84 Azimuth/Bearing: 317° N43W 5.3mils True (±20°) Elevation Angle: -08.5° Horizon Angle: +01.2° Zoom: 0.5X 10746+00</small></p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10749+00	Field Station#	10746+00		
Pic 9 Desc.	RCE functional	Pic 10 Desc.	Crew 1704 stabilizing row		
 <p><small>Date & Time: Mon, Jul 25, 2022, 08:21:39 EDT Position: +037.345720° / -080.639285° (±11.5m) Altitude: 2348ft (±13.1m) Datum: WGS-84 Azimuth/Bearing: 127° S53E 2.0mils True (±10°) Elevation Angle: -49.3° Horizon Angle: -02.0° Zoom: 0.5X 10740+00</small></p>		<p style="text-align: center;">Insert image here</p>			
GPS Location	See photo	GPS Location			
Field Station#	10740+00	Field Station#			
Pic 11 Desc.	Picture showing condition of row	Pic 12 Desc.			

A/E	124300137	Date/Time	7/25/2022 6:48 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40202
Inspector	Chris Burns			Date/Time	7/25/2022 7:38 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10798+92
State	VA	Inspection Area	Partial	Station End	10859+46
County	Giles	Ground	Dry	Temperature (°F)	78.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)






E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/25/2022 7:38 AM	Report #	40202
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Discussed RoW/ECD conditions, within this section, with fellow EI Joe Sweeden. Performed SWPPP inspection from MP 204.53 (10798+92) and MP 205.67 (10859+46). Accompanied by fellow EI Joe Sweeden. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		7/25/2022 7:38 AM		Report #							
Pictures															
															
GPS Location				1				GPS Location				2			
Field Station#				10859+00				Field Station#				10856+04			
Pic 1 Desc.				Section of RoW showing conditions and controls.				Pic 2 Desc.				S-A33.			
															
GPS Location				3				GPS Location				4			
Field Station#				10854+70				Field Station#				10847+00			
Pic 3 Desc.				S-A34.				Pic 4 Desc.				CWDP outlet protection functional.			
															
GPS Location				5				GPS Location				6			
Field Station#				10840+00				Field Station#				10834+00			
Pic 5 Desc.				Section of RoW showing conditions and controls.				Pic 6 Desc.				Section of RoW showing conditions and controls.			

AFE	124300137	Date/Time	7/25/2022 7:38 AM	Report #	
Pictures					
					
GPS Location	7	GPS Location	8		
Field Station#	10818+00	Field Station#	10809+04		
Pic 7 Desc.	Section of RoW showing conditions and controls.		Pic 8 Desc.	S-Z14.	
					
GPS Location	9	GPS Location	10		
Field Station#	10804+00	Field Station#	10799+00		
Pic 9 Desc.	Section of RoW showing conditions and controls.		Pic 10 Desc.	S-Z10/W-Z3.	
		Insert image here			
GPS Location	11	GPS Location			
Field Station#	10801+52	Field Station#			
Pic 11 Desc.	S-Z11/S-Z12/S-Z13.		Pic 12 Desc.		

A/E	124300137	Date/Time	7/25/2022 7:38 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40288
Inspector	Patrick Shields			Date/Time	7/26/2022 12:31 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10929+80
State	VA	Inspection Area	Full	Station End	11023+80
County	Giles	Ground	Wet	Temperature (°F)	75.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.20
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	7/26/2022 12:31 PM	Report #	40288
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 10929+80 (Doe Creek Road) to ST# 11023+80 (Access Road 244) Accompanied by fellow EI Jared Saunders on VA SWPPP inspection of MP 207 to MP 208.78. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. ST#s 10929+80 to 10940+25 and 10961+75 to 11023+80 have undergone temporary stabilization with seed and mulch. Minor vegetation growth is present throughout section. Clean water diversion berms, pipes and level spreaders are in place. ECDs in place per E&S sheets. The ROW is permanently stabilized from ST# 10940+25 to ST# 10961+75. Area is stabilized with seed and mulch. Vegetation growth is present. CFS in place to minimize rilling and maintain sheet flow. Sensitive resource buffers are in place at streams S-PA07, S-RR5, S-E24, and S-E25. Triple barrier protection around karst feature located at station number 10966+00. RCEs in place and maintained at Doe Creek Road crossing, Access Road 244, and Access Road 241.02. The ROW is wet and in stable condition. No sensitive resources have been impacted. Brickyard rain gauge measured 0.2" of accumulated rainfall.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/26/2022 12:31 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10930+40	Field Station#	10939+00		
Pic 1 Desc.	RCE in place	Pic 2 Desc.	P1 silt fence perimeter control in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10946+00	Field Station#	10961+00		
Pic 3 Desc.	Permanent vegetation present	Pic 4 Desc.	CFS triple stack perimeter control in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10963+25	Field Station#	10966+85		
Pic 5 Desc.	Cleanwater diversion outlet protection in place	Pic 6 Desc.	Triple protection ECDs in place at karst feature		

AFE	124300137	Date/Time	7/26/2022 12:31 PM	Report #	
Pictures					
<p>Date & Time: Tue, Jul 26, 2022, 09:44:13 EDT Position: +437.225766° / -880.545618° (±25.8m) Altitude: 2354ft (±6.5ft) Datum: WGS-84 Azimuth/Bearing: 174° S06E 300° (±11°) Elevation Grade: -0.53% Horizon Grade: -0.09% Zoom: 0.5X 10972+00</p> 		<p>Date & Time: Tue, Jul 26, 2022, 09:44:40 EDT Position: +437.225766° / -880.545618° (±25.8m) Altitude: 2354ft (±6.5ft) Datum: WGS-84 Azimuth/Bearing: 092° S08E 100° (±11°) Elevation Grade: -0.18% Horizon Grade: -0.05% Zoom: 0.5X 10974+75</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10972+00	Field Station#	10976+75		
Pic 7 Desc.	CFS triple stack perimeter control in place	Pic 8 Desc.	Cleanwater drainage features in place		
<p>Date & Time: Tue, Jul 26, 2022, 09:44:28 EDT Position: +437.225766° / -880.545618° (±25.8m) Altitude: 2354ft (±6.5ft) Datum: WGS-84 Azimuth/Bearing: 185° S06W 328° (±11°) Elevation Grade: -0.53% Horizon Grade: -0.06% Zoom: 0.5X 10984+75</p> 		<p>Date & Time: Tue, Jul 26, 2022, 09:45:00 EDT Position: +437.225766° / -880.545618° (±25.8m) Altitude: 2354ft (±6.5ft) Datum: WGS-84 Azimuth/Bearing: 185° S06W 328° (±11°) Elevation Grade: -0.53% Horizon Grade: -0.06% Zoom: 0.5X 10994+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10984+75	Field Station#	10994+00		
Pic 9 Desc.	Cleanwater diversion outlet protection in place	Pic 10 Desc.	P1 silt fence perimeter control in place		
<p>Date & Time: Tue, Jul 26, 2022, 09:45:45 EDT Position: +437.225766° / -880.545618° (±25.8m) Altitude: 2354ft (±6.5ft) Datum: WGS-84 Azimuth/Bearing: 021° N04W 570° (±12°) Elevation Grade: -0.12% Horizon Grade: -0.01% Zoom: 0.5X 11004+00</p> 		<p>Date & Time: Tue, Jul 26, 2022, 09:46:25 EDT Position: +437.225766° / -880.545618° (±25.8m) Altitude: 2354ft (±6.5ft) Datum: WGS-84 Azimuth/Bearing: 012° N04W 570° (±12°) Elevation Grade: -0.00% Horizon Grade: -0.00% Zoom: 0.5X 11014+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11004+00	Field Station#	11016+00		
Pic 11 Desc.	Cleanwater diversion berm in place	Pic 12 Desc.	Stream buffer in place		

A/E	124300137	Date/Time	7/26/2022 12:31 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40290
Inspector	Clint Sears			Date/Time	7/26/2022 12:55 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+80
State	VA	Inspection Area	Partial	Station End	11098+47
County	Giles	Ground	Wet	Temperature (°F)	78.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.20
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Waterbar	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	7/26/2022 12:55 PM	Report #	40290
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with Environmental staff. Completed VA SWPPP Inspection from Mp 208.78 to MP 210.2 St#11023+80 to St#11098+47. A portion of this section of Row has undergone permanent restoration and has abundant vegetation. Other sections have been temporarily stabilized. All ECD's and BMP's are in acceptable condition. Vegetation/stabilization are sufficient. Karst ECD's are in place and in acceptable condition. Sensitive resource buffer zones have abundant vegetation. Row is wet and in stable condition. AR244,245.02 and RCE are in acceptable condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/26/2022 12:55 PM	Report #	
Pictures					
<p>Date & Time: Tue, Jul 26, 2022, 10:09:59 EDT Position: +037 213275+ / +080 55353+ (+9997 7ft) Altitude: 2077ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 116° S34E 2062mils True (±12°) Elevation Angle: -15.6° Horizon Angle: +02.7° Zoom: 1.0x 11095+00</p> 		<p>Date & Time: Tue, Jul 26, 2022, 10:08:59 EDT Position: +037 311419+ / +080 553543+ (+9997 7ft) Altitude: 2114ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 147° S33E 2613mils True (±12°) Elevation Angle: -22.2° Horizon Angle: +01.6° Zoom: 1.0x 11082+50</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11095+00	Field Station#	11082+50		
Pic 1 Desc.	Section of Row showing conditions and controls	Pic 2 Desc.	Section of Row showing conditions and controls		
<p>Date & Time: Tue, Jul 26, 2022, 09:55:39 EDT Position: +037 311419+ / +080 553543+ (+9997 7ft) Altitude: 2197ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 100° S65E 1776mils True (±12°) Elevation Angle: -03.5° Horizon Angle: +03.1° Zoom: 1.0x 11079+00</p> 		<p>Date & Time: Tue, Jul 26, 2022, 09:55:39 EDT Position: +037 311419+ / +080 553543+ (+9997 7ft) Altitude: 2264ft (+21.3ft) Datum: WGS-84 Azimuth/Bearing: 276° N84W 4907mils True (±12°) Elevation Angle: -10.1° Horizon Angle: +03.1° Zoom: 1.0x 11076+50</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11079+00	Field Station#	11076+50		
Pic 3 Desc.	Permanently restored section of Row	Pic 4 Desc.	Section of Row showing conditions and controls		
<p>Date & Time: Tue, Jul 26, 2022, 09:54:01 EDT Position: +037 213275+ / +080 55353+ (+9997 7ft) Altitude: 2197ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 086° N85E 1511mils True (±12°) Elevation Angle: -02.5° Horizon Angle: +05.1° Zoom: 1.0x 11059+00</p> 		<p>Date & Time: Tue, Jul 26, 2022, 09:51:17 EDT Position: +037 213275+ / +080 55353+ (+9997 7ft) Altitude: 2184ft (+29.8ft) Datum: WGS-84 Azimuth/Bearing: 109° S71E 1938mils True (±12°) Elevation Angle: -18.3° Horizon Angle: +00.1° Zoom: 1.0x 11065+21</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11059+81	Field Station#	11065+21		
Pic 5 Desc.	Section of Row showing conditions and controls	Pic 6 Desc.	Section of Row showing conditions and controls		

AFE 124300137		Date/Time	7/26/2022 12:55 PM	Report #	
Pictures					
<p>Date & Time: Tue, Jul 26, 2022, 09:31:23 EDT Position: +037.318381° / -080.647442° (+145.7ft) Altitude: 2107ft (+58.6ft) Datum: WGS-84 Azimuth/Bearing: 189° S08W 3342mils True (+12°) Elevation Angle: +31.9° Horizon Angle: -01.5° Zoom: 1.0X 11050+14 S-IJ16B</p> 		<p>Date & Time: Tue, Jul 26, 2022, 09:36:29 EDT Position: +037.318382° / -080.638197° (+140.8ft) Altitude: 2108ft (+58.9ft) Datum: WGS-84 Azimuth/Bearing: 181° S08W 3311mils True (+12°) Elevation Angle: +31.9° Horizon Angle: -01.3° Zoom: 1.0X 11045+00</p> 			
GPS Location		See photo		GPS Location	
Field Station#		11050+14		Field Station#	
Pic 7 Desc.		S-IJ16B looking downstream		Pic 8 Desc.	
				Section of Row showing conditions and controls	
<p>Date & Time: Tue, Jul 26, 2022, 09:18:11 EDT Position: +037.312071° / -080.551240° (+142.0ft) Altitude: 2320ft (+69.3ft) Datum: WGS-84 Azimuth/Bearing: 178° S04E 3129mils True (+12°) Elevation Angle: +02.2° Horizon Angle: -00.2° Zoom: 1.0X 11035+06</p> 		<p>Date & Time: Tue, Jul 26, 2022, 09:15:04 EDT Position: +037.312071° / -080.551240° (+142.0ft) Altitude: 2320ft (+69.3ft) Datum: WGS-84 Azimuth/Bearing: 192° S22W 3413mils True (+12°) Elevation Angle: +02.9° Horizon Angle: -01.2° Zoom: 1.0X 11031+08</p> 			
GPS Location		See photo		GPS Location	
Field Station#		11035+06		Field Station#	
Pic 9 Desc.		Section of Row showing conditions and controls		Pic 10 Desc.	
				Slope drain pipe and perimeter controls are in acceptable condition	
<p>Date & Time: Tue, Jul 26, 2022, 08:54:59 EDT Position: +037.262255° / -080.645515° (+140.8ft) Altitude: 2329ft (+69.3ft) Datum: WGS-84 Azimuth/Bearing: 085° N85E 1511mils True (+14°) Elevation Angle: -03.3° Horizon Angle: -00.7° Zoom: 1.0X 5-IJ18 11025+54</p> 		<p>Date & Time: Tue, Jul 26, 2022, 08:59:26 EDT Position: +037.312684° / -080.533430° (+138.8ft) Altitude: 1936ft (+46.6ft) Datum: WGS-84 Azimuth/Bearing: 152° S28E 2702mils True (+14°) Elevation Angle: -09.4° Horizon Angle: -00.2° Zoom: 1.0X 11098+47</p> 			
GPS Location		See photo		GPS Location	
Field Station#		11024+54		Field Station#	
Pic 11 Desc.		Section of Row showing conditions and controls at S-IJ18		Pic 12 Desc.	
				RCE and AR245.02 are maintained in acceptable condition	

A/E	124300137	Date/Time	7/26/2022 12:55 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40263
Inspector	Eric Hanlon			Date/Time	7/26/2022 6:42 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11184+85
State	VA	Inspection Area	Partial	Station End	11254+99
County	Giles	Ground	Wet	Temperature (°F)	70.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Berm	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/26/2022 6:42 AM	Report #	40263
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection from ST# 11184+85 (MP 210.0) to ST# 11254+99 (MP 213.6). No Compliance issues noted: Observance: Perimeter controls in place Permanent & temporary stabilization in place. - Permanent waterbars (other) and level spreaders are installed as per the approved plan and are functioning as designed. The row has been final stabilized from 11184+85 to near station 11222+50. @11222+50 to 11206+27 the stabilization is thin and is being monitored. - Temporary stabilization near 11222+50 to near 11253+50. This section of row has been stabilized. There are temporary ECDs (water bars, TSDP, P1 silt fencing, CFS, and CC4 ECB that all appear to function according to design. AR-249.02 & 244 RCE's are maintained in acceptable condition. Some subsidence between winding way and AR 249.02 we are monitoring it. The ROW is wet and in stable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/26/2022 6:42 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11253+00	Field Station#	11249+00		
Pic 1 Desc.	SSF functional	Pic 2 Desc.	Erosion control blanket in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11233+00	Field Station#	11245+00		
Pic 3 Desc.	Picture showing condition of row	Pic 4 Desc.	Water bars and end treatments in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11218+00	Field Station#	11205+89		
Pic 5 Desc.	Subsidence being monitored	Pic 6 Desc.	Stabilization thin being monitored		

AFE	124300137	Date/Time	7/26/2022 6:42 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11203+00		Field Station#	11196+00	
Pic 7 Desc.	Picture showing condition of row		Pic 8 Desc.	Perimeter controls in place	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11191+00		Field Station#	11190+00	
Pic 9 Desc.	Clean water drainage feature in place		Pic 10 Desc.	Permanent water bars and level spreader in place	
				Insert image here	
GPS Location	See photo		GPS Location		
Field Station#	11184+85		Field Station#		
Pic 11 Desc.	Rock check dams in place		Pic 12 Desc.		

A/E	124300137	Date/Time	7/26/2022 6:42 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40268
Inspector	Chris Burns			Date/Time	7/26/2022 8:16 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11098+47
State	VA	Inspection Area	Partial	Station End	11184+85
County	Giles	Ground	Damp	Temperature (°F)	76.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	1.00



1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)




E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/26/2022 8:16 AM	Report #	40268
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Discussed RoW/ECD conditions, within this section, with fellow EI Joe Sweeden. Performed SWPPP inspection from MP 210.2 (11098+47) and MP 211.83 (11184+85). Accompanied by fellow EI Joe Sweeden. This section of RoW is partially restored. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Section 6 - other (waterbars) Assessed AR 245.02.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/26/2022 8:16 AM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11104+00	Field Station#	11117+00		
Pic 1 Desc.	Section of restored RoW showing conditions and controls.	Pic 2 Desc.	Section of restored RoW showing conditions and controls.		
					
GPS Location	3	GPS Location	4		
Field Station#	11128+50	Field Station#	11139+25		
Pic 3 Desc.	Section of restored RoW showing conditions and controls.	Pic 4 Desc.	Section of restored RoW showing conditions and controls.		
					
GPS Location	5	GPS Location	6		
Field Station#	11151+00	Field Station#	11158+68		
Pic 5 Desc.	Section of RoW showing conditions and controls.	Pic 6 Desc.	S-NN17.		

AFE	124300137	Date/Time	7/26/2022 8:16 AM	Report #	
Pictures					
 <p><small>Date & Time: Tue, Jul 26, 2022, 09:05:45 EDT Position: 2024534.872 N / 2621007.826 E (±15.17) Altitude: 10880 (±14.20) Datum: WGS-84 Azimuth Bearing: 332° N35W 5778mils True (±12°) Elevation Angle: -0.9° Horizon Angle: +0.0° Zoom: 0.5X 11167+50</small></p>		 <p><small>Date & Time: Tue, Jul 26, 2022, 09:05:45 EDT Position: 2024516.880 N / 2621024.020 N (±14.00) Altitude: 10856 (±15.20) Datum: WGS-84 Azimuth Bearing: 180° S97E 1088mils True (±13°) Elevation Angle: -0.5° Horizon Angle: -0.1° Zoom: 0.5X 11176+00</small></p>			
GPS Location	7	GPS Location	8		
Field Station#	11167+50	Field Station#	11176+00		
Pic 7 Desc.	CWDP outlet protection functional.		Pic 8 Desc.	Section of restored RoW showing conditions and controls.	
 <p><small>Date & Time: Tue, Jul 26, 2022, 09:09:02 EDT Position: 2040804.781 E / 2519303.601 N (±18.20) Altitude: 1782ft (±11.5ft) Datum: WGS-84 Azimuth Bearing: 234° S54W 4160mils True (±12°) Elevation Angle: -23.2° Horizon Angle: +05.0° Zoom: 0.5X 11184+00</small></p>		 <p><small>Date & Time: Tue, Jul 26, 2022, 10:00:23 EDT Position: 2040804.781 E / 2519303.601 N (±18.20) Altitude: 1782ft (±11.5ft) Datum: WGS-84 Azimuth Bearing: 105° S75E 1867mils True (±10°) Elevation Angle: +02.1° Horizon Angle: -04.5° Zoom: 0.5X 11098+43</small></p>			
GPS Location	9	GPS Location	10		
Field Station#	11184+00	Field Station#	11098+43		
Pic 9 Desc.	Representative photo of permanent waterbar and level spreaders installed.		Pic 10 Desc.	AR 245.02.	
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	7/26/2022 8:16 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40345
Inspector	Patrick Shields			Date/Time	7/27/2022 10:47 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11471+56
State	VA	Inspection Area	Full	Station End	11524+16
County	Giles	Ground	Wet	Temperature (°F)	74.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.70
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Filter Fabric Fence)	Communication	See comments		
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/27/2022 10:47 AM	Report #	40345
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>Completed VA SWPPP inspection from ST# 11471+56 (Steele Acres) to ST# 11524+16 (AR-258.02) Accompanied by fellow EI Jared Saunders on SWPPP inspection of MP 217.26 to MP 218.26 Deficiencies found at the following station numbers: 11505+90 to 11507+65 Repair multiple broken stakes and holes in P1 silt fence perimeter control damaged by livestock. All issues have been communicated to PPL contractor via punch list Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. This section of ROW has undergone temporary stabilization. Topsoil stock piles and cleanwater diversion berms have been stabilized. Slope drains with stone inlet protection, Perimeter controls, and waterbars with end treatments are in place. Triple protection ECDs are in place at karst feature. Sensitive resource buffers are in place at stream crossings S-PP3, and S-PP4. AR-258.01, 258.02, and Stever's Gap road crossing RCEs are maintained in acceptable condition. The ROW is wet and in stable condition. No sensitive resources have been impacted. Steele Acres rain gauge measured 0.7" of accumulated rainfall.</p>					
<p>Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.</p>					

AFE	124300137	Date/Time	7/27/2022 10:47 AM	Report #	
Pictures					
<p>Date & Time Wed Jul 27, 2022, 05:04:01 EDT Position: +037.922742° / -80.494007° (±3.00') Altitude: 2210ft (±3.00') Datum: WGS-84 Azimuth/Bearing: 322° S42W 394mils True (±12°) Elevation Grade: -04% Horizon Grade: +00% Zoom: 0.5X 11472+25</p> 		<p>Date & Time Wed Jul 27, 2022, 05:04:01 EDT Position: +037.922742° / -80.494007° (±3.00') Altitude: 2107ft (±3.00') Datum: WGS-84 Azimuth/Bearing: 194° S14W 344mils True (±12°) Elevation Grade: -03% Horizon Grade: +00% Zoom: 0.5X 11472+25</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11507+65	Field Station#	11472+25		
Pic 1 Desc.	Multiple holes and broken stakes in P1 silt fence perimeter control	Pic 2 Desc.	Triple protection ECDs in place at karst feature		
<p>Date & Time Wed Jul 27, 2022, 05:15:44 EDT Position: +037.922742° / -80.494007° (±3.00') Altitude: 2275ft (±3.00') Datum: WGS-84 Azimuth/Bearing: 222° S42W 394mils True (±12°) Elevation Grade: -04% Horizon Grade: +010% Zoom: 0.5X 11476+75</p> 		<p>Date & Time Wed Jul 27, 2022, 05:11:09 EDT Position: +037.922742° / -80.494007° (±3.00') Altitude: 2244ft (±3.00') Datum: WGS-84 Azimuth/Bearing: 122° S12W 363mils True (±12°) Elevation Grade: -01% Horizon Grade: +00% Zoom: 0.5X 11477+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11476+75	Field Station#	11477+00		
Pic 3 Desc.	Stone inlet protection in place	Pic 4 Desc.	Supersilt fence perimeter control in place		
<p>Date & Time Wed Jul 27, 2022, 05:16:55 EDT Position: +037.922742° / -80.494007° (±3.00') Altitude: 2230ft (±3.00') Datum: WGS-84 Azimuth/Bearing: 330° S30W 444mils True (±12°) Elevation Grade: -01% Horizon Grade: +00% Zoom: 0.5X 11479+00</p> 		<p>Date & Time Wed Jul 27, 2022, 05:16:55 EDT Position: +037.922742° / -80.494007° (±3.00') Altitude: 2180ft (±3.00') Datum: WGS-84 Azimuth/Bearing: 330° S30W 444mils True (±12°) Elevation Grade: -01% Horizon Grade: +00% Zoom: 0.5X 11488+85</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11479+00	Field Station#	11488+85		
Pic 5 Desc.	Cleanwater drainage feature in place	Pic 6 Desc.	Plunge pool in place		

AFE	124300137	Date/Time	7/27/2022 10:47 AM	Report #	
Pictures					
<p>Date & Time: Wed, Jul 27, 2022, 09:54:07 EDT Position: +487.23554° / -86.42544° (±37.40) Altitude: 2260 (±3.40) Datum: WGS-84 Azimuth/Bearing: 238° 325W 3566mils True (±12°) Elevation Grade: -003% Horizon Grade: -003% Zoom: 0.5X 11495+00</p> 		<p>Date & Time: Wed, Jul 27, 2022, 09:54:07 EDT Position: +487.23554° / -86.42544° (±37.40) Altitude: 2260 (±3.40) Datum: WGS-84 Azimuth/Bearing: 238° 325W 3566mils True (±12°) Elevation Grade: -003% Horizon Grade: -003% Zoom: 0.5X 11495+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11490+25	Field Station#	11496+00		
Pic 7 Desc.	RCE in place	Pic 8 Desc.	CFS perimeter control in place		
<p>Date & Time: Wed, Jul 27, 2022, 09:54:07 EDT Position: +487.23554° / -86.42544° (±37.40) Altitude: 2260 (±3.40) Datum: WGS-84 Azimuth/Bearing: 090° 180W 1400mils True (±12°) Elevation Grade: -003% Horizon Grade: -003% Zoom: 0.5X 11503+50</p> 		<p>Date & Time: Wed, Jul 27, 2022, 09:54:07 EDT Position: +487.23554° / -86.42544° (±37.40) Altitude: 2260 (±3.40) Datum: WGS-84 Azimuth/Bearing: 238° 325W 3566mils True (±12°) Elevation Grade: -011% Horizon Grade: -008% Zoom: 1.0X 11507+50</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11503+50	Field Station#	11507+50		
Pic 9 Desc.	Cleanwater diversion berm in place	Pic 10 Desc.	Stream buffer in place		
<p>Date & Time: Wed, Jul 27, 2022, 09:54:07 EDT Position: +487.237834° / -86.423512° (±37.40) Altitude: 2262 (±3.40) Datum: WGS-84 Azimuth/Bearing: 238° 325W 3566mils True (±12°) Elevation Grade: -003% Horizon Grade: -003% Zoom: 0.5X 11513+50</p> 		<p>Date & Time: Wed, Jul 27, 2022, 09:54:07 EDT Position: +487.23554° / -86.42544° (±37.40) Altitude: 2260 (±3.40) Datum: WGS-84 Azimuth/Bearing: 238° 325W 3566mils True (±12°) Elevation Grade: -011% Horizon Grade: -008% Zoom: 0.5X 11518+75</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11513+50	Field Station#	11518+75		
Pic 11 Desc.	Stone inlet protection in place	Pic 12 Desc.	Stream buffer in place		

A/E	124300137	Date/Time	7/27/2022 10:47 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40344
Inspector	Clint Sears			Date/Time	7/27/2022 10:49 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+99
State	VA	Inspection Area	Partial	Station End	11353+67
County	Giles	Ground	Wet	Temperature (°F)	79.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	7.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)






E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	See punch list		
Erosion Control Blanket	Acceptable			
Equipment Bridge	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/27/2022 10:49 AM	Report #	40344
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with Environmental staff. Completed VA SWPPP inspection from MP213.6 to MP 215.04 St#11254+99 to St#11353+67 Deficiencies found at the following station number. St#11298+08 P1 Damaged along AR253.02 All deficiencies were communicated to PPL personnel via punch list. Crews began to replace damaged P1 before the end of the day. This section of Row has undergone temporary vegetation/stabilization. All other ECD'S and BMP's were in acceptable condition. Completed inspection during light to heavy rain. No sensitive resource have been impacted. Row is wet and in stable condition. Assessed AR256.02 broad based dips and P1 checks were in acceptable condition at time of inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/27/2022 10:49 AM	Report #	
Pictures					
 <p>Date & Time: Wed Jul 27, 2022, 09:59:11 EDT Position: -037.333417 / -080.480691 (-54532.9ft) Altitude: 2162ft (+33.3ft) Datum: WGS-84 Azimuth/Bearing: 123.507E 307.6mils True (+12°) Elevation Angle: -04.7 Horizon Angle: -01.2 Zoom: 1.0x 11329+42</p>		 <p>Date & Time: Wed Jul 27, 2022, 09:59:55 EDT Position: -037.333417 / -080.480691 (-54532.9ft) Altitude: 2088ft (+4.4ft) Datum: WGS-84 Azimuth/Bearing: 205.529W 337.6mils True (+12°) Elevation Angle: -23.3 Horizon Angle: -01.8 Zoom: 1.0x 11298+08</p>		GPS Location	See photo
Field Station#	11329+42	Field Station#	11298+08	GPS Location	See photo
Pic 1 Desc.	Perimeter controls are in place	Pic 2 Desc.	Damaged P1	GPS Location	See photo
 <p>Date & Time: Wed Jul 27, 2022, 09:20:18 EDT Position: -037.295973 / -080.481815 (-53051.0ft) Altitude: 2114ft (+26.7ft) Datum: WGS-84 Azimuth/Bearing: 131.549E 232.9mils True (+12°) Elevation Angle: -09.7 Horizon Angle: -00.6 Zoom: 1.0x 11292+80</p>		 <p>Date & Time: Wed Jul 27, 2022, 09:22:19 EDT Position: -037.295973 / -080.480181 (-54779.0ft) Altitude: 2155ft (+29.9ft) Datum: WGS-84 Azimuth/Bearing: 272.188W 483.6mils True (+12°) Elevation Angle: -12.7 Horizon Angle: -01.4 Zoom: 1.0x 11296+20</p>		GPS Location	See photo
Field Station#	11292+80	Field Station#	11296+20	GPS Location	See photo
Pic 3 Desc.	Conditions and controls at S-MM18 looking upstream	Pic 4 Desc.	Overview of conditions and controls at S-MM18	GPS Location	See photo
 <p>Date & Time: Wed Jul 27, 2022, 09:16:36 EDT Position: -037.295973 / -080.483331 (-53833.0ft) Altitude: 2283ft (+31.3ft) Datum: WGS-84 Azimuth/Bearing: 076.176E 135.1mils True (+13°) Elevation Angle: -17.0 Horizon Angle: -02.7 Zoom: 1.0x 11283+75</p>		 <p>Date & Time: Wed Jul 27, 2022, 09:13:09 EDT Position: -037.295973 / -080.485551 (-5302.2ft) Altitude: 2204ft (+23.1ft) Datum: WGS-84 Azimuth/Bearing: 202.522W 359.1mils True (+12°) Elevation Angle: -32.6 Horizon Angle: -00.3 Zoom: 1.0x 11281+00</p>		GPS Location	See photo
Field Station#	11283+75	Field Station#	11281+00	GPS Location	See photo
Pic 5 Desc.	Section of Row showing conditions and controls	Pic 6 Desc.	Slope drain pipe, sump pit and perimeter controls	GPS Location	See photo

AFE	124300137	Date/Time	7/27/2022 10:49 AM	Report #	
Pictures					
 <p>Date & Time: Wed Jul 27, 2022 09:07:42 EDT Position: +037.298257° / -080.491996° (+3240.7ft) Altitude: 2240ft (+28.1ft) Datum: WGS-84 Azimuth/Bearing: 178° S02E 3164mils True (+13°) Elevation Angle: -02.9° Horizon Angle: -00.3° Zoom: 1.0X 11272+00</p>		 <p>Date & Time: Wed Jul 27, 2022 09:05:49 EDT Position: +037.298257° / -080.491996° (+3240.7ft) Altitude: 2229ft (+26.74ft) Datum: WGS-84 Azimuth/Bearing: 191° S11W 3396mils True (+13°) Elevation Angle: -04.9° Horizon Angle: -01.4° Zoom: 1.0X 11268+00</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11272+00	Field Station#	11268+00		
Pic 7 Desc.	Plunge pool and Perimeter controls are in acceptable condition	Pic 8 Desc.	Temporary vegetation/stabilization		
 <p>Date & Time: Wed Jul 27, 2022 09:57:24 EDT Position: +037.301259° / -080.446412° (+3245.9ft) Altitude: 2160ft (+20.32ft) Datum: WGS-84 Azimuth/Bearing: 230° S50W 4089mils True (+12°) Elevation Angle: -02.9° Horizon Angle: -00.0° Zoom: 1.0X 11329+42</p>		 <p>Date & Time: Wed Jul 27, 2022 09:58:29 EDT Position: +037.299047° / -080.444043° (+3200.2ft) Altitude: 1990ft (+20.4ft) Datum: WGS-84 Azimuth/Bearing: 201° N79W 4494mils True (+12°) Elevation Angle: -24.5° Horizon Angle: -00.3° Zoom: 1.0X 11257+00</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11329+42	Field Station#	11257+00		
Pic 9 Desc.	AR256.02	Pic 10 Desc.	CFS perimeter controls and SSF are in acceptable condition		
 <p>Date & Time: Wed Jul 27, 2022 09:48:53 EDT Position: +037.305408° / -080.467228° (+3193.3ft) Altitude: 2004ft (+20.0ft) Datum: WGS-84 Azimuth/Bearing: 339° N23W 5991mils True (+12°) Elevation Angle: -23.9° Horizon Angle: -00.7° Zoom: 1.0X 11352+97</p>		 <p>Date & Time: Wed Jul 27, 2022 09:56:39 EDT Position: +037.305597° / -080.470597° (+3200.3ft) Altitude: 2136ft (+20.8ft) Datum: WGS-84 Azimuth/Bearing: 306° S33W 4729mils True (+17°) Elevation Angle: -09.6° Horizon Angle: -00.6° Zoom: 1.0X 11330+00</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11352+97	Field Station#	11330+00		
Pic 11 Desc.	Looking downstream at S-NN11	Pic 12 Desc.	Section of Row showing conditions and controls at S-NN12		

A/E	124300137	Date/Time	7/27/2022 10:49 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40329
Inspector	Chris Burns			Date/Time	7/27/2022 7:52 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11353+67
State	VA	Inspection Area	Partial	Station End	11471+56
County	Giles	Ground	Wet	Temperature (°F)	77.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.70
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/27/2022 7:52 AM	Report #	40329
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 215.04 (11353+67) and MP 217.26 (11471+56). Accompanied by fellow EI Joe Sweeden. Inspection completed during ongoing rain event. Continued rainfall may result in issues identified in future inspection. This section of RoW is partially restored. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Section 6 - other (waterbars).					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/27/2022 7:52 AM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11469+00	Field Station#	11451+87		
Pic 1 Desc.	Section of RoW showing conditions and controls.		Pic 2 Desc.	S-0012.	
					
GPS Location	3	GPS Location	4		
Field Station#	11451+18	Field Station#	11448+93		
Pic 3 Desc.	S-0013.		Pic 4 Desc.	S-0014/S-CD12.	
					
GPS Location	5	GPS Location	6		
Field Station#	11438+75	Field Station#	11432+00		
Pic 5 Desc.	Section of restored RoW showing conditions and controls.		Pic 6 Desc.	Representative photo of permanent waterbar and level spreaders installed.	

AFE	124300137	Date/Time	7/27/2022 7:52 AM	Report #	
Pictures					
GPS Location	7	GPS Location	8		
Field Station#	11397+00	Field Station#	11381+00		
Pic 7 Desc.	Section of restored RoW showing conditions and controls.		Pic 8 Desc.	Section of restored RoW showing conditions and controls.	
GPS Location	9	GPS Location	10		
Field Station#	11363+00	Field Station#	11360+54		
Pic 9 Desc.	Section of RoW showing conditions and controls.		Pic 10 Desc.	S-KL43.	
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	7/27/2022 7:52 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40336
Inspector	Rob Robertson			Date/Time	7/27/2022 10:07 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11524+16
State	VA	Inspection Area	Partial	Station End	11600+01
County	Montgomery	Ground	Wet	Temperature (°F)	73.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.70
				Rain Accumulation Time (days)	1.00






1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Rock Construction Entrance	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/27/2022 10:07 AM	Report #	40336
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>Completed a regular scheduled VADEQ SWPPP inspection on JNF and private property at Sinking Creek Mountain. This area received approximately 0.7" of rainfall in the past 24 hours and light rain occurred throughout the inspection. The ROW was found stable with no erosion or sediment migration due to runoff. Both restored and temporarily stabilized areas have adequate grasses or erosion control matting present to hold soils. ECDs are in place with no maintenance needs identified. Resource buffers are well vegetated and have effective ECDs installed. There is no impact at any of the adjacent resources or those crossed by the route. Access points are in good condition. No evidence of vandalism was discovered. Vegetation coverage and ditch subsidence will continue to be monitored. No action necessary at this time. Some ECDs are worn, specifically CFS, that will have to be replaced before ground disturbance. No environmental concerns at this time.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 7/27/2022 10:07 AM		Report #	
Pictures					
<div><div><div>Date & Time: Wed Jul 27, 2022, 08:37:45 EDT Position: +037.328305° / +081.418179° (+18.30) Altitude: 1928ft (+11.4ft) Datum: WGS-84 Azimuth/Bearing: 165° S18E 2933mils True (+12.1) Elevation Angle: +01.2° Horizon Angle: +03.0° Zoom: 0.5X 11524+16</div></div></div>		<div><div><div>Date & Time: Wed, Jul 27, 2022, 08:37:45 EDT Position: +037.328305° / +081.418179° (+18.30) Altitude: 2034ft (+10.4ft) Datum: WGS-84 Azimuth/Bearing: 97° N29° S330mils True (+12.1) Elevation Angle: +01.1° Horizon Angle: +00.7° Zoom: 0.5X 11528+33</div></div></div>			
GPS Location		On photo		GPS Location	
Field Station#		11524+16		Field Station#	
Pic 1 Desc.		Access points in good condition.		Pic 2 Desc.	
				Heavy vegetation. ECDs in place. ROW stable.	
<div><div><div>Date & Time: Wed Jul 27, 2022, 08:45:01 EDT Position: +037.328305° / +081.418179° (+18.30) Altitude: 2482ft (+11.4ft) Datum: WGS-84 Azimuth/Bearing: 165° S18E 2933mils True (+12.1) Elevation Angle: +01.2° Horizon Angle: +03.0° Zoom: 0.5X 11538+00</div></div></div>		<div><div><div>Date & Time: Wed, Jul 27, 2022, 08:45:01 EDT Position: +037.328305° / +081.418179° (+18.30) Altitude: 2482ft (+11.4ft) Datum: WGS-84 Azimuth/Bearing: 165° S18E 2933mils True (+12.1) Elevation Angle: +01.2° Horizon Angle: +03.0° Zoom: 0.5X 11540+00</div></div></div>			
GPS Location		On photo		GPS Location	
Field Station#		11538+00		Field Station#	
Pic 3 Desc.		ECDs in place. No erosion occurring.		Pic 4 Desc.	
				ROW stable. Slope breakers in place.	
<div><div><div>Date & Time: Wed Jul 27, 2022, 09:12:51 EDT Position: +037.321044° / +88.0412506° (+10.0m) Altitude: 785m (+12.0m) Datum: WGS-84 Azimuth/Bearing: 288° N72W 5120mils Magnetic (+13.1) Elevation Angle: +00.0° Horizon Angle: +05.3° Zoom: 1.0X 11569+00</div></div></div>		<div><div><div>Date & Time: Wed Jul 27, 2022, 09:16:39 EDT Position: +037.318112° / +88.0410072° (+5.6m) Altitude: 697m (+8.9m) Datum: WGS-84 Azimuth/Bearing: 302° N51W 5423mils Magnetic (+13.1) Elevation Angle: +01.8° Horizon Angle: +02.6° Zoom: 1.0X 11580+00</div></div></div>			
GPS Location		On photo		GPS Location	
Field Station#		11569+00		Field Station#	
Pic 5 Desc.		The ROW is stable at S-PP22.		Pic 6 Desc.	
				Heavy vegetation. ECDs are in place.	

AFE	124300137	Date/Time	7/27/2022 10:07 AM	Report #	
Pictures					
 <p>Date & Time: Wed, Jul 27, 2022, 09:36:49 EDT Position: +037.316957, -080.409543 (+5.0m) Altitude: 626m (+5.0m) Datum: WGS-84 Azimuth/Bearing: 027.1630W (+0.00mils Magnetic (+12°)) Elevation Angle: -02° Horizon Angle: -02° Zoom: 1.0X 11584+00</p>		 <p>Date & Time: Wed, Jul 27, 2022, 09:35:44 EDT Position: +037.316957, -080.409112 (+5.0m) Altitude: 626m (+5.0m) Datum: WGS-84 Azimuth/Bearing: 027.1630W (+0.00mils Magnetic (+12°)) Elevation Angle: -02° Horizon Angle: -02° Zoom: 1.0X 11585+00</p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11584+00	Field Station#	11585+48		
Pic 7 Desc.	Perimeter ECDs are in place. Heavy vegetation. No erosion.	Pic 8 Desc.	The S-PP21 crossing is stable.		
 <p>Date & Time: Wed, Jul 27, 2022, 09:36:49 EDT Position: +037.316470, -080.409543 (+5.0m) Altitude: 626m (+5.0m) Datum: WGS-84 Azimuth/Bearing: 023.1630W (+0.00mils Magnetic (+12°)) Elevation Angle: -02° Horizon Angle: -02° Zoom: 1.0X 11588+00</p>		 <p>Date & Time: Wed, Jul 27, 2022, 09:36:49 EDT Position: +037.316235, -080.409543 (+5.0m) Altitude: 626m (+5.0m) Datum: WGS-84 Azimuth/Bearing: 344.1630W (+0.00mils Magnetic (+12°)) Elevation Angle: -19.9° Horizon Angle: -02° Zoom: 1.0X Adjacent wetland W-CD46</p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11588+41	Field Station#	11589+25		
Pic 9 Desc.	The S-PP20 crossing is stable.	Pic 10 Desc.	Adjacent resource W-CD46 has not been impacted.		
 <p>Date & Time: Wed, Jul 27, 2022, 09:32:05 EDT Position: +037.316489, -080.408871 (+5.0m) Altitude: 628m (+5.0m) Datum: WGS-84 Azimuth/Bearing: 031.1630W (+0.00mils Magnetic (+12°)) Elevation Angle: -02° Horizon Angle: -02° Zoom: 1.0X 11588+00</p>		<p>Insert image here</p>			
GPS Location	On photo	GPS Location			
Field Station#	11588+00	Field Station#			
Pic 11 Desc.	ECDs in place along edge of LOD.	Pic 12 Desc.			

A/E	124300137	Date/Time	7/27/2022 10:07 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40403
Inspector	Patrick Shields			Date/Time	7/28/2022 3:34 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11788+52
State	VA	Inspection Area	Full	Station End	11899+89
County	Montgomery	Ground	Wet	Temperature (°F)	76.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.30
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) No
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Roadside Ditch	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/28/2022 3:34 PM	Report #	40403
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11788+52 (Mount Tabor Road) to ST# 11899+89 (AR 266.03) MP 223.27 to MP 225.37. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. This section of ROW has undergone permanent restoration. Permanent waterbars (section 6 other) with level spreaders in place where designated on E&S sheets. Perimeter controls have been removed due to final restoration vegetation growth. The only remaining ECDs exist around the Mount tabor RCE and along AR 266.03. AR 266.03 and Mount Tabor road crossing RCEs are maintained in acceptable condition. The ROW is wet and in stable condition. No sensitive resources have been impacted MT Tabor rain gauge measured 0.3" of accumulated rainfall.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/28/2022 3:34 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11788+52	Field Station#	11899+89		
Pic 1 Desc.	MT Tabor rain gauge measured 0.3" of rainfall	Pic 2 Desc.	RCE in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11854+00	Field Station#	11830+50		
Pic 3 Desc.	Permanent waterbar in place	Pic 4 Desc.	Level spreader in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11811+00	Field Station#	11788+52		
Pic 5 Desc.	Permanent vegetation present	Pic 6 Desc.	RCE in place		

A/E	124300137	Date/Time	7/28/2022 3:34 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	7/28/2022 3:34 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40390
Inspector	Joe Sweeden			Date/Time	7/28/2022 9:38 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	012005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	69.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.70
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/28/2022 9:38 AM	Report #	40390
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed VA SWPP at Yard 29. Observances: The Yard received 0.70" of rain overnight and has received over 3.00" for the week. Equipment in the yard was free of leaks. The perimeter compost sock was in place and functioning as designed. The rock road approach was clean, no mud or other debris on road. The yard was free of debris. No trash was seen. Trash receptacles in the Yard were clearly labeled. Temporary stabilization was sufficient.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/28/2022 9:38 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	see photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 1 Desc.	Compost sock	Pic 2 Desc.	Compost sock		
					
GPS Location	see photo	GPS Location	see photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 3 Desc.	Yard 29	Pic 4 Desc.	Waste bin		
					
GPS Location	see photo	GPS Location	see photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 5 Desc.	Equipment	Pic 6 Desc.	RCE		

A/E	124300137	Date/Time	7/28/2022 9:38 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	7/28/2022 9:38 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40398
Inspector	Clint Sears			Date/Time	7/28/2022 1:04 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11899+89
State	VA	Inspection Area	Partial	Station End	12005+00
County	Montgomery	Ground	Wet	Temperature (°F)	81.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.30
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Rock Check Dam	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Housekeeping	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/28/2022 1:04 PM	Report #	40398
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with Environmental staff. Completed VA SWPPP inspection from MP225.37 to MP 227.37 St#11899+89 to St#12005+00 No deficiencies were found at this time. This section of Row has undergone permanent restoration and has abundant vegetation. Perimeter controls in some areas are worn but in acceptable condition. A portion of this section of Row has had perimeter controls removed due to heavy vegetation. No sensitive resource have been impacted. AR266 and 266.03 are maintained in acceptable condition. Row is wet and in stable condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time	7/28/2022 1:04 PM	Report #	
Pictures					
<p>Date & Time: Thu, Jul 28, 2022 11:31:12 EDT Position: +32° 22' 09.1" / -80° 32' 48.9" (-11921) Altitude: 1792ft (-115m) Datum: WGS-84 Azimuth/Bearing: 013 N44W 548mils True (-13) Elevation Angle: +0.1° Horizon Angle: +0.2° Zoom: 1.0x 11972+00</p> 		<p>Date & Time: Thu, Jul 28, 2022 10:24:05 EDT Position: +32° 23' 02.8" / -80° 32' 02.8" (-11904) Altitude: 2007ft (-603m) Datum: WGS-84 Azimuth/Bearing: 243 S64W 440mils True (-13) Elevation Angle: +0.1° Horizon Angle: +0.1° Zoom: 1.0x 11904+15</p> 			
GPS Location		See photo		GPS Location	
Field Station#		11972+00		Field Station#	
Pic 1 Desc.		Section of Row showing conditions and controls		Pic 2 Desc.	
<p>Date & Time: Thu, Jul 28, 2022 10:06:01 EDT Position: +31° 29' 59.9" / -80° 32' 41.1" (-11908) Altitude: 2524ft (-772m) Datum: WGS-84 Azimuth/Bearing: 327 N33W 581mils True (-13) Elevation Angle: +0.8° Horizon Angle: +0.2° Zoom: 1.0x 11908+30</p> 		<p>Date & Time: Thu, Jul 28, 2022 10:06:01 EDT Position: +31° 29' 59.9" / -80° 32' 41.1" (-11931) Altitude: 2524ft (-772m) Datum: WGS-84 Azimuth/Bearing: 105 S85E 300mils True (-13) Elevation Angle: +0.8° Horizon Angle: +0.8° Zoom: 1.0x 11931+50</p> 			
GPS Location		See photo		GPS Location	
Field Station#		11908+30		Field Station#	
Pic 3 Desc.		Representational photo of water bar and level spreader		Pic 4 Desc.	
<p>Date & Time: Thu, Jul 28, 2022 11:16:18 EDT Position: +31° 29' 59.9" / -80° 32' 41.1" (-11934) Altitude: 2079ft (-633m) Datum: WGS-84 Azimuth/Bearing: 163 S17E 899mils True (-12) Elevation Angle: +1.0° Horizon Angle: +0.1° Zoom: 1.0x 11899+89</p> 		<p>Date & Time: Thu, Jul 28, 2022 10:06:01 EDT Position: +31° 29' 59.9" / -80° 32' 41.1" (-11931) Altitude: 2524ft (-772m) Datum: WGS-84 Azimuth/Bearing: 105 S85E 300mils True (-13) Elevation Angle: +0.8° Horizon Angle: +0.8° Zoom: 1.0x 11931+50</p> 			
GPS Location		See photo		GPS Location	
Field Station#		11934+45		Field Station#	
Pic 5 Desc.		Section of Row with abundant vegetation		Pic 6 Desc.	
				AR266.03 broad based dips and P1 are in acceptable condition	

AFE 124300137		Date/Time	7/28/2022 1:04 PM	Report #	
Pictures					
<p>Date & Time: Thu, Jul 28, 2022, 11:35:55 EDT Position: +437.249426° / -680.322459° (+24.7ft) Altitude: 1861ft (+52.9ft) Datum: WGS-84 Azimuth/Bearing: 340° N20W 604mils True (+17°) Elevation Angle: +12.2° Horizon Angle: +02.7° Zoom: 1.0X 11978+00</p> 		<p>Date & Time: Thu, Jul 28, 2022, 11:45:49 EDT Position: +437.249426° / -680.319394° (+24.8ft) Altitude: 1878ft (+53.0ft) Datum: WGS-84 Azimuth/Bearing: 355° N25E 654mils True (+18°) Elevation Angle: +10.2° Horizon Angle: +01.2° Zoom: 1.0X 12005+00</p> 			
GPS Location		See photo		GPS Location	
Field Station#		11978+00		Field Station#	
Pic 7 Desc.		Section of Row showing conditions and controls		Pic 8 Desc.	
<p>Date & Time: Thu, Jul 28, 2022, 11:45:49 EDT Position: +437.249426° / -680.319394° (+24.8ft) Altitude: 1878ft (+53.0ft) Datum: WGS-84 Azimuth/Bearing: 316° S26W 600mils True (+14°) Elevation Angle: +01.9° Horizon Angle: +01.1° Zoom: 1.0X 12002+50</p> 		<p>Date & Time: Thu, Jul 28, 2022, 11:45:49 EDT Position: +437.249426° / -680.319394° (+24.8ft) Altitude: 1878ft (+53.0ft) Datum: WGS-84 Azimuth/Bearing: 316° S26W 600mils True (+14°) Elevation Angle: +01.9° Horizon Angle: +01.1° Zoom: 1.0X 11981+00</p> 			
GPS Location		See photo		GPS Location	
Field Station#		12002+50		Field Station#	
Pic 9 Desc.		Section of Row showing conditions and controls		Pic 10 Desc.	
<p>Date & Time: Thu, Jul 28, 2022, 11:45:49 EDT Position: +437.249426° / -680.319394° (+24.8ft) Altitude: 1878ft (+53.0ft) Datum: WGS-84 Azimuth/Bearing: 301° N29W 600mils True (+14°) Elevation Angle: +01.2° Horizon Angle: +01.1° Zoom: 1.0X 11993+00</p> 		<p>Date & Time: Thu, Jul 28, 2022, 11:46:44 EDT Position: +437.310989° / -680.265414° (+19.0ft) Altitude: 2210ft (+31.4ft) Datum: WGS-84 Azimuth/Bearing: 028° N28E 649mils True (+13°) Elevation Angle: +08.8° Horizon Angle: +04.7° Zoom: 1.0X 11929+47</p> 			
GPS Location		See photo		GPS Location	
Field Station#		11993+00		Field Station#	
Pic 11 Desc.		Section of Row with abundant vegetation		Pic 12 Desc.	
				ECD's are in acceptable condition	

A/E	124300137	Date/Time	7/28/2022 1:04 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40391
Inspector	Joe Sweeden			Date/Time	7/28/2022 10:17 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	71.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	1.30
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waste Management	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/28/2022 10:17 AM	Report #	40391
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed weekly SWPP inspection at Yard 28 Yard 28 received 1.30" of precipitation over the last 24 hours. No deficiencies found. Observances: The perimeter controls were in place and functioning as designed. No activity in the yard. Trucks and Porta-Johns are stacked in the yard Equipment in the yard was free of leaks. The perimeter P1 and compost sock was in place and functioning as designed. The rock road approach was clean, no mud or other debris on road. The yard was free of debris.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/28/2022 10:17 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	see photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	RCE		Pic 2 Desc.	Waste bins	
					
GPS Location	see photo		GPS Location	see photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	Stacked equipment		Pic 4 Desc.	RCE	
					
GPS Location	see photo		GPS Location	see photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	Equipment		Pic 6 Desc.	Equipment	

A/E	124300137	Date/Time	7/28/2022 10:17 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	7/28/2022 10:17 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40371
Inspector	Chris Burns			Date/Time	7/28/2022 6:11 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Partial	Station End	11788+52
County	Montgomery	Ground	Wet	Temperature (°F)	78.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.30
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)






E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/28/2022 6:11 AM	Report #	40371
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 221.02 (11670+00) to MP 223.27 (11788+52). Inspection completed during ongoing rain event. All perimeter controls, ECDs and BMPs functional at time of inspection. No impact to sensitive resources observed. Vegetation or stabilization sufficient. Continued rainfall could result in additional issues being identified during future inspections.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	7/28/2022 6:11 AM	Report #	
Pictures					
 <p>Date & Time: Thu, Jul 28, 2022, 07:43:00 EDT Position: 2083627.820 E, 2519824.989 N (±26.4M) Altitude: 2458ft (±11.0M) Datum: WGS-84 Azimuth/Bearing: 212° S32W 376ft/mile True (±12°) Elevation Angle: -20.8° Horizon Angle: -09.3° Zoom: 0.5X 11671+00</p>		 <p>Date & Time: Thu, Jul 28, 2022, 08:11:35 EDT Position: 2083627.820 E, 2519824.989 N (±26.4M) Altitude: 2458ft (±11.0M) Datum: WGS-84 Azimuth/Bearing: 212° S32W 376ft/mile True (±12°) Elevation Angle: -20.8° Horizon Angle: -09.3° Zoom: 0.5X 11687+42S-MN21</p>			
GPS Location	1	GPS Location	2		
Field Station#	11671+00	Field Station#	11687+42		
Pic 1 Desc.	Section of RoW showing conditions and controls.	Pic 2 Desc.	S-MN21.		
 <p>Date & Time: Thu, Jul 28, 2022, 08:45:13 EDT Position: 2083627.820 E, 2519824.989 N (±26.4M) Altitude: 2458ft (±11.0M) Datum: WGS-84 Azimuth/Bearing: 149° S88E 361ft/mile True (±12°) Elevation Angle: -14.5° Horizon Angle: -08.2° Zoom: 0.5X 11698+50</p>		 <p>Date & Time: Thu, Jul 28, 2022, 08:45:50 EDT Position: 2083627.820 E, 2519824.989 N (±26.4M) Altitude: 2458ft (±11.0M) Datum: WGS-84 Azimuth/Bearing: 024° N24E 042ft/mile True (±12°) Elevation Angle: -12.9° Horizon Angle: -02.2° Zoom: 0.5X 11704+10S-MN22</p>			
GPS Location	3	GPS Location	4		
Field Station#	11698+50	Field Station#	11704+10		
Pic 3 Desc.	Perimeter controls functional.	Pic 4 Desc.	S-MN22.		
 <p>Date & Time: Thu, Jul 28, 2022, 08:49:11 EDT Position: 2083627.820 E, 2519824.989 N (±26.4M) Altitude: 2458ft (±11.0M) Datum: WGS-84 Azimuth/Bearing: 189° S81E 347ft/mile True (±12°) Elevation Angle: -07.5° Horizon Angle: -01.7° Zoom: 0.5X 11713+50</p>		 <p>Date & Time: Thu, Jul 28, 2022, 08:49:50 EDT Position: 2083627.820 E, 2519824.989 N (±26.4M) Altitude: 2458ft (±11.0M) Datum: WGS-84 Azimuth/Bearing: 099° S81E 347ft/mile True (±12°) Elevation Angle: -00.3° Horizon Angle: -01.7° Zoom: 0.5X 11725+00</p>			
GPS Location	5	GPS Location	6		
Field Station#	11713+50	Field Station#	11725+00		
Pic 5 Desc.	Section of RoW showing conditions and controls.	Pic 6 Desc.	Section of RoW showing conditions and controls.		

AFE	124300137	Date/Time	7/28/2022 6:11 AM	Report #	
Pictures					
					
GPS Location	7	GPS Location	8		
Field Station#	11740+55	Field Station#	11743+97		
Pic 7 Desc.	S-EF65.	Pic 8 Desc.	S-EF62.		
					
GPS Location	9	GPS Location	10		
Field Station#	11752+00	Field Station#	11767+44		
Pic 9 Desc.	Section of RoW showing conditions and controls.	Pic 10 Desc.	S-IJ52/W-IJ46.		
		<p>Insert image here</p>			
GPS Location	11	GPS Location			
Field Station#	11788+52	Field Station#			
Pic 11 Desc.	RCE Mt Tabor rd.	Pic 12 Desc.			

A/E	124300137	Date/Time	7/28/2022 6:11 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40405
Inspector	Jared Saunders			Date/Time	7/28/2022 4:09 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	81.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/28/2022 4:09 PM	Report #	40405
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed VA SWPPP inspection of LDY-26 Yard is used to store various materials needed for construction. Both MVP and PPL employee personal vehicles are parked here. Large fuel island containment is maintained in acceptable condition. Secondary containments are in place to be used when fueling vehicles. Waste management and housekeeping are acceptable. Dumpsters are in place with adequate signage to dispose of materials properly into correct bins. Rock surface of the yard is in acceptable condition. CFS perimeter controls and orange safety fence are in place. Light plants, porta potties, gas cans, and other hazardous materials are in secondary containment units. Spill kits and fire extinguishers are available on site. Additional portable fuel cells and welding machines have appropriate secondary containment. This yard has heavy vehicle traffic.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	7/28/2022 4:09 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	Triple stack CFS in place along LOD.		Pic 2 Desc.	Rock line channel in place.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	Triple stack 18 inch CFS in place.		Pic 4 Desc.	Dumpsters utilized for waste management.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	Secondary containment in place under fuel cell.		Pic 6 Desc.	RCE in place at yard entrance.	

A/E	124300137	Date/Time	7/28/2022 4:09 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	7/28/2022 4:09 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40393
Inspector	Rob Robertson			Date/Time	7/28/2022 11:34 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Partial	Station End	11600+01
County	Montgomery	Ground	Wet	Temperature (°F)	72.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.30
				Rain Accumulation Time (days)	1.00





1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Rock Construction Entrance	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/28/2022 11:34 AM	Report #	40393
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>A regular scheduled VADEQ SWPPP inspection was completed today on JNF and private property at Brush Mountain. The area received approximately 0.3" of rainfall in the past 24 hours. The ROW remains stable with no erosion caused by runoff. Slope breakers, sumps and end treatments are functional. There is currently adequate vegetation and/or mulch on the surface. ECDs are in place with no maintenance needs identified today. Worn CFS located on JNF will be replaced before ground disturbance occurs. Resource buffers are well vegetated and no impact has occurred to streams. RCEs are in good condition.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/28/2022 11:34 AM	Report #	
Pictures					
 <p>Date & Time: Thu Jul 28, 2022, 06:29:37 EDT Position: +037.306931° / -080.397410° (+5.0m) Altitude: 855m (+5.0m) Datum: WGS-84 Azimuth/Bearing: 131° S49E 2329mils Magnetic (+12°) Elevation Angle: -09.8° Horizon Angle: -03.6° Zoom: 1.0X 11668+00</p>		 <p>Date & Time: Thu Jul 28, 2022, 06:37:05 EDT Position: +037.307545° / -080.397402° (+5.0m) Altitude: 720m (+5.0m) Datum: WGS-84 Azimuth/Bearing: 301° S81W 1573mils Magnetic (+12°) Elevation Angle: -07.1° Horizon Angle: -04.3° Zoom: 1.0X 11661+00</p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11668+00	Field Station#	11661+00		
Pic 1 Desc.	Top of Brush Mountain stable. No evidence of vandalism discovered.	Pic 2 Desc.	Runoff being properly controlled.		
 <p>Date & Time: Thu Jul 28, 2022, 06:40:40 EDT Position: +037.306931° / -080.397410° (+5.0m) Altitude: 720m (+5.0m) Datum: WGS-84 Azimuth/Bearing: 343° N17W 6098mils Magnetic (+12°) Elevation Angle: -17.5° Horizon Angle: -01.6° Zoom: 1.0X 11653+00</p>		 <p>Date & Time: Thu Jul 28, 2022, 06:45:26 EDT Position: +037.307545° / -080.397437° (+5.0m) Altitude: 711m (+5.0m) Datum: WGS-84 Azimuth/Bearing: 171° S99E 3608mils Magnetic (+12°) Elevation Angle: -07.6° Horizon Angle: -04.3° Zoom: 1.0X 11651+00</p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11653+00	Field Station#	11651+00		
Pic 3 Desc.	Slope breakers functional. ROW well vegetated.	Pic 4 Desc.	ROW stable. ECDs are in place.		
 <p>Date & Time: Thu Jul 28, 2022, 06:49:30 EDT Position: +037.308102° / -080.397308° (+5.0m) Altitude: 691m (+5.0m) Datum: WGS-84 Azimuth/Bearing: 350° N10W 6222mils Magnetic (+12°) Elevation Angle: -16.5° Horizon Angle: -00.4° Zoom: 1.0X 11650+00</p>		 <p>Date & Time: Thu Jul 28, 2022, 06:49:30 EDT Position: +037.308102° / -080.397402° (+5.0m) Altitude: 691m (+5.0m) Datum: WGS-84 Azimuth/Bearing: 277° N83W 4024mils Magnetic (+12°) Elevation Angle: -13.8° Horizon Angle: -00.4° Zoom: 1.0X 11645+00</p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11650+00	Field Station#	11645+00		
Pic 5 Desc.	ROW stable with ECDs in place.	Pic 6 Desc.	Heavy vegetation. ROW stable.		

AFE	124300137	Date/Time	7/28/2022 11:34 AM	Report #	
Pictures					
 <p><small>Date & Time: Thu, Jul 28, 2022, 09:00:11 EDT Position: +037.313504, -7-080.377834 (±10.0m) Altitude: 607m (±12.0m) Datum: WGS-84 Azimuth/Bearing: 004° N 001.004mils Magnetic (±12°) Elevation Angle: +2.9° Horizon Angle: +00.0° Zone: 18 S: 10/18</small></p>		 <p><small>Date & Time: Thu, Jul 28, 2022, 09:02:13 EDT Position: +037.313728, -7-080.388302 (±10.0m) Altitude: 592m (±12.0m) Datum: WGS-84 Azimuth/Bearing: 004° N 001.004mils Magnetic (±12°) Elevation Angle: +2.9° Horizon Angle: +01.0° Zone: 18 S: 10/18</small></p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11628+50	Field Station#	11626+04		
Pic 7 Desc.	ECDs along LOD are in place. ROW is stable.	Pic 8 Desc.	The S-HH18 crossing is stable.		
 <p><small>Date & Time: Thu, Jul 28, 2022, 09:08:54 EDT Position: +037.313616, -7-080.402124 (±10.0m) Altitude: 570m (±16.0m) Datum: WGS-84 Azimuth/Bearing: 281° N 78W 3996mils Magnetic (±12°) Elevation Angle: -12.1° Horizon Angle: +01.6° Zone: 18 S: 11614+20, S-RR14</small></p>		 <p><small>Date & Time: Thu, Jul 28, 2022, 09:00:18 EDT Position: +037.313577, -7-080.404634 (±5.0m) Altitude: 570m (±6.0m) Datum: WGS-84 Azimuth/Bearing: 179° S 01E 3182mils Magnetic (±12°) Elevation Angle: -05.3° Horizon Angle: +00.0° Zone: 18 S: 11607+81</small></p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11614+20	Field Station#	11607+81		
Pic 9 Desc.	The S-RR14 crossing is stable.	Pic 10 Desc.	The S-006 crossing is currently stable.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	7/28/2022 11:34 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40452
Inspector	Patrick Shields			Date/Time	7/29/2022 3:33 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10749+92
State	VA	Inspection Area	Full	Station End	10798+92
County	Giles	Ground	Wet	Temperature (°F)	79.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/29/2022 3:33 PM	Report #	40452
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 10749+92 (Hendrickson) to ST# 10798+92 (Cascade) Accompanied by fellow EI Jared Saunders on VA SWPPP inspection of MP 203.6 to MP 204.53. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. This section of ROW is temporarily stabilized with seed and mulch. Vegetation growth is present throughout section. Clean water diversion berms, pipes and level spreaders are in place. ECDs in place per E&S sheets. Sensitive resource buffers are in place at stream crossings S-G35, S-SS4, S-Z9, S-Z7 braid 1, and S-Z7 braid 2. Hendrickson, Big Branch Hollow, and Cascade Road crossing RCEs are maintained in acceptable condition. The ROW is wet and in stable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	7/29/2022 3:33 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10750+50	Field Station#	10752+50		
Pic 1 Desc.	RCE in place	Pic 2 Desc.	Waterbars in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10758+50	Field Station#	10761+60		
Pic 3 Desc.	Stream buffer in place	Pic 4 Desc.	Stone inlet protection in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10764+75	Field Station#	10765+85		
Pic 5 Desc.	Stream buffer in place	Pic 6 Desc.	Cleanwater diversion outlet protection in place		

AFE 124300137		Date/Time	7/29/2022 3:33 PM	Report #	
Pictures					
<p>Date & Time: Fri Jul 29, 2022 07:00:55 EDT Position: +037.344296° / -080.629989° (±18.8ft) Altitude: 2180ft (±26.2ft) Datum: WGS-84 Azimuth/Bearing: 240° S60W 627mils True (±12°) Elevation Grade: -011% Horizon Grade: -014% Zoom: 0.5X 10769+00</p> 		<p>Date & Time: Fri Jul 29, 2022 07:00:55 EDT Position: +037.344994° / -080.628300° (±17.8ft) Altitude: 2180ft (±11.5ft) Datum: WGS-84 Azimuth/Bearing: 110° S25W 646mils True (±12°) Elevation Grade: -002% Horizon Grade: -002% Zoom: 0.5X 10771+75</p> 			
GPS Location	See photo		GPS Location	See photo	
Field Station#	10769+00		Field Station#	10771+75	
Pic 7 Desc.	CFS perimeter control in place		Pic 8 Desc.	Cleanwater diversion outlet protection in place	
<p>Date & Time: Fri Jul 29, 2022 09:06:25 EDT Position: +037.342782° / -080.627260° (±20.3ft) Altitude: 2195ft (±25.9ft) Datum: WGS-84 Azimuth/Bearing: 068° N08E 1249mils True (±12°) Elevation Grade: -000% Horizon Grade: -009% Zoom: 0.5X 10777+50</p> 		<p>Date & Time: Fri Jul 29, 2022 09:10:00 EDT Position: +037.329587° / -080.624918° (±43.9ft) Altitude: 2077ft (±29.4ft) Datum: WGS-84 Azimuth/Bearing: 231° S71W 662mils True (±12°) Elevation Grade: -022% Horizon Grade: -094% Zoom: 0.5X 10784+00</p> 			
GPS Location	See photo		GPS Location	See photo	
Field Station#	10777+50		Field Station#	10784+00	
Pic 9 Desc.	Cleanwater drainage feature in place		Pic 10 Desc.	CFS perimeter control in place	
<p>Date & Time: Fri Jul 29, 2022 09:18:02 EDT Position: +037.342872° / -080.632235° (±15.4ft) Altitude: 1937ft (±11.2ft) Datum: WGS-84 Azimuth/Bearing: 089° N38E 0476mils True (±12°) Elevation Grade: -005% Horizon Grade: -005% Zoom: 0.5X 10792+00</p> 		<p>Date & Time: Fri Jul 29, 2022 09:30:00 EDT Position: +037.328687° / -080.628300° (±14.5ft) Altitude: 1817ft (±11.0ft) Datum: WGS-84 Azimuth/Bearing: 100° S85E 581mils True (±12°) Elevation Grade: -003% Horizon Grade: -003% Zoom: 0.5X 10798+00</p> 			
GPS Location	See photo		GPS Location	See photo	
Field Station#	10792+00		Field Station#	10798+00	
Pic 11 Desc.	Cleanwater diversion berm in place		Pic 12 Desc.	RCE in place	

A/E	124300137	Date/Time	7/29/2022 3:33 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40436
Inspector	Clint Sears			Date/Time	7/29/2022 11:22 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10859+46
State	VA	Inspection Area	Partial	Station End	10929+80
County	Giles	Ground	Wet	Temperature (°F)	81.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Acceptable			
Stone Inlet Protection	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/29/2022 11:22 AM	Report #	40436
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with Environmental staff. Completed VA SWPPP inspection from (MP 205.67 to MP 207 St#10859+46 to St#10929+80) No deficiencies were found at time of inspection. This section of Row has undergone temporary stabilization. All ECD's and BMPs are in acceptable condition. Vegetation/stabilization is sufficient. Sensitive resource buffers have abundant vegetation. No sensitive resources have been impacted. Row is wet and in stable condition. Rain gage at Kow camp 0.1" inches of accumulation.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	7/29/2022 11:22 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10927+71	Field Station#	10920+00		
Pic 1 Desc.	Looking upstream at S-Y3	Pic 2 Desc.	Section of Row showing conditions and controls		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10915+50	Field Station#	10905+00		
Pic 3 Desc.	SSF is in acceptable condition	Pic 4 Desc.	P1 silt fence is in acceptable condition		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10899+00	Field Station#	10891+75		
Pic 5 Desc.	Section of Row showing conditions and controls	Pic 6 Desc.	Section of Row showing conditions and controls		

AFE	124300137	Date/Time	7/29/2022 11:22 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10885+00	Field Station#	10883+87		
Pic 7 Desc.	Section of Row showing conditions and controls	Pic 8 Desc.	Rain gage at Kow camp with 0.1" inches of accumulation		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10883+08	Field Station#	10882+42		
Pic 9 Desc.	Looking upstream at S-A32	Pic 10 Desc.	Section of Row showing conditions and controls		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10877+50	Field Station#	10864+55		
Pic 11 Desc.	Section of Row showing conditions and controls	Pic 12 Desc.	Level spreader in place		

A/E	124300137	Date/Time	7/29/2022 11:22 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40423
Inspector	Eric Hanlon			Date/Time	7/29/2022 7:07 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10655+00
State	VA	Inspection Area	Full	Station End	10749+92
County	Giles	Ground	Muddy	Temperature (°F)	77.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.05
				Rain Accumulation Time (days)	1.00



1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Waterbar	Communication			
Other - Explain in Comments	Communication			
Compost Filter Sock	Acceptable			
Energy Dissipater	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/29/2022 7:07 AM	Report #	40423
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection from ST# 10655+00 (MP 201.6) to ST# 10749+92 (MP 203.6). Compliance issues noted: @10737+00 rilling need stabilization, @ 10735+00 water bar throat needs stabilized. Observance: Perimeter controls in place & functioning as designed. ROW has been temporary stabilized. No areas with open ditch. All other ECDs and BMPs functional at time of inspection. 50' buffers in place at stream crossings S-G33, S-G32, S-G30 and W-Z11. AR-240, 241.04, 241.01, 241, Hendrickson and Big Stony creek road crossing RCEs are maintained in acceptable condition. The ROW is muddy and in stable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/29/2022 7:07 AM	Report #	
Pictures					
 <p>Date & Time: Fri Jul 29, 2022 09:54:42 EDT Position: +039.34704 / -080.66186 (±13.7m) Altitude: 2213ft (±19.7m) Datum: WGS-84 Azimuth/Bearing: 342° N16W 6080mils True (±13°) Elevation Angle: -24.2° Horizon Angle: -06.7° Zoom: 1.0X 10664+00</p>		 <p>Date & Time: Fri Jul 29, 2022 09:36:25 EDT Position: +039.34923 / -080.65635 (±19.233m) Altitude: 2143ft (±19.7m) Datum: WGS-84 Azimuth/Bearing: 274° N86W 4697mils True (±13°) Elevation Angle: -13.7° Horizon Angle: -08.3° Zoom: 1.0X 10679+39</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10664+00	Field Station#	10679+39		
Pic 1 Desc.	End treatment in place	Pic 2 Desc.	Equipment bridge functional		
 <p>Date & Time: Fri Jul 29, 2022 09:28:50 EDT Position: +039.34754 / -080.65433 (±14.1m) Altitude: 2056ft (±11.7m) Datum: WGS-84 Azimuth/Bearing: 250° S70W 4444mils True (±12°) Elevation Angle: -18.6° Horizon Angle: -05.3° Zoom: 1.0X 10691+00</p>		 <p>Date & Time: Fri Jul 29, 2022 09:18:11 EDT Position: +039.34531 / -080.64929 (±20.936m) Altitude: 2276ft (±20.7m) Datum: WGS-84 Azimuth/Bearing: 302° N89W 5314mils True (±13°) Elevation Angle: -39.8° Horizon Angle: -01.1° Zoom: 1.0X 10698+00</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10691+00	Field Station#	10698+00		
Pic 3 Desc.	Level spreader in place	Pic 4 Desc.	Resource buffers in place		
 <p>Date & Time: Fri Jul 29, 2022 08:34:02 EDT Position: +039.34639 / -080.64907 (±14.7m) Altitude: 2276ft (±11.7m) Datum: WGS-84 Azimuth/Bearing: 230° S50W 4089mils True (±12°) Elevation Angle: -25.3° Horizon Angle: -02.6° Zoom: 0.5X 10735+00</p>		 <p>Date & Time: Fri Jul 29, 2022 08:33:35 EDT Position: +039.34621 / -080.64029 (±15.1m) Altitude: 2276ft (±11.7m) Datum: WGS-84 Azimuth/Bearing: 262° S82W 4688mils True (±12°) Elevation Angle: -37.6° Horizon Angle: -00.4° Zoom: 0.5X 10737+00</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10735+00	Field Station#	10737+00		
Pic 5 Desc.	Water bar throat needs stabilized	Pic 6 Desc.	Rilling needs stabilized		

A/E	124300137	Date/Time	7/29/2022 7:07 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location			
Field Station#	10749+00	Field Station#			
Pic 7 Desc.	RCE functional	Pic 8 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	7/29/2022 7:07 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	40425
Inspector	Chris Burns			Date/Time	7/29/2022 7:25 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10798+92
State	VA	Inspection Area	Partial	Station End	10859+46
County	Giles	Ground	Wet	Temperature (°F)	76.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/29/2022 7:25 AM	Report #	40425
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Discussed RoW/ECD conditions, within this section, with fellow EI Joe Sweeden. Performed SWPPP inspection from MP 204.53 (10798+92) and MP 205.67 (10859+46). Accompanied by fellow EI Joe Sweeden. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/29/2022 7:25 AM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	10859+25	Field Station#	10856+04		
Pic 1 Desc.	Section of RoW showing conditions and controls.	Pic 2 Desc.	S-A33.		
					
GPS Location	3	GPS Location	4		
Field Station#	10854+70	Field Station#	10843+00		
Pic 3 Desc.	S-A34.	Pic 4 Desc.	CWDP outlet protection functional.		
					
GPS Location	5	GPS Location	6		
Field Station#	10835+50	Field Station#	10826+00		
Pic 5 Desc.	Section of RoW showing conditions and controls.	Pic 6 Desc.	Perimeter controls functional.		

AFE		124300137		Date/Time		7/29/2022 7:25 AM		Report #			
Pictures											
											
GPS Location		7		GPS Location		8					
Field Station#		10818+00		Field Station#		10809+04					
Pic 7 Desc.		Section of RoW showing conditions and controls.		Pic 8 Desc.		S-Z14.					
											
GPS Location		9		GPS Location		10					
Field Station#		10804+00		Field Station#		10801+52					
Pic 9 Desc.		Section of RoW showing conditions and controls.		Pic 10 Desc.		S-Z11/S-Z12/S-Z13.					
											
GPS Location		11		GPS Location							
Field Station#		10799+00		Field Station#							
Pic 11 Desc.		S-Z10/W-Z3.		Pic 12 Desc.							

A/E	124300137	Date/Time	7/29/2022 7:25 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		