









# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39476
<b>Inspector</b>	Ben Farmer			<b>Date/Time</b>	7/5/2022 1:26 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	13958+31
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	14062+17
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Check Dam	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Waterbar	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No





<b>A/E</b>	124300139	<b>Date/Time</b>	7/5/2022 1:26 PM	<b>Report #</b>	39476
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable	Permanent vegetation remains in go			
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 75F) Rain Gauge= 0.0" 13958+31-14062+17  -This section remains stabilized. -CWD/CWD inlets are in good condition and functioning as intended -MVP-ATWS-1446 remains stabilized with controls in place. -P1 is in good condition at all stream and wetland buffers. -No evidence of 3rd party pond discharging onto ROW at 14000+00 -Resource buffers remain well vegetated. -Slope on the CIS of Highway 220 remains stabilized with controls in place. -Waterbars/end treatments are functioning as intended. -CFS is in good condition -Slope drain is functioning as intended at 14058+00 -Rock check dams are functioning at 14059+00. -Vegetation continues to fill in throughout this section					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300139	<b>Date/Time</b>	7/5/2022 1:26 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	13958+31	<b>Field Station#</b>	13960+00		
<b>Pic 1 Desc.</b>	RCEs are in good condition at all road crossings	<b>Pic 2 Desc.</b>	CWDs are functioning as intended		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	13970+00	<b>Field Station#</b>	13997+50		
<b>Pic 3 Desc.</b>	Vegetation continues to fill in throughout this section	<b>Pic 4 Desc.</b>	P1 is in good condition at all stream and wetland buffers		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	13998+15	<b>Field Station#</b>	14000+00		
<b>Pic 5 Desc.</b>	Equipment bridge ECDs are functioning as intended	<b>Pic 6 Desc.</b>	No evidence of 3rd party pond discharging onto ROW		



<b>AFE</b>	124300139	<b>Date/Time</b>	7/5/2022 1:26 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	14009+11	<b>Field Station#</b>	14027+00		
<b>Pic 7 Desc.</b>	Slope remains stabilized	<b>Pic 8 Desc.</b>	CFS is in good condition throughout this section		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	14033+00	<b>Field Station#</b>	14033+00		
<b>Pic 9 Desc.</b>	Waterbars are in good condition	<b>Pic 10 Desc.</b>	End treatments are functioning as intended		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	14035+00	<b>Field Station#</b>	14050+00		
<b>Pic 11 Desc.</b>	Resource buffers remain well vegetated	<b>Pic 12 Desc.</b>	Slope remains stabilized with controls in place		

<b>AFE</b>	124300139	<b>Date/Time</b>	7/5/2022 1:26 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	14057+00		<b>Field Station#</b>	14060+00	
<b>Pic 13 Desc.</b>	Slope drain is functioning as intended		<b>Pic 14 Desc.</b>	Rock check dams are in good condition and functioning	
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 15 Desc.</b>			<b>Pic 16 Desc.</b>		
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 17 Desc.</b>			<b>Pic 18 Desc.</b>		















## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39463
<b>Inspector</b>	Justin Burch			<b>Date/Time</b>	7/5/2022 10:50 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	15260+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	15370+62
<b>County</b>	Pittsylvania	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	91.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	7.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Vegetative Stabilization (Permanent)		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Equipment Bridge		Acceptable			
Waterbar		Acceptable			
Waterbar End Treatment		Acceptable			
Sump Pit		Acceptable			
Compost Filter Sock		Acceptable			
Silt Fence (Reinforce Filter Fence)		Acceptable			
Sensitive Resource Buffer		Acceptable			
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300139	<b>Date/Time</b>	7/5/2022 10:50 AM	<b>Report #</b>	39463
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable	Permanent Vegetation			
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> <li>The EI performed a SWPPP inspection from 15260+00 to 15370+62 (Pigg River HDD Exit to Snowberry Road). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection.</li> <li>The EI did not observe that any contractor activity has occurred in the area since the last SWPPP inspection.</li> <li>Since the last SWPPP inspection the area has received one rain event with a total of 0.10" at Snowberry Road.</li> <li>The ROW ground condition is dry.</li> <li>At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15355+00 to 15370+00.</li> <li>At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion.</li> </ul>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300139	<b>Date/Time</b>	7/5/2022 10:50 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15369+00	<b>Field Station#</b>	15350+00		
<b>Pic 1 Desc.</b>	Permanent vegetative stabilization in acceptable condition	<b>Pic 2 Desc.</b>	Temporary vegetative stabilization in acceptable condition		
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15346+80	<b>Field Station#</b>	15343+00		
<b>Pic 3 Desc.</b>	Equipment bridge in acceptable condition	<b>Pic 4 Desc.</b>	Waterbar in acceptable condition		
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15343+00	<b>Field Station#</b>	15338+00		
<b>Pic 5 Desc.</b>	Waterbar end treatment in acceptable condition	<b>Pic 6 Desc.</b>	Sump pit in acceptable condition		



<b>A/E</b>	124300139	<b>Date/Time</b>	7/5/2022 10:50 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15332+00	<b>Field Station#</b>	15315+00		
<b>Pic 7 Desc.</b>	Perimeter CFS and temporary vegetative stabilization in acceptable conditions		<b>Pic 8 Desc.</b>	P1 silt fence and sensitive resource buffer in acceptable conditions	
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15305+00	<b>Field Station#</b>	15305+00		
<b>Pic 9 Desc.</b>	Waterbar in acceptable condition		<b>Pic 10 Desc.</b>	Waterbar end treatment in acceptable condition	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>			<b>Pic 12 Desc.</b>		









<b>A/E</b>	124300139	<b>Date/Time</b>	7/5/2022 10:50 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39453
<b>Inspector</b>	Ben Davenport			<b>Date/Time</b>	7/5/2022 11:26 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	14454+22
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	14546+75
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	85.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Compost Filter Sock	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Sump Pit	Acceptable				
Slope Drain Pipe	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300139	<b>Date/Time</b>	7/5/2022 11:26 AM	<b>Report #</b>	39453
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable	Permanent Vegetation			
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> <li>-Available for work</li> <li>-Received instruction from Lead EI for daily tasks</li> <li>-Sunny with dry ground conditions during inspection</li> <li>-Performed SWPPP inspection on portion of MVP Spread I section</li> <li>-Covered territory between station# 14454+22 — 14546+75 (Webster Rd to Tobacco Rd)</li> <li>-Walked ROW making note of condition of ROW and environmental controls</li> <li>-Verified the completion and accuracy of punch list items in covered area from previous inspections</li> <li>-Perimeter controls and ECDs were inspected; no issues identified</li> <li>-Inspection observed condition of equipment bridges and surrounding ECDs around stream crossings and resource buffers; no issues identified</li> <li>-Inspection observed condition of RCEs and culverts in section; no issues identified</li> <li>-Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified</li> <li>-Inspection observed condition of temporary stabilization and vegetation in section; no issues identified</li> <li>-Continue to monitor ROW for signs of erosion</li> <li>-No items added to environmental punch list in section</li> </ul>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	7/5/2022 11:26 AM	Report #	
Pictures					
 <p data-bbox="191 514 493 531">37°0'30" N 79°45'15" W 272°W COURSE -1° GPS</p> <p data-bbox="625 514 748 531">07.05.2022 10:09:01</p> <p data-bbox="253 531 396 548">Sorry no results found</p> <p data-bbox="586 531 760 548">Accur +/-15.5 Ft ALT 1050 Ft</p>			 <p data-bbox="894 514 1182 531">37°1'0" N 79°45'34" W 347°N COURSE -1° GPS</p> <p data-bbox="1320 514 1443 531">07.05.2022 11:29:31</p> <p data-bbox="870 531 1170 548">1401 SR-674, Glade Hill, VA 24092, United States</p> <p data-bbox="1287 531 1455 548">Accur +/-15.1 Ft ALT 911 Ft</p>		
GPS Location	1	GPS Location	2	Field Station#	14477+00
Pic 1 Desc.	Sump pit and CFS end treatment performing intended functions.				
Pic 2 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer; ROW stabilized and vegetated in temporary area.				
 <p data-bbox="191 1094 493 1110">37°0'47" N 79°45'22" W 348°N COURSE -1° GPS</p> <p data-bbox="625 1094 748 1110">07.05.2022 11:22:02</p> <p data-bbox="215 1110 435 1127">Glade Hill, VA 24092, United States</p> <p data-bbox="586 1110 760 1127">Accur +/-68.7 Ft ALT 1025 Ft</p>			 <p data-bbox="894 1094 1182 1110">37°0'43" N 79°45'18" W 6°N COURSE -1° GPS</p> <p data-bbox="1320 1094 1443 1110">07.05.2022 11:18:42</p> <p data-bbox="911 1110 1130 1127">Glade Hill, VA 24092, United States</p> <p data-bbox="1287 1110 1455 1127">Accur +/-15.1 Ft ALT 1016 Ft</p>		
GPS Location	3	GPS Location	4	Field Station#	14516+00
Pic 3 Desc.	Perimeter SSF and CFS performing intended functions.				
Pic 4 Desc.	Slope drain pipe in place and functional.				
 <p data-bbox="191 1673 493 1690">37°0'23" N 79°45'12" W 10°N COURSE -1° GPS</p> <p data-bbox="625 1673 748 1690">07.05.2022 10:02:47</p> <p data-bbox="253 1690 396 1707">Sorry no results found</p> <p data-bbox="586 1690 760 1707">Accur +/-13.5 Ft ALT 990 Ft</p>			 <p data-bbox="894 1673 1182 1690">37°0'19" N 79°45'9" W 6°N COURSE 173° GPS</p> <p data-bbox="1320 1673 1443 1690">07.05.2022 10:00:02</p> <p data-bbox="951 1690 1094 1707">Sorry no results found</p> <p data-bbox="1287 1690 1455 1707">Accur +/-11.6 Ft ALT 951 Ft</p>		
GPS Location	5	GPS Location	6	Field Station#	14537+00
Pic 5 Desc.	ROW stabilized and vegetated in temporary area; water bars performing intended functions.				
Pic 6 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.				

<b>A/E</b>	124300139	<b>Date/Time</b>	7/5/2022 11:26 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	7/5/2022 11:26 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I		<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I	
<b>Contractor</b>	Precision				<b>Report #</b>	39478	
<b>Inspector</b>	Charles Head				<b>Date/Time</b>	7/5/2022 1:52 PM	
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP		<b>Station Begin</b>	14802+19	
<b>State</b>	VA	<b>Inspection Area</b>	Full		<b>Station End</b>	14928+52	
<b>County</b>	Franklin	<b>Ground</b>	Dry		<b>Temperature (°F)</b>	91.00	
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy		<b>Rain Gauge (in)</b>	0.00	
					<b>Rain Accumulation Time (days)</b>	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Cleanwater Diversion Pipe		Acceptable					
Compost Filter Sock		Acceptable					
Equipment Bridge		Acceptable					
Rock Construction Entrance		Acceptable					
Sensitive Resource Buffer		Acceptable					
Sensitive Resource Signage		Acceptable					
Silt Fence (Filter Fabric Fence)		Acceptable					
Silt Fence (Reinforce Filter Fence)		Acceptable					
Waterbar		Acceptable					
<b>5. Site Conditions</b>							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

<b>A/E</b>	124300139	<b>Date/Time</b>	7/5/2022 1:52 PM	<b>Report #</b>	39478
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE	124300139	Date/Time	7/5/2022 1:52 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14805+00	Field Station#	14838+00		
Pic 1 Desc.	Approximately 14805+00. Overview of stream crossing, equipment bridge and ECDs at stream S-H23.		Pic 2 Desc.	Approximately 14838+00. Overview of ROW.	
GPS Location	0	GPS Location	0		
Field Station#	14846+00	Field Station#	14859+00		
Pic 3 Desc.	Approximately 14846+00. Overview of road crossing and RCEs.		Pic 4 Desc.	Approximately 14859+00. Overview of ROW.	
GPS Location	0	GPS Location	0		
Field Station#	14870+50	Field Station#	14925+00		
Pic 5 Desc.	Approximately 14870+50. Overview of stream crossing, equipment bridge and ECDs at stream S-SS8.		Pic 6 Desc.	Approximately 14925+00. Overview of ROW. Permanent vegetation. Observed electric fence at gap had been taken down. Appears landowner is letting livestock graze section of	

<b>A/E</b>	124300139	<b>Date/Time</b>	7/5/2022 1:52 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	7/5/2022 1:52 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39465
<b>Inspector</b>	John White			<b>Date/Time</b>	7/5/2022 11:11 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	15647+03
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	15772+27
<b>County</b>	Pittsylvania	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	86.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300139	<b>Date/Time</b>	7/5/2022 11:11 AM	<b>Report #</b>	39465
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300139	<b>Date/Time</b>	7/5/2022 11:11 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p><b>South West Elevation</b>          64°NE (T) 36°52'6"N, 79°24'8"W ±13ft ▲ 829ft          Your Watermark 05 Jul 2022 10:30:00</p>		 <p><b>North East Elevation</b>          207°SW (T) 36°53'57"N, 79°23'45"W ±53812ft ▲ 833ft          Your Watermark 05 Jul 2022 10:42:50</p>			
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15772+27	<b>Field Station#</b>	15756+00		
<b>Pic 1 Desc.</b>	Observing temporary stabilization,access road and ECD's	<b>Pic 2 Desc.</b>	Observing temporary stabilization,end treatment and ECD's		
 <p><b>South Elevation</b>          357°N (T) 36°52'2"N, 79°24'25"W ±9019ft ▲ 795ft          Your Watermark 05 Jul 2022 10:51:53</p>		 <p><b>South West Elevation</b>          44°NE (T) 36°52'47"N, 79°25'17"W ±114ft ▲ 818ft          Your Watermark 05 Jul 2022 11:02:33</p>			
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15735+00	<b>Field Station#</b>	15695+00		
<b>Pic 3 Desc.</b>	Observing temporary stabilization,CWD outlet and ECD's	<b>Pic 4 Desc.</b>	Observing temporary stabilization,water bar and CFS checks		
 <p><b>West Elevation</b>          70°E (T) 36°52'47"N, 79°25'16"W ±62ft ▲ 802ft          Your Watermark 05 Jul 2022 11:03:27</p>		 <p><b>South West Elevation</b>          28°NE (T) 36°52'45"N, 79°25'14"W ±5833ft ▲ 802ft          Your Watermark 05 Jul 2022 11:05:14</p>			
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15697+00	<b>Field Station#</b>	15700+40		
<b>Pic 5 Desc.</b>	Observing temporary stabilization,ump and end treatment	<b>Pic 6 Desc.</b>	Observing temporary stabilization,buffer, equipment crossing and ECD's		

<b>A/E</b>	124300139	<b>Date/Time</b>	7/5/2022 11:11 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	7/5/2022 11:11 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		













# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39520
<b>Inspector</b>	Ben Farmer			<b>Date/Time</b>	7/6/2022 2:24 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	14062+17
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	14171+36
<b>County</b>	Franklin	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	70.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	1.00
				<b>Rain Accumulation Time (days)</b>	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Housekeeping	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300139	<b>Date/Time</b>	7/6/2022 2:24 PM	<b>Report #</b>	39520
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable	Permanent vegetation remains in go			
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 70F) Rain Gauge= 1.0" 14062+17-14171+36  -RCEs are in good condition at all road crossings. -Equipment bridge ECDs are in place and functioning -CWDs are functioning as intended. -MVP-FR-309.05 is in good condition with controls in place. -P1 is in good condition at all stream and wetland buffers. -Resource buffers remain well vegetated. -CFS is in good condition throughout this section -Waterbars/end treatments are in good condition and functioning -Slope drain is functioning as intended at 14157+00. -Vegetation continues to fill in throughout this section					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300139	<b>Date/Time</b>	7/6/2022 2:24 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	14062+17		<b>Field Station#</b>	14066+77	
<b>Pic 1 Desc.</b>	RCEs are in good condition at all road crossings		<b>Pic 2 Desc.</b>	Equipment bridge ECDs are in good condition and functioning	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	14070+00		<b>Field Station#</b>	14081+46	
<b>Pic 3 Desc.</b>	CWDs are functioning as intended		<b>Pic 4 Desc.</b>	MVP-FR-309.05 is in good condition with controls in place	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	14156+00		<b>Field Station#</b>	14157+55	
<b>Pic 5 Desc.</b>	Slope drain is in good condition and functioning		<b>Pic 6 Desc.</b>	Resource buffers remain well vegetated	



<b>AFE</b>	124300139	<b>Date/Time</b>	7/6/2022 2:24 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	14158+00		<b>Field Station#</b>	14165+00	
<b>Pic 7 Desc.</b>	P1 is in good condition at all stream and wetland buffers		<b>Pic 8 Desc.</b>	CFS is in good condition throughout this section	
				Insert image here	
<b>GPS Location</b>	See photo		<b>GPS Location</b>		
<b>Field Station#</b>	14168+00		<b>Field Station#</b>		
<b>Pic 9 Desc.</b>	Topsoil berms remain stabilized		<b>Pic 10 Desc.</b>		
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 11 Desc.</b>			<b>Pic 12 Desc.</b>		

<b>A/E</b>	124300139	<b>Date/Time</b>	7/6/2022 2:24 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39506
<b>Inspector</b>	Justin Burch			<b>Date/Time</b>	7/6/2022 10:22 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	15370+62
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	15480+67
<b>County</b>	Pittsylvania	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	95.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	7.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Sump Pit	Acceptable				
Equipment Bridge	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Compost Filter Sock	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>AFE</b>	124300139	<b>Date/Time</b>	7/6/2022 10:22 AM	<b>Report #</b>	39506
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable	Permanent Vegetation			
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> <li>The EI performed a SWPPP inspection from 15370+62 to 15480+67 (Snowberry Road to Toshes Road). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection.</li> <li>No contractor activity was observed by the EI in the area since the last SWPPP inspection.</li> <li>The EI observed that the perimeter solar farm ECDs on the CIS of Toshes Road appeared to be in acceptable condition.</li> <li>Since the last SWPPP inspection the area has received one rain event with totals of 0.10" at Snowberry Road.</li> <li>The ROW ground condition is damp.</li> <li>At the time of inspection temporary vegetative stabilization was adequately mulched to inhibit erosion and recently planted grass is continuing to grow and fill in.</li> <li>At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 15438+00 to 15445+00.</li> </ul>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



A/E	124300139	Date/Time	7/6/2022 10:22 AM	Report #	
<b>Pictures</b>					
<p>42°NE (T) ● 17 N 633214 4087059 ±59ft ▲ 796ft 15390+00 07-06-2022, 08:37:28</p>		<p>49°NE (T) ● 17 N 633225 4087081 ±22ft ▲ 785ft 15390+00 07-06-2022, 08:38:05</p>			
<b>GPS Location</b>		0		<b>GPS Location</b>	
<b>Field Station#</b>		15390+00		<b>Field Station#</b>	
<b>Pic 1 Desc.</b>		Waterbar in acceptable condition		<b>Pic 2 Desc.</b>	
				Waterbar end treatment in acceptable condition	
<p>187°S (T) ● 17 N 633335 4087020 ±124ft ▲ 812ft 15394+00 07-06-2022, 08:49:56</p>		<p>263°W (T) ● 17 N 635553 4089609 ±19685ft ▲ 821ft 15399+00 07-06-2022, 09:11:39</p>			
<b>GPS Location</b>		0		<b>GPS Location</b>	
<b>Field Station#</b>		15394+00		<b>Field Station#</b>	
<b>Pic 3 Desc.</b>		P1 silt fence in acceptable condition		<b>Pic 4 Desc.</b>	
				Temporary vegetative stabilization in acceptable condition	
<p>4°N (T) ● 17 N 633592 4086929 ±177ft ▲ 839ft 15403+00 07-06-2022, 09:22:10</p>		<p>131°SE (T) ● 17 N 636311 4090473 ±19685ft ▲ 836ft 15414+13 07-06-2022, 09:32:08</p>			
<b>GPS Location</b>		0		<b>GPS Location</b>	
<b>Field Station#</b>		15403+00		<b>Field Station#</b>	
<b>Pic 5 Desc.</b>		Sump pit in acceptable condition		<b>Pic 6 Desc.</b>	
				Equipment bridge in acceptable condition	



<b>A/E</b>	124300139	<b>Date/Time</b>	7/6/2022 10:22 AM	<b>Report #</b>	
<b>Pictures</b>					
320°NW (T) 17 N 634053 4086752 ±36ft ▲ 823ft  15419+00 07-06-2022, 09:40:22		28°NE (T) 17 N 634194 4086689 ±45ft ▲ 817ft  15424+00 07-06-2022, 09:55:20			
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15419+00	<b>Field Station#</b>	15424+00		
<b>Pic 7 Desc.</b>	Temporary vegetative stabilization in acceptable condition	<b>Pic 8 Desc.</b>	Waterbar in acceptable condition		
45°NE (T) 17 N 634211 4086720 ±16ft ▲ 800ft  15424+00 07-06-2022, 09:56:18		280°W (T) 17 N 634270 4086677 ±554ft ▲ 770ft  15427+00 07-06-2022, 10:10:59			
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15424+00	<b>Field Station#</b>	15427+00		
<b>Pic 9 Desc.</b>	Waterbar end treatment in acceptable condition	<b>Pic 10 Desc.</b>	Super silt fence in acceptable condition		
129°SE (T) 17 N 634631 4086461 ±26ft ▲ 843ft  15443+00 07-06-2022, 10:36:19		247°SW (T) 17 N 635234 4086182 ±65ft ▲ 882ft  15464+00 07-06-2022, 10:50:14			
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15443+00	<b>Field Station#</b>	15464+00		
<b>Pic 11 Desc.</b>	Permanent vegetative stabilization and perimeter CFS in acceptable conditions	<b>Pic 12 Desc.</b>	Solar farm perimeter ECDs appear to be in acceptable conditions		

<b>A/E</b>	124300139	<b>Date/Time</b>	7/6/2022 10:22 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report


<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39483
<b>Inspector</b>	Logan Box			<b>Date/Time</b>	7/6/2022 4:35 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	13670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	13748+30
<b>County</b>	Franklin	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	88.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	1.00
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
3rd Party Damages	Communication				
Silt Fence (Filter Fabric Fence)	Communication				
Silt Fence (Reinforce Filter Fence)	Communication				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Timber Mat	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Rock Construction Entrance	Acceptable				
Sump Pit	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>AFE</b>	124300139	<b>Date/Time</b>	7/6/2022 4:35 PM	<b>Report #</b>	39483
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and ECDs at road crossings during routine inspection.</p> <p>Monitored sump pits and end treatment throughout areas of row.</p> <p>During inspection today the EI observed a area where 3rd party damages were done to the P1 and causing disturbed area where the land owner has made a travel lane across the LOD. The EI documented as non project related activities. Added the items to the punch list to be repaired and area stabilized.</p> <p>During routine inspection today the EI observed a section of reinforced silt fence that requires maintenance. Documented and added to the punch list for repair.</p> <p>Total measurable rainfall for today was 1" in the inspection area from rain events yesterday evening.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300139	<b>Date/Time</b>	7/6/2022 4:35 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	0000	<b>GPS Location</b>	0000		
<b>Field Station#</b>	13704+40	<b>Field Station#</b>	13704+90		
<b>Pic 1 Desc.</b>	Photo showing 3rd party activities where a land owner has made a travel lane across the row. Documented and added to the punch list to have the disturbed area stabilized.		<b>Pic 2 Desc.</b>	Additional photo showing where a land order has made a low water crossing downstream of the row outside the LOD. Documented as non project related activities.	
					
<b>GPS Location</b>	0000	<b>GPS Location</b>	0000		
<b>Field Station#</b>	13704+40	<b>Field Station#</b>	13704+90		
<b>Pic 3 Desc.</b>	3rd party damages to P1, Documented and sent in to be added to the punch list for repair.		<b>Pic 4 Desc.</b>	Additional photo showing where a land order has made a low water crossing downstream of the row outside the LOD. Documented as non project related activities.	
					
<b>GPS Location</b>	00000	<b>GPS Location</b>	00000		
<b>Field Station#</b>	13707+50	<b>Field Station#</b>	13696+03		
<b>Pic 5 Desc.</b>	Monitored sump pits and end treatment during routine inspection. No environmental issues observed at the time of inspection.		<b>Pic 6 Desc.</b>	Monitored ECDs at wetland area. All in place and functioning at the time of inspection.	



<b>A/E</b>	124300139	<b>Date/Time</b>	7/6/2022 4:35 PM	<b>Report #</b>	
<b>Pictures</b>					
		<p>Insert image here</p>		<p>Insert image here</p>	
<b>GPS Location</b>	00000	<b>GPS Location</b>			
<b>Field Station#</b>	13683+12	<b>Field Station#</b>			
<b>Pic 7 Desc.</b>	Row photo showing stabilization where equipment mats are in place in low area of row. No environmental issues observed at the time of inspection.	<b>Pic 8 Desc.</b>			
<p>Insert image here</p>		<p>Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
<p>Insert image here</p>		<p>Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300139	<b>Date/Time</b>	7/6/2022 4:35 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39470
<b>Inspector</b>	Ben Davenport			<b>Date/Time</b>	7/6/2022 12:33 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	14546+75
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	14649+67
<b>County</b>	Franklin	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	88.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	1.00
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Sump Pit	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Sediment Filter Log	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>AFE</b>	124300139	<b>Date/Time</b>	7/6/2022 12:33 PM	<b>Report #</b>	39470
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable	Permanent Vegetation			
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Checked rain gauges in covered area -Sunny with damp ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14546+75 — 14649+67 (Tobacco Rd to Hwy 40 crossing) -Walked ROW making note of condition of ROW and environmental controls -Verified the completion and accuracy of punch list items in covered area from previous inspections -Perimeter controls and ECDs were inspected; no issues identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -No items added to environmental punch list in section  -Rain Gauge Totals: +Farm View: 1.00 inches recorded +Timber Ridge: 0.90 inches recorded					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300139	<b>Date/Time</b>	7/6/2022 12:33 PM	<b>Report #</b>	
<b>Pictures</b>					
					
37°07' N 79°44'57" W 73°E COURSE 157' GPS 07.06.2022 08:56:40 Accur +/-15.4 Ft ALT 909 Ft			37°04' N 79°44'52" W 161°S COURSE 40' GPS 07.06.2022 09:02:35 594 Tobacco Rd, Glade Hill, VA 24092, United States Accur +/-15.4 Ft ALT 891 Ft		
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	14563+00	<b>Field Station#</b>	14567+00		
<b>Pic 1 Desc.</b>	Natural drainage area in good condition.	<b>Pic 2 Desc.</b>	Sump pit and CFS end treatment performing intended functions.		
					
37°04' N 79°44'52" W 102°E COURSE 147' GPS 07.06.2022 08:58:57 594 Tobacco Rd, Glade Hill, VA 24092, United States Accur +/-11.6 Ft ALT 889 Ft			36°59'54" N 79°44'22" W 99°E COURSE -1' GPS 07.06.2022 07:39:51 753 Simmons Creek Rd, Union Hall, VA 24176, United States Accur +/-15.6 Ft ALT 953 Ft		
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	14568+10	<b>Field Station#</b>	14595+00		
<b>Pic 3 Desc.</b>	Equipment bridge and surrounding ECDs in place and functional; signage visible and intact.	<b>Pic 4 Desc.</b>	Water bars performing intended functions.		
					
36°59'47" N 79°44'13" W 325°NW COURSE 230' GPS 07.06.2022 07:35:13 Sorry no results found Accur +/-17.9 Ft ALT 883 Ft			36°59'45" N 79°44'7" W 118°SE COURSE 31' GPS 07.06.2022 07:32:23 Union Hall, VA 24176, United States Accur +/-22.5 Ft ALT 909 Ft		
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	14602+50	<b>Field Station#</b>	14611+17		
<b>Pic 5 Desc.</b>	ROW stabilized and vegetated in temporary area.	<b>Pic 6 Desc.</b>	Equipment bridge and surrounding ECDs in place and functional; signage visible and intact.		



<b>A/E</b>	124300139	<b>Date/Time</b>	7/6/2022 12:33 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		







<b>A/E</b>	124300139	<b>Date/Time</b>	7/6/2022 12:33 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39510
<b>Inspector</b>	Charles Head			<b>Date/Time</b>	7/6/2022 11:11 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	14928+52
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	15063+85
<b>County</b>	Franklin/Pittsylvania	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	82.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.25
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
3rd Party Damages	Communication	Repair livestock/wildlife damage to F			
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	Repair livestock/wildlife damage			
Waterbar	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>AFE</b>	124300139	<b>Date/Time</b>	7/6/2022 11:11 AM	<b>Report #</b>	39510
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on daily punch list.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300139	<b>Date/Time</b>	7/6/2022 11:11 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15055+80	<b>Field Station#</b>	15044+90		
<b>Pic 1 Desc.</b>	Approximately 15055+80. Overview of stream crossing, equipment bridge and ECDs at stream S-D2-EPH.		<b>Pic 2 Desc.</b>	Approximately 15044+90. Overview of stream crossing, equipment bridge and ECDs at stream S-D2.	
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15000+00	<b>Field Station#</b>	14981+55		
<b>Pic 3 Desc.</b>	Approximately 15000+00. Overview of ROW.		<b>Pic 4 Desc.</b>	Approximately 14981+55. Overview of road crossing and RCEs.	
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	14968+00	<b>Field Station#</b>	15047+50		
<b>Pic 5 Desc.</b>	Approximately 14968+00. Overview of ROW. Permanent vegetation.		<b>Pic 6 Desc.</b>	Approximately 15047+50. P-1 requires maintenance. Damaged by livestock/wildlife.	



<b>A/E</b>	124300139	<b>Date/Time</b>	7/6/2022 11:11 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	7/6/2022 11:11 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		













# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39504
<b>Inspector</b>	John White			<b>Date/Time</b>	7/6/2022 10:06 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	15772+27
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	15947+64
<b>County</b>	Pittsylvania	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	78.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.60
				<b>Rain Accumulation Time (days)</b>	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Compost Filter Sock		Communication	Perform maintenance		
Silt Fence (Filter Fabric Fence)		Communication	Perform maintenance		
Housekeeping		Acceptable			
Equipment Bridge		Acceptable			
Rock Filter Outlet		Acceptable			
Rock-lined Channel		Acceptable			
Cleanwater Diversion Pipe		Acceptable			
Sump Pit		Acceptable			
Waterbar		Acceptable			
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300139	<b>Date/Time</b>	7/6/2022 10:06 AM	<b>Report #</b>	39504
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. Checked rain gauges, Anderson Mill #2=.6", Mill Creek =.6, Transco =2.1. Other than that there were no issues to report at the time of Inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300139	<b>Date/Time</b>	7/6/2022 10:06 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15826+90	<b>Field Station#</b>	15827+50		
<b>Pic 1 Desc.</b>	Observing P1 that requires maintenance		<b>Pic 2 Desc.</b>	Observing P1 that requires maintenance	
					
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15827+50	<b>Field Station#</b>	15849+30		
<b>Pic 3 Desc.</b>	Observing CFS that requires maintenance		<b>Pic 4 Desc.</b>	Observing CFS that requires maintenance	
					
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15827+60	<b>Field Station#</b>	15830+00		
<b>Pic 5 Desc.</b>	Observing P1 that requires maintenance		<b>Pic 6 Desc.</b>	Observing CFS that requires maintenance	

<b>AFE</b>	124300139	<b>Date/Time</b>	7/6/2022 10:06 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>South Elevation</b> <small>349°N (T) 36°51'12"N, 79°23'25"W ±298ft ▲ 809ft</small> 		<b>North Elevation</b> <small>182°S (T) 36°51'8"N, 79°23'18"W ±52ft ▲ 803ft</small> 			
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15839+00	<b>Field Station#</b>	15845+50		
<b>Pic 7 Desc.</b>	Observing temporary stabilization, rock drain and ECD's	<b>Pic 8 Desc.</b>	Observing temporary stabilization, CWD outlet, sump, end treatment and ECD's		
<b>West Elevation</b> <small>76°E (T) 36°51'8"N, 79°23'17"W ±4773ft ▲ 808ft</small> 		<b>North East Elevation</b> <small>220°SW (T) 36°51'14"N, 79°23'26"W ±242ft ▲ 816ft</small> 			
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15851+55	<b>Field Station#</b>	15835+00		
<b>Pic 9 Desc.</b>	Observing temporary stabilization, water bar, signage, buffer, equipment crossing and ECD's	<b>Pic 10 Desc.</b>	Observing the Contractor performing ECD maintenance		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300139	<b>Date/Time</b>	7/6/2022 10:06 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I	
<b>Contractor</b>	Precision			<b>Report #</b>	39566	
<b>Inspector</b>	Glenn Mike Renfro			<b>Date/Time</b>	7/7/2022 10:19 AM	
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	0000+00	
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	0000+00	
<b>County</b>	Franklin	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	81.00	
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	1.00	
				<b>Rain Accumulation Time (days)</b>	7.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable					
Housekeeping	Acceptable					
Rock Construction Entrance	Acceptable					
Secondary Containment	Acceptable					
Other - Explain in Comments	Acceptable	Inlet protection for catch basins				
<b>5. Site Conditions</b>						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No



<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 10:19 AM	<b>Report #</b>	39566
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
-Performed SWPPP inspections of Spread I laydown yards MVP-LY-045 and MVP-LY-046 in Rocky Mount, Va. - The locations have received 1" of rainfall since the last inspection and site conditions were damp. . - All perimeter ECD's were inspected and no issues were observed. - The inlet protection for the catch basins at LY-046 were found to be in acceptable condition. - All secondary containment structures were inspected and no issues were identified at the time of inspection. - The RCE at LY-045 was in good condition. - All equipment at both locations were inspected and no leaks were observed the during inspection. - The General Construction permits and contact information are posted at the entrance of LY-046 as required. - There ware no problems identified during today's inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	7/7/2022 10:19 AM	Report #	
Pictures					
					
GPS Location	See picture		GPS Location	See picture	
Field Station#	0000+00		Field Station#	0000+00	
Pic 1 Desc.	Perimeter ECD's on west side of LY-045 near employee parking area in good condition.		Pic 2 Desc.	RCE at LY-045 in good condition.	
					
GPS Location	See picture		GPS Location	See picture	
Field Station#	0000+00		Field Station#	0000+00	
Pic 3 Desc.	Secondary containment structure on south end of tent at LY-045 in good condition.		Pic 4 Desc.	Perimeter ECD's on north end of LY-045 in good condition.	
					
GPS Location	See picture		GPS Location	See picture	
Field Station#	0000+00		Field Station#	0000+00	
Pic 5 Desc.	Perimeter ECD's on south end of LY-046 in good condition.		Pic 6 Desc.	Secondary containment structure for fuel cell at LY-046 in good condition.	

<b>AFE</b>	124300139	<b>Date/Time</b>	7/7/2022 10:19 AM	<b>Report #</b>	
<b>Pictures</b>					
		Insert image here			
<b>GPS Location</b>	See picture				
<b>Field Station#</b>	0000+00	<b>Field Station#</b>			
<b>Pic 7 Desc.</b>	Perimeter ECD's and inlet protection for catch basin at LY-046 in good condition.		<b>Pic 8 Desc.</b>		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 10:19 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		











# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I	
<b>Contractor</b>	Precision			<b>Report #</b>	39583	
<b>Inspector</b>	Frank Craycroft			<b>Date/Time</b>	7/7/2022 3:01 PM	
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	0+00	
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	0+00	
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	90.00	
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00	
				<b>Rain Accumulation Time (days)</b>	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Rock Construction Entrance		Acceptable				
Secondary Containment		Acceptable				
Timber Mat		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waste Management		Acceptable				
<b>5. Site Conditions</b>						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 3:01 PM	<b>Report #</b>	39583
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted SWPPP inspection of LY-032, -033, -048, and ANC-006. All perimeter ECDs were functional and in good condition. Portable equipment and hazardous materials were maintained within secondary containment. Construction entrances were free of dirt buildup and yards were free of loose debris and trash. Stormwater drain inlets had proper perimeter protection and were free of vegetation and debris. No issues were observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	7/7/2022 3:01 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 1 Desc.	LY-033 Stormwater drain inlet protection		Pic 2 Desc.	LY-032 Secondary containment	
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 3 Desc.	LY-033 Rock construction entrance		Pic 4 Desc.	LY-032 Staging area	
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 5 Desc.	ANC-006 Stormwater drain inlet protection		Pic 6 Desc.	ANC-006 Secondary containment	

<b>AFE</b>	124300139	<b>Date/Time</b>	7/7/2022 3:01 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	0+00	<b>Field Station#</b>	0+00		
<b>Pic 7 Desc.</b>	LY-048 Housekeeping	<b>Pic 8 Desc.</b>	LY-048 Temporary vegetation		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			









<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 3:01 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39580
<b>Inspector</b>	Ben Farmer			<b>Date/Time</b>	7/7/2022 2:50 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	14171+36
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	14311+57
<b>County</b>	Franklin	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Waterbar	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>AFE</b>	124300139	<b>Date/Time</b>	7/7/2022 2:50 PM	<b>Report #</b>	39580
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable	Permanent vegetation remains in go			
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 80F) Rain Gauge= 0.0" 14171+36-14311+57  -RCEs are in good condition at all road crossings. -Equipment bridge ECDs are in good condition and functioning -CWDs are functioning as intended. -SSF is in good condition -P1 is in good condition at all stream and wetland buffers. -Waterbars are in good condition throughout this section. -Slope drain is in good condition and functioning at 14232+00 -Resource buffers remain well vegetated. -CFS is in good condition throughout this section -Topsoil berms remain stabilized					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300139	<b>Date/Time</b>	7/7/2022 2:50 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	14176+09	<b>Field Station#</b>	14180+00		
<b>Pic 1 Desc.</b>	Equipment bridge ECDs are in good condition and functioning	<b>Pic 2 Desc.</b>	CWDs are functioning as intended		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	14181+00	<b>Field Station#</b>	14209+02		
<b>Pic 3 Desc.</b>	SSF is in good condition throughout this section	<b>Pic 4 Desc.</b>	Equipment bridge ECDs are in good condition and functioning		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	14213+75	<b>Field Station#</b>	14223+41		
<b>Pic 5 Desc.</b>	Resource buffers remain well vegetated	<b>Pic 6 Desc.</b>	MVP-FR-311 remains in good condition with controls in place		



<b>AFE</b>	124300139	<b>Date/Time</b>	7/7/2022 2:50 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	14232+00		<b>Field Station#</b>	14273+00	
<b>Pic 7 Desc.</b>	Slope drain is functioning as intended		<b>Pic 8 Desc.</b>	CFS is in good condition throughout this section	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	14277+00		<b>Field Station#</b>	14277+00	
<b>Pic 9 Desc.</b>	Waterbars are in good condition		<b>Pic 10 Desc.</b>	End treatments are functioning as intended	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	14278+50		<b>Field Station#</b>	14305+00	
<b>Pic 11 Desc.</b>	P1 is in good condition at all stream and wetland buffers		<b>Pic 12 Desc.</b>	CWDs are functioning as intended	

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 2:50 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		







# Visual Site Inspection Report

<b>Project Name</b>	H-603 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-603 Pipeline Spread I	
<b>Contractor</b>	Precision			<b>Report #</b>	39557	
<b>Inspector</b>	John White			<b>Date/Time</b>	7/7/2022 9:46 AM	
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	00+00	
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	24+53	
<b>County</b>	Pittsylvania	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	83.00	
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	2.30	
				<b>Rain Accumulation Time (days)</b>	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Rock Construction Entrance		Acceptable				
Sensitive Resource Buffer		Acceptable				
Sump Pit		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waterbar		Acceptable				
Waterbar End Treatment		Acceptable				
<b>5. Site Conditions</b>						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 9:46 AM	<b>Report #</b>	39557
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 9:46 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>South East Elevation</b> 332°NW (T) 36°50'7"N, 79°20'23"W ±39ft ▲652ft  <small>Your Watermark 07 Jul 2022, 07:52:04</small>			<b>East Elevation</b> 290°W (T) 36°50'1"N, 79°20'15"W ±45ft ▲656ft  <small>Your Watermark 07 Jul 2022, 07:52:45</small>		
<b>GPS Location</b>	O		<b>GPS Location</b>	O	
<b>Field Station#</b>	14+00		<b>Field Station#</b>	22+00	
<b>Pic 1 Desc.</b>	Observing temporary stabilization,RCE,buffer and ECD's		<b>Pic 2 Desc.</b>	Observing temporary stabilization and buffer	
<b>West Elevation</b> 83°E (T) 36°50'6"N, 79°20'23"W ±853ft ▲647ft  <small>Your Watermark 07 Jul 2022, 07:54:23</small>			<b>North Elevation</b> 168°S (T) 36°50'6"N, 79°20'24"W ±45ft ▲656ft  <small>Your Watermark 07 Jul 2022, 07:54:31</small>		
<b>GPS Location</b>	O		<b>GPS Location</b>	O	
<b>Field Station#</b>	12+00		<b>Field Station#</b>	6+00	
<b>Pic 3 Desc.</b>	Observing temporary stabilization, sump and end treatment		<b>Pic 4 Desc.</b>	Observing temporary stabilization and water bar	
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 5 Desc.</b>			<b>Pic 6 Desc.</b>		

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 9:46 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 9:46 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report





<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39568
<b>Inspector</b>	Justin Burch			<b>Date/Time</b>	7/7/2022 10:32 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	15480+67
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	15584+23
<b>County</b>	Pittsylvania	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	92.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.50
				<b>Rain Accumulation Time (days)</b>	7.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Vegetative Stabilization (Temporary)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Sensitive Resource Buffer	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Equipment Bridge	Acceptable				
Slope Drain Pipe	Acceptable				
Sump Pit	Acceptable				
Rock Construction Entrance	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 10:32 AM	<b>Report #</b>	39568
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable	Permanent Vegetation			
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> <li>The EI performed a SWPPP inspection from 15480+67 to 15584+23 (Toshes Road to Anderson Mill Road 1). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection.</li> <li>The EI observed that the solar farm ECDs adjacent to the ROW on both sides of Climax Road appeared to be in acceptable condition and that solar farm grading is continuing between Toshes Road and Climax Road.</li> <li>The EI did not observe that any contractor activity has occurred in the area since the last SWPPP inspection.</li> <li>Since the last SWPPP inspection the area has received two rain events with a total of 0.60" at Snowberry Road.</li> <li>The ROW ground condition is wet.</li> <li>At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15482+00 to 15495+00.</li> <li>At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion.</li> </ul>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 10:32 AM	<b>Report #</b>	
<b>Pictures</b>					
332°NW (T) 17 N 635973 4085250 ±3894ft ▲ 940ft  15498+00 07-07-2022, 09:15:33		297°NW (T) 17 N 636192 4085455 ±16ft ▲ 858ft  15508+00 07-07-2022, 09:22:34			
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15498+00	<b>Field Station#</b>	15508+00		
<b>Pic 1 Desc.</b>	Temporary vegetative stabilization in acceptable condition	<b>Pic 2 Desc.</b>	P1 silt fence and sensitive resource buffer in acceptable condition		
245°SW (T) 17 N 636242 4085418 ±13ft ▲ 876ft  15510+00 07-07-2022, 09:24:08		267°W (T) 17 N 636222 4085408 ±16ft ▲ 872ft  15510+00 07-07-2022, 09:24:34			
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15510+00	<b>Field Station#</b>	15510+00		
<b>Pic 3 Desc.</b>	Waterbar in acceptable condition	<b>Pic 4 Desc.</b>	Waterbar end treatment in acceptable condition		
145°SE (T) 17 N 636363 4085298 ±32ft ▲ 863ft  15517+00 07-07-2022, 09:27:27		335°NW (T) 17 N 636370 4085289 ±22ft ▲ 861ft  15521+00 07-07-2022, 09:35:20			
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15517+00	<b>Field Station#</b>	15521+00		
<b>Pic 5 Desc.</b>	Temporary vegetative stabilization in acceptable condition	<b>Pic 6 Desc.</b>	Equipment bridge in acceptable condition		



<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 10:32 AM	<b>Report #</b>	
<b>Pictures</b>					
<small>52°NE (T) 17 N 637702 4084511 ±52ft ▲ 832ft</small> 		<small>84°E (T) 17 N 637713 4084522 ±1870ft ▲ 837ft</small> 			
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15570+00	<b>Field Station#</b>	15570+00		
<b>Pic 7 Desc.</b>	Waterbar in acceptable condition	<b>Pic 8 Desc.</b>	Waterbar end treatment in acceptable condition		
<small>321°NW (T) 17 N 637898 4084411 ±16ft ▲ 780ft</small> 		<small>115°SE (T) 17 N 638090 4084286 ±32ft ▲ 811ft</small> 			
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15576+00	<b>Field Station#</b>	15584+00		
<b>Pic 9 Desc.</b>	Slope drain pipe and sump pit in acceptable condition	<b>Pic 10 Desc.</b>	Rock construction entrance in acceptable condition		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 10:32 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-602 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-602 Pipeline Spread I	
<b>Contractor</b>	Precision			<b>Report #</b>	39564	
<b>Inspector</b>	John White			<b>Date/Time</b>	7/7/2022 9:59 AM	
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	00+00	
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	19+25	
<b>County</b>	Pittsylvania	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	84.00	
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	2.30	
				<b>Rain Accumulation Time (days)</b>	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock		Acceptable				
Equipment Bridge		Acceptable				
Housekeeping		Acceptable				
Sediment Filter Log		Acceptable				
Sensitive Resource Buffer		Acceptable				
Sensitive Resource Signage		Acceptable				
Silt Fence (Filter Fabric Fence)		Acceptable				
Sump Pit		Acceptable				
Waterbar		Acceptable				
<b>5. Site Conditions</b>						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 9:59 AM	<b>Report #</b>	39564
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 9:59 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>North Elevation</b> 199°S (T) 36°49'52"N, 79°20'34"W ±3914ft ▲643ft  <small>Your Watermark 07 Jul 2022, 08:19:58</small>		<b>North Elevation</b> 188°S (T) 36°49'45"N, 79°20'40"W ±1400ft ▲631ft  <small>Your Watermark 07 Jul 2022, 08:20:38</small>			
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	6+00	<b>Field Station#</b>	12+65		
<b>Pic 1 Desc.</b>	Observing temporary stabilization and access road		<b>Pic 2 Desc.</b>	Observing temporary stabilization,buffer, equipment crossing and ECD's	
<b>West Elevation</b> 70°E (T) 36°49'44"N, 79°20'39"W ±1371ft ▲625ft  <small>Your Watermark 07 Jul 2022, 08:21:27</small>		<b>North West Elevation</b> 157°SE (T) 36°49'43"N, 79°20'40"W ±42ft ▲621ft  <small>Your Watermark 07 Jul 2022, 08:21:33</small>			
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	13+50	<b>Field Station#</b>	15+00		
<b>Pic 3 Desc.</b>	Observing temporary stabilization,water bar, sump, end treatment and ECD's		<b>Pic 4 Desc.</b>	Observing temporary stabilization and signage	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 5 Desc.</b>			<b>Pic 6 Desc.</b>		

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 9:59 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 9:59 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		




# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39572
<b>Inspector</b>	Logan Box			<b>Date/Time</b>	7/7/2022 4:44 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	13748+30
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	13853+45
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	92.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Waterbar	Acceptable				
Erosion Control Blanket	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Sump Pit	Acceptable				
Plunge Pool	Acceptable				
Rock Construction Entrance	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 4:44 PM	<b>Report #</b>	39572
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout. Inspected all stream and wetland crossings, checked equipment bridges and protection. Monitored RCEs and ECDs at road crossings during routine inspection. Monitored sump pits and end treatment throughout areas of row. During inspection today there were no environmental issues observed at the time of inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 4:44 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	00000	<b>GPS Location</b>	0000		
<b>Field Station#</b>	13847+03	<b>Field Station#</b>	13846+93		
<b>Pic 1 Desc.</b>	Monitored equipment bridge and ECDs at stream crossing. No environmental issues observed at the time of inspection.		<b>Pic 2 Desc.</b>	Stream observation photo facing upstream during routine. No environmental issues observed at the time of inspection.	
					
<b>GPS Location</b>	0000	<b>GPS Location</b>	0000		
<b>Field Station#</b>	13782+68	<b>Field Station#</b>	13845+89		
<b>Pic 3 Desc.</b>	Monitored ECDs throughout the row inspection. No environmental issues observed at the time of inspection.		<b>Pic 4 Desc.</b>	Stabilization observation on side slope. Good coverage noted.	
					
<b>GPS Location</b>	00000	<b>GPS Location</b>	000000		
<b>Field Station#</b>	13787+00	<b>Field Station#</b>	13846+93		
<b>Pic 5 Desc.</b>	Row photo showing water bars in place in a temporary area of row. Good stabilization noted during the time of inspection.		<b>Pic 6 Desc.</b>	Stream observation photo facing downstream during routine inspection. No environmental issues observed at the time of inspection.	



<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 4:44 PM	<b>Report #</b>	
<b>Pictures</b>					
		<p>Insert image here</p>		<p>Insert image here</p>	
<b>GPS Location</b>	00000	<b>GPS Location</b>	0000		
<b>Field Station#</b>	13784+20	<b>Field Station#</b>			
<b>Pic 7 Desc.</b>	Monitored sump pit and plunge pool after recent rain events, all in place and functioning at the time of inspection.		<b>Pic 8 Desc.</b>		
<p>Insert image here</p>		<p>Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
<p>Insert image here</p>		<p>Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 4:44 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39527
<b>Inspector</b>	Ben Davenport			<b>Date/Time</b>	7/7/2022 12:01 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	14649+67
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	14694+77
<b>County</b>	Franklin	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	88.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	1.40
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Compost Filter Sock		Communication	Routine maintenance		
Sediment Filter Log		Communication	Routine maintenance		
Vegetative Stabilization (Permanent)		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Silt Fence (Filter Fabric Fence)		Acceptable			
Temporary Diversion Berm		Acceptable			
Waterbar		Acceptable			
Waterbar End Treatment		Acceptable			
Sump Pit		Acceptable			
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>AFE</b>	124300139	<b>Date/Time</b>	7/7/2022 12:01 PM	<b>Report #</b>	39527
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable	Permanent Vegetation			
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Checked rain gauges in covered area -Sunny with damp ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14649+67 — 14694+77 (Hwy 40 crossing to Jacks Creek Rd) -Walked ROW making note of condition of ROW and environmental controls -Verified the completion and accuracy of punch list items in covered area from previous inspections -Perimeter controls and ECDs were inspected; no issues identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; 2 issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -2 items added to environmental punch list in section  -Rain Gauge Totals: +Farm View: 0.25 inches recorded +Timber Ridge: 1.40 inches recorded					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300139	<b>Date/Time</b>	7/7/2022 12:01 PM	<b>Report #</b>	
<b>Pictures</b>					
					
36°59'25" N 79°43'24" W 81°E COURSE 195° GPS Sorry no results found 07.07.2022 10:26:09 Accur +/-15.4 Ft ALT 992 Ft			36°59'21" N 79°43'19" W 117°SE COURSE 96° GPS Sorry no results found 07.07.2022 10:29:10 Accur +/-15.4 Ft ALT 942 Ft		
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	14652+00	<b>Field Station#</b>	14656+87		
<b>Pic 1 Desc.</b>	Routine maintenance. Repair/replace damaged perimeter CFS.		<b>Pic 2 Desc.</b>	Routine maintenance. Replace all bridge wattles at S-H38.	
					
36°59'25" N 79°43'24" W 202°S COURSE 126° GPS Sorry no results found 07.07.2022 10:26:19 Accur +/-15.4 Ft ALT 987 Ft			36°59'21" N 79°43'17" W 115°SE COURSE 97° GPS Sorry no results found 07.07.2022 10:29:34 Accur +/-15.4 Ft ALT 943 Ft		
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	14654+00	<b>Field Station#</b>	14663+50		
<b>Pic 3 Desc.</b>	ROW stabilized and vegetated in final cleanup area.		<b>Pic 4 Desc.</b>	Temporary diversion berm stabilized and vegetated; ROW stabilized and vegetated.	
					
36°59'20" N 79°43'13" W 311°NW COURSE 160° GPS Union Hall, VA 24176, United States 07.07.2022 10:31:31 Accur +/-223.0 Ft ALT 941 Ft			36°59'22" N 79°43'21" W 94°E COURSE 307° GPS 07.07.2022 10:28:12 Accur +/-15.4 Ft ALT 952 Ft		
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	14678+00	<b>Field Station#</b>	14681+00		
<b>Pic 5 Desc.</b>	Sump pit and CFS end treatment performing intended functions.		<b>Pic 6 Desc.</b>	Perimeter P1 silt fence in good condition.	

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 12:01 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 12:01 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39556
<b>Inspector</b>	Charles Head			<b>Date/Time</b>	7/7/2022 9:24 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	15063+85
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	15142+66
<b>County</b>	Pittsylvania	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	81.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.50
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Waterbar	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 9:24 AM	<b>Report #</b>	39556
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 9:24 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15138+00	<b>Field Station#</b>	15113+50		
<b>Pic 1 Desc.</b>	Approximately 15138+00. Overview of ROW.	<b>Pic 2 Desc.</b>	Approximately 15113+50. Overview of road crossing and RCEs.		
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15065+00	<b>Field Station#</b>	15072+86		
<b>Pic 3 Desc.</b>	Approximately 15065+00. Overview of ROW.	<b>Pic 4 Desc.</b>	Approximately 15072+86. Overview of stream crossing, equipment bridge and ECDs at stream S-G11.		
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15086+00	<b>Field Station#</b>	15116+00		
<b>Pic 5 Desc.</b>	Approximately 15086+00. Overview of ROW.	<b>Pic 6 Desc.</b>	Approximately 15116+00. Overview of ROW.		

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 9:24 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 9:24 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		











# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39565
<b>Inspector</b>	John White			<b>Date/Time</b>	7/7/2022 10:05 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	15947+64
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	16027+46
<b>County</b>	Pittsylvania	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	84.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	2.30
				<b>Rain Accumulation Time (days)</b>	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Cleanwater Diversion Berm		Acceptable			
Cleanwater Diversion Pipe		Acceptable			
Compost Filter Sock		Acceptable			
Equipment Bridge		Acceptable			
Housekeeping		Acceptable			
Rock Filter Outlet		Acceptable			
Sediment Filter Log		Acceptable			
Sump Pit		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 10:05 AM	<b>Report #</b>	39565
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. Checked rain gauges, Anderson Mill #2=.5", Mill Creek =.10", Transco =.10". There were no issues to report at the time of Inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300139	<b>Date/Time</b>	7/7/2022 10:05 AM	<b>Report #</b>	
<b>Pictures</b>					
	<b>South East Elevation</b> 297°NW (T) 36°49'50"N, 79°20'37"W ±298ft ▲ 640ft  <small>Your Watermark 07 Jul 2022 09:31:42</small>			<b>North Elevation</b> 201°S (T) 36°49'50"N, 79°20'38"W ±22ft ▲ 639ft  <small>Your Watermark 07 Jul 2022 09:31:53</small>	
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	16023+00	<b>Field Station#</b>	16020+00		
<b>Pic 1 Desc.</b>	Observing temporary stabilization	<b>Pic 2 Desc.</b>	Observing temporary stabilization and water bar		
	<b>North West Elevation</b> 154°SE (T) 36°49'50"N, 79°20'41"W ±9297ft ▲ 638ft  <small>Your Watermark 07 Jul 2022 09:34:15</small>			<b>North Elevation</b> 165°S (T) 36°49'46"N, 79°20'45"W ±3503ft ▲ 608ft  <small>Your Watermark 07 Jul 2022 09:35:26</small>	
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	16016+36	<b>Field Station#</b>	16012+00		
<b>Pic 3 Desc.</b>	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	<b>Pic 4 Desc.</b>	Observing temporary stabilization and CWD berm		
	<b>South West Elevation</b> 52°NE (T) 36°49'45"N, 79°20'49"W ±108ft ▲ 611ft  <small>Your Watermark 07 Jul 2022 09:36:39</small>			<b>West Elevation</b> 90°E (T) 36°49'43"N, 79°20'52"W ±203ft ▲ 621ft  <small>Your Watermark 07 Jul 2022 09:37:07</small>	
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	16010+00	<b>Field Station#</b>	16007+00		
<b>Pic 5 Desc.</b>	Observing temporary stabilization, CWD outlet and ECD's	<b>Pic 6 Desc.</b>	Observing temporary stabilization, sump and end treatment		

<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 10:05 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









<b>A/E</b>	124300139	<b>Date/Time</b>	7/7/2022 10:05 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39617
<b>Inspector</b>	Ben Farmer			<b>Date/Time</b>	7/8/2022 12:39 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	13853+45
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	13958+31
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.40
				<b>Rain Accumulation Time (days)</b>	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Waterbar	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300139	<b>Date/Time</b>	7/8/2022 12:39 PM	<b>Report #</b>	39617
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable	Permanent vegetation remains in go			
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 80F) Rain Gauge= 0.4" 13853+45-13958+31  -Resource buffers remain well vegetated at all stream and wetland crossings. -CWDs are in good condition and functioning as intended -Equipment bridge ECDs are in good condition and functioning. -P1 is in good condition at all stream and wetland buffers -CFS is in good condition throughout this section. -Steep slope at 13889+00 remains stabilized. -RCEs are in good condition at all road crossings. -Topsoil berms remain stabilized. -Sediment trap at 13897+00 is in good condition with no evidence of discharge. -Waterbars/end treatments are in good condition. -Slope drain is functioning at 13955+00. -Vegetation continues to fill in throughout this section.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300139	<b>Date/Time</b>	7/8/2022 12:39 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	13863+00		<b>Field Station#</b>	13875+73	
<b>Pic 1 Desc.</b>	Resource buffers remain well vegetated		<b>Pic 2 Desc.</b>	Equipment bridge ECDs are functioning as intended	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	13876+00		<b>Field Station#</b>	13888+00	
<b>Pic 3 Desc.</b>	P1 is in good condition at all stream and wetland buffers		<b>Pic 4 Desc.</b>	Slope drain is in good condition and functioning	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	13890+00		<b>Field Station#</b>	13892+45	
<b>Pic 5 Desc.</b>	Waterbars are in good condition		<b>Pic 6 Desc.</b>	RCEs are in good condition at all road crossings	



<b>AFE</b>	124300139	<b>Date/Time</b>	7/8/2022 12:39 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	13897+00		<b>Field Station#</b>	13897+00	
<b>Pic 7 Desc.</b>	Topsoil berms remain stabilized		<b>Pic 8 Desc.</b>	Sediment trap is functioning as intended	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	13925+00		<b>Field Station#</b>	13939+50	
<b>Pic 9 Desc.</b>	CFS is in good condition throughout this section		<b>Pic 10 Desc.</b>	SSF is in good condition	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	13942+00		<b>Field Station#</b>	13953+00	
<b>Pic 11 Desc.</b>	CWDs are in good condition and functioning		<b>Pic 12 Desc.</b>	Slope drain outlet is functioning as intended.	

<b>A/E</b>	124300139	<b>Date/Time</b>	7/8/2022 12:39 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report





<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39616
<b>Inspector</b>	Justin Burch			<b>Date/Time</b>	7/8/2022 12:12 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	15142+66
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	15260+00
<b>County</b>	Pittsylvania	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	86.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	1.20
				<b>Rain Accumulation Time (days)</b>	7.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Vegetative Stabilization (Temporary)		Acceptable			
Waterbar		Acceptable			
Waterbar End Treatment		Acceptable			
Equipment Bridge		Acceptable			
Silt Fence (Reinforce Filter Fence)		Acceptable			
Slope Drain Pipe		Acceptable			
Sump Pit		Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)		Acceptable			
Compost Filter Sock		Communication			
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300139	<b>Date/Time</b>	7/8/2022 12:12 PM	<b>Report #</b>	39616
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable	Permanent Vegetation			
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> <li>The EI performed a SWPPP inspection from 15142+66 to 15260+00 (Rock Creek Road to the Pigg River HDD Exit). One issue was submitted for the punch list consisting of a location where heavy rainfall had dislocated CFS checks and the perimeter CFS on both sides of the ROW was covered with sediment and debris. Other inspected ECDs were observed as in compliance at the time of inspection.</li> <li>The EI did not observe that any contractor activity has occurred in the area since the last SWPPP inspection.</li> <li>Since the last SWPPP inspection the inspection area has received three rainfall events totaling 1.20" at Snowberry Road.</li> <li>The ROW ground condition is dry.</li> <li>At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15145+00 to 15153+00 and from 15173+00 to 15260+00.</li> <li>At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion.</li> </ul>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300139	<b>Date/Time</b>	7/8/2022 12:12 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15153+00	<b>Field Station#</b>	15159+00		
<b>Pic 1 Desc.</b>	Temporary vegetative stabilization in acceptable condition	<b>Pic 2 Desc.</b>	Waterbar in acceptable condition		
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15159+00	<b>Field Station#</b>	15165+00		
<b>Pic 3 Desc.</b>	Waterbar end treatment in acceptable condition	<b>Pic 4 Desc.</b>	Temporary vegetative stabilization in acceptable condition		
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15168+59	<b>Field Station#</b>	15169+00		
<b>Pic 5 Desc.</b>	Equipment bridge in acceptable condition	<b>Pic 6 Desc.</b>	P1 silt fence and temporary vegetative stabilization in acceptable conditions		



<b>AFE</b>	124300139	<b>Date/Time</b>	7/8/2022 12:12 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15169+00	<b>Field Station#</b>	15170+00		
<b>Pic 7 Desc.</b>	Slope drain pipe and sump pit in acceptable conditions		<b>Pic 8 Desc.</b>	Super silt fence in acceptable condition	
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15195+00	<b>Field Station#</b>	15229+00		
<b>Pic 9 Desc.</b>	CFS checks are dislocated and perimeter CFS on both sides of the ROW is covered with sediment and debris		<b>Pic 10 Desc.</b>	Waterbar end treatment in acceptable condition	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>			<b>Pic 12 Desc.</b>		

<b>A/E</b>	124300139	<b>Date/Time</b>	7/8/2022 12:12 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39586
<b>Inspector</b>	Ben Davenport			<b>Date/Time</b>	7/8/2022 1:15 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	14311+57
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	14454+22
<b>County</b>	Franklin	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	88.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.60
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Rock Construction Entrance	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Sensitive Resource Buffer	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Temporary Diversion Berm	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>AFE</b>	124300139	<b>Date/Time</b>	7/8/2022 1:15 PM	<b>Report #</b>	39586
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable	Permanent Vegetation			
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Checked rain gauges in covered area -Sunny with damp ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14311+57 — 14454+22 (Farm View Rd to Webster Rd) -Walked ROW making note of condition of ROW and environmental controls -Verified the completion and accuracy of punch list items in covered area from previous inspections -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -No items added to environmental punch list  -Rain Gauge Totals: +Farm View: 0.30 inches recorded +Timber Ridge: 0.60 inches recorded					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300139	<b>Date/Time</b>	7/8/2022 1:15 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<small>37°23'34" N 79°48'35" W 258°W COURSE 0° GPS 530 Farm View Rd, Glade Hill, VA 24092, United States 07.08.2022 10:27:42 Accur +/-15.5 Ft ALT 1071 Ft</small>			<small>37°2'34" N 79°48'36" W 181°S COURSE 201° GPS 530 Farm View Rd, Glade Hill, VA 24092, United States 07.08.2022 10:28:30 Accur +/-11.6 Ft ALT 1068 Ft</small>		
<b>GPS Location</b>	1		<b>GPS Location</b>	2	
<b>Field Station#</b>	14311+57		<b>Field Station#</b>	14312+00	
<b>Pic 1 Desc.</b>	RCE in good condition.		<b>Pic 2 Desc.</b>	Perimeter P1 silt fence in place and functional.	
					
<small>37°2'9" N 79°47'55" W 304°NW COURSE 167° GPS Glade Hill, VA 24092, United States 07.08.2022 11:55:27 Accur +/-12.0 Ft ALT 1097 Ft</small>			<small>37°2'8" N 79°47'47" W 159°SE COURSE -1° GPS Glade Hill, VA 24092, United States 07.08.2022 11:51:45 Accur +/-15.1 Ft ALT 1106 Ft</small>		
<b>GPS Location</b>	3		<b>GPS Location</b>	4	
<b>Field Station#</b>	14353+53		<b>Field Station#</b>	14362+00	
<b>Pic 3 Desc.</b>	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.		<b>Pic 4 Desc.</b>	Plunge pool in good condition.	
					
<small>37°2'9" N 79°47'54" W 309°NW COURSE -1° GPS Glade Hill, VA 24092, United States 07.08.2022 11:54:43 Accur +/-15.1 Ft ALT 1104 Ft</small>			<small>37°2'5" N 79°47'37" W 144°SE COURSE -1° GPS Glade Hill, VA 24092, United States 07.08.2022 12:02:21 Accur +/-15.1 Ft ALT 1084 Ft</small>		
<b>GPS Location</b>	5		<b>GPS Location</b>	6	
<b>Field Station#</b>	14371+00		<b>Field Station#</b>	14383+00	
<b>Pic 5 Desc.</b>	Sump pit and CFS end treatment performing intended functions.		<b>Pic 6 Desc.</b>	ROW stabilized and vegetated in temporary area; temporary diversion berm stabilized and vegetated.	

<b>A/E</b>	124300139	<b>Date/Time</b>	7/8/2022 1:15 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300139	<b>Date/Time</b>	7/8/2022 1:15 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39610
<b>Inspector</b>	Charles Head			<b>Date/Time</b>	7/8/2022 10:15 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	14694+77
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	14802+19
<b>County</b>	Franklin	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	81.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.25
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Communication	Re-stake CFS			
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300139	<b>Date/Time</b>	7/8/2022 10:15 AM	<b>Report #</b>	39610
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on daily punch list.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300139	<b>Date/Time</b>	7/8/2022 10:15 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	14758+50	<b>Field Station#</b>	14800+00		
<b>Pic 1 Desc.</b>	Approximately 14758+50. Overview of road crossing and RCEs.		<b>Pic 2 Desc.</b>	Approximately 14800+00. Overview of ROW.	
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	15700+75	<b>Field Station#</b>	14723+00		
<b>Pic 3 Desc.</b>	Approximately 14700+75. Overview of stream crossing, equipment bridge and ECDs at stream S-H32.		<b>Pic 4 Desc.</b>	Approximately 14723+00. Overview of ROW.	
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	14696+00	<b>Field Station#</b>	14717+00		
<b>Pic 5 Desc.</b>	Approximately 14696+00. Overview of ROW.		<b>Pic 6 Desc.</b>	Approximately 14717+00. CFS requires maintenance.	

<b>A/E</b>	124300139	<b>Date/Time</b>	7/8/2022 10:15 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









<b>A/E</b>	124300139	<b>Date/Time</b>	7/8/2022 10:15 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	39605
<b>Inspector</b>	John White			<b>Date/Time</b>	7/8/2022 9:48 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	15584+23
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	15647+03
<b>County</b>	Pittsylvania	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	1.60
				<b>Rain Accumulation Time (days)</b>	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Cleanwater Diversion Pipe		Acceptable			
Compost Filter Sock		Acceptable			
Equipment Bridge		Acceptable			
Housekeeping		Acceptable			
Rock Construction Entrance		Acceptable			
Rock Filter Outlet		Acceptable			
Sensitive Resource Buffer		Acceptable			
Sensitive Resource Signage		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300139	<b>Date/Time</b>	7/8/2022 9:48 AM	<b>Report #</b>	39605
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300139	<b>Date/Time</b>	7/8/2022 9:48 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>South Elevation</b> 17°N (T) 36°53'19"N, 79°25'57"W ±118ft ▲ 814ft 		<b>North East Elevation</b> 233°SW (T) 36°53'20"N, 79°25'58"W ±19ft ▲ 820ft 			
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15647+03	<b>Field Station#</b>	15646+00		
<b>Pic 1 Desc.</b>	Observing road crossing and RCE's	<b>Pic 2 Desc.</b>	Observing temporary stabilization, sump and end treatment		
<b>South Elevation</b> 347°N (T) 36°53'28"N, 79°26'0"W ±85ft ▲ 791ft 		<b>East Elevation</b> 293°W (T) 36°53'29"N, 79°26'0"W ±52ft ▲ 782ft 			
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15638+00	<b>Field Station#</b>	15636+45		
<b>Pic 3 Desc.</b>	Observing temporary stabilization and water bar	<b>Pic 4 Desc.</b>	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
<b>South Elevation</b> 344°N (T) 36°53'32"N, 79°26'6"W ±68ft ▲ 781ft 		<b>West Elevation</b> 84°E (T) 36°53'39"N, 79°26'53"W ±4648ft ▲ 831ft 			
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15632+00	<b>Field Station#</b>	15590+00		
<b>Pic 5 Desc.</b>	Observing temporary stabilization, CWD outlet and ECD's	<b>Pic 6 Desc.</b>	Observing temporary stabilization and water bars		



<b>A/E</b>	124300139	<b>Date/Time</b>	7/8/2022 9:48 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	7/8/2022 9:48 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	Transco Interconnect Station	<b>AFE</b>	124300113	<b>Spread</b>	Transco Interconnect Sta
<b>Contractor</b>	Kanahwa			<b>Report #</b>	39563
<b>Inspector</b>	John White			<b>Date/Time</b>	7/7/2022 9:53 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	00+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	00+00
<b>County</b>	Pittsylvania	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	84.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	2.30
				<b>Rain Accumulation Time (days)</b>	6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Rock-lined Channel	Acceptable			
Sediment Basin	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300113	<b>Date/Time</b>	7/7/2022 9:53 AM	<b>Report #</b>	39563
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed SWPPP Inspection on the Transco Facility and Lay down yard. There were no issues to report at the time of Inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300113	<b>Date/Time</b>	7/7/2022 9:53 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	00+00	<b>Field Station#</b>	00+00		
<b>Pic 1 Desc.</b>	Observing RCE	<b>Pic 2 Desc.</b>	Observing temporary stabilization, access road and rock check dams		
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	00+00	<b>Field Station#</b>	00+00		
<b>Pic 3 Desc.</b>	Observing lay down yard	<b>Pic 4 Desc.</b>	Observing temporary stabilization, rock drain and CFS checks		
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	00+00	<b>Field Station#</b>	00+00		
<b>Pic 5 Desc.</b>	Observing temporary stabilization and sediment basin	<b>Pic 6 Desc.</b>	Observing temporary stabilization, storm water pond and ECD's		

<b>A/E</b>	124300113	<b>Date/Time</b>	7/7/2022 9:53 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300113	<b>Date/Time</b>	7/7/2022 9:53 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>			
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>			
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>			