Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	**AFE**	124300137	**Spread**	H-600 Pipeline Spread G
Contractor	Precision			**Report #**	6056
Inspector	Clinton Banks			**Date/Time**	8/9/2018 8:50 AM

Permit #	TBD	**Inspection Type**	VA SWPP	**Station Begin**	+28
State	VA	**Inspection Area**	Full	**Station End**	+26
County	Giles	**Ground**	Dry	**Temperature (ºF)**	72.00
Municipality	N/A	**Weather**	Cloudy	**Rain Gauge (in)**	0.00
GPS Location	37.4171057412253, -80.7423727551809			**Rain Accumulation Time (days)**	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?	Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)	No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)	Yes

4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame
Compost Filter Sock	Acceptable		
Housekeeping	Acceptable		
Rock Construction Entrance	Acceptable		
Containment For Diesel Fuel	Acceptable		
Compost Filter Sock	Acceptable		
Housekeeping	Acceptable		
Rock Construction Entrance	Acceptable		

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	8/9/2018 8:50 AM	Report #	6056

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted Weekly VA SWPP at LY 26 and LY 28.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/9/2018 8:50 AM	Report #	6056

Pictures

GPS Location	37.3358210921635, -80.8082070854314
Description	LY 28

GPS Location	37.3193118130498, -80.6575427886412
Description	Fuel Containment at LY 26



GPS Location	37.3178632418041, -80.6582650636143
Description	Repairing Sock at LY 26

GPS Location	37.3178121960138, -80.6586181931949
Description	Lower parking lot atLY 26

Insert image here

GPS Location	
Description	

Insert image here

GPS Location	
Description	