Mountain Valley Visual Site Inspection Report										
Project Name H-600 Pipeline Spread G		AFE 124300137			Spread	H-600 Pipeline Spread G		pread G		
Contractor Precision		1 1			Report #	2794				
Inspector Brian Shields						Date/Time	6/8/2018 8:12 AM		AM	
Permit #	ТВГ)		Inspection Type VA SWPP			Station Begin 11788+43			
State	VA			Inspection Area Partial			Station End 11489+70			
County	Mor	ontgomery		Ground	Dry		Temperature (º		ture (ºF)	80.00
Municipality	Municipality N/A		Weather Sunny			Rain Gauge (in)		0.00		
GPS Location 37.2429856836663, -80.4285			5734208295 Rain A			ccumulation Time (days)			1.00	
1. Are the appr	ove	d (stampe	d) E&S Plan	and PCSM Plan pres	sent on si	te?				Yes
				the limits of disturba ermitting Coordinato				?		No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes				
4. E&S BMPs (is required.)	(List	: BMPs and	l note if insta	lled and maintained	as per th	e plan. If o	corrective acti	on i	is needed,	a pictui
E&S BMPs			Compliance Level		Correc	Corrective Action			Corrective Time Frame	
Compost Filter So	ock			Acceptable						
Permanent Diversion Berm			Acceptable							
Rock Construction Entrance			Acceptable							
Silt Fence (Filter Fabric Fence)			Acceptable							
Silt Fence (Reinforced Filter Fabric Fence)			Acceptable							
Sump Pit			Acceptable							
Vegetative Stabilization (Temporary)			Acceptable							
Waterbar				Acceptable						
5. Site Conditi	ons	3								
beyond defined	limit	ts of distur	bance resulti	iment, gravel, oil, HE ng from earth disturl ironmental Permittin	bance act	ivity or ine	•			No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes				
Are slopes 3:1 a	ınd (greater sta	abilized with a	appropriate BMPs as	per E&S	plans?				Yes
Han a new alim/alida baan abaam ad2 //f year approlate Clida Danart Form)										

MVP-34 REV 0 Page 1 of 3

Yes

Has a new slip/slide been observed? (If yes, complete Slide Report Form)

AFE 124300137	Date/Time 6/8/201	8 8:12 AM	Report #	2794
PCSM BMPs (List BMPs and note if inst picture is required.)	alled and maintained a	s per the plan. If correc	tive action is	needed, a
PCSM BMPs	Compliance Level			Corrective Time Frame
7. Identify all remedial measures that have	been taken since the p	revious inspection was	conducted.	
Comments (Reference above questions as Swppp inspection mp223.2 to 220.8 and mp219.		7.2 to 247.0		
Installed ECDs are functioning as designed with				
Areas requiring temporary stabilization have bee				
A reas requiring temporary stabilization have bee	in stabilized.			

MVP-34 REV 0 Page 2 of 3

maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 6/8/2018 8:12 AM			Report # 2794		
		Pictu	ıres				
Dark as finnes in Jun 8 00 Providing - 017, 2 20 2019 * / Aufflades * 1/22 11 Durbins - 6/05 - Auffladds * 1/22 11 Elonfellan Aug (s. 11.00*) Hundron (Aug (s. 11.00*) 2 20 2011 12	AS, ASP (EOT 2016)? VIE. 1881 Frid's True)		Dale & Time Fin St. 197, 2002. Altitude 28031 Datum, WGS-84 Azimuth +174 -3893mit Elevation Angle -00.3 Horizon Angle -02.6 Zoom 17	20,27 EUT 2010 000,2000 01			
	37.2429856836663, -80.4285734		GPS Location		6663, -80.4285734208295		
Description	Installed compost filter sock. GPS in photo above.	S coordinates	Description		waterbars near st#11669+08. es in photo above.		
Derine & Thomas, Pril Jum (8 18 Peuddinns - 4007/2004/2007 / AITIURAS, 2007/17 Derinams, 1998 - 146 Auftrautin, -1997 - 1460/2001 Electron Aurylins - 1500/2 Hortenn Aurylins			Date Time 1 (81) All the state of the state	94.51 EDT 2018 000.770000			
GPS Location	37.2429856836663, -80.4285734	4208295	GPS Location	37.242985683	6663, -80.4285734208295		
Description	Stabilized topsoil stockpiles near GPS coordinates in photo above	st#11766+89.	Description	Super silt fence coordinates in	e near st#11760+00. GPS photo above.		
	Insert image here			Insert ima	age here		
GPS Location	37.2429856836663, -80.4285734	4208295	GPS Location	37.242985683	6663, -80.4285734208295		
Description			Description				

MVP-34 REV 0 Page 3 of 3