Mour Mour	nta V	ain alley		Visual S	Site In	specti	on Repo	ort		
Project Name H-600 Pipeline Spread G		<b>AFE</b> 124300137			Spread	H-600 Pipeline Spread G		oread G		
Contractor Precision			' '			Report #	3073			
Inspector Clinton Banks						Date/Time	6/14/2018 2:02 PM			
Permit #	Permit # TBD			Inspection Type VA SWPP			Station Begin 12005+00			
State	VA			Inspection Area	Full		Station End 11988+96			
County	Мо	ntgomery		Ground	Damp	np Temperature (ºF			re (ºF)	80.00
Municipality	N/A	\		Weather	Sunny	Rain Gauge (in)			0.00	
<b>GPS Location</b>	37.	268147701	4322, -80.3167	7212848368		Rain Accumulation Time (days)			days)	3.00
1. Are the appre	ove	d (stampe	d) E&S Plan a	and PCSM Plan pre	sent on si	te?				Yes
(If yes, notify	2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings?  (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)								No	
followed? (If	<ol> <li>Is Construction sequence outlined in the construction notes of the E&amp;S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)</li> <li>E&amp;S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture.)</li> </ol>									
is required.)	LISI	. BMPS and	i note ii insta	nied and maintained	as per ui	e pian. Ii (	corrective acti	on is n	eeaea,	a picture
E&S BMPs		Compliance Level		Correc	ective Action		Corrective Time Frame			
Compost Filter So	ock			Acceptable						
Clean Water Diversion			Acceptable							
Dewatering Work Area			Acceptable							
Housekeeping			Acceptable							
Waterbar			Acceptable							
					$\perp$					
5. Site Conditi										
beyond defined	limi	ts of distur	bance resulti	iment, gravel, oil, HI ng from earth disturl ironmental Permittin	oance act	ivity or ine				No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes			
<u> </u>				appropriate BMPs as	<u> </u>	<u> </u>				Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)								No		

MVP-34 REV 0 Page 1 of 3

<b>AFE</b> 124300137	Date/Time 6/14/20	18 2:02 PM	Report #	3073				
<ol><li>PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)</li></ol>								
PCSM BMPs	Compliance Level	Corrective Ac	Corrective Time Frame					
7. Identify all remedial measures that have been taken since the previous inspection was conducted.								
Comments (Reference above questions as appropriate.)								
Arrived at Catawba Road conducted SWPP Env 227.0  Note: It is a condition of National Pollutant (								

weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a

MVP-34 REV 0 Page 2 of 3

<b>AFE</b> 124300137	7	Date/Time 6/14/2018 2:02 PM			Report #	3073
		Pict	ures			
		Insert image here				
	37.32991313256, -80.737067463	31313	GPS Location			
Description	Clean water deversion		Description			
	Insert image here			Insert im	age here	
GPS Location			GPS Location			
Description			Description			
	Insert image here			Insert im	age here	
GPS Location			GPS Location			
Description			Description			

MVP-34 REV 0 Page 3 of 3