



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	3306
Inspector	Clinton Banks			Date/Time	6/20/2018 7:42 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	+37
State	WV	Inspection Area	Full	Station End	+37
County	Monroe	Ground	Dry	Temperature (°F)	70.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
GPS Location	37.3299732703957, -80.737033495913			Rain Accumulation Time (days)	6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame
Silt Fence (Filter Fabric Fence)	Acceptable		
Compost Filter Sock	Acceptable		
Permanent Diversion Berm	Acceptable		
Compost Filter Berm	Acceptable		

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? WV: Exceeding 7 days if to be left inactive for more than 21 days	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/20/2018 7:42 AM	Report #	3306
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs		Compliance Level	Corrective Action	Corrective Time Frame	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at Precision Yard 37 Conducted Weekly SWPP check, also checked equipment before departed Yard 37.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	6/20/2018 7:42 AM	Report #	3306
Pictures					
Insert image here					
GPS Location	37.4174710595127, -80.741578173797	GPS Location	37.4171401793486, -80.7424694952376		
Description		Description	Wetland Crossing W-IJ82 Yard 37		
Insert image here		Insert image here			
GPS Location		GPS Location			
Description		Description			
Insert image here		Insert image here			
GPS Location		GPS Location			
Description		Description			