Mountain Valley PIPELINE US Visual Site Inspection Report										
Project Name H-600 Pipe		line Spread G AFE 124300137			Spread	H-600 Pipeline Spread G				
Contractor Precision						Report #	4324			
Inspector Clinton Banks						Date/Time	7/9/2018 9:29 AM			
Permit #	Permit # TBD			Inspection Type VA SWPP			Station Beg	jin +28		
State	VA			Inspection Area	Full		Station End +26			
County	Gile	es		Ground	Dry		Temperature (°F) 73.00			73.00
Municipality	N/A	١		Weather	Sunny		Rain Gauge (in)			0.00
GPS Location	37.	7.3954026799093, -80.7883572212452			Rain A	accumulation Time (days)			1.00	
Are the approved (stamped) E&S Plan a				and PCSM Plan present on site?						Yes
Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)										No
 Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a 								Yes		
is required.)	LISI	L DIMPS all	i note ii insta	neu anu mamtameu	as per t	пе рап. п	corrective acti	OH IS H	eeueu,	а рісціге
E&S BMPs			Compliance Level		Correc	tive Action		Corrective Time Frame		
Compost Filter Sock			Acceptable							
Housekeeping			Acceptable							
Rock Construction Entrance			Acceptable							
Compost Filter Berm			Acceptable							
Rock Construction Entrance			Acceptable							
Containment For Diesel Fuel			Acceptable							
					+					
5. Site Conditi	ons									
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.										
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?									Yes	
Are slopes 3:1 a	ınd	greater sta	abilized with a	ppropriate BMPs as	per E&	S plans?				Yes
Has a new slip/s	slide	been obs	served? (If ye	s, complete Slide R	eport Fo	rm)				No

MVP-34 REV 0 Page 1 of 3

AFE 124300137	Date/Time 7/9/201	8 9:29 AM	Report #	4324						
 PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) 										
PCSM BMPs	Compliance Level	Corrective Action		Corrective Time Frame						
7. Identify all remedial measures that have been taken since the previous inspection was conducted.										
Comments (Reference above questions as	appropriate.)									
Conducted Weekly SWPP at LY 28 & LY 26, did	not observed any Enviro	nmental Discrepancies at	either yard.							
Note: It is a condition of National Pollutant [Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a									
maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a										

MVP-34 REV 0 Page 2 of 3

weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.

MVP-34 REV 0 Page 3 of 3