Mour Mour	ita V	ain alley		Visual S	Site In	specti	on Repo	ort	İ	
Project Name H-600 Pipeline Spread G			<b>AFE</b> 124300137			Spread	H-6	H-600 Pipeline Spread G		
Contractor Precision			-			Report #	548			
Inspector Rob Robertson						Date/Time	7/3	0/2018 6:17	7 PM	
Permit # TBD			Inspection Type VA SWPP			Station Beg	jin	10458+91		
State	VA			Inspection Area	Full		Station End 10459+03			
County	Gile	es		Ground	Damp		Temperature (°F)			73.00
Municipality	N/A			Weather	Cloudy		Rain Gauge (in)			0.20
<b>GPS Location</b> 37.1331805719697, -80.3944			597401347 Rain A			ccumulation Time (days)			1.00	
1. Are the appr	ove	d (stampe	d) E&S Plan a	and PCSM Plan pres	sent on s	ite?				Yes
				the limits of disturba ermitting Coordinato				?		No
				e construction notes ntal Permitting Coor					et being	Yes
<ol><li>E&amp;S BMPs ( is required.)</li></ol>	(List	BMPs and	I note if insta	lled and maintained	as per th	e plan. If	corrective acti	on i	is needed,	a pictur
E&S BMPs		Compliance Level		Correc	orrective Action			Corrective Time Frame		
Compost Filter So	ock			Acceptable						
Housekeeping				Acceptable						
Silt Fence (Filter Fabric Fence)			Acceptable							
Vegetative Stabilization (Temporary)			Acceptable							
Waterbar				Acceptable						
5. Site Conditi										
beyond defined	limit	ts of distur	bance resulti	ment, gravel, oil, HI ng from earth disturl ironmental Permittin	oance ac	tivity or ine	•			No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes				
Are slopes 3:1 a	ınd (	greater sta	abilized with a	ppropriate BMPs as	per E&S	plans?				N/A
Lieu e new elin/elide been ebeen/ed2 (If vec complete Clide Depart Form)						Nia				

MVP-34 REV 0 Page 1 of 3

No

Has a new slip/slide been observed? (If yes, complete Slide Report Form)

AFE	124300137	<b>Date/Time</b> 7/30/20	018 6:17 PM	Report #	5480		
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a							
picture is required.)							
PCSM BMPs		Compliance Level	Corrective Ac	Corrective Time Frame			
		20701			Time Traine		
7. Identify all remedial measures that have been taken since the previous inspection was conducted.							
Comn	nents (Reference above questions as	appropriate.)					
precipi areas o FS LEG in good	med a 4-day SWPPP inspection of enviro tation in the last 24 hours in this area. I for sediment migration beyond the approved and Global Security traffic around the condition. Mystery Ridge Road controls nance needs. I was informed that the world the condition is a second to the condition of the condition is a second to the condition of the condition in the condition is a second to the condition of the condition of the condition in the condition of the conditio	ound ample environmenta ed limits. There is no cons lock on both roads. Pocal are functional but in nee	controls in place on both struction activity traffic on one nontas Road was found st d of maintenance. I have r	roads. I did no either road curr able with contr notified the con	t locate any ently. There is ols in place and tractor of		
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a							

weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a

MVP-34 REV 0 Page 2 of 3

<b>AFE</b> 12430013	7	Date/Time	7/30/2018 6:17 Pi	М	Report #	5480	
Pictures							
Districts Maria Maria General Control of the Maria Mar	Page No Carte Cart		Oute 2 Timis Main Nation Possitions 207 of 22 228 Affides 227119 Outum West at Annual Possition 249 St Elevation Grade - 024 Herzan Grane, 003 Zoom 15 V. San Whitery Ridgi Flood conf	an aste 17-bit est dec 20-45 sg. 72E 761 mils (flag) ots need maintenance			
	37.1331587548844, -80.3945016		GPS Location				
Description	ECD maintenance needs identifie Ridge Road.	ed on Mystery	Description	ECD maintenan Ridge Road.	ice needs ide	ntified on Mystery	
Date & mee Man, Jul 30 Pessing, 2037-23 20 77 Allinde 31531 Ostum WSS-34 Azmutin Sannin 167 S Erestion Brade, 937 Horzandrader 1088 Zoom, XX We link Radic Radic 2037	2016 10 religional Tipo del constitución		Elevation Grade: -040% Horizon Grade: -001 % Zoom: 1X	2018. 11 07 23 EDT -080 (4) 28 &5			
GPS Location	37.1331380820248, -80.3945505	5247269	<b>GPS Location</b>	37.1331583886	053, -80.394	5007636317	
Description	ECD maintenance needs identifice Ridge Road.	ed on Mystery	Description	ECDs in accept Road.	able conditior	n on Pocahontas	
	Insert image here			Insert ima	ge here		
GPS Location			GPS Location				
Description			Description				

MVP-34 REV 0 Page 3 of 3