Moun	ita V	alley		Visual S	Site In	specti	on Repo	ort			
Project Name H-		H-600 Pipe	-600 Pipeline Spread H			<b>I</b> 124300138		H-60	00 Pipeline S <sub>l</sub>	oread H	
Contractor Precision			,			Report #	833				
Inspector Pat Davis							Date/Time	Date/Time 4/7/2018 12:35			
Permit #	ТВЕ	)		Inspection Type Weekly			Station Beg	Station Begin 11998+00			
State	VA			Inspection Area	Full		Station End 12640+00				
County	Mor	ntgomery		Ground	Wet		Temperature (ºF)			43.00	
Municipality	N/A			Weather	Light Rair	1	Rain Gauge (in)			0.20	
GPS Location	37.1	187396152	9109, -80.1743	3487921358		Rain Ad	ccumulation	1.00			
1. Are the appro	1. Are the approved (stamped) E&S Plan a				and PCSM Plan present on site?						
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings?  (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)										No	
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)								Yes			
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)											
E&S BMPs			Compliance Level		Corrective Action			rective Frame			
5. Site Conditi					•				<u>'</u>		
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.											
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?									N/A		
Are slopes 3:1 a	ınd g	greater sta	abilized with a	ppropriate BMPs as	per E&S	plans?				N/A	
Has a new slip/slide been observed? (If yes, complete Slide Report Form)									No		

MVP-34 REV 0 Page 1 of 3

<b>AFE</b> 124300138	Date/Time 4/7/201	8 12:35 PM	Report #	833								
<ol> <li>PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)</li> </ol>												
PCSM BMPs	Compliance Level	Corrective Ac	Corrective Time Frame									
7. Identify all remedial measures that have been taken since the previous inspection was conducted.												
Comments (Reference above questions as a	appropriate.)											
Attended morning spread inspectors meeting. Cl crossings and access road between station 1199 pipeline right of way or access roads. Check for	neck rain gauges at Cata 8+00 to station 12640+0 tree felling crew working	wba Road (.2), MVP-MN- 0. No impact to VDOT or from MP 231.7 to MP 232	278.01 (.1). C other public ro 2.4 near Reese	heck road ads from the Mountain Road.								
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a												

MVP-34 REV 0 Page 2 of 3

maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300138 Date/Time 4/7/2018 12:35 PM Report # |833 **Pictures** 37.2789040235382, -80.029002626136 **GPS Location** 37.2788818600003, -80.0287985523045 **GPS Location** MVP-MN-270.01\_040718 Half Acre of Rock MVP-MN-270\_040718 Bacchae Road at Flatwoods Road looking N. No impact on VDOT Roadways. See photo for correct gps Road @ Flatwoods Road. Looking N. No Description Description impact on VDOT Roadway. See photo for 15'34", -80°16'52", 416.0m, 29 **GPS Location GPS Location** 37.2788501764064, -80.0287641026825 37.2788272519012, -80.0287164096535 MVP-MN-272\_040718 @ Flatwoods Road MVP-MN-278.01 040718 feature S-KL32 looking SE. No impact on VDOT Roadway. looking W. See photo for correct gps location. Description Description see photo for correct gps location GPS Location 37.2788233124067, -80.0287052617222 **GPS Location** 37.2788244858731, -80.0287041720748 MVP-MN-278.01 040718 Yellow Finch Road MVP-MN-274 040718 @ Bradshaw Road looking NW. No impact to VDOT roadways. See photo for correct gps location. @ Cove Hollow Road no impact to VDOT Description Description roadways. See photo for correct gps location.

MVP-34 REV 0 Page 3 of 3