Certification Statement

I certify under penalty of law that I have read and understand this document and that this document and all attachments were prepared in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Inspector's Name (printed): Mike Ren fro

Inspector's Signature:

Date: 8-31-18

Spread I Laydown Yord
Report # 7357
SWIN 1369
ESIN 0946

Mountain Valley Visual Site Inspection Report									
Project Name H-600 Pipeline Spread I		AFE 124300139		Spread	H-600 Pipeline Spread I				
Contractor Precision					Report #	7357			
Inspector Glenn Mike Renfro					Date/Time	8/31/2018 7:51 AM			
Permit #	TBD	Inspection Type	VA SWPP		Station Beg	in 0000+0)		
State	VA	Inspection Area	Full		Station End 0000+00)		
County	Franklin	Ground	Dry		Temperature (°F) 99.00		99.00		
Municipality	N/A	Weather	Sunny		Rain Gauge (in) 0.00		0.00		
GPS Location	36.9718794179572, -79.870	1271202903		Rain Ac	ccumulation Time (days) 1.00				
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes			
Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No		
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes			
 E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) 									
1	E&S BMPs	Compliance Level		Correct	rive Action		Corrective Time Frame		
Compost Filter Sock		Acceptable							
Housekeeping		Acceptable							
Rock Construction Entrance		Acceptable							
Silt Fence (Filter Fabric Fence)		Acceptable							
		2 18 15							
5. Site Condition	ons		1						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.									
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							N/A		
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							N/A		
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No		

MVP-34 REV 0 Page 1 of 3

AFE 124300139	Date/Time 8/31/2018 7:51 AM									
6. PCSM BMPs (List BMPs and note if ins	stalled and maintained a	s per the plan. If correc	tive action is	needed, a						
picture is required.)				Corrective						
PCSM BMPs	Compliance	Corrective Ac	Corrective Action							
. com bin c	Level	Corrective Action		Time Frame						
7. Identify all remedial measures that have	e been taken since the p	revious inspection was	conducted.							
(2)										
Comments (Reference above questions as appropriate.) Performed SWPPP inspection on Main laydown yard in Rocky Mount, Va. All perimeter ECD's were inspected and no problems										
were found. All secondary containment structur	es were in good condition	The RCF was found to be	clean and roa	d clear of any						
debris. The drain inlet protection on the parking	lot drains were all found to	be in good condition. The	site is current	tly in compliance.						
Note: It is a condition of National Pollutant	Discharge Elimination Sy	ystem and Erosion and	Sediment pe	rmits that a						
maintenance program be conducted to prov weekly basis and after each stormwater eve	ride for the operation and	are provided comments	APS to be insp	pected on a						
replacement are needed or have been mad	e for BMPs as a result of	f the inspection. Failur	e to conduct	the required						
inspection may result in permit suspension	inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required									
as part of a permit condition this form may be used to meet those monitoring requirements.										

MVP-34 REV 0 Page 2 of 3

MVP-34 REV 0 Page 3 of 3