## Certification Statement

I certify under penalty of law that I have read and understand this document and that this document and all attachments were prepared in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Inspector's Name (printed): Mike Rentio

Inspector's Signature:

Date: 9-6-18

Spread I Laydown yord
Report # 7437
SWIN 1369
ESIN 090

	P	IPELINE uc		Visual					
Project Name H-600 Pipeline Spread I			<b>AFE</b> 124300139			Spread	H-600 Pipeline	H-600 Pipeline Spread I	
Contractor Precision						Report #	7437		
Inspector Glenn Mike Renfro						Date/Time	9/6/2018 2:44 PM		
Permit #	Permit # TBD			Inspection Type VA SWPP			Station Begin 0000+00		
State	VA			Inspection Area	Full		Station E	nd 0000+00	
County	Fra	nklin		Ground	Dry		Temp	erature (ºF)	90.00
Municipality	N/A	4		Weather	Sunny		Rain	Gauge (in)	0.00
GPS Location	36.	971895522	4647, -79.8702	2716784138		Rain A	ccumulation '	1.00	
1. Are the appr	ove	d (stampe	d) E&S Plan	and PCSM Plan pre	sent on si	ite?			Yes
<ol><li>Are there ac (If yes, notify</li></ol>	tiviti the	ies occurri MVP Env	ng outside of ironmental P	the limits of disturbatermitting Coordinate	ance show or and exp	vn on the plain in co	plan drawings? mments.)		No
followed? (If	No	, notify MV	P Environme	e construction notes ntal Permitting Coor	dinator ar	nd explain	in comments.)		Yes
<ol><li>E&amp;S BMPs is required.)</li></ol>	(Lis	t BMPs and	I note if insta	lled and maintained	as per th	e plan. If	corrective action	on is needed,	a pictu
E&S BMPs			Compliance Level		Correc	ctive Action		Corrective Time Frame	
Compost Filter S	ock			Acceptable					
Housekeeping				Acceptable					
Rock Construction	n Er	ntrance	Ng - Wyarasteka — A	Acceptable	e and the second			W. C	ergy was ex
Silt Fence (Filter I	Fabi	ric Fence)		Acceptable					
					+				
5. Site Condition	ons								
beyond defined I	imit	s of disturk	ance resultin	ment, gravel, oil, HD og from earth disturt onmental Permitting	ance acti	ivity or ine			No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							N/A		
re slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							N/A		
and the same of th			erved? (If yes					THE RESERVE AND PARTY AND PERSONS ASSESSMENT	

MVP-34 REV 0 Page 1 of 3

<b>PCSM BMPs</b> (List BMPs and note if picture is required.)	installed and maintained as	s per the plan. It come	ective action is	Heeded, o	
PCSM BMPs	Compliance Level	Corrective A	action	Corrective Time Fram	
				10.00	
			7		
				1. 11. 1	
			CONTRACTOR DESCRIPTION OF THE PERSON OF THE		
. Identify all remedial measures that h	ave been taken since the pr	revious inspection was	s conducted.		
		revious inspection was	s conducted.		
Comments (Reference above questions Deformed SWPPP inspection on main layor	5 as appropriate.) own yard in Rocky Mount, Va. as free of any debris. All secon	All perimeter ECD's wer	e inspected and	mpliance The	
Comments (Reference above questions Performed SWPPP inspection on main layd	<b>5 as appropriate.)</b> own yard in Rocky Mount, Va. as free of any debris. All secon ved laydown yard were in good	All perimeter ECD's wer	e inspected and	mpliance The	
Comments (Reference above questions erformed SWPPP inspection on main layd begreed. The RCF is clean and the road w	<b>5 as appropriate.)</b> own yard in Rocky Mount, Va. as free of any debris. All secon ved laydown yard were in good	All perimeter ECD's wer dary containment's stru- d condition. The site in c	e inspected and	mpliance The	
Comments (Reference above questions Performed SWPPP inspection on main layor because of the ROF is clean and the road w	<b>5 as appropriate.)</b> own yard in Rocky Mount, Va. as free of any debris. All secon ved laydown yard were in good	All perimeter ECD's wer dary containment's stru- d condition. The site in c	e inspected and	mpliance The	
Comments (Reference above questions Performed SWPPP inspection on main layor because of the ROF is clean and the road w	<b>5 as appropriate.)</b> own yard in Rocky Mount, Va. as free of any debris. All secon ved laydown yard were in good	All perimeter ECD's wer dary containment's stru- d condition. The site in c	e inspected and	mpliance The	
Comments (Reference above questions Performed SWPPP inspection on main layd observed. The RCE is clean and the road worotection for the three drain inlets at the pa	<b>5 as appropriate.)</b> own yard in Rocky Mount, Va. as free of any debris. All secon ved laydown yard were in good	All perimeter ECD's wer dary containment's stru- d condition. The site in c	e inspected and	mpliance The	

MVP-34 REV 0 Page 2 of 3

replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b> 12430013	9	Date/Time	9/6/2018 2:44 PM	1	Report #	7437
		Pict	ures			
GPS Location	36.9719030712575, -79.8702620		GPS Location			
Description	Perimeter ECD's in good condition northwest corner of paved yard.	on at	Description	secondary contai compliance.	nment for ba	rrel storage in
GPS Location	36.9718979013489, -79.8702720		GPS Location	36.971900753070	05, -79.87024	17410675
Description	Perimeter ECD's in good conditio end of gavel laydown yard	on at north	Description	Inlet protection ne good condition.	ear tool storaç	ge building in
	Insert image here			Insert imag	e here	
GPS Location			GPS Location			
Description			Description			

MVP-34 REV 0 Page 3 of 3